

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Architectural Inspection

M884

Asset: P.S. 18 ANNEX (GYM) - MANHATTAN, 4130 9TH AVENUE, MANHATTAN, NY, 10034

Inspection Id	Inspection Type	Time In	Last Edited
291	ARCHITECTURAL - ASSOCIATE	2023-10-19 08:54AM	2023-10-19 03:19PM
348	ARCHITECTURAL - SENIOR	2023-10-19 07:37AM	2024-04-21 02:36PM

Asset Data

Question	Answer
Was the Building Fully Accessible for Inspection?	Yes
Principal(s) Information	
Principal Name	Connie Mejia
Principal Organization	P.S. 18 - Annex
Meeting with Principal?	Yes
Principal Feedback	The Principal had no comments about the condition of the building at this time.
Principal Name	Bryanna Velazquez
Principal Organization	P.S./I.S. 278 - Manhattan
Meeting with Principal?	Yes
Principal Feedback	The Principal had no comments about the condition of the building at this time.
Custodian	Edwardo Collazo
Was the Custodian Present?	No
Fireman	Albert Rosa
Was the Fireman Present?	Yes
Building Square Footage	9,000
Comments on the Area (for Athletic Field, Playing Surfaces, Leased Spaces)	None
Comments on the Stories (Floors) plus Basements	2 (No Basement)
Comments on the Year Built	1935
Student Population	535
Staff Population	2
Comments on the Number of Classrooms	1
Weather	Fair
Facade Photo	



9th Avenue - North View

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Architectural Inspection


M884

Main Entrance Photo



Facade A - 9th Avenue

Roof Photo



Roof 1 - Southeast View

Do Stormwater Management/Green Infrastructure systems exist?

Type

Have any Systems/Major Building Components been upgraded?

Have there been any New Building Additions?

Tandem

Leased Space?

Year Leased

Inspection Type

No

No Storm Water Management Type Selected

Systems: Upgraded Ceiling tile and wall padding

Years: 2018

No New Construction

No Tandem

Yes

1991

Full Inspection

Priority Condition

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
No condition recorded							

Structural Engineer Required

Structural Condition Type	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
No condition recorded						

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Architectural Inspection

M884

Programmatic Accessibility

Programmatic Accessibility Status Question	Response
Is the Primary or secondary entrance on an accessible route?	Yes
Is the building a multi-story building?	Yes
Are All floors of the building accessible through compliant means?	Yes
Accessible classrooms exists on each floor?	Yes
Boys and Girls or Unisex accessible toilets exist on at least every other floor?	Yes
If the following spaces exist, are they ALL accessible? Art Room, Auditorium, Cafeteria, Computer, Gymnasiums, Library, Multipurpose Room, Science Labs	Yes

Physical Breakdown Structure	Exists	Complies	Required	Deficiency	Assistive Listening System	Fire Alarm Strobe
------------------------------	--------	----------	----------	------------	----------------------------	-------------------

PROGRAMMATIC ACCESSIBILITY

Exterior Routes

Exterior Entrances & Exits		Yes				
Exterior H/C Lifts	No		No			
Exterior Ramps and Railings	No		No			

Interior Routes

Corridor and Lobby H/C Lifts	Yes	Yes				
Interior Corridor Doors And Hardware	Yes	Yes				
Interior Corridors & Lobbies		Yes				
Interior Elevators	No					
Interior Lobby Doors And Hardware		Yes				
Interior Ramps	No					

Rooms & Spaces

Art Rooms	No					
Auditorium	No					
Cafeteria	No					
Classrooms	No					
Computer Rooms	No					
Gymnasium	No					
Library	No					
Main Office	No					
Multi-purpose Room						
1st Floor	Yes	Yes			No	Yes
Nurse's Office	No					
Pool	No					
Science Lab	No					
Toilet Rooms (boys)						
Room 110 (Unisex)	Yes	Yes				
Toilet Rooms (girls)						
Room 110 (Unisex)	Yes	Yes				
Toilet Rooms (staff)	No					


**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Architectural Inspection



M884

Building Template

M884



Inspection

Question	Response
Architectural	
EXTERIOR	Inspected
AREAWAY	Does not exist
AWNINGS AND CANOPIES	Does not exist
CHIMNEY	Does not exist
COPING	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
CORNICE	Does not exist
DOORS	Inspected
DOORS AND FRAMES	Inspected
Condition	3- Fair
Deficiency	METAL CLAD:DETERIORATED DOOR AND FRAME - MINOR DETERIORATION
Deficiency Location/Instance	
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo 1	


Exit 5

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Architectural Inspection

M884

Question	Response
EXTERIOR	
DOORS	
DOORS AND FRAMES	
Deficiency Photo 2	No photo recorded
Violations	No violations recorded
DOOR HARDWARE	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
LINTELS	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
TRANSOM/SIDE LIGHT	Does not exist
EXTERIOR WALLS	Inspected
Material Type(s)	Masonry
Replacement Quantity	2,000
Replacement Uom	S.F.
Instance on Facades A and B	Inspected
Instance Condition	2- Between Good and Fair
Instance Quantity	2,000
Instance Quantity Uom	S.F.
Deficiency	No deficiencies recorded
EXTERIOR SOFFITS	Does not exist
LOADING DOCK	Does not exist
LOUVER	Does not exist
PARAPETS	Inspected
Material Type(s)	Masonry
Replacement Quantity	500
Replacement Uom	C.F.
Instance on Facades A and B	Inspected
Instance Condition	2- Between Good and Fair
Instance Quantity	500
Instance Quantity Uom	CF
Deficiency	No deficiencies recorded
PLAZA DECK	Does not exist
ROOF	Inspected
ROOFING	Inspected
ROOF HATCH/SMOKE HATCH	Does not exist
LEADERS, GUTTERS, DOWNSPOUTS, SCUPPERS	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
ROOF BARRIER/FENCE	Does not exist
ROOF CAGE	Does not exist
ROOFING	Inspected
Replacement Quantity	6,000
Replacement Uom	S.F.
Instance on Modified Bitumen:Roof 1	Inspected
Instance Roof Photo	



Roof 1

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Architectural Inspection

M884

Question	Response
EXTERIOR	
ROOF	
ROOFING	
ROOFING	
Instance Condition	4- Between Fair and Poor
Instance Quantity	6,000
Instance Quantity Uom	S.F.
Does the roof have major mechanical equipment sitting on Dunnage Steel less than 18" above the Roofing?	Yes
Does this Roof Instance have a Sustainable Roof System?	Yes
Sustainable Roof System Type	White Roof
Sustainable Roof System Location (Roof Number)	Roof 1
Do solar panels exist on these roofs?	No
Is/Are the roof(s) suitable for Solar Panel installation?	No
Installation Year	1990
Source of Installation Year	Inspector Estimate
Deficiency	MODIFIED BITUMEN:ROOFING:DELAMINATION
Deficiency Location/Instance	
Deficiency Quantity	200
Quantity Uom	S.F.
Potential Action	REPLACE ROOFING WITHOUT MAJOR EQUIPMENT REMOVAL
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 2
Deficiency Photo 1	
Deficiency Photo 2	No photo recorded
Violations	No violations recorded
Deficiency	MODIFIED BITUMEN:ROOFING:BEYOND USEFUL LIFE
Deficiency Location/Instance	Modified Bitumen:Roof 1
Deficiency Quantity	6,000
Quantity Uom	S.F.
Potential Action	REPLACE ROOFING WITH MAJOR EQUIPMENT REMOVAL
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo 2	No photo recorded
Violations	No violations recorded
ROOFING DRAINS	Does not exist
SPECIALTIES	Inspected
BULKHEAD/PENTHOUSE	Inspected
Condition	3- Fair
Deficiency	BULKHEAD/PENTHOUSE WALLS/EXTERIOR:CRACKS/SPALLING - MINOR

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Architectural Inspection

M884

Question	Response
----------	----------


EXTERIOR

ROOF

SPECIALTIES

BULKHEAD/PENTHOUSE

Deficiency Location/Instance



Deficiency Quantity

100

Quantity Uom

S.F.

Potential Action

REPAIR

Urgency of Action

PRIORITY 3

Purpose of Action

LEVEL 2

Deficiency Photo 1



Bulkhead BH

Deficiency Photo 2

No photo recorded

Violations

No violations recorded

CUPOLA/ SPIRES/ TOWERS

Does not exist

DORMER

Does not exist

DUNNAGE STEEL

Does not exist

SKYLIGHT/ROOF VENT

Does not exist

ROOF/GRAVITY TANK

Does not exist

STAIRS/RAMPS: EXTERIOR

Does not exist

WINDOWS

Inspected

Replacement Quantity

150

Replacement Uom

S.F.

EXTERIOR GUARDS

Inspected

Condition

2- Between Good and Fair

Deficiency

No deficiencies recorded

LINTELS

Inspected

Condition

2- Between Good and Fair

Deficiency

No deficiencies recorded

WINDOWS

Inspected

Material Type(s)

Aluminum

Instance on Aluminum - Double Hung: Facades A and B

Inspected

Instance Condition

3- Fair

Instance Quantity

150

Instance Quantity Uom

S.F.

Installation Year

2005

Source of Installation Year

Inspector Estimate

Are these windows insulated?

Yes

Deficiency

No deficiencies recorded

INTERIOR

Inspected

POOLS

Does not exist


STRUCTURAL

Inspected

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Architectural Inspection



M884

Question	Response
INTERIOR	
STRUCTURAL	
COLUMNS/BEAMS/BEARING WALLS	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
FLOOR STRUCTURE	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
FOUNDATION WALLS	Inaccessible
ROOF STRUCTURE	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
VAULTS-BUNKERS	Does not exist
AUDITORIUM	Does not exist
CAFETERIA	Does not exist
CLASSROOMS/CORRIDORS/ADMIN SPACES	Inspected
Ceiling	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Door(s)	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Floor Finish	Inspected
Condition	2- Between Good and Fair
Deficiency	VINYL TILES:DETERIORATED SUBSTRATE
Deficiency Location/Instance	Corridor near Room 105, Rooms 110B, 110C
Deficiency Quantity	50
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo 1	
	Corridor near Room 105
Deficiency Photo 2	No photo recorded
Violations	No violations recorded
Walls	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Specialties	Does not exist
GYMNASIUM	Does not exist
INTERIOR DOOR HARDWARE	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
INTERIOR GUARDS	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
KITCHEN	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Architectural Inspection

M884

Question	Response
INTERIOR	
LIBRARY	Does not exist
LOCKER ROOM	Does not exist
MULTI-PURPOSE ROOM	Inspected
Instance on 1st Floor	Inspected
Ceiling	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Door(s)	
Instance on 1st Floor	Inspected
Instance Condition	4- Between Fair and Poor
Deficiency	WOOD:DETERIORATED DOOR
Deficiency Location/Instance	Main Entrance
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo 1	
	Main Entrance
Deficiency Photo 2	No photo recorded
Violations	No violations recorded
Fixed Equipment	
Instance on 1st Floor	Does not exist
Floor Finish	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	WOOD:DAMAGED/DETERIORATED
Deficiency Location/Instance	Near Drinking Fountain
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo 1	
	Near Drinking Fountain
Deficiency Photo 2	No photo recorded
Violations	No violations recorded
Deficiency	CERAMIC TILE:BROKEN/MISSING TILES
Deficiency Location/Instance	Near Drinking Fountain

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Architectural Inspection


M884

Question	Response
INTERIOR	
MULTI-PURPOSE ROOM	
Floor Finish	
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo 1	
Deficiency Photo 2	Near Drinking Fountain
Violations	No photo recorded No violations recorded
Sliding-folding Partition	
Instance on 1st Floor	Does not exist
Stage	
Instance on 1st Floor	Does not exist
Walls	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	WALL PADDING:DETERIORATED
Deficiency Location/Instance	Column, Near Entrance , Near Drinking Fountain
Deficiency Quantity	100
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo 1	
Deficiency Photo 2	Column
Violations	No photo recorded No violations recorded
Window Curtains/Shades/Blinds	
Instance on 1st Floor	Does not exist
SCIENCE DEMO ROOM	
Does not exist	
SCIENCE LAB	
Does not exist	
SCIENCE PREP ROOM	
Does not exist	
SHOWER ROOM	
Does not exist	
STAIRS/RAMPS: INTERIOR	
Do Letter Stair Signs Exist?	Inspected
Ceiling	Yes
Condition	Inspected
Deficiency	2- Between Good and Fair No deficiencies recorded

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Architectural Inspection


M884

Question	Response
INTERIOR	
STAIRS/RAMPS: INTERIOR	
Door(s)	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Partition	Does not exist
Railings	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Stairs and Landings	Inspected
Condition	2- Between Good and Fair
Deficiency	SHEET VINYL:WORN-OUT TREAD/NOSINGS
Deficiency Location/Instance	Near entrance
Deficiency Quantity	15
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo 1	
Deficiency Photo 2	Near Entrance
Violations	No photo recorded No violations recorded
Walls	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
TOILET ROOMS - STAFF	Does not exist
TOILET ROOMS - STUDENTS	Inspected
Ceiling	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Door(s)	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Floor Finish	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Stalls	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Walls	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
LIFE SAFETY	Inspected
F.D. HOLDING AREA	Does not exist
STEEL STAIRS	Does not exist
SITE	Inspected
CONTAINERIZATION	Does not exist

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Architectural Inspection

M884

Question	Response
SITE	
DRAINAGE SYSTEM FOR ASPHALT	Does not exist
DRAINAGE SYSTEM FOR CONCRETE	Does not exist
DRAINAGE SYSTEM FOR SOIL	Does not exist
DRINKING FOUNTAINS	Does not exist
FENCES	Does not exist
IRRIGATION SYSTEM	Does not exist
PAVING	Inspected
Student Non-Use	Does not exist
Student Use	Does not exist
Site Sidewalks & Walkways	Inspected
Asphalt	Does not exist
Concrete	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Pavers	Does not exist
DOT Sidewalk	Inspected
Asphalt	Does not exist
Concrete	Inspected
Condition	3- Fair
Deficiency	DAMAGED/DETERIORATED/MISSING SECTIONS
Deficiency Location/Instance	9th Avenue
Deficiency Quantity	125
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo 1	
Deficiency Photo 2	9th Avenue
Violations	No photo recorded No violations recorded
Pavers	Does not exist
PLAYGROUNDS	Does not exist
PLAYING SURFACE	Does not exist
RETAINING WALLS	Does not exist
SEATING	Does not exist
SITE WALLS (NOT RETAINING WALLS)	Does not exist
STAIRS/RAMPS: EXTERIOR	Does not exist

NYC Department of Education
Building Condition Assessment Survey 2023-2024

Architectural Inspection

M884

Does the SCA expect asset to have artwork?

No