Building Condition Assessment Survey 2023-2024

Electrical Inspection

	,		TREET, MANHATTAN, NY,	
				Last Edited
			2023-11-15 11:02AM	2023-12-08 10:07AN
Components been upgraded?		Systems:	Retrofitted LED Lighting, Comp with Receptacles), IPDVS/CCT	
		Years:	2023	
		Systems:	Intercom System (Elevator)	
		Years:	2020	
		Systems:		x)
		Years:		
		Systems:	Lights	ack), Exit/Emergency
		Years:	2010	
		Systems:	Multipurpose Room (Theater Li	ghting System)
		Years:	2000	
		-		d Components
		Years:		
			ound	
/				
		No		
IN FIRE RESCUE AREAS			Dasnansa	
ance Areas Fire Rescue Areas a	nd/or Holding Root		•	
Condition Description	Component Affected	Location Description		Photo mage
		Response	9	
		Does not	exist	
		Does not		
		Inspected		
r				
		Inspected Inspected		
r		Inspected		
r ent		Inspected Inspected Inspected		
r		Inspected Inspected		
r e nt r		Inspected Inspected Inspected Does not	exist	
r e nt r		Inspected Inspected Inspected	exist	
r ent r r cent		Inspected Inspected Does not Does not	exist exist	
r e nt r		Inspected Inspected Inspected Does not	exist exist	
r ent r r cent r		Inspected Inspected Does not Does not Does not	exist exist exist	
r ent r r cent		Inspected Inspected Does not Does not	exist exist exist	
r ent r cent r		Inspected Inspected Does not Does not Does not Inspected	exist exist exist	
r ent r r cent r		Inspected Inspected Does not Does not Does not	exist exist exist	
r ent r r cent r r		Inspected Inspected Does not Does not Does not Inspected Does not	exist exist exist exist	
r ent r cent r		Inspected Inspected Does not Does not Does not Inspected	exist exist exist exist	
r ent r r cent r r		Inspected Inspected Does not Does not Does not Inspected Does not	exist exist exist exist exist	
	Condition) Exist? om? IN FIRE RESCUE AREAS ance Areas, Fire Rescue Areas, and/or Holding Room Condition Component	Years: Systems: Years: Systems: Years: Systems: Years: Systems: Years: Systems: Years: Systems: Years: Below Gr Years: Below Gr Yes Mo IN FIRE RESCUE AREAS I ance Areas, Fire Rescue Areas, and/or Holding Rooms in I Condition Description Affected Description I Does not	Components been upgraded? Systems: Retrofitted LED Lighting, Com with Receptacles), IPDVS/CCT Years: 2023 Systems: Intercom System (Elevator) Years: 2020 Systems: Partial Exit Lights (Battery Pacl Years: 2010 Systems: Multipurpose Room (Theater Li Years: 2010 Systems: All Other Electrical Systems an Years: 1996 Below Ground Years: 1996 Below Ground No IN FIRE RESCUE AREAS IN THE

Building Condition Assessment Survey 2023-2024

Electrical Inspection

trical Inspection		M893
Question	Response	
CAFETERIA		
Lighting		
Lighting Fixture - LED		
Recessed Mounted		
Deficiency	No deficiencies recorded	
Local Sound System		
Instance on 11th Floor	Does not exist	
Projection System		
Instance on 11th Floor	Does not exist	
Theater Lighting System		
Instance on 11th Floor	Does not exist	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected	
Lighting	Inspected	
Does a Chandelier Exist?	No	
Lighting Fixture - Fluorescent	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Inspected	
Pendant Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
COMPUTER LAB	Inspected	
Instance on Room 906	Inspected	
Power Panel?	No	
Lighting		
Instance on Room 906	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 906	Does not exist	
Lighting Fixture - HID		
Instance on Room 906	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 906	Does not exist	
Lighting Fixture - LED		
Instance on Room 906	Inspected	
Pendant Mounted		
Instance on Room 906	Does not exist	
Surface Mounted		
Instance on Room 906	Does not exist	
Recessed Mounted		
Instance on Room 906	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Raceway With Receptacles		
Instance on Room 906	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
GYMNASIUM	Does not exist	
KITCHEN	Inspected	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

Duestion	Response	
KITCHEN		
Instance on 11th Floor	Inspected	
Lighting	inspected .	
Instance on 11th Floor	Inspected	
Lighting Fixture - Fluorescent	1.	
Instance on 11th Floor	Does not exist	
Lighting Fixture - HID		
Instance on 11th Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 11th Floor	Does not exist	
Lighting Fixture - LED		
Instance on 11th Floor	Inspected	
Pendant Mounted		
Instance on 11th Floor	Does not exist	
Surface Mounted		
Instance on 11th Floor	Does not exist	
Recessed Mounted		
Instance on 11th Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
LIBRARY	Inspected	
Instance on Room 1106	Inspected	
Lighting	inspected	
Instance on Room 1106	Inspected	
Lighting Fixture - Fluorescent	1	
Instance on Room 1106	Does not exist	
Lighting Fixture - HID		
Instance on Room 1106	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 1106	Does not exist	
Lighting Fixture - LED		
Instance on Room 1106	Inspected	
Pendant Mounted		
Instance on Room 1106	Does not exist	
Surface Mounted		
Instance on Room 1106	Does not exist	
Recessed Mounted		
Instance on Room 1106	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Raceway With Receptacles		
Instance on Room 1106	Does not exist	
Projection System		
Instance on Room 1106	Does not exist	
LOCKER ROOM	Does not exist	
MULTIPURPOSE ROOM	Inspected	
Instance on Room 708	Inspected	
Lighting	hispecies	
Instance on Room 708	Inspected	
Lighting Fixture - Fluorescent	hispecied	
Instance on Room 708	Does not exist	
Lighting Fixture - HID		
Instance on Room 708	Does not exist	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

en em map een en		1110/0
Question	Response	
MULTIPURPOSE ROOM		
Lighting		
Lighting Fixture - Incandescent		
Instance on Room 708	Does not exist	
Lighting Fixture - LED		
Instance on Room 708	Inspected	
Pendant Mounted		
Instance on Room 708	Does not exist	
Surface Mounted		
Instance on Room 708	Does not exist	
Recessed Mounted		
Instance on Room 708	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Local Sound System		
Instance on Room 708	Does not exist	
Projection System		
Instance on Room 708	Does not exist	
Theater Lighting System		
Instance on Room 708	Inspected	
Dimming System		
Instance on Room 708	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Theater Lighting		
Instance on Room 708	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Inspected	
Instance on Room 1005	Inaccessible	
Instance on Room 703	Inspected	
Power Panel?	Yes	
Alternative Use	Yes	
Lighting	105	
Instance on Room 703	Inspected	
Lighting Fixture - Fluorescent	1	
Instance on Room 703	Does not exist	
Lighting Fixture - HID		
Instance on Room 703	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 703	Does not exist	
Lighting Fixture - LED		
Instance on Room 703	Inspected	
Pendant Mounted		
Instance on Room 703	Does not exist	
Surface Mounted		
Instance on Room 703	Does not exist	
Recessed Mounted		
Instance on Room 703	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Emergency Gas Shut-Off Valve		
Instance on Room 703	Inspected	
	mspected	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

M895	
11075	

rical Inspection		M895
uestion	Response	
SCIENCE LAB		
Emergency Gas Shut-Off Valve		
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Emergency Shut-Off Power		
Instance on Room 703	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Power Supply		
Instance on Room 703	Inspected	
Instructor Unit		
Instance on Room 703	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Meter Demonstration Unit		
Instance on Room 703	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Student Unit		
Instance on Room 703	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Projection System		
Instance on Room 703	Does not exist	
SCIENCE PREP ROOM	Inspected	
Instance on Room 702	Inspected	
Power Panel?	No	
Alternative Use	Yes	
Lighting		
Instance on Room 702	Inspected	
Lighting Fixture - Fluorescent	*	
Instance on Room 702	Does not exist	
Lighting Fixture - HID		
Instance on Room 702	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 702	Does not exist	
Lighting Fixture - LED		
Instance on Room 702	Inspected	
Pendant Mounted	*	
Instance on Room 702	Does not exist	
Surface Mounted		
Instance on Room 702	Does not exist	
Recessed Mounted		
Instance on Room 702	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Emergency Gas Shut-Off Valve		
Instance on Room 702	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Emergency Shut-Off Power		
Instance on Room 702	Inspected	
Instance Condition	3- Fair	

NYC Department of Education Building Condition Assessment Survey 2023-2024

Electrical Inspection

ricai Inspection	Mi
Question	Response
SCIENCE PREP ROOM	
Power Supply	
Instance on Room 702	Does not exist
SWIMMING POOL	Does not exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Does not exist
Recessed Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
TOILET ROOM - STUDENT	Inspected
	Inspected
Lighting Fixture - Fluorescent	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Does not exist
Recessed Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
	Does not exist
AUXILIARY SIGNAL/BELL SYSTEM	
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not exist
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Does not exist
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Does not exist
EXIT/EMERGENCY LIGHT	Inspected
Condition	3- Fair
Deficiency	FIXTURE LAMP NOT OPERATIONAL
Deficiency Location/Instance	Multipurpose Room 708
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	FIXTURE LENS MISSING
Deficiency Location/Instance	Multipurpose Room 708
Deficiency Quantity	1
Quantity Uom	EACH

Building Condition Assessment Survey 2023-2024

Electrical Inspection

ricai Inspection	Ī	V1093
uestion	Response	
EXIT/EMERGENCY LIGHT		
Potential Action	INSTALL LENS	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
FIRE ALARM SYSTEM	Inspected	
Bell/Horn	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Strobe	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Manual Pull Station	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fan Shutdown Control Condition	Inspected 3- Fair	
	-	
Deficiency	No deficiencies recorded	
Duct Smoke Detector	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Area Smoke Detector	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
CO Detector	Does not exist	
Heat Detector	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Elevator Recall	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Magnetic Door Holder/Contactor	Does not exist	
Fused Cutout Panel	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Digital Communicator	Does not exist	-
Main Panel	Does not exist	
Sub-Panel	Inspected	
Bell At Panel	Does not exist	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Room 914	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Faraday	
Model	15222	
EquipmentId	Strobe Control Panel	
Installation Year	1996	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	Room 1016	
Instance Condition	3- Fair	
Instance Quantity	1	
	EACH	
Instance Quantity Uom		
Manufacturer	Faraday	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

*	Desponse	
uestion	Response	
FIRE ALARM SYSTEM		
Sub-Panel		
Fire Alarm Control Panel (Electronic)	15222	
Model	15222 Strobe Control Panel	
EquipmentId	1996	
Installation Year Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Standard)	Does not exist	
Remote Annunciator	Inspected	
Display Monitor	Does not exist	
Panel	Inspected	
Condition	3- Fair	
	No deficiencies recorded	
Deficiency		
Printer	Does not exist	
Punch Register	Does not exist	
Sprinkler Flow/Air Pressure Switch	Inspected 3- Fair	
Condition		
Deficiency	No deficiencies recorded	
Tamper Flow Switch/Chain	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
GROUNDING SYSTEM	Does not exist	
INTERCOM SYSTEM	Inspected	
Elevator	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Holding Area	Does not exist	
LAN	Inspected	
Local Distribution Frame (I/LDF)	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Main Equipment Rack (MDF)	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
LIGHTNING PROTECTION	Does not exist	
MOTOR CONTROLLER	Inspected	
MOTOR CONTROL CENTER	Does not exist	
MOTOR STARTER/CONTACTOR	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Variable Frequency Drive	Does not exist	
PANEL BOARD	Inspected	
Fused Disconnect Switch Type	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
	Does not exist	
Fused Knife Switch Type Fused Toggle Switch Type	Does not exist	
rused Toggle Switch Type Molded Case Circuit Breaker Type	Inspected	
Condition	3- Fair	
Deficiency	NO SPARE	
Deficiency Location/Instance	Kitchen	
Deficiency Quantity	1	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

ieur inspection		10102
uestion	Response	
PANEL BOARD		
Molded Case Circuit Breaker Type		
Potential Action	INSTALL NEW PANEL BOARD	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
PUBLIC ADDRESS SYSTEM	Inspected	
Instance	Room 911	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Model	Rauland Telecenter System 21	
Installation Year	1996	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
SECURITY	Inspected	
IPDVS/CCTV System	Inspected	
Condition	1- Good	
Installation Year	2023	
Source of Installation Year	Inspector Estimate	
Deficiency	No deficiencies recorded	
Intrusion Alarm System	Inspected	
Central Control Panel	Inspected	
Instance	Room 914	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Model		
	FA1200C 1996	
Installation Year Source of Installation Year	Documented	
	BEYOND USEFUL LIFE	
Deficiency Deficiency Location/Instance	Room 914	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 3	
Violations	No violations recorded	
Instance	Custodian's Office - Room 811	
Instance Condition	3- Fair	
Instance Quantity	- Tall 1	
	EACH	
Instance Quantity Uom		
Model	Vista - 50P 1996	
Installation Year Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Custodian's Office - Room 811	
Deficiency Quantity	l	
Quantity Uom	EACH	
Potential Action	REPLACE	
	PRIORITY 1	
Urgency of Action		
Urgency of Action		
Purpose of Action	LEVEL 3	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

estion	Response	
ECURITY		
Intrusion Alarm System		
Central Control Panel		
Instance Quantity	1	
Instance Quantity Uom	EACH	
Model	Vista - 128B	
Installation Year	1996	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Custodian's Office - Room 811	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 3	
Violations	No violations recorded	
Infrared Sensor	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Panic Switch	Inspected	
Condition	3- Fair	
	No deficiencies recorded	
Deficiency		
Remote Annunciator	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Siren/Strobe	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting - Security	Does not exist	
ERVICE SWITCH	Inspected	
Instance	Basement Electrical Room	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	All City Switchboard	
EquipmentId	Board of ED Floors 7, 8	
Capacity/Size Quantity	1200	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	1996	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	Basement Electrical Room	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	All City Switchboard	
EquipmentId	Board of ED Floors 9, 10, 11	
Equipmentia Capacity/Size Quantity	1600	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	1996	
	1770	
	Documented	
Source of Installation Year Deficiency	Documented No deficiencies recorded	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

icui Inspection	1
uestion	Response
SWITCHBOARD	
Number of Spares	2
Fused Disconnect Switch Type	Inspected
Instance	Room 711
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	All City Switchboard
EquipmentId	MDB 7 - Section #1, #2
Capacity/Size Quantity	1200
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	2
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Service Switch Size
Installation Year	1996
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	Room 914
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	All City Switchboard
EquipmentId	N/A
Capacity/Size Quantity	1600
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	2
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Service Switch Size
Installation Year	1996
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Does not exist
FELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
TRANSFORMER	Does not exist

TRANSFORMER

Does not exist