Building Condition Assessment Survey 2023-2024

lectrical Inspe	ection						M90
Asset:	BALLET TECH/PUB. SCL F	OR DANCE - 1	MANHATTAN,	890 BROADWA	AY, MANHATT	AN, NY, 10	003
Inspection Id	Inspection Type				Time In		Last Edited
1349	ELECTRICAL				2023-11	-30 11:27AN	1 2023-12-18 02:41PM
sset Data							
Question				Answer			
Have any Syste	ms/Major Building Components bed	en upgraded?		Systems:	Partial Molded (Case Circuit E	Breaker Panel Board
				Years:	2023		
				Systems:		0 0 1	Floor Classrooms, 7th
							ms, 8th Floor Boys (Stairways, 7th Floor
							ms and Corridors, 7th
							ire Alarm System (CO
					Detector)		
				Years:	2022		
				Systems:	Partial Emergen	cy Lighting (I	Battery Pack)
				Years:	2021		
				Systems:	Intercom System	n (Elevator)	
				Years:	2020		
				Systems:	Recessed LED I	Lighting	
				Years:	2019		
				Systems:	Fire Alarm Syste	em	
				Years:	2017		
				Systems:		Lights, LAN	, Telephone System
				Years:	2016	1.1.00	G. I. 51 F. D
				Systems:			Studios, 7th Floor Boys
				Years:	Locker Room, 8th Floor Girls Locker Room) 2014		Locker Room)
				Systems:	Incandescent Lig	ghting	
				Years:	2002		
Type of Service				Below Gr	ound		
	e Whiteboard (IWB) Exist?			No			
Water Penetration	on In Electrical Room?			No			
DEDICATED	INTERCOMS IN FIRE RES	CUE AREAS					
Question					Response		
Are there any your building	Life Rescue Assistance Areas, Fire?	Rescue Areas, an	d/or Holding Roor	ns in N	No		
riority Conditi							
Exist Prio	•		Component	Location	()	Person(s)	Photo
	egory Description	<u> </u>	Affected	Description	Notified	Title	Image
No condition re	corded						
nspection							
Question				Response			
Electrical	FIELD			Does not o	eviet		
ATHLETIC FIELD AUDITORIUM				Does not o			
CAFETERIA				Does not o			
	M/CORRIDOR/ADMINISTRAT	IVE SPACE		Inspected			
Lighting				Inspected			
	nandelier Exist?			No			
Lighting	Fixture - Fluorescent			Does not o	exist		
Lighting	Fixture - HID			Does not o			
Lighting	Fixture - Incandescent			Does not o	exist		
Lighting	Fixture - LED			Inspected			
Pendant Mounted				Inspected			
Condition				2- Betwee	n Good and Fair		

Building Condition Assessment Survey 2023-2024

uestion	Response	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE		
Lighting		
Lighting Fixture - LED		
Pendant Mounted		
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
COMPUTER LAB	Does not exist	
GYMNASIUM	Does not exist	
KITCHEN	Does not exist	
LIBRARY	Does not exist	
LOCKER ROOM	Inspected	
Instance on 7th Floor - Boys, 8th Floor - Girls	Inspected	
Alternative Use	No	
Instance on 8th Floor - Boys	Inspected	
Alternative Use	No	
Instance on 7th Floor - Girls	Inspected	
Alternative Use	No	
Lighting		
Instance on 7th Floor - Boys, 8th Floor - Girls	Inspected	
Instance on 8th Floor - Boys	Inspected	
Instance on 7th Floor - Girls	Inspected	
Lighting Fixture - Fluorescent	•	
Instance on 7th Floor - Boys, 8th Floor - Girls	Does not exist	
Instance on 7th Floor - Girls	Does not exist	
Instance on 8th Floor - Boys	Does not exist	
Lighting Fixture - HID		
Instance on 7th Floor - Boys, 8th Floor - Girls	Does not exist	
Instance on 7th Floor - Girls	Does not exist	
Instance on 8th Floor - Boys	Does not exist	
Lighting Fixture - Incandescent		
Instance on 7th Floor - Boys, 8th Floor - Girls	Does not exist	
Instance on 7th Floor - Girls	Does not exist	
Instance on 8th Floor - Boys	Does not exist	
Lighting Fixture - LED		
Instance on 7th Floor - Boys, 8th Floor - Girls	Inspected	
Instance on 7th Floor - Girls	Inspected	
Instance on 8th Floor - Boys	Inspected	
Pendant Mounted		
Instance on 7th Floor - Boys, 8th Floor - Girls	Does not exist	
Instance on 7th Floor - Girls	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Instance on 8th Floor - Boys	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on 7th Floor - Boys, 8th Floor - Girls	Inspected	
Instance Condition	2- Between Good and Fair	

Building Condition Assessment Survey 2023-2024

incui inspection		141703
Question	Response	
LOCKER ROOM		
Lighting		
Lighting Fixture - LED		
Surface Mounted		
Deficiency	No deficiencies recorded	
Instance on 7th Floor - Girls	Does not exist	
Instance on 8th Floor - Boys	Does not exist	
Recessed Mounted		
Instance on 7th Floor - Boys, 8th Floor - Girls	Does not exist	
Instance on 7th Floor - Girls	Does not exist	
Instance on 8th Floor - Boys	Does not exist	
MULTIPURPOSE ROOM	Does not exist	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Does not exist	
	Does not exist	
SCIENCE PREP ROOM		
SWIMMING POOL	Does not exist	
TOILET ROOM - STAFF	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Inspected	
Pendant Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Does not exist	
Recessed Mounted	Does not exist	
Lighting Fixture - LED	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
TOILET ROOM - STUDENT	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Inspected	
Pendant Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
AUXILIARY SIGNAL/BELL SYSTEM	Does not exist	
EMERGENCY DC STANDBY BATTERY POWER	Does not exist	
EMERGENCY GENERATOR SET	Does not exist	
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not exist	
EMERGENCY LIGHTING	Inspected	
Battery Pack	Inspected	
	p-5566	
Condition	2- Between Good and Fair	

Building Condition Assessment Survey 2023-2024

ricai inspection	M90:
Puestion	Response
EMERGENCY LIGHTING	
Non Battery Pack	Does not exist
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EXIT/EMERGENCY LIGHT	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
FIRE ALARM SYSTEM	Inspected
Bell/Horn	Inspected 2- Between Good and Fair
Condition	
Deficiency	No deficiencies recorded
Strobe	Inspected 2- Between Good and Fair
Condition	
Deficiency	No deficiencies recorded
Manual Pull Station	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Duct Smoke Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Area Smoke Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
CO Detector	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Heat Detector	Does not exist
Elevator Recall	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Magnetic Door Holder/Contactor	Does not exist
Fused Cutout Panel	Does not exist
Fire Alarm Digital Communicator	Does not exist
Main Panel	Does not exist
Sub-Panel	Does not exist
Remote Annunciator	Does not exist
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Tamper Flow Switch/Chain	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Does not exist
INTERCOM SYSTEM	Inspected
Elevator Condition	Inspected 1- Good

Building Condition Assessment Survey 2023-2024

aricai inspection	M1903
Question	Response
INTERCOM SYSTEM	
Elevator	
Deficiency	No deficiencies recorded
Holding Area	Does not exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not exist
MOTOR CONTROLLER	Inspected
MOTOR CONTROLLER MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Does not exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Does not exist
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Does not exist
Molded Case Circuit Breaker Type	Inspected
Condition	3- Fair
Deficiency	NO SPARE
Deficiency Location/Instance	7th Floor Corridor
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
	PANEL BOARD DOOR LOCK IS MISSING
Deficiency Deficiency Location/Instance	7th Floor Corridor
Deficiency Quantity	7th Floor Corridor 3
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	Does not exist
SECURITY	Does not exist
SERVICE SWITCH	Inspected
Instance	Basement Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Federal Pacific Electric
EquipmentId	7th FL
Capacity/Size Quantity	400
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1970
Source of Installation Year	T. C. T. C.
Source of installation real	Inspector Estimate

Building Condition Assessment Survey 2023-2024

Question	Response		
SERVICE SWITCH			
Deficiency Location/Instance	Basement Electrical Room		
Deficiency Quantity	1		
Quantity Uom	EACH		
Potential Action	REPLACE		
Urgency of Action	PRIORITY 1		
Purpose of Action	LEVEL 2		
Violations	No violations recorded		
SWITCHBOARD	Inspected		
Number of Spares	0		
Fused Disconnect Switch Type	Inspected		
Instance	7th Floor Corridor		
Instance Condition	3- Fair		
Instance Quantity	1		
Instance Quantity Uom	EACH		
Manufacturer	I.T.E. Imperial Corp.		
EquipmentId	N/A		
Capacity/Size Quantity	400		
Capacity/Size UOM	Amps Total		
Capacity/Size 2 Quantity	1		
Capacity/Size 2 UOM	Section(s)		
Source of Capacity/Size	Inspector Estimate		
Installation Year	1970		
Source of Installation Year	Inspector Estimate		
Deficiency	BEYOND USEFUL LIFE		
Deficiency Location/Instance	7th Floor Corridor		
Deficiency Quantity	1		
Quantity Uom	EACH		
Potential Action	REPLACE		
Urgency of Action	PRIORITY 1		
Purpose of Action	LEVEL 2		
Violations	No violations recorded		
Fused Knife Switch Type	Does not exist		
Molded Case Circuit Breaker Type	Does not exist		
TELEPHONE SYSTEM	Inspected		
PBX/Intercom	Inspected		
Condition	2- Between Good and Fair		
Deficiency	No deficiencies recorded		
Standard	Inspected		
Condition	2- Between Good and Fair		
Deficiency	No deficiencies recorded		
TRANSFORMER	Does not exist		