Building Condition Assessment Survey 2023-2024

Electrical Inspection	M965
-----------------------	------

Inspection	n Id Inspection Type				Time	In	Last Edited
	1448 ELECTRICAL					-12-05 11:27AN	
					2023-	-12-03 11.2/AN	1 2023-12-03 03.00FN
Isset Data Ouestion				Answer			
		Components been upgraded?		Systems:	IPDVS/CCTV	/ System, Public	Address System
Trave arry	Systems/Wajor Building C	components occir upgraded:		Years:	2022	. System, I wond	
				Systems:	Lighting - Sec	curity	
				Years:	2017, 1997	,	
				Systems:		nergency Lights	
				Years:	2017		
				Systems:	Telephone Sy	stem	
				Years:	2013		
				Systems:	Fire Alarm Sy	stem	
				Years:	2008		
				Systems:	All Other Ele	ctrical Systems	and Components
				Years:	1997		
Type of S	ervice			Below Gr	ound		
	eractive Whiteboard (IWB)			Yes			
	netration In Electrical Room			No			
		N FIRE RESCUE AREAS					
Question			1/ ** 11: 5		Response		
Are the your bu		nce Areas, Fire Rescue Areas, a	nd/or Holding Roon	ns in S	No		
Priority Co							
Exist	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo
Last Year?	Category	Description	Affected	Description	Notified	Title	Image
Yes	Exit/Emergency Light - Not Operational	N/A	Exit/Emergenc y Light	Rooms T11, T15, T22, T27	Jorge Sepulveda	Handyman	No Photo Taken
Yes	Exit Light - Not Operational	N/A	Exit Light	Rooms T1, T2, T13, T20, T23	Jorge Sepulveda	Handyman	No Photo Taken
Yes	Emergency Lighting - Not Operational	N/A	Emergency Lighting	Rooms T1, T2, T13, T20, T23	Jorge Sepulveda	Handyman	No Photo Taken
Inspection	ı						
Question	1			Response			
Electrica	ıl						
	ETIC FIELD			Does not o			
	ORIUM			Does not o			
CAFE				Does not o	exist		
		OMINISTRATIVE SPACE		Inspected			
Light	ting es a Chandelier Exist?			Inspected			
	hting Fixture - Fluorescei			No Inspected			
_	nting Fixture - Fluorescei	ıı		Does not o	exist		
_	urface Mounted			Inspected			
	Condition			3- Fair			
	Deficiency				G FIXTURE R	EYOND USEF	UL LIFE
	Deficiency Quantity			450	G I IA I UKE D	PIOND OBEL	
	Quantity Uom			EACH			
	Potential Action				E-UPGRADE		
	Urgency of Action			PRIORIT			
	Purpose of Action			LEVEL 2			
	Violations			No violati	ons recorded		
CAS Partners	Version 2.0 (P)		Page 1	of 6			Print Date: 8/8/202

Building Condition Assessment Survey 2023-2024

aricai inspection	NI9C
Question	Response
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	
Lighting Fixture - Fluorescent	
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
COMPUTER LAB	Does not exist
GYMNASIUM	Does not exist
KITCHEN	Does not exist
LIBRARY	Does not exist
	Does not exist
LOCKER ROOM	
MULTIPURPOSE ROOM	Does not exist
SCIENCE DEMO ROOM	Does not exist
SCIENCE LAB	Does not exist
SCIENCE PREP ROOM	Does not exist
SWIMMING POOL	Does not exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	27 FA CH
Quantity Uom Potential Action	EACH PERLACE LIBORADE
Urgency of Action	REPLACE-UPGRADE PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - Incandescent Lighting Fixture - LED	Does not exist
AUXILIARY SIGNAL/BELL SYSTEM	Does not exist
AUAILIANI SIGNAL/DELL SISIEM	Duce not exist

Building Condition Assessment Survey 2023-2024

vection	Dosnonso	
estion	Response	
EMERGENCY GENERATOR SET	Does not exist	
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not exist	
EMERGENCY LIGHTING	Inspected	
Battery Pack	Inspected	
Condition	5- Poor	
Deficiency	BATTERY NOT OPERATIONAL	
Deficiency Location/Instance	Rooms T1, T2, T13, T20, T23	
Deficiency Quantity	5	
Quantity Uom	EACH	
Potential Action	REPLACE BATTERY	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	
Violations	No violations recorded	
Non Battery Pack	Does not exist	
EXIT LIGHT	Inspected	
Battery Pack	Inspected	
Condition	5- Poor	
Deficiency	BATTERY NOT OPERATIONAL	
Deficiency Location/Instance	Rooms T1, T2, T13, T20, T23	
Deficiency Quantity	5	
Quantity Uom	EACH	
Potential Action	REPLACE BATTERY	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	
Violations	No violations recorded	
Non Battery Pack	Does not exist	
EXIT/EMERGENCY LIGHT	Inspected	
Condition	3- Fair	
Deficiency	BATTERY NOT OPERATIONAL	
Deficiency Location/Instance	Rooms T11, T15, T22, T27	
Deficiency Quantity	4	
Quantity Uom	EACH	
Potential Action	REPLACE BATTERY	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	
Violations	No violations recorded	
FIRE ALARM SYSTEM	Inspected	
Bell/Horn	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Strobe	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Manual Pull Station	Inspected	
Condition	2- Between Good and Fair	
Deficiency	PULL STATION COVER IS MISSING	
Deficiency Deficiency Location/Instance	Room T20	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	INSTALL COVER	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
	Does not exist	
Fan Shutdown Control	Does not exist	

Building Condition Assessment Survey 2023-2024

near inspection		111703
Question	Response	
FIRE ALARM SYSTEM		
Area Smoke Detector	Does not exist	
CO Detector	Does not exist	
Heat Detector	Does not exist	
Elevator Recall	Does not exist	
Magnetic Door Holder/Contactor	Does not exist	
Fused Cutout Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Digital Communicator	Does not exist	
Main Panel	Inspected	
Bell At Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Room T16	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Mircom	
Model	FX - 2000	
EquipmentId	Fire Alarm Control	
Installation Year	2008	
Source of Installation Year	Inspector Estimate	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Standard)	Does not exist	
Sub-Panel	Does not exist	
Remote Annunciator	Does not exist	
Sprinkler Flow/Air Pressure Switch	Does not exist Does not exist	
Tamper Flow Switch/Chain GROUNDING SYSTEM	Inspected	
	3- Fair	
Condition	No deficiencies recorded	
Deficiency		
INTERCOM SYSTEM	Does not exist	
LAN	Inspected	
Local Distribution Frame (I/LDF)	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Main Equipment Rack (MDF)	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
LIGHTNING PROTECTION	Does not exist	
MOTOR CONTROLLER	Does not exist	
PANEL BOARD	Inspected	
Fused Disconnect Switch Type	Does not exist	
Fused Knife Switch Type	Does not exist	
Fused Toggle Switch Type	Does not exist	
Molded Case Circuit Breaker Type	Inspected	
Condition	3- Fair	
Deficiency	NO SPARE	
Deficiency Location/Instance	Rooms T20, T30	
Deficiency Quantity	2	
Quantity Uom	EACH	
Potential Action	INSTALL NEW PANEL BOARD	
Urgency of Action	PRIORITY 3	

Building Condition Assessment Survey 2023-2024

Question	Response
PANEL BOARD	
Molded Case Circuit Breaker Type	
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	Room T30
Instance Condition	1- Good
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Visiplex
Installation Year	2022
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SECURITY	Inspected
IPDVS/CCTV System	Inspected
Condition	1- Good
Installation Year	2022
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Intrusion Alarm System	Does not exist
Lighting - Security	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Location/Instance	Building Perimeters
Deficiency Quantity	8
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 3
Violations	No violations recorded
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Location/Instance	Building Perimeters
Deficiency Quantity	12
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 3
Violations	No violations recorded
SERVICE SWITCH	Inspected
Instance	Outside Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Siemens
EquipmentId	N/A
Capacity/Size Quantity	2500
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1997
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SWITCHBOARD	Inspected
Number of Spares	15
Fused Disconnect Switch Type	Does not exist
Fused Knife Switch Type	Does not exist

Building Condition Assessment Survey 2023-2024

Question	Response
SWITCHBOARD	
Molded Case Circuit Breaker Type	Inspected
Instance	Outside Electrical Room
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Siemens
EquipmentId	N/A
Capacity/Size Quantity	2500
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	2
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Nameplate
Installation Year	1997
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
TRANSFORMER	Does not exist