Building Condition Assessment Survey 2023-2024

Electrical Inspection M971

Asset:	THE SPRUCE STREET EDUCATIONAL CAMPUS NY, 10038	- MANHATTAN, 12 SPRU	CE STREET, MANHAT	TAN,
Inspection Id	Inspection Type		Time In	Last Edited
3764	ELECTRICAL		2024-03-07 09:05AM	2024-05-13 12:40PM
set Data				
Question		Answer		
Have any Syste	ms/Major Building Components been upgraded?	Systems: All	Electrical Systems and Comp	ponents
		Years: 201	1	
Type of Service		Below Ground		
Does Interactive	e Whiteboard (IWB) Exist?	Yes		

DEDICATEI	INTERCOME	IN DIDE DE	SCOTIE ADEAC
DEDICALEI) INTERCOMS	IN FIRE RE	LSCUE AKEAS

Water Penetration In Electrical Room?

Question	Response	
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in	Yes	
your building?		
Are dedicated intercoms available in all of these spaces for use during a fire?	Yes	
Are all dedicated intercoms operational?	Yes	

No

Priority Condition

Exist	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo
Last Year?	Category	Description	Affected	Description	Notified	Title	Image
No	Fire Alarm System - Defective	Panel in trouble mode	Fire Alarm System	Main Entrance Lobby	Carlos Husking	Fireman	FIRE ALARM CONTROL P

Inspection

estion	Response	
etrical		
THLETIC FIELD	Does not exist	
UDITORIUM	Inspected	
Instance on 2nd Floor	Inspected	
House Lighting		
Instance on 2nd Floor	Inspected	
Does a Chandelier Exist?	No	
Lighting Fixture - Fluorescent		
Instance on 2nd Floor	Inspected	
Pendant Mounted		
Instance on 2nd Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on 2nd Floor	Does not exist	
Recessed Mounted		
Instance on 2nd Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on 2nd Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 2nd Floor	Does not exist	
Lighting Fixture - LED		
Instance on 2nd Floor	Does not exist	
Local Sound System		

Electrical Inspection	M19/1

Question	Response
AUDITORIUM	
Local Sound System	
Instance on 2nd Floor	Inspected
Instance Condition	3- Fair
Installation Year	2011
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Projection System	
Instance on 2nd Floor	Inspected
Instance Condition	3- Fair
Is the projector on a cart or installed on the ceiling?	Ceiling
Deficiency	No deficiencies recorded
Theater Lighting System	
Instance on 2nd Floor	Inspected
Dimming System	
Instance on 2nd Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Theater Lighting	
Instance on 2nd Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
CAFETERIA	Inspected
Instance on 1st Floor	Inspected
Lighting	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Inspected
Pendant Mounted	1
Instance on 1st Floor	Does not exist
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - LED	
Instance on 1st Floor	Does not exist
Local Sound System	Does not valst
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Installation Year	2011
·····	

Building Condition Assessment Survey 2023-2024

	M1971
Response	
Documented	
No deficiencies recorded	
Does not exist	
Inspected No	
Inspected	
3- Fair	
No deficiencies recorded	
Inspected	
3- Fair	
LIGHTING FIXTURE NOT OPERATIONAL	
1	
EACH	
REPAIR	
PRIORITY 3	
LEVEL 2	
No violations recorded	
Inspected	
3- Fair	
No deficiencies recorded	
Does not exist	
Inspected	
Does not exist	
Does not exist	
Inspected	
2- Between Good and Fair	
No deficiencies recorded	
Does not exist	
Does not exist	
Inspected	
Inspected	
Inspected	
Inspected	
Inspected	
3- Fair	
No deficiencies recorded	
Does not exist	
Does not exist	
Does not exist	
	Docs not exist Does not exist Inspected Inspe

Question Response	Electrical Inspection		N19/1
	Question	Response	

Question	Response
GYMNASIUM	
Lighting	
Lighting Fixture - LED	
Instance on 3rd Floor	Does not exist
Local Sound System	
Instance on 3rd Floor	Inspected
Instance Condition	3- Fair
Installation Year	2011
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Projection System	
Instance on 3rd Floor	Does not exist
Scoreboard	
Instance on 3rd Floor	Inspected
Instance Condition	5- Poor
Deficiency	NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Theater Lighting System	
Instance on 3rd Floor	Does not exist
KITCHEN	Inspected
Instance on 1st Floor	Inspected
Lighting	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	2000 100 01100
Instance on 1st Floor	Does not exist
LIBRARY	Inspected
Instance on Room 411	Inspected
Lighting	Turnested
Instance on Room 411	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 411	Inspected
Pendant Mounted	
Instance on Room 411	Does not exist
Surface Mounted	
Instance on Room 411	Does not exist

Electrical Inspection	M971
Liectricai Inspection	W19/1

aricai Inspection		W19/1
Question	Response	
LIBRARY		
Lighting		
Lighting Fixture - Fluorescent		
Recessed Mounted		
Instance on Room 411	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on Room 411	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 411	Does not exist	
Lighting Fixture - LED		
Instance on Room 411	Does not exist	
Raceway With Receptacles		
Instance on Room 411	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Projection System		
Instance on Room 411	Does not exist	
LOCKER ROOM	Inspected	
Instance on Room 347 - Boys, Room 349 - Girls	Inspected	
Alternative Use	Yes	
Lighting		
Instance on Room 347 - Boys, Room 349 - Girls	Inspected	
Lighting Fixture - Fluorescent	1	
Instance on Room 347 - Boys, Room 349 - Girls	Inspected	
Pendant Mounted	1	
Instance on Room 347 - Boys, Room 349 - Girls	Does not exist	
Surface Mounted		
Instance on Room 347 - Boys, Room 349 - Girls	Does not exist	
Recessed Mounted		
Instance on Room 347 - Boys, Room 349 - Girls	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID	10 001010101010	
Instance on Room 347 - Boys, Room 349 - Girls	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Instance on Room 347 - Boys, Room 349 - Girls	Does not exist	
Lighting Fixture - LED	Does not exist	
Instance on Room 347 - Boys, Room 349 - Girls	Does not exist	
MULTIPURPOSE ROOM	Inspected	
Instance on Room 223	Inspected	
Lighting Instance on Room 223	T.,	
	Inspected	
Lighting Fixture - Fluorescent	T.,	
Instance on Room 223	Inspected	
Pendant Mounted Instance on Room 223	Does not exist	
	Does not exist	
Surface Mounted	D " ' ' '	
Instance on Room 223	Does not exist	
Recessed Mounted	T	
Instance on Room 223	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	

Question	Response	
MULTIPURPOSE ROOM		
Lighting		
Lighting Fixture - HID		
Instance on Room 223	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 223	Does not exist	
Lighting Fixture - LED		
Instance on Room 223	Does not exist	
Local Sound System		
Instance on Room 223	Inspected	
Instance Condition	3- Fair	
Installation Year	2011	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on Room 223	Does not exist	
Theater Lighting System		
Instance on Room 223	Does not exist	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Inspected	
Instance on Room 405	Inspected	
Power Panel?	No	
Alternative Use	No	
Instance on Room 409	Inspected	
Power Panel?	Yes	
Alternative Use	No	
Lighting		
Instance on Room 405	Inspected	
Instance on Room 409	Inspected	
Lighting Fixture - Fluorescent	•	
Instance on Room 405	Inspected	

Installation Year	2011	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on Room 223	Does not exist	
Theater Lighting System		
Instance on Room 223	Does not exist	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Inspected	
Instance on Room 405	Inspected	
Power Panel?	No	
Alternative Use	No	
Instance on Room 409	Inspected	
Power Panel?	Yes	
Alternative Use	No	
Lighting		
Instance on Room 405	Inspected	
Instance on Room 409	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 405	Inspected	
Instance on Room 409	Inspected	
Pendant Mounted		
Instance on Room 405	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 409	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 405	Does not exist	
Instance on Room 409	Does not exist	
Recessed Mounted		
Instance on Room 405	Does not exist	
Instance on Room 409	Does not exist	
Lighting Fixture - HID		
Instance on Room 405	Does not exist	
Instance on Room 409	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 405	Does not exist	
Instance on Room 409	Does not exist	
Lighting Fixture - LED		
Instance on Room 405	Does not exist	
Instance on Room 409	Does not exist	
Partners Version 2.0 (P)	Page 6 of 14	Print Date: 8/8/2024

trical Inspection		M97
Question	Response	
SCIENCE LAB		
Emergency Gas Shut-Off Valve		
Instance on Room 405	Does not exist	
Instance on Room 409	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Emergency Shut-Off Power		
Instance on Room 405	Does not exist	
Instance on Room 409	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Power Supply		
Instance on Room 405	Does not exist	
Instance on Room 409	Does not exist	
Projection System		
Instance on Room 405	Does not exist	
Instance on Room 409	Does not exist	
SCIENCE PREP ROOM	Inspected	
Instance on Room 407	Inspected	
Power Panel?	No	
Alternative Use	No	
Lighting		
Instance on Room 407	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 407	Inspected	
Pendant Mounted		
Instance on Room 407	Does not exist	
Surface Mounted		
Instance on Room 407	Does not exist	
Recessed Mounted		

Electrical Inspection	M971

Question	Response
TOILET ROOM - STAFF	Teopolist .
Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	Does not exist
Recessed Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Does not exist
Recessed Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Inspected
Automatic Transfer Switch (ATS)	Inspected
Instance	ATS Room M45A
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	ASCO
EquipmentId	ATS#1
Capacity/Size Quantity	100
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate 2011
Installation Year Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Instance	ATS Room M45A
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	ASCO
EquipmentId	ATS#2
Capacity/Size Quantity	100
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2011
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Battery Charger	Does not exist
Emergency Distribution Board Number of Spares	Inspected 1
Fused Disconnect Switch Type	Inspected
ruseu Disconnect Switch Type	пърсски

Building Condition Assessment Survey 2023-2024

icui inspection	14137
uestion	Response
EMERGENCY GENERATOR SET	
Emergency Distribution Board	
Fused Disconnect Switch Type	
Instance	ATS Room M45A
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Electrotech
EquipmentId	HV - EMDP
Capacity/Size Quantity	300
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Inspector Estimate
Installation Year	2011
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Molded Case Circuit Breaker Type	Does not exist
Diesel	Does not exist
Natural Gas	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not exist
EMERGENCY LIGHTING	Inspected
Battery Pack	Does not exist
Non Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	3- Fair
Deficiency	FIXTURE LAMP NOT OPERATIONAL
Deficiency Location/Instance	4th Floor by Stair E
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
Non Battery Pack	Does not exist
EXIT/EMERGENCY LIGHT	Does not exist
FIRE ALARM SYSTEM	Inspected
Bell/Horn	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Manual Pull Station	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Duct Smoke Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded

Building Condition Assessment Survey 2023-2024

cui inspection		1/1//1
estion	Response	
IRE ALARM SYSTEM		
Area Smoke Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
CO Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Heat Detector	Does not exist	
Elevator Recall	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Magnetic Door Holder/Contactor	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Fused Cutout Panel	Does not exist	
Fire Alarm Digital Communicator	Inspected	
Instance	Telecommunication Room 230	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Ademco	
EquipmentId	Fire Alarm Communicator	
Installation Year	2011	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Main Panel	Inspected	
Bell At Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Main Entrance Lobby	
Instance Condition	3- Fair	
Instance Quantity		
	1 EACH	
Instance Quantity Uom		
Manufacturer	Firecom	
Model	ITC 2000	
EquipmentId	Fire Alarm Control Panel 2011	
Installation Year		
Source of Installation Year	Documented SYSTEM DEFECTIVE	
Deficiency Deficiency Quantity	SYSTEM DEFECTIVE	
	I EACH	
Quantity Uom Potential Action	EACH REPAIR SYSTEM	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	
Violations	No violations recorded	
Fire Alarm Control Panel (Standard)	Does not exist	
Sub-Panel	Does not exist	
Remote Annunciator	Inspected Does not exist	
Display Monitor		
Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Printer	Inspected	
Condition	2- Between Good and Fair	

Building Condition Assessment Survey 2023-2024

Question	Response
FIRE ALARM SYSTEM	
Remote Annunciator	
Printer	
Deficiency	No deficiencies recorded
Punch Register	Does not exist
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Tamper Flow Switch/Chain	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Does not exist
INTERCOM SYSTEM	Inspected
Elevator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Holding Area	Does not exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not exist
MOTOR CONTROLLER	Inspected
MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Does not exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Does not exist
Molded Case Circuit Breaker Type	Inspected 2- Between Good and Fair
Condition Deficiency	NO SPARE
Deficiency Location/Instance	MDF Room 230, IDF Room 330
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	INSTALL NEW PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	Telecommunication Room 230
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Rauland TC2105
Installation Year	2011

Building Condition Assessment Survey 2023-2024

Duestion	Response
PUBLIC ADDRESS SYSTEM	
Source of Installation Year	Documented
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	MDF Room 230, by Rooms (208, 230), Science Lab Room 405
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
SECURITY	Inspected
IPDVS/CCTV System	Inspected
Condition	3- Fair
Installation Year	2011
Source of Installation Year	Documented
Deficiency	CAMERA NOT OPERATIONAL
Deficiency Location/Instance	1st Floor Corridor
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Violations	No violations recorded
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Custodian's Office Room 321
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 128BP
	2011
Installation Year	
Source of Installation Year	Documented No deficiencies recorded
Deficiency	
Infrared Sensor	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting - Security	Does not exist
SERVICE SWITCH	Does not exist
SWITCHBOARD	Inspected
Number of Spares	4
Fused Disconnect Switch Type	Inspected
Instance	Mechanical Room M45B
Instance Condition	2- Between Good and Fair
· · · · · · · · · · · · · · · · · · ·	
Instance Quantity	1 EACH
Instance Quantity Uom	EACH
Manufacturer	Electrotech

Building Condition Assessment Survey 2023-2024

Question	Response	
SWITCHBOARD		
Fused Disconnect Switch Type		
EquipmentId	Distribution Switchboard LV-DP MEZ	
Capacity/Size Quantity	2000	
Capacity/Size UOM	Amps Total	
Capacity/Size 2 Quantity	2	
Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Nameplate	
Installation Year	2011	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	Mechanical Room M45B	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Electrotech	
EquipmentId	Distribution Switchboard MDP	
Capacity/Size Quantity	2000	
Capacity/Size UOM	Amps Total	
Capacity/Size 2 Quantity	2	
Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Nameplate	
Installation Year	2011	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fused Knife Switch Type	Does not exist	
Molded Case Circuit Breaker Type	Does not exist	
TELEPHONE SYSTEM	Inspected	
PBX/Intercom	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Standard	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
	Inspected	
TRANSFORMER		
Instance	Mechanical Room M45B	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Cutler Hammer	
EquipmentId	N/A	
Capacity/Size Quantity	75	
Capacity/Size UOM	kVA	
Source of Capacity/Size	Nameplate	
Installation Year	2011	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance	Mechanical Room M45B	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
	EACH	
Instance Quantity Uom		
Manufacturer	Rex Power Magnetics	
EquipmentId	N/A	
Capacity/Size Quantity	500	
Capacity/Size UOM	kVA	
Source of Capacity/Size	Nameplate	

Building Condition Assessment Survey 2023-2024

Question	Response
TRANSFORMER	
Installation Year	2011
Source of Installation Year	Documented
Deficiency	No deficiencies recorded