

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

Q037

Asset: P.S. 37 - QUEENS, 179-37 137 AVENUE, New York, 11434

Inspection Id	Inspection Type	Time In	Last Edited
EE : Q037	Electrical	2023-11-03 7:31 AM	2024-06-21 9:52 AM

Asset Data

Question	Answer
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration in Electrical Room?	Yes
Have any Systems/Major Building Components been upgraded?	Yes
	Systems: Fire Alarm System, Motor Controller (Motor Starter/Contactor), Intercom System (Elevator)
	Years: Under Construction
	Systems: LED Lighting (Kitchen Office), LAN
	Years: 2023
	Systems: Lightning Protection
	Years: 2021
	Systems: Partial Switchboard, Intrusion Alarm System (Panic Switch)
	Years: 2020
	Systems: Partial Fused Disconnect Switch Type Panel Board
	Years: 2019
	Systems: Public Address System (Amplifier, Tuner)
	Years: 2018
	Systems: Most Exit Lights (Battery Pack)
	Years: 2017, 2021
	Systems: IPDVS/CCTV System
	Years: 2014
	Systems: Interior Fluorescent Lighting
	Years: 2013
	Systems: Auditorium (Theater Lighting System, Local Sound System), Cafeteria (Local Sound System)
	Years: 2010
	Systems: Intrusion Alarm System
	Years: 2002
	Systems: Most Security Lights
	Years: 1995, 2022
	Systems: Emergency Light/Exit Light Panel
	Years: 1992
	Systems: Partial Molded Case Circuit Breaker Type Panel Board
	Years: 1990, 2010, 2020

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	No

Priority Condition

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
No	Water Penetration in Electrical Room	N/A	Electrical Equipment	Electrical Room (Original Building)	Kevin Willis	Custodian	Sent to DSF	

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Q037

Electrical Inspection

Yes Public Address System - System Defective The announcement is inconsistent in Auditorium, Cafeteria, Gymnasium, and most of the classrooms. PUBLIC ADDRESS SYSTEM General Office Kevin Willis Custodian Sent to DSF

Inspection

Question	Response
Electrical	
AUDITORIUM	Inspected
Instance on 1st Floor	Inspected
House Lighting	Inspected
Does a Chandelier exist?	No
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Surface Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	10
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Recessed Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not Exist
Local Sound System	Inspected
Instance on 1st Floor	Inspected
Installation Year	2010
Source of Installation	Custodial Staff

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

Q037

Question	Response
AUDITORIUM	
Local Sound System	
Condition	3 - Fair
Deficiency	No deficiencies recorded
Projection System	
Is the projector on a cart or installed on the ceiling?	Inspected
Instance on 1st Floor	Ceiling
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Theater Lighting System	
Instance on 1st Floor	Inspected
Instance on 1st Floor	Inspected
Dimming System	
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Theater Lighting	
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
CAFETERIA	
Instance on Ground Floor	Inspected
Instance on Ground Floor	Inspected
Lighting	
Instance on Ground Floor	Inspected
Instance on Ground Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on Ground Floor	Inspected
Pendant Mounted	
Instance on Ground Floor	Inspected
Instance on Ground Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Ground Floor	Does not Exist
Instance on Ground Floor	Does not Exist
Recessed Mounted	
Instance on Ground Floor	Inspected
Instance on Ground Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Ground Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on Ground Floor	Does not Exist
Lighting Fixture - LED	
Instance on Ground Floor	Does not Exist
Local Sound System	
Instance on Ground Floor	Inspected
Instance on Ground Floor	Inspected
Installation Year	2010
Source of Installation	Custodial Staff
Condition	3 - Fair
Deficiency	No deficiencies recorded
Projection System	
Instance on Ground Floor	Does not Exist
Instance on Ground Floor	Does not Exist
Theater Lighting System	
Instance on Ground Floor	Does not Exist

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

Q037

Question	Response
CAFETERIA	Inspected
Theater Lighting System	Does not Exist
Instance on Ground Floor	Does not Exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected
Lighting	Inspected
Does a Chandelier exist?	No
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo	No photo recorded
Violations	No violations recorded.
Surface Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
COMPUTER LAB	Inspected
Instance on Room 317	Inspected
Power Panel	Yes
Lighting	Inspected
Instance on Room 317	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 317	Inspected
Pendant Mounted	Inspected
Instance on Room 317	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Instance on Room 317	Does not Exist
Recessed Mounted	Does not Exist
Instance on Room 317	Does not Exist
Lighting Fixture - HID	
Instance on Room 317	Does not Exist
Lighting Fixture - Incandescent	

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

Q037

Question	Response
COMPUTER LAB	
Lighting	Inspected
Lighting Fixture - Incandescent	
Instance on Room 317	Does not Exist
Lighting Fixture - LED	
Instance on Room 317	Does not Exist
Raceway With Receptacles	Inspected
Instance on Room 317	Inspected
Condition	3 - Fair
Deficiency	RECEPTACLES NOT OPERATIONAL
Deficiency Quantity	7
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
GYMNASIUM	Inspected
Instance on 3rd Floor	Inspected
Lighting	Inspected
Instance on 3rd Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 3rd Floor	Inspected
Pendant Mounted	Inspected
Instance on 3rd Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Instance on 3rd Floor	Does not Exist
Recessed Mounted	Does not Exist
Instance on 3rd Floor	Does not Exist
Lighting Fixture - HID	
Instance on 3rd Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 3rd Floor	Does not Exist
Lighting Fixture - LED	
Instance on 3rd Floor	Does not Exist
Local Sound System	Inspected
Instance on 3rd Floor	Inspected
Installation Year	1975
Source of Installation	Documented
Condition	5 - Poor
Deficiency	AMPLIFIER NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE SYSTEM
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q037

Question	Response
GYMNASIUM	
Local Sound System	Inspected
Violations	No violations recorded.
Projection System	Does not Exist
Instance on 3rd Floor	Does not Exist
Scoreboard	Does not Exist
Instance on 3rd Floor	Does not Exist
Theater Lighting System	Does not Exist
Instance on 3rd Floor	Does not Exist
KITCHEN	
	Inspected
Instance on Ground Floor	Inspected
Lighting	Inspected
Instance on Ground Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on Ground Floor	Inspected
Pendant Mounted	Does not Exist
Instance on Ground Floor	Does not Exist
Surface Mounted	Does not Exist
Instance on Ground Floor	Does not Exist
Recessed Mounted	Inspected
Instance on Ground Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Ground Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on Ground Floor	Does not Exist
Lighting Fixture - LED	
Instance on Ground Floor	Does not Exist
LIBRARY	
	Inspected
Instance on Room 309/311	Inspected
Lighting	Inspected
Instance on Room 309/311	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 309/311	Inspected
Pendant Mounted	Inspected
Instance on Room 309/311	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Instance on Room 309/311	Does not Exist
Recessed Mounted	Does not Exist
Instance on Room 309/311	Does not Exist
Lighting Fixture - HID	
Instance on Room 309/311	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 309/311	Does not Exist
Lighting Fixture - LED	
Instance on Room 309/311	Does not Exist

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

Q037

Question	Response
LIBRARY	
Raceway With Receptacles	Does not Exist
Instance on Room 309/311	Does not Exist
Projection System	Does not Exist
Instance on Room 309/311	Does not Exist
LOCKER ROOM	Does not Exist
MULTIPURPOSE ROOM	Does not Exist
SCIENCE DEMO ROOM	Does not Exist
SCIENCE LAB	Does not Exist
SCIENCE PREP ROOM	Does not Exist
SWIMMING POOL	Does not Exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Replacement Quantity	88,000
Replacement Uom	S.F.
Condition	3 - Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not Exist
EMERGENCY GENERATOR SET	Does not Exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	3 - Fair
Deficiency	PANEL BOARD DOOR LOCK IS MISSING
Deficiency Location/Instance	Electrical Room (Original Building)

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

Q037

Question	Response
EMERGENCY LIGHT/EXIT LIGHT PANEL	
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<hr/>	
Deficiency	LESS THAN 20% SPARE CIRCUIT BREAKERS
Deficiency Location/Instance	Electrical Room (Original Building)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL NEW PANEL BOARD
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<hr/>	
EMERGENCY LIGHTING	Inspected
<hr/>	
Battery Pack	Inspected
<hr/>	
Condition	3 - Fair
<hr/>	
Deficiency	BATTERY NOT OPERATIONAL
Deficiency Location/Instance	Auditorium, Gymnasium
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE BATTERY
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<hr/>	
Non Battery Pack	Inspected
<hr/>	
Condition	3 - Fair
Deficiency	No deficiencies recorded
<hr/>	
EXIT LIGHT	Inspected
<hr/>	
Battery Pack	Inspected
<hr/>	
Condition	1 - Good
<hr/>	
Deficiency	FIXTURE NOT OPERATIONAL
Deficiency Location/Instance	Behind Auditorium
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<hr/>	
Non Battery Pack	Inspected
<hr/>	
Condition	3 - Fair
Deficiency	No deficiencies recorded
<hr/>	
EXIT/EMERGENCY LIGHT	Does not Exist
<hr/>	
FIRE ALARM SYSTEM	Under Construction

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

Q037

Question	Response
GROUNDING SYSTEM	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Inspected
Elevator	Under Construction
Holding Area	Does not Exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
MOTOR CONTROLLER	Inspected
Motor Control Center	Inspected
Instance	Penthouse
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	American Switchboard
Equipment	Roof Exhaust Control Center
Capacity/Size Quantity	200
Capacity/Size UOM	Amps
Capacity/Size2 Quantity	1
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Inspector Estimate
Installation Year	1974
Source of Installation	Documented
Deficiency	No deficiencies recorded
Motor Starter/Contactor	Under Construction
Variable Frequency Drive	Does not Exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	3 - Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Penthouse, Basement Mechanical Room
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Fused Knife Switch Type	Inspected
Condition	3 - Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

Q037

Question	Response
PANEL BOARD	
Fused Knife Switch Type	
Deficiency Location/Instance	Corridor by Rooms (211, 301, 309), Basement Mechanical Room
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Fused Toggle Switch Type	
Condition	Inspected
Condition	3 - Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room (Original Building)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Molded Case Circuit Breaker Type	
Condition	Inspected
Condition	3 - Fair
Deficiency	PANEL BOARD COVER IS MISSING
Deficiency Location/Instance	Corridor by Room 202
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL BOARD COVER IS MISSING
Deficiency Location/Instance	Corridor by Room B2
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	1st Floor Women's Toilet Room, Cafeteria, Kitchen, Auditorium, Rooms (109, 117), Corridor by Rooms (B2, G6, G12, 13, 102, 201, 202, 211, 227, 258, 302, 357)
Deficiency Quantity	18
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

Q037

Question	Response
PANEL BOARD	Inspected
Molded Case Circuit Breaker Type	
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
PUBLIC ADDRESS SYSTEM	Inspected
Replacement Quantity	88,000
Replacement Uom	S.F.
Instance	General Office
Instance Condition	4 - Between Fair and Poor
Instance Quantity	1
Instance Quantity Uom	EACH
Model	N/A
Installation Year	1974
Source of Installation	Documented
Deficiency	SYSTEM DEFECTIVE
Deficiency Location/Instance	General Office
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE SYSTEM
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
SECURITY	Inspected
IPDVS/CCTV System	Inspected
Replacement Quantity	88,000
Replacement Uom	S.F.
Installation Year	2014
Source of Installation	Custodial Staff
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Intrusion Alarm System	Inspected
Replacement Quantity	88,000
Replacement Uom	S.F.
Central Control Panel	Inspected
Instance	Custodian's Office
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	N/A
Installation Year	2002
Source of Installation	Inspector Estimate
Deficiency	PANEL NOT CONNECTED TO DOE CENTRAL STATION
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL CONNECTION
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Deficiency Photo1	No photo recorded

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

Q037

Question	Response
SECURITY	
Intrusion Alarm System	
Central Control Panel	Inspected
Violations	No violations recorded.
Infrared Sensor	
Condition	3 - Fair
Deficiency	No deficiencies recorded
Panic Switch	
Condition	1 - Good
Deficiency	No deficiencies recorded
Remote Annunciator	
Condition	3 - Fair
Deficiency	No deficiencies recorded
Siren/Stroke	
Condition	3 - Fair
Deficiency	No deficiencies recorded
Lighting - Security	
Replacement Uom	EACH
Condition	2 - Between Good and Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Location/Instance	Exterior Wall facing Belknap Street
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 3
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
SERVICE SWITCH	
	Inspected
Instance	Electrical Room (Original Building)
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	American Switchboard Co.
Equipment	NEW BUILD. SW.
Capacity/Size Quantity	1,600
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1974
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room (Original Building)
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Metropolitan
Equipment	MAIN DISTR. SWBD, FUSE 1000A
Capacity/Size Quantity	1,000
Capacity/Size UOM	Amps

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

Q037

Question	Response
SERVICE SWITCH	
Source of Capacity/Size	Fuse Size
Installation Year	1964
Source of Installation	Inspector Estimate
Deficiency	No deficiencies recorded
Instance	Electrical Room (Original Building)
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	General Electric
Equipment	AIR COND. SW.
Capacity/Size Quantity	600
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1974
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room (Original Building)
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	General Electric
Equipment	OIL BURNER SW.
Capacity/Size Quantity	100
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1974
Source of Installation	Documented
Deficiency	No deficiencies recorded
SWITCHBOARD	Inspected
Number of Spares	6
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room (Original Building)
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Metropolitan Electric
Equipment	MAIN SW. BOARD
Capacity/Size Quantity	1,000
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	2
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Service Switch Fuse Size
Installation Year	1964
Source of Installation	Inspector Estimate
Deficiency	No deficiencies recorded
Instance	New Electrical Room (Original Building)
Instance Condition	1 - Good
Instance Quantity	1

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

Q037

Question	Response
SWITCHBOARD	
Fused Disconnect Switch Type	
Instance Quantity Uom	EACH
Instance Manufacturer	Siemens
Equipment	N/A
Capacity/Size Quantity	1,600
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	2
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Nameplate
Installation Year	2020
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Does not Exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
TRANSFORMER	Does not Exist