

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

Q040

Asset: P.S. 40 - QUEENS, 109-20 UNION HALL STREET, New York, 11433

Inspection Id	Inspection Type	Time In	Last Edited
EE : Q040	Electrical	2023-11-17 7:30 AM	2024-06-21 9:57 AM

Asset Data

Question	Answer
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration in Electrical Room?	No
Have any Systems/Major Building Components been upgraded?	Yes
	Systems: LAN
	Years: 2023
	Systems: Computer Lab - Room 306 (Raceway With Receptacles), Exit Lights (Battery Pack)
	Years: 2019
	Systems: Computer Lab - Room 308 (Raceway With Receptacles)
	Years: 2018
	Systems: Intrusion Alarm System (Central Control Panel)
	Years: 2015
	Systems: Fused Disconnect Switch Type Panel Board, IPDVS/CCTV System, Service Switch, Switchboard
	Years: 2012
	Systems: Local Sound System, Public Address System, Intrusion Alarm System
	Years: 2009
	Systems: Security Lights
	Years: 2008, 2019
	Systems: Interior Lighting, Auditorium (Theater Lighting System)
	Years: 2008
	Systems: Molded Case Circuit Breaker Type Panel Board
	Years: 1990, 2012
	Systems: Emergency Light/Exit Light Panel
	Years: 1990

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	No

Priority Condition

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
No	Intercom System - Does Not Exist	N/A	Intercom System - Holding Area	Rooms 200, 300, 400	Frank Herlihy	Custodian	Sent to DSF	
No	Emergency Lighting - Battery Not Operational	N/A	EMERGENCY LIGHTING Battery Pack	Auditorium, Auditorium Lobby, Gymnasium, Corridor by Room 001, 1st Floor Staff Toilets, Cafeteria Lobby, Vestibule by Exit 9	Frank Herlihy	Custodian	Sent to DSF	

Inspection

Question	Response
----------	----------

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

Q040

Question	Response
Electrical	
AUDITORIUM	Inspected
Instance on 1st Floor	Inspected
House Lighting	Inspected
Does a Chandelier exist?	No
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Surface Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Inspected
Pendant Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Surface Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Recessed Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not Exist
Local Sound System	Inspected
Instance on 1st Floor	Inspected
Installation Year	2009
Source of Installation	Custodial Staff

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

Q040

Question	Response
AUDITORIUM	
Local Sound System	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Projection System	Inspected
Is the projector on a cart or installed on the ceiling?	Ceiling
Instance on 1st Floor	Inspected
Condition	5 - Poor
Deficiency	VIDEO PROJECTOR IS NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Theater Lighting System	Inspected
Instance on 1st Floor	Inspected
Dimming System	
Instance on 1st Floor	Does not Exist
Theater Lighting	
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
CAFETERIA	Inspected
Instance on 1st Floor	Inspected
Lighting	Inspected
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Surface Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not Exist
Local Sound System	Inspected
Instance on 1st Floor	Inspected
Installation Year	2009
Source of Installation	Custodial Staff
Condition	3 - Fair

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

Q040

Question	Response
CAFETERIA	
Local Sound System	Inspected
Deficiency	No deficiencies recorded
Projection System	Does not Exist
Instance on 1st Floor	Does not Exist
Theater Lighting System	Does not Exist
Instance on 1st Floor	Does not Exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	Inspected
Does a Chandelier exist?	No
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo	No photo recorded
Violations	No violations recorded.
Surface Mounted	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
COMPUTER LAB	
Lighting	Inspected
Instance on Rooms 306, 308	Inspected
Power Panel	No
Lighting	Inspected
Instance on Rooms 306, 308	Inspected
Lighting Fixture - Fluorescent	Inspected
Instance on Rooms 306, 308	Inspected
Pendant Mounted	Inspected
Instance on Rooms 306, 308	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Instance on Rooms 306, 308	Does not Exist
Recessed Mounted	Does not Exist
Instance on Rooms 306, 308	Does not Exist
Lighting Fixture - HID	Does not Exist
Instance on Rooms 306, 308	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Instance on Rooms 306, 308	Does not Exist
Lighting Fixture - LED	Does not Exist
Instance on Rooms 306, 308	Does not Exist

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

Q040

Question	Response
COMPUTER LAB	
Raceway With Receptacles	Inspected
Instance on Rooms 306, 308	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
GYMNASIUM	
Instance on 2nd Floor	Inspected
Lighting	Inspected
Instance on 2nd Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 2nd Floor	Inspected
Pendant Mounted	
Instance on 2nd Floor	Does not Exist
Surface Mounted	
Instance on 2nd Floor	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	10
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Recessed Mounted	
Instance on 2nd Floor	Does not Exist
Lighting Fixture - HID	
Instance on 2nd Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 2nd Floor	Does not Exist
Lighting Fixture - LED	
Instance on 2nd Floor	Does not Exist
Local Sound System	
Instance on 2nd Floor	Inspected
Installation Year	2009
Source of Installation	Custodial Staff
Condition	3 - Fair
Deficiency	No deficiencies recorded
Projection System	
Instance on 2nd Floor	Does not Exist
Scoreboard	
Instance on 2nd Floor	Does not Exist
Theater Lighting System	
Instance on 2nd Floor	Does not Exist
KITCHEN	
Instance on 1st Floor	Inspected
Lighting	Inspected
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

Q040

Question	Response
KITCHEN	
Lighting	
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Surface Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not Exist
LIBRARY	Inspected
Instance on Room 405/407	Inspected
Lighting	Inspected
Instance on Room 405/407	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 405/407	Inspected
Pendant Mounted	Inspected
Instance on Room 405/407	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Instance on Room 405/407	Does not Exist
Recessed Mounted	Does not Exist
Instance on Room 405/407	Does not Exist
Lighting Fixture - HID	
Instance on Room 405/407	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 405/407	Does not Exist
Lighting Fixture - LED	
Instance on Room 405/407	Does not Exist
Raceway With Receptacles	Does not Exist
Instance on Room 405/407	Does not Exist
Projection System	Does not Exist
Instance on Room 405/407	Does not Exist
LOCKER ROOM	Inspected
Instance on 2nd Floor - Boys	Inspected
Alternative use	Yes
Instance on 2nd Floor - Girls	Inspected
Alternative use	Yes
Lighting	Inspected
Instance on 2nd Floor - Girls	Inspected

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

Q040

Question	Response
LOCKER ROOM	
Lighting	
Instance on 2nd Floor - Boys	Inspected
Lighting Fixture - Fluorescent	
Instance on 2nd Floor - Girls	Inspected
Instance on 2nd Floor - Boys	Inspected
Pendant Mounted	
Instance on 2nd Floor - Girls	Does not Exist
Instance on 2nd Floor - Boys	Does not Exist
Surface Mounted	
Instance on 2nd Floor - Girls	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on 2nd Floor - Boys	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 2nd Floor - Girls	Does not Exist
Instance on 2nd Floor - Boys	Does not Exist
Lighting Fixture - HID	
Instance on 2nd Floor - Girls	Does not Exist
Instance on 2nd Floor - Boys	Does not Exist
Lighting Fixture - Incandescent	
Instance on 2nd Floor - Girls	Does not Exist
Instance on 2nd Floor - Boys	Inspected
Pendant Mounted	
Instance on 2nd Floor - Boys	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Surface Mounted	
Instance on 2nd Floor - Boys	Does not Exist
Recessed Mounted	
Instance on 2nd Floor - Boys	Does not Exist
Lighting Fixture - LED	
Instance on 2nd Floor - Girls	Does not Exist
Instance on 2nd Floor - Boys	Does not Exist
MULTIPURPOSE ROOM	
Instance on 1st Floor	Inspected
Lighting	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

Q040

Question	Response
MULTIPURPOSE ROOM	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Surface Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not Exist
Local Sound System	Does not Exist
Instance on 1st Floor	Does not Exist
Projection System	Does not Exist
Instance on 1st Floor	Does not Exist
Theater Lighting System	Does not Exist
Instance on 1st Floor	Does not Exist
SCIENCE DEMO ROOM	Inspected
Instance on Room 401	Inspected
Power Panel	No
Alternative use	No
Lighting	Inspected
Instance on Room 401	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 401	Inspected
Pendant Mounted	Inspected
Instance on Room 401	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Instance on Room 401	Does not Exist
Recessed Mounted	Does not Exist
Instance on Room 401	Does not Exist
Lighting Fixture - HID	
Instance on Room 401	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 401	Does not Exist
Lighting Fixture - LED	
Instance on Room 401	Does not Exist
Emergency Gas Shut-Off Valve	Does not Exist
Instance on Room 401	Does not Exist
Emergency Shut-Off Power	Does not Exist
Instance on Room 401	Does not Exist

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

Q040

Question	Response
SCIENCE DEMO ROOM	Inspected
Power Supply	Does not Exist
Instance on Room 401	Does not Exist
Projection System	Does not Exist
Instance on Room 401	Does not Exist
SCIENCE LAB	Does not Exist
SCIENCE PREP ROOM	Does not Exist
SWIMMING POOL	Does not Exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Replacement Quantity	102,000
Replacement Uom	S.F.
Condition	3 - Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not Exist
EMERGENCY GENERATOR SET	Does not Exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	3 - Fair
Deficiency	BATTERY NOT OPERATIONAL
Deficiency Location/Instance	Auditorium, Auditorium Lobby, Gymnasium, Corridor by Room 001, 1st Floor Staff Toilets, Cafeteria Lobby, Vestibule by Exit 9
Deficiency Quantity	13

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

Q040

Question	Response
EMERGENCY LIGHTING	
Battery Pack	
Quantity Uom	EACH
Potential Action	REPLACE BATTERY
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo	No photo recorded
Violations	35655427Y
Non Battery Pack	
Condition	Inspected
Deficiency	3 - Fair
EXIT LIGHT	
Battery Pack	
Condition	Inspected
Deficiency	1 - Good
Non Battery Pack	
Does not Exist	
EXIT/EMERGENCY LIGHT	
Does not Exist	
FIRE ALARM SYSTEM	
Inspected	
Replacement Quantity	102,000
Replacement Uom	S.F.
Bell/Horn	
Condition	Inspected
Deficiency	3 - Fair
Strobe	
Does not Exist	
Manual Pull Station	
Condition	Inspected
Deficiency	3 - Fair
Fan Shutdown Control	
Does not Exist	
Duct Smoke Detector	
Does not Exist	
Area Smoke Detector	
Does not Exist	
CO Detector	
Does not Exist	
Heat Detector	
Does not Exist	
Elevator Recall	
Does not Exist	
Magnetic Door Holder/Contactor	
Does not Exist	
Fused Cutout Panel	
Condition	Inspected
Deficiency	3 - Fair
Fire Alarm Digital Communicator	
Does not Exist	
Main Panel	
Inspected	
Bell At Panel	
Condition	Inspected
Deficiency	3 - Fair
Fire Alarm Control Panel (Electronic)	
Does not Exist	
Fire Alarm Control Panel (Standard)	
Instance	Inspected
Instance Condition	Boiler Room
Instance Quantity	3 - Fair
Instance Quantity Uom	1
Instance Manufacturer	EACH
	ACME

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

Q040

Question	Response
FIRE ALARM SYSTEM	
Main Panel	
Fire Alarm Control Panel (Standard)	
Equipment	N/A
Installation Year	1942
Source of Installation	Documented
Deficiency	No deficiencies recorded
Sub-Panel	Inspected
Bell At Panel	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Does not Exist
Fire Alarm Control Panel (Standard)	Inspected
Instance	Electrical Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	ACME
Equipment	Register Control BD.
Installation Year	1942
Source of Installation	Documented
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Display Monitor	Does not Exist
Panel	Does not Exist
Printer	Does not Exist
Punch Register	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Sprinkler Flow/Air Pressure Switch	Does not Exist
Tamper Flow Switch/Chain	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Inspected
Elevator	Does not Exist
Holding Area	Does not Exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not Exist
MOTOR CONTROLLER	Inspected
Motor Control Center	Does not Exist

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

Q040

Question	Response
MOTOR CONTROLLER	
Motor Starter/Contactor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Does not Exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not Exist
Fused Toggle Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Inspected
Condition	2 - Between Good and Fair
Deficiency	PANEL BOARD DOOR LOCK IS MISSING
Deficiency Location/Instance	Gymnasium
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	NO SPARE
Deficiency Location/Instance	Corridor by Rooms (308, 309)
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	INSTALL NEW PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
PUBLIC ADDRESS SYSTEM	Inspected
Replacement Quantity	102,000
Replacement Uom	S.F.
Instance	General Office - Room 210
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Dukane 250
Installation Year	2009
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded
SECURITY	Inspected
IPDVS/CCTV System	Inspected
Replacement Quantity	102,000
Replacement Uom	S.F.
Installation Year	2012
Source of Installation	Custodial Staff
Condition	2 - Between Good and Fair

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

Q040

Question	Response
SECURITY	
IPDVS/CCTV System	Inspected
Deficiency	No deficiencies recorded
Intrusion Alarm System	Inspected
Replacement Quantity	102,000
Replacement Uom	S.F.
Central Control Panel	Inspected
Instance	Custodian's Office - Room 214
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista-128BPT
Installation Year	2015
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3 - Fair
Deficiency	SIREN/STROBE NOT ACTIVE
Deficiency Location/Instance	Corridor by Rooms (207, 307, 325, 328, 407, 425, 433, 506), Exterior Wall facing Union Hall Street
Deficiency Quantity	9
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Lighting - Security	Inspected
Replacement Uom	EACH
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
SERVICE SWITCH	
Instance	Electrical Room
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Siemens
Equipment	Main Service Switch
Capacity/Size Quantity	2,500
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

Q040

Question	Response
SERVICE SWITCH	Inspected
Installation Year	2012
Source of Installation	Documented
Deficiency	No deficiencies recorded
SWITCHBOARD	Inspected
Number of Spares	6
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Siemens
Equipment	N/A
Capacity/Size Quantity	2,500
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	4
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Nameplate
Installation Year	2012
Source of Installation	Documented
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Does not Exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
TRANSFORMER	Does not Exist