#### **Building Condition Assessment Survey 2023 - 2024**

#### Electrical Inspection

#### Asset: P.S. 50 - QUEENS, 143-26 101 AVENUE, New York, 11435

Inspection Id Inspection Type		Time In	Last Edited
EE : Q050 Electrical		2024-01-11 7:52 AM	2024-06-21 9:58 Al
sset Data			
Question	Answer		
Type of Service	Below Gro	bund	
Does Interactive Whiteboard (IWB) Exist?	Yes		
Water Penetration in Electrical Room?	No		
Have any Systems/Major Building Components been upgraded?	Yes		
	Systems:	Retrofitted LED Lighting - Exce Main Entrance Lobby, Gymnasi Building, Science Lab Recessed Lighting, Science Prep Recessed	um, Cafeteria, Addition and Incandescent
	Years:	2023	
	Systems:	Fire Alarm System	
	Years:	2022	
	Systems:	Local Sound System (Cafeteria, Generator Set, Emergency Light Exit Lights (Battery Pack), Ligh Address System	ing (Non Battery Pack),
	Years:	2019	
	Systems:	Auditorium (Local Sound Syster	n)
	Years:	2018	
	Systems:	Security Lights	
	Years:	2016, 2023	
	Systems:	LED Lighting (Auditorium Lobl Gymnasium, Cafeteria, Additior Recessed and Incandescent Ligh Recessed Lighting), Auxiliary S Grounding System, Intercom Sy Controller (Most Motor Starters. Frequency Drive), IPDVS/CCTY System, Telephone System, Aud System, Theater Lighting Syster	Building, Science Lab ting, Science Prep ignal/Bell System, stem (Elevator), Motor (Contactor, Variable V System, Intrusion Ala litorium (Projection
	Years:	2016	
	Systems:	Auditorium	
	Years:	2010	
	Systems:	Fused Disconnect Switch Type I	Panel Board
	Years:	2002	
	Systems:	Service Switch, Switchboard	
	Years:	1992, 2016	
	Systems:	Molded Case Circuit Breaker Ty	pe Panel Board
	Years:	1992, 2002, 2016	
DEDICATED INTERCOMS IN FIRE RESCUE AREAS			
Question	Response		
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	Yes		
Are dedicated intercoms available in all of these spaces for use during a fire?	Yes		
Are all dedicated intercoms operational?	Yes		
iority Condition			
Priority Priority Condition Component Location Condition Exist Category Description Affected Description Last Year?	Person(s) Notified	Person(s) Title Status	PhotoImage
No condition recorded			
spection			
Question	Respons	5e	

#### **Building Condition Assessment Survey 2023 - 2024**

Question	Response	
lectrical		
AUDITORIUM	Inspected	
Instance on 2nd Floor	Inspected	
House Lighting	Inspected	
Does a Chandelier exist?	No	
Instance on 2nd Floor	Inspected	
Lighting Fixture - Fluorescent	*	
Instance on 2nd Floor	Does not Exist	
Lighting Fixture - HID		
Instance on 2nd Floor	Does not Exist	
Lighting Fixture - Incandescent	2000 100 2.000	
Instance on 2nd Floor	Does not Exist	
	DOUS NOT LAIST	
Lighting Fixture - LED Instance on 2nd Floor	Inspected	
	Inspected	
Pendant Mounted	Inspected	
Instance on 2nd Floor	Inspected	
Condition	2 - Between Good and Fair	
Deficiency Surface Mounted	No deficiencies recorded	
	Inspected	
Instance on 2nd Floor Condition	Inspected 2 - Between Good and Fair	
Deficiency	2 - Between Good and Fair No deficiencies recorded	
Recessed Mounted	Does not Exist	
Instance on 2nd Floor	Does not Exist	
Local Sound System Instance on 2nd Floor	Inspected	
Installation Year	Inspected 2018	
Source of Installation	Custodial Staff	
Condition	2 - Between Good and Fair	
Deficiency Projection System	No deficiencies recorded Inspected	
Is the projector on a cart or installed on the ceiling?	Ceiling	
Instance on 2nd Floor	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Theater Lighting System	Inspected	
Instance on 2nd Floor	Inspected	
Dimming System		
Instance on 2nd Floor	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Theater Lighting		
Instance on 2nd Floor	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
CAFETERIA	Inspected	
Instance on 1st Floor	Inspected	
	-	
Lighting	Inspected	

Lighting Fixture - Fluorescent

und Fair
orded
nd Fair
orded
nd Fair
orded
braed
nd Fair
orded
סועכע
nd Fair
orded
סוונים

# Building Condition Assessment Survey 2023 - 2024

trical Inspection		Ç
iestion	Response	
COMPUTER LAB		
Lighting		
Lighting Fixture - Fluorescent		
Instance on Room 313	Does not Exist	
Lighting Fixture - HID		
Instance on Room 313	Does not Exist	
Lighting Fixture - Incandescent		
Instance on Room 313	Does not Exist	
Lighting Fixture - LED		
Instance on Room 313	Inspected	
Pendant Mounted	Inspected	
Instance on Room 313	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Does not Exist	
Instance on Room 313	Does not Exist	
Recessed Mounted	Inspected	
Instance on Room 313	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Raceway With Receptacles	Inspected	
Instance on Room 313	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
SYMNASIUM	Inspected	
Instance on 4th Floor	Inspected	
Lighting	Inspected	
Instance on 4th Floor	Inspected	
Lighting Fixture - Fluorescent	mspecce	
Instance on 4th Floor	Does not Exist	
	Does not LAIst	
Lighting Fixture - HID Instance on 4th Floor	Does not Exist	
	Does not Exist	
Lighting Fixture - Incandescent		
Instance on 4th Floor	Does not Exist	
Lighting Fixture - LED		
Instance on 4th Floor	Inspected	
Pendant Mounted	Inspected	
Instance on 4th Floor	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Does not Exist	
Instance on 4th Floor	Does not Exist	
Recessed Mounted	Inspected	
Instance on 4th Floor	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Local Sound System	Inspected	
Instance on 4th Floor	Inspected	
Installation Year	2019	

Source of Installation

Custodial Staff

#### **Building Condition Assessment Survey 2023 - 2024**

uestion	Response	
GYMNASIUM		
Local Sound System	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Projection System	Does not Exist	
Instance on 4th Floor	Does not Exist	
Scoreboard	Does not Exist	
Instance on 4th Floor	Does not Exist	
Theater Lighting System	Does not Exist	
Instance on 4th Floor	Does not Exist	
KITCHEN	Inspected	
Instance on 1st Floor	Inspected	
Lighting	Inspected	
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Does not Exist	
Lighting Fixture - HID		
Instance on 1st Floor	Does not Exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not Exist	
Lighting Fixture - LED		
Instance on 1st Floor	Inspected	
Pendant Mounted	Does not Exist	
Instance on 1st Floor	Does not Exist	
Surface Mounted	Does not Exist	
Instance on 1st Floor	Does not Exist	
Recessed Mounted	Inspected	
Instance on 1st Floor	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
LIBRARY	Inspected	
Instance on Room 123	Inspected	
Lighting	Inspected	
Instance on Room 123	Inspected	
Lighting Fixture - Fluorescent	*	
Instance on Room 123	Does not Exist	
Lighting Fixture - HID		
Instance on Room 123	Does not Exist	
Lighting Fixture - Incandescent		
Instance on Room 123	Does not Exist	
	Does not Exist	
Lighting Fixture - LED Instance on Room 123	Increated	
	Inspected	
Pendant Mounted	Inspected	
Instance on Room 123	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Does not Exist	
Instance on Room 123	Does not Exist	

**Recessed Mounted** 

Does not Exist

#### **Building Condition Assessment Survey 2023 - 2024**

trical Inspection	Response	
LIBRARY	Kesponse	
	Inspected	
Lighting	Inspected	
Lighting Fixture - LED Recessed Mounted		
Instance on Room 123	Does not Exist	
Raceway With Receptacles	Inspected	
Instance on Room 123	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Projection System	Does not Exist	
Instance on Room 123	Does not Exist	
LOCKER ROOM	Does not Exist	
MULTIPURPOSE ROOM	Does not Exist	
SCIENCE DEMO ROOM	Does not Exist	
SCIENCE LAB	Inspected	
Instance on Rooms 315, 317	Inspected	
Power Panel	No	
Alternative use	No	
Lighting	Inspected	
Instance on Rooms 315, 317	Inspected	
Lighting Fixture - Fluorescent		
Instance on Rooms 315, 317	Does not Exist	
Lighting Fixture - HID		
Instance on Rooms 315, 317	Does not Exist	
Lighting Fixture - Incandescent		
Instance on Rooms 315, 317	Inspected	
Pendant Mounted	Does not Exist	
Instance on Rooms 315, 317	Does not Exist	
Surface Mounted	Inspected	
Instance on Rooms 315, 317	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not Exist	
Instance on Rooms 315, 317	Does not Exist	
Lighting Fixture - LED		
Instance on Rooms 315, 317	Inspected	
Pendant Mounted	Inspected	
Instance on Rooms 315, 317	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Does not Exist	
Instance on Rooms 315, 317	Does not Exist	
Recessed Mounted	Inspected	
Instance on Rooms 315, 317	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Emergency Gas Shut-Off Valve	Does not Exist	
Instance on Rooms 315, 317	Does not Exist	
Emergency Shut-Off Power	Does not Exist	
Instance on Pooms 315, 317	Does not Exist	

Instance on Rooms 315, 317

Does not Exist

uestion	Response	
SCIENCE LAB	Å	
Power Supply	Does not Exist	
Instance on Rooms 315, 317	Does not Exist	
Projection System	Does not Exist	
Instance on Rooms 315, 317	Does not Exist	
SCIENCE PREP ROOM	Inspected	
Instance on Room 315A	Inspected	
Power Panel	No	
Alternative use	No	
Lighting	Inspected	
Instance on Room 315A	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 315A	Does not Exist	
Lighting Fixture - HID		
Instance on Room 315A	Does not Exist	
Lighting Fixture - Incandescent		
Instance on Room 315A	Does not Exist	
Lighting Fixture - LED		
Instance on Room 315A	Inspected	
Pendant Mounted	Does not Exist	
Instance on Room 315A	Does not Exist	
Surface Mounted	Does not Exist	
Instance on Room 315A	Does not Exist	
Recessed Mounted	Inspected	
Instance on Room 315A	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Emergency Gas Shut-Off Valve	Does not Exist	
Instance on Room 315A	Does not Exist	
Emergency Shut-Off Power	Does not Exist	
Instance on Room 315A	Does not Exist	
Power Supply	Does not Exist	
Instance on Room 315A	Does not Exist	
SWIMMING POOL	Does not Exist	
TOILET ROOM - STAFF	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Does not Exist	
Lighting Fixture - HID	Does not Exist	
Lighting Fixture - Incandescent	Does not Exist	
Lighting Fixture - LED	Inspected	
Pendant Mounted	Does not Exist	
Surface Mounted	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
TOILET ROOM - STUDENT	Inspected	

uestion	Response	
TOILET ROOM - STUDENT		
Lighting		
Lighting Fixture - Fluorescent	Does not Exist	
Lighting Fixture - HID	Does not Exist	
Lighting Fixture - Incandescent	Does not Exist	
Lighting Fixture - LED	Inspected	
Pendant Mounted	Does not Exist	
Surface Mounted	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
AUXILIARY SIGNAL/BELL SYSTEM	Inspected	
Replacement Quantity	140,000	
Replacement Uom	S.F.	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
EMERGENCY DC STANDBY BATTERY POWER	Does not Exist	
EMERGENCY GENERATOR SET	Inspected	
Automatic Transfer Switch (ATS)	Inspected	
Instance	ATS Room 010	
Instance Condition	1 - Good	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Instance Manufacturer	General Electric	
Equipment	ATS-1	
Capacity/Size Quantity	600	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	2019	
Source of Installation	Custodial Staff	
Deficiency	No deficiencies recorded	
Instance	ATS Room 010	
Instance Condition	1 - Good	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Instance Manufacturer	General Electric	
Equipment	ATS-2	
Capacity/Size Quantity	225	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	2019	
Source of Installation	Custodial Staff	
Deficiency	No deficiencies recorded	
Instance	ATS Room 010	
Instance Condition	1 - Good	
Instance Quantity	1	
Instance Quantity Uom	EACH	

### **Building Condition Assessment Survey 2023 - 2024**

#### Electrical Inspection

estion	Response
MERGENCY GENERATOR SET	карова
Automatic Transfer Switch (ATS)	
Instance Manufacturer	General Electric
Equipment	Fire Alarm System Automatic Transfer Switch
Capacity/Size Quantity	80
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2019
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded
Instance	Fire Pump Room 015
Instance Condition	1 - Good
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Tornatech
Equipment	Fire Pump Power Transfer Switch
Capacity/Size Quantity	60
Capacity/Size UOM	НР
Source of Capacity/Size	Nameplate
Installation Year	2019
Source of Installation	Documented
Deficiency	No deficiencies recorded
Battery Charger	Inspected
Instance	Schoolyard - Outdoor Generator Enclosure
Instance Condition	1 - Good
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	SENS
Equipment	Battery Charger
Capacity/Size Quantity	10
Capacity/Size UOM	AmpsDC
Capacity/Size2 Quantity	24
Capacity/Size2 UOM	VDC
Source of Capacity/Size	Nameplate
Installation Year	2019
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded
Emergency Distribution Board	Inspected
Number of Spares	2
Fused Disconnect Switch Type	Inspected
Instance	ATS Room 010
Instance Condition	1 - Good
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	All City Switchboard
Equipment	EDB1
Capacity/Size Quantity	600
Capacity/Size UOM	Amps Total
1 ·	

trical Inspection		
uestion	Response	
EMERGENCY GENERATOR SET		
Emergency Distribution Board		
Fused Disconnect Switch Type		
Capacity/Size2 UOM	Section(S)	
Source of Capacity/Size	Nameplate	
Installation Year	2019	
Source of Installation	Custodial Staff	
Deficiency	No deficiencies recorded	
Instance	ATS Room 010	
Instance Condition	1 - Good	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Instance Manufacturer	All City Switchboard	
Equipment	EDB2	
Capacity/Size Quantity	200	
Capacity/Size UOM	Amps Total	
Capacity/Size2 Quantity	1	
Capacity/Size2 UOM	Section(S)	
Source of Capacity/Size	Nameplate	
Installation Year	2019	
Source of Installation	Custodial Staff	
Deficiency	No deficiencies recorded	
Molded Case Circuit Breaker Type	Does not Exist	
Diesel	Inspected	
Instance	Schoolyard - Outdoor Generator Enclosure	
Instance Condition	1 - Good	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Instance Manufacturer	MTU onsite energy	
Equipment	Emergency Generator	
Capacity/Size Quantity	375	
Capacity/Size UOM	KVA	
Capacity/Size2 Quantity	300	
Capacity/Size2 UOM	KW	
Capacity/Size3Quantity	1,040	
Capacity/Size3 UOM	Amps	
	Amps Nameplate	
Source of Capacity/Size Installation Year	2019	
Source of Installation	2019 Custodial Staff	
Deficiency Natural Gas	No deficiencies recorded Does not Exist	
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not Exist	
EMERGENCY LIGHTING	Inspected	
Battery Pack	Does not Exist	
Non Battery Pack	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
EXIT LIGHT	Inspected	

#### **Building Condition Assessment Survey 2023 - 2024**

#### **Electrical Inspection**

Q050

estion	Response	
XIT LIGHT	корово	
Battery Pack		
Condition	1 - Good	
Deficiency	FIXTURE NOT OPERATIONAL	
Deficiency Location/Instance	Corridor by Room 123	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPAIR	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 2	
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
	Does not Exist	
Non Battery Pack XIT/EMERGENCY LIGHT	Does not Exist	
IRE ALARM SYSTEM	Inspected	
Replacement Quantity	140,000	
Replacement Uom	S.F.	
Bell/Horn	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Strobe	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Manual Pull Station	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Fan Shutdown Control	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Duct Smoke Detector	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Area Smoke Detector	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
CO Detector	Does not Exist	
Heat Detector	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Elevator Recall	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Magnetic Door Holder/Contactor	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Fused Cutout Panel	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Fire Alarm Digital Communicator	Does not Exist	

estion	Response
FIRE ALARM SYSTEM	Kesponse
Main Panel	
Bell At Panel	Does not Exist
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Main Entrance Lobby
Instance Condition	1 - Good
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Gamewell
Equipment	Fire Alarm Control Panel With D.A.C.T
Model	E3 Series
Installation Year	2022
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Does not Exist
Sub-Panel	Does not Exist
Remote Annunciator	Inspected
Display Monitor	Does not Exist
Panel	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Printer	Inspected
Condition	5 - Poor
Deficiency	PRINTER NOT OPERATIONAL
Deficiency Location/Instance	Custodian's Office
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Punch Register	Does not Exist
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Tamper Flow Switch/Chain	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
NTERCOM SYSTEM	Inspected
Elevator	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Holding Area	Does not Exist
LAN	Inspected

uestion	Response
LAN	
Local Distribution Frame (I/LDF)	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
MOTOR CONTROLLER	Inspected
Motor Control Center	Does not Exist
Motor Starter/Contactor	Inspected
Condition	2 - Between Good and Fair
Deficiency Voriable Engunary Drive	No deficiencies recorded
Variable Frequency Drive	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not Exist
Fused Toggle Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Inspected
Condition	2 - Between Good and Fair
Deficiency	NO SPARE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL NEW PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL BOARD COVER IS MISSING
Deficiency Location/Instance	Boiler Room (Original Building), Electrical Closet - Room 324
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
PUBLIC ADDRESS SYSTEM	Inspected
Replacement Quantity	140,000
Replacement Uom	S.F.
Instance	Telecommunications Room 330

uestion	Response
PUBLIC ADDRESS SYSTEM	
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Telecor II
Installation Year	2019
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded
SECURITY	Inspected
IPDVS/CCTV System	Inspected
Replacement Quantity	140,000
Replacement Uom	S.F.
Installation Year	2016
Source of Installation	Custodial Staff
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Intrusion Alarm System	Inspected
Replacement Quantity	140,000
Replacement Uom	S.F.
Central Control Panel	Inspected
Instance	Custodian's Office
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista-128BPT
Installation Year	2016
Source of Installation	Documented
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting - Security	Inspected
Replacement Uom	EACH
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
SERVICE SWITCH	Inspected
Instance	Building Addition - Electric Switchgear Room 012
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	All City Switchboard

### **Building Condition Assessment Survey 2023 - 2024**

#### Electrical Inspection

car inspection	Qu
tion	Response
RVICE SWITCH	
Equipment	3,000A Switch #1
Capacity/Size Quantity	3,000
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2016
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Building Addition - Electric Switchgear Room 012
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	All City Switchboard
Equipment	1200A Service Switch #2 (MDB1)
Capacity/Size Quantity	1,200
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2016
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Building Addition - Electric Switchgear Room 012
Instance Condition	2 - Between Good and Fair
	1
Instance Quantity	
Instance Quantity Uom	EACH
Instance Manufacturer	All City Switchboard
Equipment	600A Service Switch #3 (EDB1)
Capacity/Size Quantity	600
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2016
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Building Addition - Electric Switchgear Room 012
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	All City Switchboard
Equipment	200A Service Switch #4 (EDB2)
Capacity/Size Quantity	200
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2016
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Building Addition - Electric Switchgear Room 012
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
-	

### **Building Condition Assessment Survey 2023 - 2024**

#### **Electrical Inspection**

trical Ins	spectron	
iestion		Response
-	SWITCH	
	Equipment	Service Switch #5 Fire Pump
	Capacity/Size Quantity	800
	Capacity/Size UOM	Amps
-	Source of Capacity/Size	Nameplate
	Installation Year	2016
-	Source of Installation	Documented
-	Deficiency	No deficiencies recorded
-	Instance	Original Building - Electrical Room 100
-	Instance Condition	3 - Fair
-	Instance Quantity	1
-	Instance Quantity Uom	EACH
-	Instance Manufacturer	All City Switchboard
	Equipment	Service Switch
	Capacity/Size Quantity	2,500
	Capacity/Size UOM	Amps
-	Source of Capacity/Size	Nameplate
]	Installation Year	1992
1	Source of Installation	Documented
	Deficiency	No deficiencies recorded
SWITCHE		Inspected
-	Number of Spares	9
Fused D	isconnect Switch Type	Inspected
-	Instance	Building Addition - Electric Switchgear Room 012
-	Instance Condition	2 - Between Good and Fair
-	Instance Quantity	1
]	Instance Quantity Uom	EACH
]	Instance Manufacturer	All City Switchboard
	Equipment	"MDB1" Section #1, #2
(	Capacity/Size Quantity	1,200
(	Capacity/Size UOM	Amps Total
(	Capacity/Size2 Quantity	2
(	Capacity/Size2 UOM	Section(S)
	Source of Capacity/Size	Service Switch Size
1	Installation Year	2016
	Source of Installation	Documented
]	Deficiency	No deficiencies recorded
]	Instance	Building Addition Roof- Electrical Switchgear Room
]	Instance Condition	3 - Fair
]	Instance Quantity	1
1	Instance Quantity Uom	EACH
J	Instance Manufacturer	All City Switchboard
J	Equipment	Distribution Switchboard "HDB" Section #1, #2
(	Capacity/Size Quantity	3,000
1	Capacity/Size UOM	Amps Total
	Capacity/Size2 Quantity	2
	Capacity/Size2 UOM	Section(S)
(		~~~~~
	Source of Capacity/Size	Service Switch Size

etrical Inspection uestion	Response
SWITCHBOARD	the second s
Fused Disconnect Switch Type	
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Original Building - Electrical Room 100
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	All City Switchboard
Equipment	N/A
Capacity/Size Quantity	2,500
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	2
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Service Switch Size
Installation Year	1992
Source of Installation	Documented
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Does not Exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
TRANSFORMER	Does not Exist