Building Condition Assessment Survey 2023 - 2024

	d Inspection	Type				Time In		Last Edited
EE : Q0:	55 Electrical					2024-02-	28 10:02 AM	2024-03-27 1:20 PI
set Data								
Question					Answer			
Type of Servi	ce				Below Gro	und		
Does Interacti	ive Whiteboard (I	WB) Exist?			Yes			
Water Penetra	ation in Electrical	Room?			Yes			
Have any Sys	tems/Major Build	ling Components	been upgraded?		Yes			
					Systems:	LAN		
					Years:	2023		
					Systems:	Clocks), Cafeteri		Address System (Main Rac and System)
					Years:	2022		
					Systems:			ound System, Projection ighting (Battery Pack)
					Years:	2018		
					Systems:	Telephone System	m	
					Years:	2017		
					Systems:	Interior Lighting	, Exit Lights ((Battery Pack)
					Years: Systems:		System (Cent	ral Control Panel, Infrared
						Sensor)		
					Years:	2013		
					Systems:	Security Lights		
					Years:	2012, 2024		
					Systems:			reaker Type Panel Board
					Years:	1993, 2012, 2020		
					Systems:	Public Address S		anel, Fire Alarm System, ce Switch
	D 11/19/19 001 00	N. FIRE REGG			Years:	1993		
Question	D INTERCOMS	IN FIRE RESC	UE AREAS		Response			
Are there any	V Life Rescue Assing Rooms in your		re Rescue Areas,		No			
una, or moran								
ority Conditi	ion							
	Priority	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
ority Conditionity Condition Exist	Priority	Description N/A			Notified	Person(s) Title Fireman	Sent to DSF	
ority Conditi Priority Condition Exist Last Year?	Priority Category Water Penetration in	Description N/A	Affected Electrical	Description	Notified			
ority Conditi Priority Condition Exist .ast Year?	Priority Category Water Penetration in	Description N/A	Affected Electrical	Description	Notified Scott Cosby	Fireman		
ority Condition Condition Exist Last Year?	Priority Category Water Penetration in	Description N/A	Affected Electrical	Description	Notified	Fireman		
Priority Condition Exist Last Year? No Spection Question	Priority Category Water Penetration in Electrical Room	Description N/A	Affected Electrical	Description	Notified Scott Cosby	Fireman		
Priority Condition Priority Condition Exist Last Year? No Spection Question Electrical AUDITORIU	Priority Category Water Penetration in Electrical Room	Description N/A	Affected Electrical	Description	Notified Scott Cosby Respons Does not	Fireman Se Exist		
Priority Condition Exist Augustion Spection Question Electrical AUDITORIU CAFETERIA	Priority Category Water Penetration in Electrical Room	N/A	Affected Electrical	Description	Notified Scott Cosby Respons Does not Inspected	Fireman Se Exist		
Priority Condition Priority Condition Exist Last Year? No Spection Question Electrical AUDITORIU CAFETERIA Ins	Priority Category Water Penetration in Electrical Room	N/A	Affected Electrical	Description	Respons Does not Inspected Inspected	Fireman Se Exist		
Priority Condition Priority Condition Exist Last Year? No Spection Question Electrical AUDITORIU CAFETERIA Ins Lighting	Priority Category Water Penetration in Electrical Room	N/A N/A	Affected Electrical	Description	Respons Does not Inspected Inspected Inspected	Fireman See Exist d		
Priority Condition Priority Condition Exist Last Year? No Spection Question Electrical AUDITORIU CAFETERIA Ins Lighting Ins	Priority Category Water Penetration in Electrical Room UM A stance on 1st Floor stance on 1st Floor	N/A N/A	Affected Electrical	Description	Respons Does not Inspected Inspected	Fireman See Exist d		
Priority Condition Priority Condition Exist Last Year? No Spection Question Electrical AUDITORIU CAFETERIA Ins Lighting Ins Lighting	Priority Category Water Penetration in Electrical Room	Description N/A	Affected Electrical	Description	Respons Does not Inspected Inspected Inspected	Fireman Se Exist I I I		

Building Condition Assessment Survey 2023 - 2024

curear inspection		2000
Question	Response	
CAFETERIA		
Lighting		
Lighting Fixture - HID		
Instance on 1st Floor	Does not Exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not Exist	
Lighting Fixture - LED		
Instance on 1st Floor	Inspected	
Pendant Mounted	Does not Exist	
Instance on 1st Floor	Does not Exist	
Surface Mounted	Inspected	
Instance on 1st Floor	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not Exist	
Instance on 1st Floor	Does not Exist	
Local Sound System	Inspected	
Instance on 1st Floor	Inspected	
Installation Year	2022	
Source of Installation	Custodial Staff	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Projection System	Does not Exist	
Instance on 1st Floor	Does not Exist	
Theater Lighting System	Does not Exist	
Instance on 1st Floor	Does not Exist	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected	
Lighting	Inspected	
Does a Chandelier exist?	No	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not Exist	
Lighting Fixture - HID	Does not Exist	
Lighting Fixture - Incandescent	Does not Exist	
Lighting Fixture - LED	Does not Exist	
COMPUTER LAB	Inspected	
Instance on Room 125	Inspected	
Power Panel	Yes	
Lighting	Inspected	
Instance on Room 125	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 125	Inspected	
Pendant Mounted	Inspected	
Instance on Room 125	Inspected	
	-1	

Building Condition Assessment Survey 2023 - 2024

Question	Response
COMPUTER LAB	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Instance on Room 125	Does not Exist
Recessed Mounted	Does not Exist
Instance on Room 125	Does not Exist
Lighting Fixture - HID	
Instance on Room 125	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 125	Does not Exist
Lighting Fixture - LED	
Instance on Room 125	Does not Exist
Raceway With Receptacles	Inspected
Instance on Room 125	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
GYMNASIUM	Does not Exist
KITCHEN	Inspected
Instance on 1st Floor	Inspected
Lighting	Inspected
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Surface Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not Exist
LIBRARY	Inspected
Instance on Room 225	Inspected
Lighting	Inspected
Instance on Room 225	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 225	Inspected
Pendant Mounted	Inspected
Instance on Room 225	Inspected
	<u>F</u>

Building Condition Assessment Survey 2023 - 2024

ction	Dosnonsa	
IBRARY	Response	
Lighting Lighting Fixture - Fluorescent		
Pendant Mounted	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Does not Exist	
Instance on Room 225	Does not Exist	
Recessed Mounted	Does not Exist	
Instance on Room 225	Does not Exist	
Lighting Fixture - HID		
Instance on Room 225	Does not Exist	
Lighting Fixture - Incandescent	2 oct not 2 mil	
Instance on Room 225	Does not Exist	
Lighting Fixture - LED	Does not Exist	
Instance on Room 225	Does not Exist	
Raceway With Receptacles	Does not Exist	
Instance on Room 225	Does not Exist Does not Exist	
	Does not Exist	
Projection System Instance on Room 225	Does not Exist Does not Exist	
OCKER ROOM	Does not Exist	
MULTIPURPOSE ROOM	Inspected	
Instance on 1st Floor	Inspected	
Lighting	Inspected	
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Does not Exist	
Lighting Fixture - HID		
Instance on 1st Floor	Does not Exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not Exist	
Lighting Fixture - LED		
Instance on 1st Floor	Inspected	
Pendant Mounted	Does not Exist	
Instance on 1st Floor	Does not Exist	
Surface Mounted	Inspected	
Instance on 1st Floor	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not Exist	
Instance on 1st Floor	Does not Exist	
Local Sound System	Inspected	
Instance on 1st Floor	Inspected	
Installation Year	2018	
Source of Installation	Custodial Staff	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Projection System	Inspected	

Building Condition Assessment Survey 2023 - 2024

Question	Response
MULTIPURPOSE ROOM	
Projection System	Inspected
Instance on 1st Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Theater Lighting System	Inspected
Instance on 1st Floor	Inspected
Dimming System	
Instance on 1st Floor	Does not Exist
Theater Lighting	
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
SCIENCE DEMO ROOM	Does not Exist
SCIENCE LAB	Does not Exist
SCIENCE PREP ROOM	Does not Exist
SWIMMING POOL	Does not Exist
TOILET ROOM - STAFF	Inspected
	•
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Recessed Mounted	Does not Exist
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - Healitescent Lighting Fixture - LED	Does not Exist
Eignung Fixture - LED	DOGS HOT EAIST

Building Condition Assessment Survey 2023 - 2024

Question	Response
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Replacement Quantity	36,000
Replacement Uom	S.F.
Condition	3 - Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not Exist
EMERGENCY GENERATOR SET	Does not Exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	3 - Fair
Deficiency	LESS THAN 20% SPARE CIRCUIT BREAKERS
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL NEW PANEL BOARD
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Does not Exist
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Does not Exist
EXIT/EMERGENCY LIGHT	Does not Exist
FIRE ALARM SYSTEM	Inspected
Replacement Quantity	36,000
Replacement Uom	S.F.
Bell/Horn	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Manual Pull Station	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Does not Exist
Duct Smoke Detector	Does not Exist
Area Smoke Detector	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
CO Detector	Does not Exist
Heat Detector	Does not Exist
Elevator Recall	Does not Exist

Building Condition Assessment Survey 2023 - 2024

V.
Response
Does not Exist
Inspected
3 - Fair
No deficiencies recorded
Does not Exist
Inspected
Inspected
3 - Fair
No deficiencies recorded
Inspected
Boiler Room
3 - Fair
1
EACH
Fire Alarm & Systems Technology Inc
Fire Alarm Control Panel (Fire, Smoke, Sprinkler Panel)
N/A
1993
Documented
No deficiencies recorded
Does not Exist
Inspected
Does not Exist
Inspected
Custodian's Office
3 - Fair
1
EACH
Fire Alarm & Systems Technology Inc
Remote Annunciator W/Fan & Damper Control
N/A
1993
Documented
No deficiencies recorded
Does not Exist
Inspected
Does not Exist
Inspected
3 - Fair
No deficiencies recorded
Does not Exist
Does not Exist
Inspected
3 - Fair
3 - Fair No deficiencies recorded

Building Condition Assessment Survey 2023 - 2024

Question	Response
GROUNDING SYSTEM	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Does not Exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
MOTOR CONTROLLER	Inspected
Motor Control Center	Does not Exist
Motor Starter/Contactor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Does not Exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Does not Exist
Fused Knife Switch Type	Does not Exist
Fused Toggle Switch Type	Inspected
Condition	3 - Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Molded Case Circuit Breaker Type	Inspected
Condition	3 - Fair
Deficiency	PANEL BOARD COVER IS MISSING
Deficiency Location/Instance	Boiler Room, Electrical Room
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	NO SPARE
Deficiency Location/Instance	Cafeteria, Corridor by Rooms (219, 319), Boiler Room
Deficiency Quantity	6
Quantity Uom	EACH

Building Condition Assessment Survey 2023 - 2024

Question	Response
PANEL BOARD	
Molded Case Circuit Breaker Type	
Potential Action	REPLACE PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Cafeteria, Electrical Room
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
PUBLIC ADDRESS SYSTEM	Inspected
Replacement Quantity	36,000
Replacement Uom	S.F.
Instance	General Office
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	BOGEN NYQUIST
Installation Year	1993
Source of Installation	Documented No deficiencies recorded
Deficiency SECURITY	
	Inspected
IPDVS/CCTV System	Does not Exist
Intrusion Alarm System	Inspected
Replacement Quantity	36,000
Replacement Uom	S.F.
Central Control Panel	Inspected
Instance	Custodian's Office
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista-128BPT
Installation Year	2014
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	3 - Fair

Building Condition Assessment Survey 2023 - 2024

Question	Response
SECURITY	
Intrusion Alarm System	
Remote Annunciator	Inspected
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Lighting - Security	Inspected
Replacement Uom	EACH
Condition	1 - Good
Deficiency	TIME CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 3
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
SERVICE SWITCH	Inspected
Instance	Electrical Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	All City Switchboard
Equipment	N/A
Capacity/Size Quantity	1,200
Capacity/Size Quantity Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1993
Source of Installation	
Deficiency	Documented No deficiencies recorded
Instance	Electrical Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	All City Switchboard
Equipment	N/A
Capacity/Size Quantity	1,200
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1993
Source of Installation	Documented
Deficiency	No deficiencies recorded
SWITCHBOARD	Inspected
Number of Spares	3
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room
Instance Condition	3 - Fair

Building Condition Assessment Survey 2023 - 2024

estion	Response
WITCHBOARD	
Fused Disconnect Switch Type	
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Standard Switchboard
Equipment	N/A
Capacity/Size Quantity	1,200
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	2
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Service Switch Size
Installation Year	1969
Source of Installation	Documented
Deficiency	FUSED DISCONNECT NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Fused Knife Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Does not Exist
ELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
RANSFORMER	Does not Exist