

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

**Q085**

**Asset: P.S. 85 - QUEENS, 23-70 31 STREET, New York, 11105**

Inspection Id	Inspection Type	Time In	Last Edited
EE : Q085	Electrical	2024-02-05 7:54 AM	2024-02-23 11:19 AM

**Asset Data**

Question	Answer
Have any Systems/Major Building Components been upgraded?	Yes
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration in Electrical Room?	No
	Systems: LAN, Telephone System
	Years: 2023
	Systems: LED Lighting (Rooms 305, 307)
	Years: 2021
	Systems: IPDVS/CCTV System, Intrusion Alarm System (Panic Switch)
	Years: 2019
	Systems: Exit Lights (Battery Pack), Fire Alarm System, Grounding System, Service Switch
	Years: 2017
	Systems: Interior Lighting, Most Emergency Lighting (Non Battery Pack)
	Years: 2016
	Systems: Auditorium (Local Sound System, Theater Lighting System), Security Lights
	Years: 2014
	Systems: Auditorium (Projection System)
	Years: 2013
	Systems: Switchboard
	Years: 2009, 2017
	Systems: Intrusion Alarm System
	Years: 2006
	Systems: Emergency Light/Exit Light Panel, Public Address System
	Years: 2000
	Systems: Molded Case Circuit Breaker Type Panel Board
	Years: 1990, 2000, 2009, 2017

**DEDICATED INTERCOMS IN FIRE RESCUE AREAS**

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	No

**Priority Condition**

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
No	Exit Light - Fixture Not Operational	N/A	EXIT LIGHT   Battery Pack	Cafeteria, Gymnasium, Basement at (Staircases (A, B, C, D), Exits (2, 6) vestibules), Corridor by Rooms (101, 102, 104, 107, 109, 112, 201, 202, 204, 211, 212, 254, 301, 302, 304, 309, 311, 312, 351, 358), Boiler Room	Panagiotis Holidis	Custodian	Sent to DSF	

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q085

Yes	Water Leaks onto Electrical Equipment	N/A	Electric Outlet, Panel Board	Room 312	Panagiotis Holidis	Custodian	Sent to DSF
-----	---------------------------------------	-----	------------------------------	----------	--------------------	-----------	-------------

Inspection

Question	Response
<b>Electrical</b>	
<b>AUDITORIUM</b>	Inspected
Instance on 2nd Floor	Inspected
<b>House Lighting</b>	Inspected
Does a Chandelier exist?	No
Instance on 2nd Floor	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 2nd Floor	Inspected
<b>    Pendant Mounted</b>	Does not Exist
Instance on 2nd Floor	Does not Exist
<b>    Surface Mounted</b>	Inspected
Instance on 2nd Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>    Recessed Mounted</b>	Does not Exist
Instance on 2nd Floor	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on 2nd Floor	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 2nd Floor	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on 2nd Floor	Inspected
<b>    Pendant Mounted</b>	Does not Exist
Instance on 2nd Floor	Does not Exist
<b>    Surface Mounted</b>	Inspected
Instance on 2nd Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>    Recessed Mounted</b>	Does not Exist
Instance on 2nd Floor	Does not Exist
<b>Local Sound System</b>	Inspected
Instance on 2nd Floor	Inspected
Installation Year	2014
Source of Installation	Custodial Staff
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Projection System</b>	Inspected
Is the projector on a cart or installed on the ceiling?	Ceiling
Instance on 2nd Floor	Inspected
Condition	4 - Between Fair and Poor
Deficiency	VIDEO PROJECTOR IS NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q085

Question	Response
<b>AUDITORIUM</b>	
<b>Projection System</b>	
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Theater Lighting System</b>	
Instance on 2nd Floor	Inspected
<b>Dimming System</b>	
Instance on 2nd Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Theater Lighting</b>	
Instance on 2nd Floor	Inspected
Condition	4 - Between Fair and Poor
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Quantity	52
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>CAFETERIA</b>	
Instance on Basement	Inspected
<b>Lighting</b>	
Instance on Basement	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Basement	Inspected
<b>Pendant Mounted</b>	
Instance on Basement	Does not Exist
<b>Surface Mounted</b>	
Instance on Basement	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	
Instance on Basement	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on Basement	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Basement	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Basement	Does not Exist
<b>Local Sound System</b>	
Instance on Basement	Inspected
Installation Year	2000
Source of Installation	Inspector Estimate
Condition	5 - Poor
Deficiency	AMPLIFIER NOT OPERATIONAL
Deficiency Quantity	1

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q085

Question	Response
<b>CAFETERIA</b>	
<b>Local Sound System</b>	
Quantity Uom	EACH
Potential Action	REPLACE SYSTEM
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Projection System</b>	
Instance on Basement	Does not Exist
<b>Theater Lighting System</b>	
Instance on Basement	Does not Exist
<b>CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE</b>	
<b>Lighting</b>	Inspected
Does a Chandelier exist?	No
<b>Lighting Fixture - Fluorescent</b>	
<b>Pendant Mounted</b>	
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	
<b>Lighting Fixture - HID</b>	
<b>Lighting Fixture - Incandescent</b>	
<b>Lighting Fixture - LED</b>	
<b>Pendant Mounted</b>	
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
<b>Recessed Mounted</b>	
<b>COMPUTER LAB</b>	
Instance on Room 312	Inspected
Power Panel	Yes
<b>Lighting</b>	Inspected
Instance on Room 312	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 312	Inspected
<b>Pendant Mounted</b>	
Instance on Room 312	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	
Instance on Room 312	Does not Exist
<b>Recessed Mounted</b>	
Instance on Room 312	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on Room 312	Does not Exist
<b>Lighting Fixture - Incandescent</b>	

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q085

Question	Response
<b>COMPUTER LAB</b>	
<b>Lighting</b>	Inspected
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 312	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Room 312	Does not Exist
<b>Raceway With Receptacles</b>	Inspected
Instance on Room 312	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>GYMNASIUM</b>	Inspected
Instance on Basement	Inspected
<b>Lighting</b>	Inspected
Instance on Basement	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Basement	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on Basement	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Basement	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Basement	Inspected
<b>Pendant Mounted</b>	Inspected
Instance on Basement	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Does not Exist
Instance on Basement	Does not Exist
<b>Recessed Mounted</b>	Does not Exist
Instance on Basement	Does not Exist
<b>Local Sound System</b>	Inspected
Instance on Basement	Inspected
Installation Year	2000
Source of Installation	Inspector Estimate
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Projection System</b>	Does not Exist
Instance on Basement	Does not Exist
<b>Scoreboard</b>	Does not Exist
Instance on Basement	Does not Exist
<b>Theater Lighting System</b>	Does not Exist
Instance on Basement	Does not Exist
<b>KITCHEN</b>	Inspected
Instance on Basement	Inspected
<b>Lighting</b>	Inspected
Instance on Basement	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Basement	Inspected
<b>Pendant Mounted</b>	Does not Exist

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q085

Question	Response
<b>KITCHEN</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Pendant Mounted</b>	Does not Exist
Instance on Basement	Does not Exist
<b>Surface Mounted</b>	Inspected
Instance on Basement	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Does not Exist
Instance on Basement	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on Basement	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Basement	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Basement	Does not Exist
<b>LIBRARY</b>	Does not Exist
<b>LOCKER ROOM</b>	Does not Exist
<b>MULTIPURPOSE ROOM</b>	Does not Exist
<b>SCIENCE DEMO ROOM</b>	Does not Exist
<b>SCIENCE LAB</b>	Does not Exist
<b>SCIENCE PREP ROOM</b>	Does not Exist
<b>SWIMMING POOL</b>	Does not Exist
<b>TOILET ROOM - STAFF</b>	Inspected
<b>Lighting</b>	Inspected
<b>Lighting Fixture - Fluorescent</b>	Inspected
<b>Pendant Mounted</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Does not Exist
<b>Lighting Fixture - HID</b>	Does not Exist
<b>Lighting Fixture - Incandescent</b>	Inspected
<b>Pendant Mounted</b>	Does not Exist
<b>Surface Mounted</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Does not Exist
<b>Lighting Fixture - LED</b>	Does not Exist
<b>TOILET ROOM - STUDENT</b>	Inspected
<b>Lighting</b>	Inspected
<b>Lighting Fixture - Fluorescent</b>	Inspected
<b>Pendant Mounted</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

**Q085**

<b>Question</b>	<b>Response</b>
<b>TOILET ROOM - STUDENT</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	Inspected
<b>Surface Mounted</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Does not Exist
<b>Lighting Fixture - HID</b>	Does not Exist
<b>Lighting Fixture - Incandescent</b>	Does not Exist
<b>Lighting Fixture - LED</b>	Does not Exist
<b>AUXILIARY SIGNAL/BELL SYSTEM</b>	Inspected
Replacement Quantity	59,000
Replacement Uom	S.F.
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>EMERGENCY DC STANDBY BATTERY POWER</b>	Does not Exist
<b>EMERGENCY GENERATOR SET</b>	Does not Exist
<b>EMERGENCY LIGHT/EXIT LIGHT PANEL</b>	Inspected
Condition	3 - Fair
Deficiency	LESS THAN 20% SPARE CIRCUIT BREAKERS
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL NEW PANEL BOARD
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>EMERGENCY LIGHTING</b>	Inspected
<b>Battery Pack</b>	Inspected
Condition	3 - Fair
Deficiency	BATTERY NOT OPERATIONAL
Deficiency Location/Instance	Boiler Room, Exit 4 Vestibule, Stair A at Basement, Cafeteria, Stair B at 1st Floor, Corridor by Room 253
Deficiency Quantity	8
Quantity Uom	EACH
Potential Action	REPLACE BATTERY
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Non Battery Pack</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>EXIT LIGHT</b>	Inspected
<b>Battery Pack</b>	Inspected
Condition	3 - Fair
Deficiency	FIXTURE NOT OPERATIONAL

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q085

Question	Response
<b>EXIT LIGHT</b>	
<b>Battery Pack</b>	
Deficiency Location/Instance	Cafeteria, Gymnasium, Basement at (Staircases (A, B, C, D), Exits (2, 6) vestibules), Corridor by Rooms (101, 102, 104, 107, 109, 112, 201, 202, 204, 211, 212, 254, 301, 302, 304, 309, 311, 312, 351, 358), Boiler Room
Deficiency Quantity	39
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo	No photo recorded
Violations	No violations recorded.
<b>Non Battery Pack</b>	
	Does not Exist
<b>EXIT/EMERGENCY LIGHT</b>	
	Does not Exist
<b>FIRE ALARM SYSTEM</b>	
	Inspected
Replacement Quantity	59,000
Replacement Uom	S.F.
<b>Bell/Horn</b>	
	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Strobe</b>	
	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Manual Pull Station</b>	
	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Fan Shutdown Control</b>	
	Does not Exist
<b>Duct Smoke Detector</b>	
	Does not Exist
<b>Area Smoke Detector</b>	
	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>CO Detector</b>	
	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Heat Detector</b>	
	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Elevator Recall</b>	
	Does not Exist
<b>Magnetic Door Holder/Contactor</b>	
	Does not Exist
<b>Fused Cutout Panel</b>	
	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Fire Alarm Digital Communicator</b>	
	Does not Exist
<b>Main Panel</b>	
	Inspected
<b>Bell At Panel</b>	
	Does not Exist
<b>Fire Alarm Control Panel (Electronic)</b>	
	Inspected
Instance	Cafeteria
Instance Condition	2 - Between Good and Fair
Instance Quantity	1



**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q085

Question	Response
<b>FIRE ALARM SYSTEM</b>	
<b>Main Panel</b>	
<b>Fire Alarm Control Panel (Electronic)</b>	
Instance Quantity Uom	EACH
Instance Manufacturer	Siemens
Equipment	Fire Alarm Control Panel
Model	FireFinder
Installation Year	2017
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>Fire Alarm Control Panel (Standard)</b>	Does not Exist
<b>Sub-Panel</b>	Does not Exist
<b>Remote Annunciator</b>	Inspected
<b>Display Monitor</b>	Does not Exist
<b>Panel</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Printer</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Punch Register</b>	Does not Exist
<b>Sprinkler Flow/Air Pressure Switch</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Tamper Flow Switch/Chain</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>GROUNDING SYSTEM</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>INTERCOM SYSTEM</b>	Does not Exist
<b>LAN</b>	Inspected
<b>Local Distribution Frame (I/LDF)</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Main Equipment Rack (MDF)</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>LIGHTNING PROTECTION</b>	Does not Exist
<b>MOTOR CONTROLLER</b>	Inspected
<b>Motor Control Center</b>	Does not Exist
<b>Motor Starter/Contactor</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Variable Frequency Drive</b>	Does not Exist
<b>PANEL BOARD</b>	Inspected
<b>Fused Disconnect Switch Type</b>	Does not Exist
<b>Fused Knife Switch Type</b>	Does not Exist
<b>Fused Toggle Switch Type</b>	Does not Exist

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

**Q085**

<b>Question</b>	<b>Response</b>
<b>PANEL BOARD</b>	
<b>Molded Case Circuit Breaker Type</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	NO SPARE
Deficiency Location/Instance	Corridor by Room 203
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL NEW PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>PUBLIC ADDRESS SYSTEM</b>	
	Inspected
Replacement Quantity	59,000
Replacement Uom	S.F.
Instance	General Office
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Rauland Telecenter
Installation Year	2000
Source of Installation	Inspector Estimate
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Corridor by Rooms (212, 312)
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>SECURITY</b>	
	Inspected
<b>IPDVS/CCTV System</b>	
	Inspected
Replacement Quantity	59,000
Replacement Uom	S.F.
Installation Year	2019
Source of Installation	Custodial Staff
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Intrusion Alarm System</b>	
	Inspected
Replacement Quantity	59,000
Replacement Uom	S.F.
<b>Central Control Panel</b>	
	Inspected
Instance	Custodian's Office
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista-128B
Installation Year	2000

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q085

Question	Response
<b>SECURITY</b>	
<b>Intrusion Alarm System</b>	
<b>Central Control Panel</b>	Inspected
Source of Installation	Inspector Estimate
Deficiency	No deficiencies recorded
<b>Infrared Sensor</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Panic Switch</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Remote Annunciator</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Siren/Strobe</b>	Inspected
Condition	3 - Fair
Deficiency	SIREN/STROBE NOT ACTIVE
Deficiency Location/Instance	Cafeteria
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Lighting - Security</b>	Inspected
Replacement Uom	EACH
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>SERVICE SWITCH</b>	
	Inspected
Instance	Electrical Room
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Siemens
Equipment	MDB1 SERVICE SWITCH 2
Capacity/Size Quantity	800
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2017
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Siemens
Equipment	MDP2 SERVICE SWITCH 4
Capacity/Size Quantity	800
Capacity/Size UOM	Amps

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q085

Question	Response
<b>SERVICE SWITCH</b>	
Source of Capacity/Size	Nameplate
Installation Year	2017
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Siemens
Equipment	LPEM SERVICE SWITCH 1
Capacity/Size Quantity	100
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2017
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>SWITCHBOARD</b>	Inspected
Number of Spares	7
<b>Fused Disconnect Switch Type</b>	Inspected
Instance	Boiler Room
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Siemens
Equipment	SWITCHBOARD MDP-1
Capacity/Size Quantity	800
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	2
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Nameplate
Installation Year	2009
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Siemens
Equipment	N/A
Capacity/Size Quantity	800
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	1
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Nameplate
Installation Year	2017
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>Fused Knife Switch Type</b>	Does not Exist

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q085

<b>Question</b>	<b>Response</b>
<b>SWITCHBOARD</b>	Inspected
<b>Molded Case Circuit Breaker Type</b>	Does not Exist
<b>TELEPHONE SYSTEM</b>	Inspected
<b>PBX/Intercom</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Standard</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>TRANSFORMER</b>	Does not Exist