#### **Building Condition Assessment Survey 2023 - 2024**

### Electrical Inspection

Q094
------

#### Asset: P.S. 94 - QUEENS, 41-77 LITTLE NECK PKWY, New York, 11363

Inspection Id Inspection	Туре				Time In	Last Edited
EE : Q094 Electrical					2024-03-12 12:07 PM	2024-06-21 3:58 PM
Asset Data						
Question				Answer		
Type of Service				Below Gro	und	
Does Interactive Whiteboard (	IWB) Exist?			Yes		
Water Penetration in Electrical	Room?			No		
Have any Systems/Major Build	ding Components	been upgraded?		Yes		
				Systems:	Public Address System (Ampl Security Lights, Security Ligh Lighting, Partial Exit Lights (I	ts, Retrofitted LED
				Years:	2024	
				Systems:	LAN	
				Years:	2022	
				Systems:	Computer Lab (Raceway With	Receptacles)
				Years:	2019	
				Systems:	Telephone System	
				Years:	2018	
				Systems:	Most Emergency Lighting (Ba	ttery Pack), Security Light
				Years:	2014	-
				Systems:	Auditorium (Local Sound Syst	tem)
				Years:	2011	
				Systems:	Gymnasium (Local Sound Sys	tem)
				Years:	2007	
				Systems:	Public Address System	
				Years:	1998	
				Systems:	Partial Molded Case Circuit B	reaker Type Panel Board
				Years:	1995, 1990, 2000, 2008, 2019	
				Systems:	Emergency Light/Exit Light P Switch Type Panel Board	anel, Fused Disconnect
				Years:	1993	
DEDICATED INTERCOMS	S IN FIRE RESC	UE AREAS				
Question				Response		
Are there any Life Rescue Ass and/or Holding Rooms in you		re Rescue Areas,		No		
Priority Condition						
Priority Priority Condition Exist Category Last Year?	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title Status	PhotoImage
No condition recorded						
nspection						
Question				Respons	5e	
Electrical						
AUDITORIUM				Inspected	d	
Instance on 1st Floor				Inaccess	ible	
CAFETERIA				Inspected	d	
Instance on Baseme	nt			Inspected		
Lighting				Inspected	d	
Instance on Baseme	nt			Inspected		
				.1		
Lighting Fixture - Fluor	escent					
Lighting Fixture - Fluor Instance on Baseme				Does not	Exist	

#### **Building Condition Assessment Survey 2023 - 2024**

uestion	Response	
	Response	
CAFETERIA		
Lighting		
Lighting Fixture - HID		
Instance on Basement	Does not Exist	
Lighting Fixture - Incandescent		
Instance on Basement	Does not Exist	
Lighting Fixture - LED		
Instance on Basement	Inspected	
Pendant Mounted	Inspected	
Instance on Basement	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Instance on Basement	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not Exist	
Instance on Basement	Does not Exist	
Local Sound System	Inspected	
Instance on Basement	Inspected	
Installation Year	1998	
Source of Installation	Inspector Estimate	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Projection System	Does not Exist	
Instance on Basement	Does not Exist	
Theater Lighting System	Does not Exist	
Instance on Basement	Does not Exist	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE		
	Inspected	
Lighting	Inspected	
Does a Chandelier exist?	No	
Lighting Fixture - Fluorescent	Does not Exist	
Lighting Fixture - HID	Does not Exist	
Lighting Fixture - Incandescent	Does not Exist	
Lighting Fixture - LED	Inspected	
Pendant Mounted	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not Exist	
COMPUTER LAB	Inspected	
Instance on Room 203	Inspected	
Power Panel	Yes	
Lighting	Inspected	
Instance on Room 203	Inspected	

Instance on Room 203

Does not Exist

_	ition Assessment Survey 2023 - 2024	00
ctrical Inspection	P	Qu
Question	Response	
COMPUTER LAB		
Lighting		
Lighting Fixture - HID		
Instance on Room 203	Does not Exist	
Lighting Fixture - Incandescent		
Instance on Room 203	Does not Exist	
Lighting Fixture - LED		
Instance on Room 203	Inspected	
Pendant Mounted	Inspected	
Instance on Room 203	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Does not Exist	
Instance on Room 203	Does not Exist	
Recessed Mounted	Does not Exist	
Instance on Room 203	Does not Exist	
Raceway With Receptacles	Inspected	
Instance on Room 203	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
GYMNASIUM	Inspected	
Instance on Basement	Inspected	
Lighting	Inspected	
Instance on Basement	Inspected	
Lighting Fixture - Fluorescent		
Instance on Basement	Does not Exist	
Lighting Fixture - HID		
Instance on Basement	Does not Exist	
Lighting Fixture - Incandescent		
Instance on Basement	Does not Exist	
Lighting Fixture - LED		
Instance on Basement	Inspected	
Pendant Mounted	Does not Exist	
Instance on Basement	Does not Exist	
Surface Mounted	Inspected	
Instance on Basement	Inspected	
	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not Exist	
Instance on Basement	Does not Exist	
Local Sound System	Inspected	
Instance on Basement Installation Year	Inspected 2007	
Source of Installation	Custodial Staff	
Condition	3 - Fair	
Deficiency Projection System	No deficiencies recorded	
Projection System	Does not Exist	
Instance on Basement	Does not Exist	

uestion	Response	
GYMNASIUM	Inspected	
Scoreboard	Does not Exist	
Instance on Basement	Does not Exist	
Theater Lighting System	Does not Exist	
Instance on Basement	Does not Exist	
KITCHEN	Inspected	
Instance on Basement	Inspected	
Lighting	Inspected	
Instance on Basement	Inspected	
Lighting Fixture - Fluorescent		
Instance on Basement	Does not Exist	
Lighting Fixture - HID		
Instance on Basement	Does not Exist	
Lighting Fixture - Incandescent		
Instance on Basement	Does not Exist	
Lighting Fixture - LED		
Instance on Basement	Inspected	
Pendant Mounted	Does not Exist	
Instance on Basement	Does not Exist	
Surface Mounted	Does not Exist	
Instance on Basement	Does not Exist	
Recessed Mounted	Inspected	
Instance on Basement	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
LIBRARY	Does not Exist	
LOCKER ROOM	Does not Exist	
MULTIPURPOSE ROOM	Inspected	
Instance on Basement	Inspected	
Lighting	Inspected	
Instance on Basement	Inspected	
Lighting Fixture - Fluorescent	*	
Instance on Basement	Does not Exist	
Lighting Fixture - HID		
Instance on Basement	Does not Exist	
Lighting Fixture - Incandescent		
Instance on Basement	Does not Exist	
Lighting Fixture - LED		
Instance on Basement	Inspected	
Pendant Mounted	Inspected	
Instance on Basement	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Instance on Basement	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not Exist	

uestion	Response	
MULTIPURPOSE ROOM		
Local Sound System	Does not Exist	
Instance on Basement	Does not Exist	
Projection System	Does not Exist	
Instance on Basement	Does not Exist	
Theater Lighting System	Does not Exist	
Instance on Basement	Does not Exist	
SCIENCE DEMO ROOM	Does not Exist	
SCIENCE LAB	Does not Exist	
SCIENCE PREP ROOM	Does not Exist	
SWIMMING POOL	Does not Exist	
TOILET ROOM - STAFF	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Does not Exist	
Lighting Fixture - HID	Does not Exist	
Lighting Fixture - Incandescent	Does not Exist	
Lighting Fixture - LED	Inspected	
Pendant Mounted	Inspected	
	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not Exist	
TOILET ROOM - STUDENT	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Does not Exist	
Lighting Fixture - HID	Does not Exist	
Lighting Fixture - Incandescent	Does not Exist	
Lighting Fixture - LED	Inspected	
Pendant Mounted	Inspected	
	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not Exist	
AUXILIARY SIGNAL/BELL SYSTEM	Inspected	
Replacement Quantity	38,000	
Replacement Uom	S.F.	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
EMERGENCY DC STANDBY BATTERY POWER	Does not Exist	
EMERGENCY GENERATOR SET	Does not Exist	
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected	
	3 - Fair	
Deficiency	No deficiencies recorded	

#### **Building Condition Assessment Survey 2023 - 2024**

Q094

lestion	Response
EMERGENCY LIGHTING	
Battery Pack	Inspected
Condition	2 - Between Good and Fair
Deficiency	BATTERY NOT OPERATIONAL
Deficiency Location/Instance	Cafeteria, Main Entrance Lobby, Multipurpose Room, Boiler Room Exit 4 Vestibule, Auditorium
Deficiency Quantity	9
Quantity Uom	EACH
Potential Action	REPLACE BATTERY
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 4
Deficiency Photo1	No photo recorded
Violations	2023-ENFORC-014428-VIOR
Non Battery Pack	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Does not Exist
EXIT/EMERGENCY LIGHT	Does not Exist
FIRE ALARM SYSTEM	Inspected
Replacement Quantity	38,000
Replacement Uom	S.F.
Bell/Horn	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Strobe	Does not Exist
Manual Pull Station	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Does not Exist
Duct Smoke Detector	Does not Exist
Area Smoke Detector	Does not Exist
CO Detector	Does not Exist
Heat Detector	Does not Exist
Elevator Recall	Does not Exist
Magnetic Door Holder/Contactor	Does not Exist
Fused Cutout Panel	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Does not Exist
Main Panel	Inspected
Bell At Panel	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Does not Exist
Fire Alarm Control Panel (Standard)	Inspected

**Electrical Inspection** 

uestion	Response
FIRE ALARM SYSTEM	
Main Panel	
Fire Alarm Control Panel (Standard)	
Instance	Boiler Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	ACME
Equipment	Fire Alarm
Installation Year	1970
Source of Installation	Inspector Estimate
Deficiency	No deficiencies recorded
Sub-Panel	Does not Exist
Remote Annunciator	Does not Exist
Sprinkler Flow/Air Pressure Switch	Does not Exist
Tamper Flow Switch/Chain	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Does not Exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not Exist
MOTOR CONTROLLER	Inspected
Motor Control Center	Does not Exist
Motor Starter/Contactor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Does not Exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not Exist
Fused Toggle Switch Type	Inspected
Condition	3 - Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Custodian's Office
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1

uestion	Response
PANEL BOARD	response
Fused Toggle Switch Type	Inspected
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Molded Case Circuit Breaker Type Condition	Inspected 3 - Fair
	NO SPARE
Deficiency	
Deficiency Location/Instance	Gymnasium Fan Room
Deficiency Quantity	
Quantity Uom	EACH
Potential Action	INSTALL NEW PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1 Violations	No photo recorded No violations recorded.
Deficiency	NO SPARE
Deficiency Location/Instance	Cafeteria, Gymnasium
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Kitchen, Boiler Room, Custodian's Office, Corridor by Rooms (1 161, 206, 208)
Deficiency Quantity	8
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
PUBLIC ADDRESS SYSTEM	Inspected
Replacement Quantity	38,000
Replacement Uom	S.F.
Instance	General Office
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	BOGEN NYQUIST
Installation Year	1998
Source of Installation	Inspector Estimate
Deficiency	No deficiencies recorded
SECURITY	Inspected
IPDVS/CCTV System	Does not Exist
Intrusion Alarm System	Inspected

uestion	Response	
SECURITY		
Intrusion Alarm System		
Replacement Quantity	38,000	
Replacement Uom	S.F.	
Central Control Panel	Inspected	
Instance	Custodian's Office	
Instance Condition	3 - Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Model	N/A	
Installation Year	1996	
Source of Installation	Inspector Estimate	
Deficiency	No deficiencies recorded	
Infrared Sensor	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Panic Switch	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Remote Annunciator	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Siren/Strobe	Inspected	
Condition	3 - Fair	
Deficiency	SIREN/STROBE NOT ACTIVE	
Deficiency Location/Instance	Corridor by Room 204	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 4	
Purpose of Action	LEVEL 3	
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
Lighting - Security	Inspected	
Replacement Uom	EACH	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
SERVICE SWITCH	Inspected	
Instance	Custodian's Office	
Instance Condition	3 - Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Instance Manufacturer	I.T.E.	
Equipment	N/A	
Capacity/Size Quantity	800	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	1970	

## **Building Condition Assessment Survey 2023 - 2024**

Dunuing Conu	ntion Assessment Survey 2023 - 2024
ctrical Inspection	
Question	Response
SERVICE SWITCH	Inspected
Deficiency	No deficiencies recorded
SWITCHBOARD	Inspected
Number of Spares	4
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room (Inside Electrical Room)
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	I.T.E. Imperial Corp.
Equipment	MDP
Capacity/Size Quantity	1,000
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	2
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Nameplate
Installation Year	1970
Source of Installation	Inspector Estimate
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Does not Exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
TRANSFORMER	Does not Exist

TRANSFORMER

Does not Exist