# **Building Condition Assessment Survey 2023 - 2024**

Inspection Id	Inspection	Type				Time In	Last Edited
EE: Q132	Electrical					2023-11-16 7:44 AM	2024-06-14 9:31 A
et Data							
Question					Answer		
Type of Service					Below Grou	ınd	
Does Interactive V	Vhiteboard (I	IWB) Exist?			Yes		
Water Penetration	in Electrical	Room?			No		
Have any Systems	/Major Build	ding Components	been upgraded?		Yes		
					Systems:	LAN, Kitchen	
					Years:	2023	
					Systems:	Auditorium (Projection System) 319, Fire Alarm System (Sprink Switch)	
					Years:	2022	
					Systems:	IPDVS/CCTV System, Intrusion Sensor, Partial Remote Annunci	
					Years:	2020	
					Systems:	Intrusion Alarm System (Centra	l Control Panel)
					Years:	2017	
					Systems:	Interior Lighting, Exit Lights (B Emergency Lighting (Non Batte Light	
					Years:	2016	
					Systems:	Telephone System	
					Years:	2013	
					Systems:	Service Switch, Switchboard	
					Years:	2012	
				Systems:	Auditorium (Local Sound Syste	m)	
					Years:	2011	
					Systems: Years:	Intrusion Alarm System 2009	
					Systems:	Security Lights	
					Years:	2007	
					Systems:	Local Sound System	
					Years:	2005	
					Systems:	Public Address System	
					Years:	2002	
					Systems:	Fire Alarm System	
					Years:	1998	
					Systems:	Molded Case Circuit Breaker Ty	pe Panel Board
					Years:	1997, 2012, 2023	
					Systems:	Emergency Light/Exit Light Par	nel
					Years:	1992	
DEDICATED IN	TERCOMS	IN FIRE RESC	UE AREAS				
Question					Response		
Are there any Life	ooms in you	r building?			Yes		
during a fire?		vailable in all of the	hese spaces for use rcoms?		No Room 315		
ority Condition		IIIIIII IIII					
	ority	Condition	Component	Location	Person(s)	Person(s) Title Status	PhotoImage
ondition Exist Cat ast Year?		<b>Description</b>	Affected	<b>Description</b>	Notified	reison(s) rice Status	т полоннаде

#### **Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection Q132

No Emergency N/A EMERGENCY Cafeteria by Jose Rivera Fireman Sent to DSF Lighting - LIGHTING | (Exit 2, Exit 3 &

Battery Not Battery Pack 4, Exit 5 & 6),
Operational Gymnasium,
Electrical Room

No Fire Alarm N/A FIRE ALARM Main Entrance Jose Rivera Fireman Sent to DSF System - SYSTEM | Main Lobby

Defective Panel | Fire Alarm Control Panel (Electronic)

Inspection Question Response Electrical **AUDITORIUM** Inspected Instance on 1st Floor Inspected **House Lighting** Inspected Does a Chandelier exist? No Instance on 1st Floor Inspected **Lighting Fixture - Fluorescent** Instance on 1st Floor Inspected **Pendant Mounted** Does not Exist Instance on 1st Floor Does not Exist **Surface Mounted** Inspected Instance on 1st Floor Inspected Condition 2 - Between Good and Fair Deficiency No deficiencies recorded Recessed Mounted Does not Exist Does not Exist Instance on 1st Floor **Lighting Fixture - HID** Instance on 1st Floor Does not Exist **Lighting Fixture - Incandescent** Instance on 1st Floor Does not Exist **Lighting Fixture - LED** Instance on 1st Floor Inspected **Pendant Mounted** Inspected Instance on 1st Floor Inspected Condition 2 - Between Good and Fair No deficiencies recorded Deficiency **Surface Mounted** Inspected Instance on 1st Floor Inspected Condition 2 - Between Good and Fair No deficiencies recorded Deficiency Recessed Mounted Does not Exist Instance on 1st Floor Does not Exist **Local Sound System** Inspected Instance on 1st Floor Inspected 2011 Installation Year Source of Installation Custodial Staff Condition 3 - Fair Deficiency No deficiencies recorded **Projection System** Inspected

Print Date: 6/25/2024

# **Building Condition Assessment Survey 2023 - 2024**

icai inspection	
estion	Response
UDITORIUM	
Projection System	
Is the projector on a cart or installed on the ceiling?	Ceiling
Instance on 1st Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Theater Lighting System	Inspected
Instance on 1st Floor	Inspected
Dimming System	
Instance on 1st Floor	Does not Exist
Theater Lighting	
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	24
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
AFETERIA	Inspected
Instance on 1st Floor	Inspected
Lighting	Inspected
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor	Inspected
Pendant Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Surface Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Local Sound System	Inspected
Instance on 1st Floor	Inspected
Installation Year	2005
Source of Installation	Custodial Staff
Condition	3 - Fair
Deficiency	No deficiencies recorded
Projection System	Does not Exist
Instance on 1st Floor	Does not Exist

# **Building Condition Assessment Survey 2023 - 2024**

	QIS
Response	
Inspected	
Does not Exist	
Does not Exist	
Inspected	
Inspected	
No	
Inspected	
Inspected	
2 - Between Good and Fair	
No deficiencies recorded	
Inspected	
2 - Between Good and Fair	
No deficiencies recorded	
Inspected	
2 - Between Good and Fair	
No deficiencies recorded	
Does not Exist	
Does not Exist	
Inspected	
Inspected	
1 - Good	
No deficiencies recorded	
Does not Exist	
Does not Exist	
Does not Exist	
Inspected	
Inspected	
*	
-	
Does not Exist	
Does not Exist	
Does not Exist	
2 000 100 21100	
Inspected	
Inspected	
	Inspected Does not Exist Does not Exist Inspected 2 - Between Good and Fair No deficiencies recorded Inspected 2 - Between Good and Fair No deficiencies recorded Inspected 2 - Between Good and Fair No deficiencies recorded Does not Exist Does not Exist Inspected Inspected I - Good No deficiencies recorded Does not Exist Does not Exist Inspected Does not Exist Inspected Does not Exist Inspected Inspected Inspected Inspected Does not Exist Inspected

#### **Building Condition Assessment Survey 2023 - 2024**

Question	Response
GYMNASIUM	
Lighting	
Lighting Fixture - LED	
Surface Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Instance on 3rd Floor	Does not Exist
Local Sound System	Inspected
Instance on 3rd Floor	Inspected
Installation Year	2005
Source of Installation	Custodial Staff
Condition	3 - Fair
Deficiency	No deficiencies recorded
Projection System	Does not Exist
Instance on 3rd Floor	Does not Exist
Scoreboard	Does not Exist
Instance on 3rd Floor	Does not Exist
Theater Lighting System	Does not Exist
Instance on 3rd Floor	Does not Exist
KITCHEN	Inspected
Instance on 1st Floor	Inspected
Lighting	Inspected
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor	Inspected
Pendant Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Surface Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Recessed Mounted	
Instance on 1st Floor	Inspected
Condition	Inspected 1 - Good
Deficiency	No deficiencies recorded
LIBRARY	Inspected
Instance on Room 209	Inspected
Lighting Instance on Room 209	Inspected
	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 209	Inspected
Pendant Mounted	Inspected
Instance on Room 209	Inspected
Condition	2 - Between Good and Fair

#### **Building Condition Assessment Survey 2023 - 2024**

arear inspection	4
uestion	Response
LIBRARY	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	Inspected
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Instance on Room 209	Does not Exist
Recessed Mounted	Does not Exist
Instance on Room 209	Does not Exist
Lighting Fixture - HID	
Instance on Room 209	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 209	Does not Exist
Lighting Fixture - LED	
Instance on Room 209	Does not Exist
Raceway With Receptacles	Does not Exist
Instance on Room 209	Does not Exist
Projection System	Does not Exist
Instance on Room 209	Does not Exist
LOCKER ROOM	Does not Exist
MULTIPURPOSE ROOM	Does not Exist
SCIENCE DEMO ROOM	Does not Exist
SCIENCE LAB	Does not Exist
SCIENCE PREP ROOM	Does not Exist
SWIMMING POOL	Does not Exist
TOILET ROOM - STAFF	
	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
	D
Recessed Mounted	Does not Exist
Recessed Mounted Lighting Fixture - HID	Does not Exist  Does not Exist

# **Building Condition Assessment Survey 2023 - 2024**

Question	Response
TOILET ROOM - STUDENT	Inspected
Lighting	
Lighting Fixture - LED	Does not Exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Replacement Quantity	51,000
Replacement Uom	S.F.
Condition	3 - Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not Exist
EMERGENCY GENERATOR SET	Does not Exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	3 - Fair
Deficiency	LESS THAN 20% SPARE CIRCUIT BREAKERS
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL NEW PANEL BOARD
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	3 - Fair
Deficiency	BATTERY NOT OPERATIONAL
Deficiency Location/Instance	Cafeteria by (Exit 2, Exit 3 & 4, Exit 5 & 6), Gymnasium, Electrical Room
Deficiency Quantity	8
Quantity Uom	EACH
Potential Action	REPLACE BATTERY
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	No photo recorded
Violations	35644480J
Non Battery Pack	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Does not Exist
EXIT/EMERGENCY LIGHT	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
FIRE ALARM SYSTEM	Inspected
Replacement Quantity	51,000
Replacement Uom	S.F.
Bell/Horn	Inspected
Bell/Horn Condition	Inspected 3 - Fair

# **Building Condition Assessment Survey 2023 - 2024**

icai inspection		ν.
stion	Response	
IRE ALARM SYSTEM		
Bell/Horn	Inspected	
Deficiency	No deficiencies recorded	
Strobe	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Manual Pull Station	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Fan Shutdown Control	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Duct Smoke Detector	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Area Smoke Detector	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
CO Detector	Does not Exist	
Heat Detector	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Elevator Recall	Does not Exist	
Magnetic Door Holder/Contactor	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Fused Cutout Panel	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Digital Communicator	Does not Exist	
Main Panel	Inspected	
Bell At Panel	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Main Entrance Lobby	
Instance Condition	4 - Between Fair and Poor	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Instance Quantity Conf		
	Edwards System Technology	
Equipment	Fire Alarm Control Panel	
Model	EST	
Installation Year	1998	
Source of Installation	Documented	
Deficiency	PANEL DEFECTIVE	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action Urgency of Action	REPAIR PRIORITY 5	

#### **Building Condition Assessment Survey 2023 - 2024**

trical hispection	2
uestion	Response
FIRE ALARM SYSTEM	
Main Panel	Inspected
Fire Alarm Control Panel (Electronic)	Inspected
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Fire Alarm Control Panel (Standard)	Does not Exist
Sub-Panel	Does not Exist
Remote Annunciator	Inspected
Display Monitor	Does not Exist
Panel	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Printer	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Punch Register	Does not Exist
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Tamper Flow Switch/Chain	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Does not Exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not Exist
MOTOR CONTROLLER	Inspected
Motor Control Center	Does not Exist
Motor Starter/Contactor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Does not Exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Does not Exist
Fused Knife Switch Type	Does not Exist
Fused Toggle Switch Type	Inspected
Condition	3 - Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
,	EACH

# **Building Condition Assessment Survey 2023 - 2024**

•		
nestion	Response	
PANEL BOARD		
Fused Toggle Switch Type		
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
Molded Case Circuit Breaker Type	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	PANEL BOARD DOOR LOCK IS MISSING	
Deficiency Location/Instance	Boiler Room	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 2	
Purpose of Action	LEVEL 2	
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
PUBLIC ADDRESS SYSTEM	Inspected	
Replacement Quantity	51,000	
Replacement Uom	S.F.	
Instance	Principal's Office - 2nd Floor	
Instance Condition	3 - Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Model	Rauland Telecenter	
Installation Year	2002	
Source of Installation	Inspector Estimate	
Deficiency	CLOCK NOT OPERATIONAL	
Deficiency Location/Instance	Kitchen, Corridor by Room 101	
Deficiency Quantity	2	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
ECURITY	Inspected	
IPDVS/CCTV System	Inspected	
Replacement Quantity	51,000	
Replacement Uom	S.F.	
Installation Year	2020	
Source of Installation	Custodial Staff	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Intrusion Alarm System	Inspected	
Replacement Quantity	51,000	
Replacement Uom	S.F.	
Central Control Panel	Inspected	

# **Building Condition Assessment Survey 2023 - 2024**

Question	Response
SECURITY	
Intrusion Alarm System	
Central Control Panel	
Instance	Custodian's Office
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista-128BPT
Installation Year	2017
Source of Installation	Inspector Estimate
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Lighting - Security	Inspected
Replacement Uom	EACH
Condition	3 - Fair
Deficiency	No deficiencies recorded
SERVICE SWITCH	Inspected
Instance	Electrical Room
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Galaxy Switchgear
Equipment	Service Main
Capacity/Size Quantity	1,200
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2012
Source of Installation	Inspector Estimate
Deficiency	No deficiencies recorded
SWITCHBOARD	Inspected
Number of Spares	1
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Galaxy Switchgear
Equipment	MDP
Capacity/Size Quantity	1,200
	,

# **Building Condition Assessment Survey 2023 - 2024**

uestion	Response
SWITCHBOARD	
Fused Disconnect Switch Type	
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	2
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Service Switch Size
Installation Year	2012
Source of Installation	Inspector Estimate
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Does not Exist
FELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
TRANSFORMER	Does not Exist