

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Architectural Inspection

Q142

Asset: P.S. 752 (OLD J142) - QUEENS, 142-10 LINDEN BLVD, New York, 11436

| Inspection Id | Inspection Type | Time In | Last Edited |
|---------------|---------------------------|--------------------|--------------------|
| SA : Q142 | Architectural - Senior | 2024-01-16 7:34 AM | 2024-04-17 4:25 PM |
| AA : Q142 | Architectural - Associate | 2024-01-16 8:30 AM | 2024-06-10 4:10 PM |

Asset Data

| Question | Answer |
|--|--|
| Was the building fully accessible for inspection | No |
| Inspection Access Comment | AW1-AW4, AW6-AW19 (sidewalk bridge, scaffolding and netting), 4th Floor Shower Room (no key), Drainage System for concrete, Drainage System for soil (construction), Student non-use asphalt (snow cover), Security Lights (scaffolding) |
| Building Square Footage | 121,000 |
| Comments on the Area (for Athletic Field, Playing Surfaces, Leased Spaces) | None |
| Comments on the Stories (Floors) plus Basements | 4+B |
| Comments on the Number of Classrooms | 47 |
| Comments on the Year Built | 1930 |
| Student Population | 326 |
| Staff Population | 140 |
| Weather | Snow |
| Principal(s) Information | |
| Principal Name | Corey Proverb |
| Organization | (M645) School for Cooperative Technical Education - Queens |
| Did you meet with this Principal? | No |
| Did this Principal provide feedback? | No |
| Principal Name | Andrew Brown |
| Organization | District 79 - The Judith S. Kaye School - Queens |
| Did you meet with this Principal? | No |
| Did this Principal provide feedback? | No |
| Principal Name | Fritzy Shannon Brown |
| Organization | (Q752) Queens Transition Center (D75) - Queens |
| Did you meet with this Principal? | No |
| Did this Principal provide feedback? | No |
| Principal Name | Sabrina Fleming |
| Organization | (K755) Adult and Continuing Education - Queens |
| Did you meet with this Principal? | Yes |
| Did this Principal provide feedback? | Yes |
| Summary of Principal's Feedback | The Principal had no comments regarding the physical condition of the building at this time. |
| Custodian | Robert Cetina |
| Fireman | Jose Ramos (Cleaner) |

Facade Photo



Corner of 143rd Street and Linden
Boulevard - Southwest view

Main Entrance Photo



Facade A - Linden Boulevard

Roof Photo



Roof 1 - Southeast view

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Architectural Inspection

Q142

Have any Systems/Major Building Components been upgraded?

Yes

Systems: Exterior Walls, Chimney, Parapets, Coping - repairs;
Roofing, Roof Drains - replacement

Year: Under Construction

Systems: Columns/Beams/Bearing Walls - repairs (partial)

Year: 2022

Systems: Roofing, Stairs/Ramps (Railing) - repairs

Year: 2021

Systems: Roofing, Windows, Exterior Guards - replacement;
Parapets, Chimney - repairs; Exterior Walls - repointing
and repairs; Areaway Gratings - replacement (partial)

Year: 2000

Have there been any Building Additions?

Yes

Comments on Building Additions

1938 (+41,000 SF)


Tandem Schools?

No

Leased Space?

No

Priority Condition

| Priority Condition Exist Last Year? | Priority Category | Condition Description | Component Affected | Location Description | Person(s) Notified | Person(s) Title | PhotoImage |
|-------------------------------------|-------------------|--|--|--------------------------------|--------------------|-----------------|--|
| Yes | Tripping Hazard | Deteriorated stair tread is a potential tripping hazard. | EXTERIOR STAIRS/RAMP S: EXTERIOR STAIRS/RAMP S | Exit 5 facing inner courtyard. | Jose Ramos | Fireman |  |

Structural Engineer Required

| Structural Condition Type | Condition Description | Component Affected | Location Description | Person(s) Notified | Person(s) Title | PhotoImage |
|---------------------------|-----------------------|--------------------|----------------------|--------------------|-----------------|------------|
| No condition recorded | | | | | | |

Programmatic Accessibility

| Programmatic Accessibility Status Question | Response |
|---|----------|
| Is the primary or secondary entrance on an accessible route? | Yes |
| Is the building a multi-story building? | Yes |
| Are all floors of the building accessible through compliant means? | Yes |
| Accessible classrooms exists on each floor? | Yes |
| Boys and Girls or Unisex accessible toilets exist on at least every other floor? | Yes |
| If the following spaces exist, are they ALL accessible? Art Room, Auditorium, Cafeteria, Computer, Gymnasiums, Library, Multipurpose Room, Science Labs | No |
| If the following spaces exist, are SOME accessible? Art Room, Auditorium, Cafeteria, Computer, Gymnasiums, Library, Multipurpose Room, Science Labs | Yes |

| Physical Breakdown Structure | Exists | Required | Complies | Deficiency | Assistive Fire Listening Alarm System | Strobe |
|------------------------------|--------|----------|----------|------------|---------------------------------------|--------|
|------------------------------|--------|----------|----------|------------|---------------------------------------|--------|

| PROGRAMMATIC ACCESSIBILITY | | | | | | |
|------------------------------|--|-----|-----|-----|--|--|
| Exterior Routes | | | | | | |
| Exterior Entrances & Exits | | | | Yes | | |
| Exterior H/C Lifts | | No | No | | | |
| Exterior Ramps and Railings | | Yes | | Yes | | |
| Interior Routes | | | | | | |
| Corridor and Lobby H/C Lifts | | No | Yes | | | |


**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q142

| Physical Breakdown Structure | Exists | Required | Complies | Deficiency | Assistive Listening System | Fire Alarm Strobe |
|--------------------------------------|-----------------------|----------|----------|---------------------|----------------------------|-------------------|
| Interior Routes | | | | | | |
| Interior Corridor Doors and Hardware | Yes | | Yes | | | |
| Interior Corridors and Lobbies | | | No | Change in Elevation | | |
| Interior Elevators | Yes | | Yes | | | |
| Interior Lobby Doors and Hardware | | | Yes | | | |
| Interior Ramps | No | | | | | |
| Rooms & Spaces | | | | | | |
| Art Rooms | Room 217 | Yes | | Yes | | |
| Auditorium | 1st Floor | Yes | | Yes | FM System | Yes |
| Cafeteria | Basement | Yes | | Yes | FM System | Yes |
| Classrooms | 1st-4th Floor | Yes | | Yes | | |
| Computer Rooms | Room 317 | Yes | | Yes | | |
| Gymnasium | 3rd Floor | Yes | | No | Not on Accessible Route | FM System |
| | 4th Floor | Yes | | Yes | | FM System |
| Library | Room 319 | Yes | | Yes | | |
| Main Office | Rooms 127A, 213, 431A | Yes | | Yes | | |
| Multi-purpose Room | | No | | | | |
| Nurse's Room | Room 226 | Yes | | Yes | | |
| Pool | | No | | | | |
| Science Lab | Rooms 401, 405 | Yes | | Yes | | |
| Toilet Rooms (Boys) | 1st-4th Floor | Yes | | Yes | | |
| Toilet Rooms (Girls) | 1st-4th Floor | Yes | | Yes | | |
| Toilet Rooms (Staff) | 1st-4th Floor | Yes | | Yes | | |

Building Template






Inspection

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q142

| Question | Response |
|--|--|
| Architectural | |
| EXTERIOR | Inspected |
| AREAWAY | Inspected |
| Instance on AW1-AW8, AW10, AW11, AW14-AW19 | Inspected |
| Instance Condition | 3 - Fair |
| Instance Quantity | 16 |
| Instance Quantity Uom | EACH |
| Deficiency | AREAWAY SLAB: CRACKS AND SPALLING |
| Roof Plan reference |  |
| Deficiency Quantity | 50 |
| Quantity Uom | S.F. |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 4 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 |  |
| Violations | Facade B - AW5 No violations recorded. |
| Deficiency | AREAWAY STAIRS: DETERIORATED TREADS/RISERS/NOSINGS |
| Roof Plan reference |  |
| Deficiency Quantity | 10 |
| Quantity Uom | S.F. |
| Potential Action | REPAIR |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q142

Question

Response

EXTERIOR

AREAWAY

Deficiency Photo1



Facade B - AW5


Violations

No violations recorded.

Deficiency

AREAWAY STAIRS: MISSING RAILINGS

Roof Plan reference



Deficiency Quantity

10

Quantity Uom

L.F.

Potential Action

REPLACE


Urgency of Action

PRIORITY 5

Purpose of Action

LEVEL 6

Deficiency Photo1



Facade B - AW5

Violations

No violations recorded.

Instance on AW9, AW12, AW13

Inaccessible

Instance Quantity

3

Instance Quantity Uom

EACH

AWNINGS AND CANOPIES

Does not Exist

CHIMNEY

Inspected

Material Type(s)

Masonry

Condition

1 - Good

Deficiency

No deficiencies recorded

COPING

Inspected

Condition

3 - Fair

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q142

Question

Response


EXTERIOR

COPING

Deficiency

TERRA COTTA: CRACKED/BROKEN PIECES

Roof Plan reference



Deficiency Quantity
Quantity Uom
Potential Action
Urgency of Action
Purpose of Action
Deficiency Photo1

30
L.F.
REPLACE-IN-KIND
PRIORITY 4
LEVEL 2



Roof 1
No violations recorded.

Violations

CORNICE

Inspected

Condition

2 - Between Good and Fair

Deficiency

No deficiencies recorded

DOORS

Inspected

DOORS AND FRAMES

Inspected


Condition

5 - Poor

Deficiency

METAL: DETERIORATED DOOR AND FRAME - MAJOR DETERIORATION

Roof Plan reference






Deficiency Quantity
Quantity Uom
Potential Action
Urgency of Action

8
EACH
REPLACE
PRIORITY 4

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection



Q142

| Question | Response |
|---------------------------|--|
| EXTERIOR | |
| DOORS | |
| DOORS AND FRAMES | |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 |  |
| | Facade A |
| Violations | No violations recorded. |
| DOOR HARDWARE | |
| Condition | Inspected |
| Deficiency | 3 - Fair |
| | No deficiencies recorded |
| LINTELS | |
| Condition | Inspected |
| Deficiency | 2 - Between Good and Fair |
| | No deficiencies recorded |
| TRANSOM/SIDE LIGHT | |
| Condition | Inspected |
| Deficiency | 3 - Fair |
| Deficiency | METAL: DENTED, MAJOR RUSTING |
| Roof Plan reference |  |
| Deficiency Quantity | 10 |
| Quantity Uom | S.F. |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 4 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 |  |
| | Facade H |
| Violations | No violations recorded. |

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection



Q142

| Question | Response |
|-------------------------|--|
| EXTERIOR | |
| EXTERIOR WALLS | Inspected |
| Material Type(s) | Masonry |
| Replacement Quantity | 40,000 |
| Replacement Uom | S.F. |
| Instance on All Facades | Under Construction |
| Instance Quantity | 40,000 |
| Instance Quantity Uom | S.F. |
| EXTERIOR SOFFITS | Does not Exist |
| LOADING DOCK | Does not Exist |
| LOUVER | Inspected |
| Condition | 3 - Fair |
| Deficiency | BROKEN/ DENTED BLADES |
| RooF Plan reference |  |
| Elevation |  |
| Deficiency Quantity | 60 |
| Quantity Uom | S.F. |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 4 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 |  |
| Violations | No violations recorded. |
| PARAPETS | Inspected |
| Material Type(s) | Masonry |

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection




Q142

| Question | Response |
|---|--|
| EXTERIOR | |
| PARAPETS | |
| Replacement Quantity | 9,000 |
| Replacement Uom | C.F. |
| Instance on All Facades | Under Construction |
| Instance Quantity | 9,000 |
| Instance Quantity Uom | C.F. |
| PLAZA DECK | Does not Exist |
| ROOF | Inspected |
| Roofing | Inspected |
| Replacement Quantity | 30,400 |
| Replacement Uom | S.F. |
| ROOF HATCH/SMOKE HATCH | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| LEADERS, GUTTERS, DOWNSPOUTS, SCUPPERS | Inspected |
| Condition | 3 - Fair |
| Deficiency | DAMAGED/MISSING |
| Roof Plan reference |  |
| Deficiency Quantity | 20 |
| Quantity Uom | L.F. |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 4 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 |  |
| Violations | Roof 1 - Bulkhead 1 No violations recorded. |
| ROOF BARRIER/FENCE | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| ROOF CAGE | Does not Exist |
| ROOFING | Inspected |

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection




Q142

| Question | Response |
|---------------------------------|--|
| EXTERIOR | |
| ROOF | |
| Roofing | |
| ROOFING | |
| Instance on Built-Up: Roofs 1-6 | Under Construction |
| Instance Photo |  |
| | Roof 1 |
| Instance Quantity | 30,000 |
| Instance Quantity Uom | S.F. |
| Instance on IRMA: Roofs 7, 8 | Under Construction |
| Instance Photo |  |
| | Roof 7 |
| Instance Quantity | 400 |
| Instance Quantity Uom | S.F. |
| ROOFING DRAINS | Under Construction |
| Specialties | Inspected |
| BULKHEAD/PENTHOUSE | Inspected |
| Condition | 3 - Fair |
| Deficiency | BULKHEAD/PENTHOUSE WALLS/INTERIOR: PLASTER CRACKS/SPALLING |
| Roof Plan reference |  |
| Deficiency Quantity | 30 |
| Quantity Uom | S.F. |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q142

| Question | Response |
|-----------------------------------|--|
| EXTERIOR | |
| ROOF | |
| Specialties | |
| BULKHEAD/PENTHOUSE | |
| Deficiency Photo1 |  |
| Violations | Roof 1 No violations recorded. |
| Deficiency | BULKHEAD/PENTHOUSE DOORS: DETERIORATED DOOR |
| Roof Plan reference |  |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE DOOR |
| Urgency of Action | PRIORITY 4 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 |  |
| Violations | Roof 1 No violations recorded. |
| CUPOLA/ SPIRES/ TOWERS | Does not Exist |
| DORMER | Does not Exist |
| DUNNAGE STEEL | Does not Exist |
| SKYLIGHT/ROOF VENT | Does not Exist |
| ROOF/GRAVITY TANK | Does not Exist |
| STAIRS/RAMPS: EXTERIOR | Inspected |
| BUILDING CHEEK/FLANK WALLS | Inspected |
| Condition | 4 - Between Fair and Poor |

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q142

Question

Response

EXTERIOR


STAIRS/RAMPS: EXTERIOR

BUILDING CHEEK/FLANK WALLS

Deficiency

Roof Plan reference

STONE: DETERIORATED JOINTS



Deficiency Quantity
Quantity Uom
Potential Action
Urgency of Action
Purpose of Action
Deficiency Photo1

20
S.F.
REPOINT
PRIORITY 4
LEVEL 2



Facade A


No violations recorded.

Violations

Deficiency

Roof Plan reference

STONE: DETERIORATED JOINTS AT COPING STONES






Deficiency Quantity
Quantity Uom
Potential Action
Urgency of Action
Purpose of Action

20
L.F.
MAINTENANCE
PRIORITY 3
LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q142

| Question | Response |
|-----------------------------------|--|
| EXTERIOR | |
| STAIRS/RAMPS: EXTERIOR | |
| BUILDING CHEEK/FLANK WALLS | |
| Deficiency Photo1 |  |
| Violations | Facade H No violations recorded. |
| RAILINGS | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| STAIRS/RAMPS | Inspected |
| Condition | 5 - Poor |
| Deficiency | STONE: CRACKS/SPALLING - MINOR |
| Roof Plan reference |  |
| Deficiency Quantity | 10 |
| Quantity Uom | S.F. |
| Potential Action | REPAIR |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 |  |
| Violations | Facade A No violations recorded. |
| Deficiency | STONE: WORN-OUT TREAD/RISER/NOSING |

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q142

Question


Response

EXTERIOR

STAIRS/RAMPS: EXTERIOR

STAIRS/RAMPS

Roof Plan reference



Deficiency Quantity
Quantity Uom
Potential Action
Urgency of Action
Purpose of Action
Deficiency Photo1

10
S.F.
REPLACE
PRIORITY 4
LEVEL 2



Facade D


No violations recorded.

Violations

Deficiency

STONE: WORN-OUT TREAD/RISER/NOSING

Roof Plan reference



Deficiency Quantity
Quantity Uom
Potential Action
Urgency of Action
Purpose of Action

10
S.F.
REPLACE
PRIORITY 5
LEVEL 6

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q142

Question


Response

EXTERIOR

STAIRS/RAMPS: EXTERIOR

STAIRS/RAMPS

Deficiency Photo1



Facade E - Exit5


Violations

No violations recorded.

Deficiency

CONCRETE: CRACKS/SPALLING - MINOR

Roof Plan reference



Deficiency Quantity

10

Quantity Uom

S.F.

Potential Action

REPAIR

Urgency of Action

PRIORITY 3

Purpose of Action

LEVEL 2

Deficiency Photo1



Facade H

Violations

No violations recorded.


Deficiency


STONE: DETERIORATED JOINTS

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q142

| Question | Response |
|---|---|
| EXTERIOR | |
| STAIRS/RAMPS: EXTERIOR | |
| STAIRS/RAMPS | |
| Roof Plan reference | |
| <p>Deficiency Quantity</p> <p>Quantity Uom</p> <p>Potential Action</p> <p>Urgency of Action</p> <p>Purpose of Action</p> <p>Deficiency Photo1</p> | <p>30</p> <p>L.F.</p> <p>REPOINT</p> <p>PRIORITY 4</p> <p>LEVEL 2</p>  |
| Violations | <p>Facade A</p> <p>No violations recorded.</p> |
| WINDOWS | Inspected |
| Replacement Quantity | 13,000 |
| Replacement Uom | S.F. |
| EXTERIOR GUARDS | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| LINTELS | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| WINDOWS | Inspected |
| Material Type(s) | Aluminum |
| Instance on Aluminum - Double Hung: All Facades | Inspected |
| Instance Condition | 4 - Between Fair and Poor |
| Instance Quantity | 13,000 |
| Instance Quantity Uom | S.F. |
| Are these windows insulated | No |
| Installation Year | 2000 |
| Source of Installation | Custodial Staff |
| Deficiency | ALUMINUM - DOUBLE HUNG: AIR/WATER INFILTRATION |



30
L.F.
REPOINT
PRIORITY 4
LEVEL 2




Facade A
No violations recorded.

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection



Q142

| Question | Response |
|------------------------------------|--|
| EXTERIOR | |
| WINDOWS | |
| WINDOWS | |
| Roof Plan reference |  |
| Elevation |  |
| Deficiency Quantity | 200 |
| Quantity Uom | L.F. |
| Potential Action | REPLACE TRIM, SILLS OR WEATHERSTRIPPING |
| Urgency of Action | PRIORITY 5 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 |  |
| Violations | Facade B - 4th Floor, also 3rd, 2nd and 1st Floor, Facade E - 3rd and 2nd Floor No violations recorded. |
| INTERIOR | Inspected |
| POOLS | Does not Exist |
| STRUCTURAL | Inspected |
| COLUMNS/BEAMS/BEARING WALLS | Inspected |
| Condition | 3 - Fair |
| Deficiency | STEEL COLUMNS/BEAMS: DETERIORATED CONCRETE FIREPROOFING |
| Deficiency Location/Instance | Basement - Storage Room, Back Room |
| Deficiency Quantity | 20 |
| Quantity Uom | S.F. |
| Potential Action | REPLACE |

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q142

| Question | Response |
|------------------------------------|--|
| INTERIOR | |
| STRUCTURAL | |
| COLUMNS/BEAMS/BEARING WALLS | |
| Urgency of Action | PRIORITY 4 |
| Purpose of Action | LEVEL 5 |
| Deficiency Photo1 |  |
| | Basement - Storage Room |
| Violations | No violations recorded. |
| FLOOR STRUCTURE | |
| | Inspected |
| Condition | 3 - Fair |
| Deficiency | CONCRETE: CRACKS/SPALLED/REINFORCEMENT EXPOSED |
| Deficiency Location/Instance | Basement - Storage Rooms, Boiler Room |
| Deficiency Quantity | 100 |
| Quantity Uom | S.F. |
| Potential Action | REPAIR |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 5 |
| Deficiency Photo1 |  |
| | Basement - Storage Room |
| Violations | No violations recorded. |
| FOUNDATION WALLS | |
| | Inspected |
| Material Type(s) | Concrete |
| Condition | 4 - Between Fair and Poor |
| Deficiency | CONCRETE: CRACKED/SPALLED/REINFORCEMENT EXPOSED |
| Deficiency Location/Instance | Basement - Back Room |
| Deficiency Quantity | 10 |
| Quantity Uom | S.F. |
| Potential Action | REPAIR |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 5 |

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q142

Question

Response

INTERIOR

STRUCTURAL

FOUNDATION WALLS

Deficiency Photo1



Basement - Back Room

Violations

No violations recorded.

Deficiency

CONCRETE: CRACKED/SPALLED/REINFORCEMENT EXPOSED

Deficiency Location/Instance

Basement - Storage Room

Deficiency Quantity

20

Quantity Uom

S.F.

Potential Action

REPAIR

Urgency of Action

PRIORITY 4

Purpose of Action

LEVEL 5

Deficiency Photo1



Basement - Storage Room

Violations

No violations recorded.

Deficiency

CONCRETE: WATER INFILTRATION IN NON- INSTRUCTIONAL SPACE

Deficiency Location/Instance

Basement - Boiler Room, Storage

Deficiency Quantity

100

Quantity Uom

S.F.

Potential Action

INSTALL WATERPROOFING


Urgency of Action

PRIORITY 5

Purpose of Action

LEVEL 5

Deficiency Photo1



Basement - Boiler Room

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Architectural Inspection

Q142

| Question | Response |
|----------|----------|
|----------|----------|

INTERIOR

STRUCTURAL

FOUNDATION WALLS

Violations

Inspected

No violations recorded.

ROOF STRUCTURE

Condition

Deficiency

Inspected

2 - Between Good and Fair

No deficiencies recorded

VAULTS-BUNKERS

Foundation Walls

Condition

Deficiency

Inspected

Inspected

2 - Between Good and Fair

No deficiencies recorded

Slab Structure

Condition

Deficiency

Deficiency Location/Instance

Deficiency Quantity

Quantity Uom

Potential Action

Urgency of Action

Purpose of Action

Deficiency Photo1

Inspected

2 - Between Good and Fair

STEEL COLUMNS/BEAMS: DETERIORATED/MISSING SPRAY-ON FIREPROOFING

Basement - Ash Hoist Vault

10

S.F.

REPLACE

PRIORITY 3

LEVEL 5



Basement - Ash Hoist Vault

Violations

No violations recorded.

Vault/Ash Hoist Doors and Framing

Condition

Deficiency

Deficiency Location/Instance

Deficiency Quantity

Quantity Uom

Potential Action

Urgency of Action

Purpose of Action

Deficiency Photo1

Inspected

5 - Poor

WATER INFILTRATION

Basement - Ash Hoist Vault


10

S.F.

REPAIR

PRIORITY 5


LEVEL 2



**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection


Q142

| Question | Response |
|--|--|
| INTERIOR | |
| STRUCTURAL | Inspected |
| VAULTS-BUNKERS | |
| Vault/Ash Hoist Doors and Framing | |
| Violations | Basement - Ash Hoist Vault No violations recorded. |
| AUDITORIUM | |
| Instance on 1st Floor (676 Seats) | Inspected |
| Ceiling | |
| Instance on 1st Floor (676 Seats) | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Door(s) | |
| Instance on 1st Floor (676 Seats) | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Fixed H/C Lift | |
| Instance on 1st Floor (676 Seats) | Does not Exist |
| Fixed Seating | |
| Instance on 1st Floor (676 Seats) | Inspected |
| Condition | 5 - Poor |
| Deficiency | DAMAGED/BROKEN/INOPERABLE |
| Deficiency Location/Instance | Seats N/2, L/1, M/1 |
| Deficiency Quantity | 3 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 5 |
| Purpose of Action | LEVEL 6 |
| Deficiency Photo1 |  |
| Violations | Seat N/2 No violations recorded. |
| Deficiency | DAMAGED/BROKEN/INOPERABLE |
| Deficiency Location/Instance | Seats A/23, 25, B/19, C/19, D/23, and others |
| Deficiency Quantity | 65 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q142

| Question | Response |
|-----------------------------------|--|
| INTERIOR | |
| AUDITORIUM | Inspected |
| Fixed Seating | |
| Deficiency Photo1 |  |
| Violations | Seat A/25 No violations recorded. |
| Floor Finish | |
| Instance on 1st Floor (676 Seats) | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | VINYL TILES: DETERIORATED SUBSTRATE |
| Deficiency Location/Instance | Stage Ramp |
| Deficiency Quantity | 20 |
| Quantity Uom | S.F. |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 |  |
| Violations | Stage Ramp No violations recorded. |
| Sliding-folding Partition | |
| Instance on 1st Floor (676 Seats) | Does not Exist |
| Stage | |
| Instance on 1st Floor (676 Seats) | Inspected |
| Stage | |
| Instance on 1st Floor (676 Seats) | Inspected |
| Condition | 3 - Fair |
| Deficiency | DAMAGED FLOOR |
| Deficiency Location/Instance | Center |
| Deficiency Quantity | 60 |
| Quantity Uom | S.F. |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection



Q142

| Question | Response |
|-----------------------------------|--|
| INTERIOR | |
| AUDITORIUM | |
| Stage | |
| Stage | |
| Deficiency Photo1 |  |
| | Center |
| Violations | No violations recorded. |
| Deficiency | DAMAGED STEPS |
| Deficiency Location/Instance | Right Side |
| Deficiency Quantity | 10 |
| Quantity Uom | S.F. |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 |  |
| | Right Side |
| Violations | No violations recorded. |
| Stage Curtain Rigging | Inspected |
| Instance on 1st Floor (676 Seats) | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Stage Curtains | Inspected |
| Instance on 1st Floor (676 Seats) | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Walls | |
| Instance on 1st Floor (676 Seats) | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | STONE: CRACKS/SPALLING |
| Deficiency Location/Instance | Near Stair G |
| Deficiency Quantity | 20 |
| Quantity Uom | S.F. |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q142

| Question | Response |
|--------------------------------------|--|
| INTERIOR | |
| AUDITORIUM | |
| Walls | |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 |  |
| | Near Stair G |
| Violations | No violations recorded. |
| Window Curtains/Shades/Blinds | |
| Instance on 1st Floor (676 Seats) | Inspected |
| Condition | 3 - Fair |
| Deficiency | WORN/DAMAGED CURTAINS |
| Deficiency Location/Instance | Rear Right, Rear Left |
| Deficiency Quantity | 100 |
| Quantity Uom | S.F. |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 |  |
| | Rear Left |
| Violations | No violations recorded. |
| CAFETERIA | |
| Instance on Basement | Inspected |
| Ceiling | Inspected |
| Instance on Basement | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Door(s) | |
| Instance on Basement | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Fixed Equipment | |
| Instance on Basement | Does not Exist |
| Floor Finish | |
| Instance on Basement | Inspected |

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection


Q142

| Question | Response |
|--------------------------------------|--|
| INTERIOR | |
| CAFETERIA | |
| Floor Finish | |
| Condition | 5 - Poor |
| Deficiency | VINYL TILES: BROKEN/DETERIORATED/MISSING TILES |
| Deficiency Location/Instance | Left Side |
| Deficiency Quantity | 50 |
| Quantity Uom | S.F. |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 |  |
| Violations | Left Side No violations recorded. |
| Deficiency | VINYL TILES: DETERIORATED SUBSTRATE |
| Deficiency Location/Instance | Center, Near Serving Area, Near Stair B |
| Deficiency Quantity | 450 |
| Quantity Uom | S.F. |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 |  |
| Violations | Center No violations recorded. |
| Sliding-folding Partition | |
| Instance on Basement | Does not Exist |
| Stage | |
| Instance on Basement | Does not Exist |
| Walls | |
| Instance on Basement | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Window Curtains/Shades/Blinds | |
| Instance on Basement | Does not Exist |

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Architectural Inspection

Q142

| Question | Response |
|--|--|
| INTERIOR | |
| CLASSROOMS/CORRIDORS/ADMIN SPACES | Inspected |
| Ceiling | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | PLASTER: CRACKS/SPALLING |
| Deficiency Location/Instance | 1st Floor Elevator Lobby, Room 404 |
| Deficiency Quantity | 90 |
| Quantity Uom | S.F. |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 |  |
| Violations | Room 404 No violations recorded. |
| Door(s) | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | WOOD: DETERIORATED DOOR |
| Deficiency Location/Instance | Room 107 |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 |  |
| Violations | Room 107 No violations recorded. |
| Floor Finish | Inspected |
| Condition | 4 - Between Fair and Poor |
| Deficiency | CONCRETE: CRACKS |
| Deficiency Location/Instance | Room 126 |
| Deficiency Quantity | 50 |
| Quantity Uom | S.F. |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q142

| Question | Response |
|--|--|
| INTERIOR | |
| CLASSROOMS/CORRIDORS/ADMIN SPACES | |
| Floor Finish | |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 |  |
| Violations | Room 126 |
| Violations | No violations recorded. |
| Deficiency | VINYL TILES: TRIPPING HAZARD - ELECTRICAL OUTLET |
| Deficiency Location/Instance | Room 203 |
| Deficiency Quantity | 10 |
| Quantity Uom | S.F. |
| Potential Action | REMOVE |
| Urgency of Action | PRIORITY 5 |
| Purpose of Action | LEVEL 6 |
| Deficiency Photo1 |  |
| Violations | Room 203 |
| Violations | No violations recorded. |
| Deficiency | VINYL TILES: BROKEN/DETERIORATED/MISSING TILES |
| Deficiency Location/Instance | Rooms 107, 203, 307, 312, 315, and others |
| Deficiency Quantity | 1,400 |
| Quantity Uom | S.F. |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 |  |
| Violations | Room 107 |

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Architectural Inspection

Q142

| Question | Response |
|--|--|
| INTERIOR | |
| CLASSROOMS/CORRIDORS/ADMIN SPACES | |
| Floor Finish | |
| Violations | No violations recorded. |
| Deficiency | VINYL TILES: DETERIORATED SUBSTRATE |
| Deficiency Location/Instance | Corridor near Rooms 120, 217, 420, Rooms 215, 317, and others |
| Deficiency Quantity | 2,500 |
| Quantity Uom | S.F. |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 |  |
| Violations | Corridor near Room 420 No violations recorded. |
| Deficiency | WOOD: DAMAGED/DETERIORATED |
| Deficiency Location/Instance | Rooms 109, 113, 419 |
| Deficiency Quantity | 80 |
| Quantity Uom | S.F. |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 |  |
| Violations | Room 109 No violations recorded. |
| Deficiency | TERRAZZO: CRACKS |
| Deficiency Location/Instance | Corridor near Rooms 101, 110, 111, 1st Floor Elevator Lobby |
| Deficiency Quantity | 140 |
| Quantity Uom | S.F. |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q142

| Question | Response |
|----------|----------|
|----------|----------|

INTERIOR

CLASSROOMS/CORRIDORS/ADMIN SPACES

Floor Finish

Deficiency Photo1



Corridor near Room 110

Violations

No violations recorded.

Walls

Inspected

Condition

2 - Between Good and Fair

Deficiency

PLASTER: CRACKS/SPALLING

Deficiency Location/Instance

Corridor near Rooms 126, 309, 315

Deficiency Quantity

30

Quantity Uom

S.F.

Potential Action

REPLACE


Urgency of Action

PRIORITY 3

Purpose of Action

LEVEL 2

Deficiency Photo1



Corridor near Room 309

Violations

No violations recorded.

Deficiency

GYP SUM BOARD: DETERIORATED

Deficiency Location/Instance

Corridor near Rooms 125, 421B

Deficiency Quantity

30

Quantity Uom

S.F.

Potential Action

REPLACE


Urgency of Action

PRIORITY 3

Purpose of Action

LEVEL 2

Deficiency Photo1



**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection



Q142

| Question | Response |
|--|--|
| INTERIOR | |
| CLASSROOMS/CORRIDORS/ADMIN SPACES | |
| Walls | |
| Violations | Corridor near Room 421B No violations recorded. |
| Deficiency | GLAZED BLOCK: CRACKS/SPALLING |
| Deficiency Location/Instance | 4th Floor Elevator Lobby |
| Deficiency Quantity | 10 |
| Quantity Uom | S.F. |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 |  |
| Violations | 4th Floor Elevator Lobby No violations recorded. |
| Deficiency | STONE: CRACKS/SPALLING |
| Deficiency Location/Instance | Corridor near Rooms 109, 117 |
| Deficiency Quantity | 40 |
| Quantity Uom | S.F. |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 |  |
| Violations | Corridor near Room 109 No violations recorded. |
| Deficiency | STONE MOLDINGS: CRACKS/SPALLING |
| Deficiency Location/Instance | Main Entrance Vestibule, Corridor near Room 110 |
| Deficiency Quantity | 20 |
| Quantity Uom | L.F. |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q142

| Question | Response |
|--|--|
| INTERIOR | |
| CLASSROOMS/CORRIDORS/ADMIN SPACES | |
| Walls | |
| Deficiency Photo1 |  |
| Violations | Main Entrance Vestibule No violations recorded. |
| Specialties | Inspected |
| Classroom Locker(s) | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | DAMAGED UNITS |
| Deficiency Location/Instance | Corridor near Rooms 325, 329, 421B |
| Deficiency Quantity | 5 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 |  |
| Violations | Corridor near Room 421B No violations recorded. |
| Fixed Seating | Does not Exist |
| GYMNASIUM | |
| Instance on 3rd Floor | Inspected |
| Instance on 4th Floor | Inspected |
| Ceiling | |
| Instance on 4th Floor | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | PLASTER: CRACKS/SPALLING |
| Deficiency Location/Instance | Left Side |
| Deficiency Quantity | 10 |
| Quantity Uom | S.F. |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q142

| Question | Response |
|------------------------------|--|
| INTERIOR | |
| GYMNASIUM | |
| Ceiling | |
| Deficiency Photo1 |  |
| Violations | Left Side No violations recorded. |
| Door(s) | |
| Instance on 3rd Floor | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Instance on 4th Floor | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Fixed Equipment | |
| Instance on 3rd Floor | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Instance on 4th Floor | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Floor Finish | |
| Instance on 3rd Floor | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | WOOD: DAMAGED/DETERIORATED |
| Deficiency Location/Instance | Near Office |
| Deficiency Quantity | 40 |
| Quantity Uom | S.F. |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 |  |
| Violations | Near Office No violations recorded. |
| Deficiency | SHEET VINYL: BROKEN/DETERIORATED |

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection


Q142

| Question | Response |
|------------------------------|--|
| INTERIOR | |
| GYMNASIUM | |
| Floor Finish | |
| Deficiency Location/Instance | Office |
| Deficiency Quantity | 15 |
| Quantity Uom | S.F. |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 |  |
| Violations | Office No violations recorded. |
| Instance on 4th Floor | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | SHEET VINYL: BROKEN/DETERIORATED |
| Deficiency Location/Instance | Office |
| Deficiency Quantity | 50 |
| Quantity Uom | S.F. |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 |  |
| Violations | Office No violations recorded. |
| Seating | |
| Instance on 3rd Floor | Inspected |
| Condition | 4 - Between Fair and Poor |
| Deficiency | DAMAGED FIXED SEATING |
| Deficiency Location/Instance | Right Side, Left Side |
| Deficiency Quantity | 2 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q142

| Question | Response |
|----------------------------------|--|
| INTERIOR | |
| GYMNASIUM | |
| Seating | |
| Deficiency Photo1 |  |
| Violations | Right Side No violations recorded. |
| Sliding-folding Partition | |
| Instance on 3rd Floor | Does not Exist |
| Instance on 4th Floor | Does not Exist |
| Stage | |
| Instance on 3rd Floor | Does not Exist |
| Instance on 4th Floor | Does not Exist |
| Walls | |
| Instance on 3rd Floor | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | SALT GLAZED BRICK: CRACKS/SPALLING |
| Deficiency Location/Instance | Right Side, Left Side |
| Deficiency Quantity | 40 |
| Quantity Uom | S.F. |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 |  |
| Violations | Right Side No violations recorded. |
| Instance on 4th Floor | Inspected |
| Condition | 3 - Fair |
| Deficiency | WALL PADDING: DETERIORATED |
| Deficiency Location/Instance | Near Office |
| Deficiency Quantity | 240 |
| Quantity Uom | S.F. |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q142

| Question | Response |
|--------------------------------------|---|
| INTERIOR | |
| GYMNASIUM | |
| Walls | |
| Deficiency Photo1 |  |
| | Near Office |
| Violations | No violations recorded. |
| Deficiency | SALT GLAZED BRICK: CRACKS/SPALLING |
| Deficiency Location/Instance | Right Side, Left Side |
| Deficiency Quantity | 20 |
| Quantity Uom | S.F. |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 |  |
| | Right Side |
| Violations | No violations recorded. |
| Window Curtains/Shades/Blinds | |
| Instance on 4th Floor | Does not Exist |
| Instance on 3rd Floor | Does not Exist |
| INTERIOR DOOR HARDWARE | |
| Condition | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| INTERIOR GUARDS | |
| Condition | Inspected |
| Condition | 3 - Fair |
| Deficiency | DETERIORATED/TORN-OUT/MISSING |
| Deficiency Location/Instance | Stairs A/3, B/4, C/Bulkhead, EF/3, Cafeteria |
| Deficiency Quantity | 60 |
| Quantity Uom | S.F. |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q142

| Question | Response |
|------------------------------|--|
| INTERIOR | |
| INTERIOR GUARDS | |
| Deficiency Photo1 |  |
| Violations | Stair C/Bulkhead No violations recorded. |
| KITCHEN | Inspected |
| Instance on Basement | Inspected |
| Ceiling | |
| Instance on Basement | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Door(s) | |
| Instance on Basement | Inspected |
| Condition | 5 - Poor |
| Deficiency | METAL: DETERIORATED DOOR AND FRAME |
| Deficiency Location/Instance | Office, Stock Room, Serving Area |
| Deficiency Quantity | 4 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 |  |
| Violations | Office No violations recorded. |
| Floor Finish | |
| Instance on Basement | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | CERAMIC TILE: DETERIORATED SUBSTRATE |
| Deficiency Location/Instance | Center |
| Deficiency Quantity | 10 |
| Quantity Uom | S.F. |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q142

Question


Response

INTERIOR

KITCHEN

Floor Finish

Deficiency Photo1



Center

Violations

No violations recorded.

Deficiency

CERAMIC TILE: BROKEN/MISSING TILES

Deficiency Location/Instance

Near Stove

Deficiency Quantity

10

Quantity Uom

S.F.

Potential Action

REPLACE


Urgency of Action

PRIORITY 3

Purpose of Action

LEVEL 2

Deficiency Photo1



Near Stove

Violations

No violations recorded.

Walls

Instance on Basement

Inspected

Condition

2 - Between Good and Fair

Deficiency

CERAMIC TILE: BROKEN/ MISSING

Deficiency Location/Instance

Near Exit to Exterior

Deficiency Quantity

10

Quantity Uom

S.F.

Potential Action

REPLACE

Urgency of Action

PRIORITY 3

Purpose of Action

LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q142

| Question | Response |
|------------------------------|---|
| INTERIOR | |
| KITCHEN | |
| Walls | |
| Deficiency Photo1 |  |
| Violations | Near Exit to Exterior No violations recorded. |
| Deficiency | PLASTER: CRACKS/SPALLING |
| Deficiency Location/Instance | Office |
| Deficiency Quantity | 10 |
| Quantity Uom | S.F. |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 |  |
| Violations | Office No violations recorded. |
| LIBRARY | Inspected |
| Instance on Room 319 | Inspected |
| Built-in Furnishing | |
| Instance on Room 319 | Does not Exist |
| Ceiling | |
| Instance on Room 319 | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Door(s) | |
| Instance on Room 319 | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Floor Finish | |
| Instance on Room 319 | Inspected |
| Condition | 4 - Between Fair and Poor |
| Deficiency | VINYL TILES: DETERIORATED SUBSTRATE |
| Deficiency Location/Instance | Near Office, Left Side, Center, Right Side, Reading Room |
| Deficiency Quantity | 100 |

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Architectural Inspection

Q142

| Question | Response |
|----------|----------|
|----------|----------|

INTERIOR

LIBRARY

Floor Finish


| | |
|-------------------|------------|
| Quantity Uom | S.F. |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | |



Left Side

| | |
|------------|-------------------------|
| Violations | No violations recorded. |
|------------|-------------------------|

| | |
|------------------------------|----------------------------|
| Deficiency | WOOD: DAMAGED/DETERIORATED |
| Deficiency Location/Instance | Office |
| Deficiency Quantity | 10 |
| Quantity Uom | S.F. |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | |



Office

| | |
|------------|-------------------------|
| Violations | No violations recorded. |
|------------|-------------------------|

Walls

| | |
|------------------------------|---------------------------|
| Instance on Room 319 | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | PLASTER: CRACKS/SPALLING |
| Deficiency Location/Instance | Office |
| Deficiency Quantity | 10 |
| Quantity Uom | S.F. |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q142

| Question | Response |
|------------------------------------|--|
| INTERIOR | |
| LIBRARY | |
| Walls | |
| Deficiency Photo1 |  |
| | Office |
| Violations | No violations recorded. |
| LOCKER ROOM | |
| | Inspected |
| Instance on 3rd Floor (50 Lockers) | Inspected |
| Alternative use | Yes |
| Instance on 4th Floor (22 Lockers) | Inspected |
| Alternative use | Yes |
| Ceiling | |
| Instance on 4th Floor (22 Lockers) | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | PLASTER: CRACKS/SPALLING |
| Deficiency Location/Instance | Right Side |
| Deficiency Quantity | 10 |
| Quantity Uom | S.F. |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 |  |
| | Right Side |
| Violations | No violations recorded. |
| Door(s) | |
| Instance on 3rd Floor (50 Lockers) | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Instance on 4th Floor (22 Lockers) | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Floor Finish | |
| Instance on 3rd Floor (50 Lockers) | Inspected |
| Condition | 2 - Between Good and Fair |

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Architectural Inspection



Q142

| Question | Response |
|------------------------------------|--|
| INTERIOR | |
| LOCKER ROOM | |
| Floor Finish | |
| Deficiency | VINYL TILES: DETERIORATED SUBSTRATE |
| Deficiency Location/Instance | Center |
| Deficiency Quantity | 15 |
| Quantity Uom | S.F. |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 |  |
| | Center |
| Violations | No violations recorded. |
| Instance on 4th Floor (22 Lockers) | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | VINYL TILES: BROKEN/DETERIORATED/MISSING TILES |
| Deficiency Location/Instance | Center |
| Deficiency Quantity | 10 |
| Quantity Uom | S.F. |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 |  |
| | Center |
| Violations | No violations recorded. |
| Locker Room Lockers | |
| Instance on 3rd Floor (50 Lockers) | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Instance on 4th Floor (22 Lockers) | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Walls | |
| Instance on 3rd Floor (50 Lockers) | Inspected |

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection


Q142

| Question | Response |
|------------------------------------|--|
| INTERIOR | |
| LOCKER ROOM | |
| Walls | |
| Condition | 2 - Between Good and Fair |
| Deficiency | PLASTER: CRACKS/SPALLING |
| Deficiency Location/Instance | Right Side |
| Deficiency Quantity | 10 |
| Quantity Uom | S.F. |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 |  |
| | Right Side |
| Violations | No violations recorded. |
| Instance on 4th Floor (22 Lockers) | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | PLASTER: CRACKS/SPALLING |
| Deficiency Location/Instance | Left Side |
| Deficiency Quantity | 10 |
| Quantity Uom | S.F. |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 |  |
| | Left Side |
| Violations | No violations recorded. |
| MULTI-PURPOSE ROOM | Does not Exist |
| SCIENCE DEMO ROOM | Does not Exist |
| SCIENCE LAB | Inspected |
| Instance on Rooms 401, 405 | Inspected |
| Alternative use | No |
| Fixed Equipment | |
| Instance on Rooms 401, 405 | Inspected |
| Condition | 2 - Between Good and Fair |

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q142

| Question | Response |
|-------------------------------|--|
| INTERIOR | |
| SCIENCE LAB | Inspected |
| Fixed Equipment | |
| Deficiency | No deficiencies recorded |
| SCIENCE PREP ROOM | Inspected |
| Instance on Room 404 | Inspected |
| Alternative use | No |
| Fixed Equipment | |
| Instance on Room 404 | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| SHOWER ROOM | Inspected |
| Instance on 4th Floor | Inaccessible |
| STAIRS/RAMPS: INTERIOR | Inspected |
| Do Letter Stair Signs Exist? | Partially |
| Ceiling | |
| Condition | 2 - Between Good and Fair |
| Deficiency | PLASTER: CRACKS/SPALLING |
| Deficiency Location/Instance | Stairs B/1 Vestibule, CD/1 Vestibule, EF/1 Vestibule |
| Deficiency Quantity | 60 |
| Quantity Uom | S.F. |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 |  |
| Violations | Stair EF/1 Vestibule No violations recorded. |
| Door(s) | |
| Condition | Inspected |
| Deficiency | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Partition | |
| Condition | Inspected |
| Condition | 3 - Fair |
| Deficiency | METAL FRAME: DAMAGED/DETERIORATED |
| Deficiency Location/Instance | Stairs A/1,2, EF/2 |
| Deficiency Quantity | 15 |
| Quantity Uom | L.F. |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q142

| Question | Response |
|----------|----------|
|----------|----------|

INTERIOR

STAIRS/RAMPS: INTERIOR

Partition

Deficiency Photo1



Stair A/2

Violations

No violations recorded.

Deficiency

METAL PANEL: DAMAGED/DETERIORATED

Deficiency Location/Instance

Stairs A/3, B/1, CD/3

Deficiency Quantity

25

Quantity Uom

S.F.

Potential Action

REPLACE

Urgency of Action

PRIORITY 3

Purpose of Action

LEVEL 2

Deficiency Photo1



Stair CD/3

Violations

No violations recorded.

Railings

Inspected

Condition

5 - Poor

Deficiency

METAL: DAMAGED

Deficiency Location/Instance

Stair EF/3

Deficiency Quantity

15

Quantity Uom

L.F.

Potential Action

REPLACE


Urgency of Action

PRIORITY 3

Purpose of Action

LEVEL 2


Deficiency Photo1



**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q142

| Question | Response |
|-------------------------------|--|
| INTERIOR | |
| STAIRS/RAMPS: INTERIOR | |
| Railings | |
| Violations | Stair EF/3 No violations recorded. |
| Deficiency | METAL: MISSING |
| Deficiency Location/Instance | Stairs B/2, C/Bulkhead |
| Deficiency Quantity | 30 |
| Quantity Uom | L.F. |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 5 |
| Purpose of Action | LEVEL 6 |
| Deficiency Photo1 |  |
| Violations | Stair B/2 No violations recorded. |
| Stairs and Landings | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | CONCRETE: CRACKS/SPALLING - MAJOR |
| Deficiency Location/Instance | Stair G/1 |
| Deficiency Quantity | 10 |
| Quantity Uom | S.F. |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 |  |
| Violations | Stair G/1 No violations recorded. |
| Deficiency | METAL: RUST - MAJOR |
| Deficiency Location/Instance | Stair A/Basement |
| Deficiency Quantity | 10 |
| Quantity Uom | S.F. |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q142

| Question | Response |
|----------|----------|
|----------|----------|

INTERIOR

STAIRS/RAMPS: INTERIOR

Stairs and Landings

Deficiency Photo1



Stair A/Basement

Violations

No violations recorded.

Deficiency

STONE: BROKEN/MISSING

Deficiency Location/Instance

Main Entrance Vestibule, Stair EF/1, Exit 3 Vestibule

Deficiency Quantity

40

Quantity Uom

S.F.

Potential Action

REPLACE


Urgency of Action

PRIORITY 3

Purpose of Action

LEVEL 2

Deficiency Photo1



Main Entrance Vestibule

Violations

No violations recorded.

Walls

Inspected

Condition

2 - Between Good and Fair

Deficiency

GLAZED BLOCK: CRACKS/SPALLING

Deficiency Location/Instance

Stair A/Basement

Deficiency Quantity

20

Quantity Uom

S.F.

Potential Action

REPLACE


Urgency of Action

PRIORITY 4

Purpose of Action

LEVEL 4


Deficiency Photo1



NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Architectural Inspection



Q142

| Question | Response |
|-------------------------------|--|
| INTERIOR | |
| STAIRS/RAMPS: INTERIOR | |
| Walls | |
| Violations | Stair A/Basement 35658024N |
| Deficiency | PLASTER: CRACKS/SPALLING |
| Deficiency Location/Instance | Stair CD/2 |
| Deficiency Quantity | 10 |
| Quantity Uom | S.F. |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 |  |
| Violations | Stair CD/2 No violations recorded. |
| Deficiency | GLAZED BLOCK: CRACKS/SPALLING |
| Deficiency Location/Instance | Stair A/2 |
| Deficiency Quantity | 20 |
| Quantity Uom | S.F. |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 |  |
| Violations | Stair A/2 No violations recorded. |
| Deficiency | PLASTER: CRACKS/SPALLING |
| Deficiency Location/Instance | Stair G/1,4 |
| Deficiency Quantity | 200 |
| Quantity Uom | S.F. |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 4 |
| Purpose of Action | LEVEL 4 |

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection


Q142

| Question | Response |
|-------------------------------|--|
| INTERIOR | |
| STAIRS/RAMPS: INTERIOR | |
| Walls | |
| Deficiency Photo1 |  |
| Violations | Stair G/4 35658020X |
| TOILET ROOMS - STAFF | Inspected |
| Ceiling | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | PLASTER: CRACKS/SPALLING |
| Deficiency Location/Instance | 4th Floor Men |
| Deficiency Quantity | 10 |
| Quantity Uom | S.F. |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 |  |
| Violations | 4th Floor Men No violations recorded. |
| Door(s) | Inspected |
| Condition | 5 - Poor |
| Deficiency | METAL: DAMAGED LOUVER |
| Deficiency Location/Instance | Rooms 233, 335, 4th Floor Men |
| Deficiency Quantity | 3 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q142

| Question | Response |
|------------------------------|--|
| INTERIOR | |
| TOILET ROOMS - STAFF | |
| Door(s) | |
| Deficiency Photo1 |  |
| Violations | Room 335 No violations recorded. |
| Floor Finish | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | CERAMIC TILE: BROKEN/MISSING TILES |
| Deficiency Location/Instance | In Room 212 |
| Deficiency Quantity | 10 |
| Quantity Uom | S.F. |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 |  |
| Violations | In Room 212 No violations recorded. |
| Stalls | Inspected |
| Condition | 5 - Poor |
| Deficiency | RUST - MAJOR |
| Deficiency Location/Instance | Kitchen Staff Men, Kitchen Staff Women |
| Deficiency Quantity | 2 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q142

| Question | Response |
|----------|----------|
|----------|----------|

INTERIOR

TOILET ROOMS - STAFF

Stalls

Deficiency Photo1



Kitchen Staff Men

Violations

No violations recorded.

Walls

Inspected

Condition

2 - Between Good and Fair

Deficiency

CERAMIC TILE: BROKEN/ MISSING

Deficiency Location/Instance

In Room 212, Room 335, 4th Floor Men

Deficiency Quantity

25

Quantity Uom

S.F.

Potential Action

REPLACE


Urgency of Action

PRIORITY 3

Purpose of Action

LEVEL 2

Deficiency Photo1



4th Floor Men

Violations

No violations recorded.

TOILET ROOMS - STUDENTS

Inspected

Ceiling

Inspected

Condition

2 - Between Good and Fair

Deficiency

PLASTER: CRACKS/SPALLING

Deficiency Location/Instance

Room 234

Deficiency Quantity

10

Quantity Uom

S.F.

Potential Action

REPLACE

Urgency of Action

PRIORITY 3

Purpose of Action

LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q142

| Question | Response |
|----------|----------|
|----------|----------|

INTERIOR

TOILET ROOMS - STUDENTS

Ceiling

Deficiency Photo1



Room 234

No violations recorded.

Violations

Door(s)

Inspected

Condition

5 - Poor

Deficiency

METAL: DETERIORATED DOOR

Deficiency Location/Instance

Room 234

Deficiency Quantity

1

Quantity Uom

EACH

Potential Action

MAINTENANCE


Urgency of Action

PRIORITY 3

Purpose of Action

LEVEL 2

Deficiency Photo1



Room 234

No violations recorded.

Violations

Deficiency

METAL: DAMAGED LOUVER

Deficiency Location/Instance

Cafeteria Boys, Cafeteria Girls, Rooms 133, 135, 336, and others

Deficiency Quantity

7

Quantity Uom

EACH

Potential Action

MAINTENANCE

Urgency of Action

PRIORITY 3

Purpose of Action

LEVEL 2



Deficiency Photo1



**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q142

| Question | Response |
|--------------------------------|--|
| INTERIOR | |
| TOILET ROOMS - STUDENTS | |
| Door(s) | Inspected Room 133 |
| Violations | No violations recorded. |
| Floor Finish | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | CERAMIC TILE: BROKEN/MISSING TILES |
| Deficiency Location/Instance | Cafeteria Boys, 4th Floor Boys |
| Deficiency Quantity | 20 |
| Quantity Uom | S.F. |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 |  |
| Violations | 4th Floor Boys No violations recorded. |
| Stalls | Inspected |
| Condition | 3 - Fair |
| Deficiency | BROKEN/MISSING |
| Deficiency Location/Instance | Cafeteria Boys, Rooms 336, 432 |
| Deficiency Quantity | 3 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 |  |
| Violations | Room 432 No violations recorded. |
| Walls | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | PLASTER: CRACKS/SPALLING |
| Deficiency Location/Instance | 4th Floor Boys, 4th Floor Girls |
| Deficiency Quantity | 20 |

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Architectural Inspection



Q142

| Question | Response |
|--------------------------------|--|
| INTERIOR | |
| TOILET ROOMS - STUDENTS | |
| Walls | |
| Quantity Uom | S.F. |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 |  |
| Violations | 4th Floor Boys No violations recorded. |
| Deficiency | CERAMIC TILE: BROKEN/ MISSING |
| Deficiency Location/Instance | Cafeteria Girls, Rooms 133, 234, 4th Floor Boys, 4th Floor Girls |
| Deficiency Quantity | 50 |
| Quantity Uom | S.F. |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 |  |
| Violations | Room 133 No violations recorded. |
| LIFE SAFETY | Inspected |
| F.D. HOLDING AREA | Does not Exist |
| STEEL STAIRS | Does not Exist |
| SITE | Inspected |
| CONTAINERIZATION | Inspected |
| Condition | 5 - Poor |
| Deficiency | FENCING MISSING |
| Deficiency Location/Instance | Parking Lot |
| Deficiency Quantity | 1,050 |
| Quantity Uom | S.F. |
| Potential Action | INSTALL NEW |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection



Q142

| Question | Response |
|---|--|
| SITE | |
| CONTAINERIZATION | |
| Violations | No violations recorded. |
| Deficiency | CONTAINER DAMAGED |
| Deficiency Location/Instance | Parking Lot |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 |  |
| Violations | Parking Lot No violations recorded. |
| Deficiency | CONCRETE PAD MISSING |
| Deficiency Location/Instance | Parking Lot |
| Deficiency Quantity | 600 |
| Quantity Uom | S.F. |
| Potential Action | INSTALL NEW |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 |  |
| Violations | Parking Lot No violations recorded. |
| Drainage System for Asphalt | Inspected |
| Catch Basins/Manhole - Surrounded by asphalt | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Culverts - Asphalt Covering | Does not Exist |
| Drainage System for Concrete | Inaccessible |
| Drainage System for Soil | Inaccessible |
| DRINKING FOUNTAINS | Does not Exist |
| FENCES | Inspected |
| Condition | 4 - Between Fair and Poor |

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection



Q142

| Question | Response |
|------------------------------|--|
| SITE | |
| FENCES | |
| Deficiency | WROUGHT IRON: MISSING SECTIONS |
| Deficiency Location/Instance | 142nd Street |
| Deficiency Quantity | 40 |
| Quantity Uom | S.F. |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 |  |
| Violations | 142nd Street No violations recorded. |
| Deficiency | CHAIN LINK: RUST - MAJOR |
| Deficiency Location/Instance | 142nd Street |
| Deficiency Quantity | 500 |
| Quantity Uom | S.F. |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 |  |
| Violations | 142nd Street No violations recorded. |
| Deficiency | WROUGHT IRON: DAMAGED/DETERIORATED |
| Deficiency Location/Instance | Linden Boulevard, 142nd Street |
| Deficiency Quantity | 80 |
| Quantity Uom | S.F. |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q142

| Question | Response |
|--------------------------------------|--|
| SITE | |
| FENCES | |
| Deficiency Photo1 |  |
| Violations | Linden Boulevard No violations recorded. |
| IRRIGATION SYSTEM | Does not Exist |
| PAVING | Inspected |
| Student Non-Use | Inspected |
| Gravel Exists? | No |
| Asphalt | Inaccessible |
| Concrete | Inspected |
| Condition | 3 - Fair |
| Deficiency | DAMAGED/DETERIORATED/MISSING SECTIONS |
| Deficiency Location/Instance | Parking Lot |
| Deficiency Quantity | 225 |
| Quantity Uom | S.F. |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 |  |
| Violations | Parking Lot No violations recorded. |
| Pavers | Does not Exist |
| Student Use | Does not Exist |
| Site Sidewalks & Walkways | Inspected |
| Asphalt | Does not Exist |
| Concrete | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | DAMAGED/DETERIORATED/MISSING SECTIONS |
| Deficiency Location/Instance | 142nd Street |
| Deficiency Quantity | 25 |
| Quantity Uom | S.F. |
| Potential Action | REPLACE |

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Architectural Inspection

Q142

| Question | Response |
|--------------------------------------|--|
| SITE | |
| PAVING | |
| Site Sidewalks & Walkways | |
| Concrete | |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 |  |
| | 142nd Street |
| Violations | No violations recorded. |
| Pavers | Does not Exist |
| DOT Sidewalk | Inspected |
| Asphalt | Does not Exist |
| Concrete | Inspected |
| Condition | 4 - Between Fair and Poor |
| Deficiency | HEAVING |
| Deficiency Location/Instance | Linden Boulevard |
| Deficiency Quantity | 100 |
| Quantity Uom | S.F. |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 5 |
| Purpose of Action | LEVEL 6 |
| Deficiency Photo1 |  |
| | Linden Boulevard |
| Violations | No violations recorded. |
| Deficiency | HEAVING |
| Deficiency Location/Instance | Linden Boulevard |
| Deficiency Quantity | 50 |
| Quantity Uom | S.F. |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q142

| Question | Response |
|---|--|
| SITE | |
| PAVING | |
| DOT Sidewalk | |
| Concrete | |
| Deficiency Photo1 |  |
| Violations | Linden Boulevard No violations recorded. |
| Deficiency | DAMAGED/DETERIORATED/MISSING SECTIONS |
| Deficiency Location/Instance | 143rd Street, Linden Boulevard, 142nd Street |
| Deficiency Quantity | 875 |
| Quantity Uom | S.F. |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 |  |
| Violations | 143rd Street No violations recorded. |
| Pavers | Does not Exist |
| PLAYGROUNDS | Does not Exist |
| PLAYING SURFACE | Does not Exist |
| RETAINING WALLS | Does not Exist |
| SEATING | Does not Exist |
| SITE WALLS (NOT RETAINING WALLS) | Does not Exist |
| STAIRS/RAMPS: EXTERIOR | Does not Exist |
| ARTWORK | Does not Exist |