Building Condition Assessment Survey 2023 - 2024

Inspection Id	Inspection [Гуре				Time In	Last Edited
EE: Q155	Electrical					2024-02-13 8:05 AM	2024-02-23 11:23 Al
Asset Data							
Question					Answer		
Type of Service					Below Gro	ound	
Does Interactive W	hiteboard (Γ	WB) Exist?			Yes		
Water Penetration i	in Electrical	Room?			No		
Have any Systems/	Major Build	ing Components	been upgraded?		Yes		
					Systems:	Motor Controller (Most Motor Intrusion Alarm System	Starter/Contactor), LAN,
					Years:	2023	
					Systems:	Local Sound System (Auditoriu	m, Cafeteria)
					Years:	2020	
					Systems:	Exit Lights	
					Years:	2019	
					Systems:	Auditorium (Projection System), Telephone System
					Years:	2016	
					Systems:	Gymnasium (Lighting), Public IPDVS/CCTV System	Address System (Tuner),
					Years:	2015	
					Systems:	Security Lights	
					Years:	2005	
					Systems:	Public Address System (Amplit	ïer)
					Years:	2004	
					Systems:	Interior Fluorescent Lighting, R Lighting (Auditorium, Cafeteria Corridor, Toilet Room)	
					Years:	1999	
					Systems:	Partial Molded Case Circuit Bro	eaker Type Panel Board
					Years:	1990, 2000, 2020	
					Systems:	Emergency Light/Exit Light Pa	nel
					Years:	1990	
DEDICATED IN	TERCOMS	IN FIRE RESC	UE AREAS				
Question					Response		
Are there any Life and/or Holding Ro			re Rescue Areas,		No		
riority Condition							
Priority Prio Condition Exist Cate Last Year?		Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title Status	PhotoImage
No condition recorded							
nspection							
Question					Respons	se	
Electrical							
AUDITORIUM					Inspecte	d	
Instance	on 1st Floor	r			Inspecte	d	
House Lighting					Inspecte		
	Chandelier ex	xist?			No		
	on 1st Floor				Inspecte	d	
					mspecter	-	
Lighting Fixtu					Inamast-	d	
	on 1st Floor				Inspecte		
D J 4 M .	ounted				Does not	t Exist	

Building Condition Assessment Survey 2023 - 2024

uestion	Response
AUDITORIUM	
House Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	
Instance on 1st Floor	Does not Exist
Surface Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not Exist
Local Sound System	Inspected
Instance on 1st Floor	Inspected
Installation Year	2020
Source of Installation	Custodial Staff
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Projection System	Inspected
Is the projector on a cart or installed on the ceiling?	Ceiling
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Theater Lighting System	Inspected
Instance on 1st Floor	Inspected
Dimming System	<u> </u>
Instance on 1st Floor	Does not Exist
Theater Lighting	
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	21
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
CAFETERIA	Inspected
Instance on 1st Floor	Inspected
Lighting	Inspected
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected

Building Condition Assessment Survey 2023 - 2024

Question	Response
CAFETERIA	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Surface Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not Exist
Local Sound System	Inspected
Instance on 1st Floor	Inspected
Installation Year	2020
Source of Installation	Custodial Staff
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Projection System	Does not Exist
Instance on 1st Floor	Does not Exist
Theater_Lighting System	Does not Exist
Instance on 1st Floor	Does not Exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected
Lighting	Inspected
Does a Chandelier exist?	No
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
COMPUTER LAB	Inspected
Instance on 4th Floor - Room W3	Inspected
Power Panel	Yes
Lighting	Inspected
Instance on 4th Floor - Room W3	Inspected
Lighting Fixture - Fluorescent	
Instance on 4th Floor - Room W3	Inspected
Pendant Mounted	Inspected
	-

Building Condition Assessment Survey 2023 - 2024

urear mspection	V.
uestion	Response
COMPUTER LAB	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	Inspected
Instance on 4th Floor - Room W3	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Instance on 4th Floor - Room W3	Does not Exist
Recessed Mounted	Does not Exist
Instance on 4th Floor - Room W3	Does not Exist
Lighting Fixture - HID	
Instance on 4th Floor - Room W3	Does not Exist
Lighting Fixture - Incandescent	2000 100 2.1100
Instance on 4th Floor - Room W3	Does not Exist
	DOCS HOLEAIST
Lighting Fixture - LED Instance on 4th Floor - Room W3	December Entire
-	Does not Exist
Raceway With Receptacles	Inspected
Instance on 4th Floor - Room W3	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
GYMNAS <u>IUM</u>	Inspected
Instance on 3rd Floor	Inspected
Lighting	Inspected
Instance on 3rd Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 3rd Floor	Does not Exist
Lighting Fixture - HID	
Instance on 3rd Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 3rd Floor	Does not Exist
Lighting Fixture - LED	
Instance on 3rd Floor	Inspected
Pendant Mounted	Inspected
Instance on 3rd Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL
	LIGHTING FIXTURE NOT OPERATIONAL 1
Deficiency Quantity	I EACH
Quantity Uom	
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Surface Mounted	Does not Exist
Instance on 3rd Floor	Does not Exist
Recessed Mounted	Does not Exist
Instance on 3rd Floor	Does not Exist
Local Sound System	Inspected

Building Condition Assessment Survey 2023 - 2024

near inspection		V-1
estion	Response	
SYMNASIUM		
Local Sound System		
Instance on 3rd Floor	Inspected	
Installation Year	1967	
Source of Installation	Inspector Estimate	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Projection System	Does not Exist	
Instance on 3rd Floor	Does not Exist	
Scoreboard	Does not Exist	
Instance on 3rd Floor	Does not Exist	
Theater Lighting System	Does not Exist	
Instance on 3rd Floor	Does not Exist	
KITCHEN	Inspected	
Instance on 1st Floor	Inspected	
Lighting	Inspected	
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Inspected	
Pendant Mounted	Does not Exist	
Instance on 1st Floor	Does not Exist Does not Exist	
Surface Mounted	Inspected	
Instance on 1st Floor	Inspected	
Condition	3 - Fair	
Deficiency Recessed Mounted	No deficiencies recorded	
-	Does not Exist	
Instance on 1st Floor	Does not Exist	
Lighting Fixture - HID	D	
Instance on 1st Floor	Does not Exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not Exist	
Lighting Fixture - LED		
Instance on 1st Floor	Does not Exist	
IBRARY	Inspected	
Instance on Room 309	Inspected	
Lighting	Inspected	
Instance on Room 309	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 309	Inspected	
Pendant Mounted	Inspected	
Instance on Room 309	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Does not Exist	
Instance on Room 309	Does not Exist	
Recessed Mounted	Does not Exist	
Instance on Room 309	Does not Exist	

Building Condition Assessment Survey 2023 - 2024

Question	Response
LIBRARY	
Lighting	
Lighting Fixture - Incandescent	
Instance on Room 309	Does not Exist
Lighting Fixture - LED	
Instance on Room 309	Does not Exist
Raceway With Receptacles	Inspected
Instance on Room 309	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Projection System	Does not Exist
Instance on Room 309	Does not Exist
LOCKER ROOM	Does not Exist
MULTIPURPOSE ROOM	Does not Exist
SCIENCE DEMO ROOM	Does not Exist
SCIENCE LAB	Does not Exist
SCIENCE PREP ROOM	Does not Exist
SWIMMING POOL	Does not Exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Replacement Quantity	67,000
Replacement Uom	S.F.
Condition	3 - Fair

Building Condition Assessment Survey 2023 - 2024

Question	Response
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not Exist
EMERGENCY GENERATOR SET	Does not Exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Non Battery Pack	Does not Exist
EXIT/EMERGENCY LIGHT	Does not Exist
FIRE ALARM SYSTEM	Inspected
Replacement Quantity	67,000
Replacement Uom	S.F.
Bell/Horn	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Strobe	Does not Exist
Manual Pull Station	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Does not Exist
Duct Smoke Detector	Does not Exist
Area Smoke Detector	Does not Exist
CO Detector	Does not Exist
Heat Detector	Does not Exist
Elevator Recall	Does not Exist
Magnetic Door Holder/Contactor	Does not Exist
Fused Cutout Panel	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Does not Exist
Main Panel	Inspected
Bell At Panel	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Does not Exist
Fire Alarm Control Panel (Standard)	Inspected
Instance	Boiler Room
Instance Condition	3 - Fair
mstance Condition	5 - 1 au

Building Condition Assessment Survey 2023 - 2024

uestion	Response
FIRE ALARM SYSTEM	
Main Panel	
Fire Alarm Control Panel (Standard)	
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Edwards
Equipment	Fire Alarm Control Panel
Installation Year	1967
Source of Installation	Documented
Deficiency	No deficiencies recorded
Sub-Panel	Does not Exist
Remote Annunciator	Does not Exist
Sprinkler Flow/Air Pressure Switch	Does not Exist
Tamper Flow Switch/Chain	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Does not Exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not Exist
MOTOR CONTROLLER	Inspected
Motor Control Center	Does not Exist
Motor Starter/Contactor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Does not Exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Does not Exist
Fused Knife Switch Type	Does not Exist
Fused Toggle Switch Type	Inspected
Condition	3 - Fair
Deficiency	PANEL BOARD DOOR LOCK IS MISSING
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL BOARD BEYOND USEFUL LIFE

Building Condition Assessment Survey 2023 - 2024

icai inspection	-	
stion	Response	
ANEL BOARD		
Fused Toggle Switch Type		
Deficiency Location/Instance	Electrical Room	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
Molded Case Circuit Breaker Type	Inspected	
Condition	3 - Fair	
Deficiency	PANEL BOARD DOOR LOCK IS MISSING	
Deficiency Location/Instance	Storage Closet Next to Room 404	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 2	
Purpose of Action	LEVEL 2	
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
Deficiency	PANEL BOARD COVER IS MISSING	
Deficiency Location/Instance	Electrical Room	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 2	
Purpose of Action	LEVEL 2	
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
Deficiency	PANEL BOARD BEYOND USEFUL LIFE	
Deficiency Location/Instance	Corridor by Rooms (209, 211, 301, 309, 401, 419), 1st Floor Corri	
Deliciting Escardin Instance	outside Cafeteria, Auditorium, Projection Room, Electrical Room, Boiler Room, Basement Boiler Room	
Deficiency Quantity	13	
Quantity Uom	EACH	
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
Deficiency	NO SPARE	
Deficiency Location/Instance	Corridor by Rooms (301, 401, 419), Cafeteria, Kitchen, Boiler Roc	
Deficiency Quantity	6	
Quantity Uom	EACH	
Potential Action	REPLACE PANEL BOARD	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Deficiency Photo1	No photo recorded	

Building Condition Assessment Survey 2023 - 2024

estion	Response		
UBLIC ADDRESS SYSTEM	Inspected		
Replacement Quantity	67,000		
Replacement Uom	S.F.		
Instance	General Office		
Instance Condition	3 - Fair		
Instance Quantity	1		
Instance Quantity Uom	EACH		
Model	N/A		
Installation Year	1967		
Source of Installation	Inspector Estimate		
Deficiency	CLOCK NOT OPERATIONAL		
Deficiency Location/Instance	Classrooms and Corridors		
Deficiency Quantity	20		
Quantity Uom	EACH		
Potential Action	REPLACE		
Urgency of Action	PRIORITY 3		
Purpose of Action	LEVEL 2		
Deficiency Photo1	No photo recorded		
Violations	No violations recorded.		
ECURITY	Inspected		
IPDVS/CCTV System	Inspected		
Replacement Quantity	67,000		
Replacement Uom	S.F.		
Installation Year	2015		
Source of Installation	Inspector Estimate		
Condition	2 - Between Good and Fair		
Deficiency	No deficiencies recorded		
Intrusion Alarm System	Inspected		
Replacement Quantity	67,000		
Replacement Uom	S.F.		
Central Control Panel	Inspected		
Instance	Custodian's Office		
Instance Condition	1 - Good		
Instance Quantity	1		
Instance Quantity Uom	EACH		
Model	Vista-128BPT		
Installation Year	2023		
Source of Installation	Custodial Staff		
Deficiency	No deficiencies recorded		
Infrared Sensor	Inspected		
Condition	1 - Good		
Deficiency	No deficiencies recorded		
Panic Switch	Inspected		
Condition	1 - Good		
Deficiency	No deficiencies recorded		
Remote Annunciator	Inspected		
Condition	1 - Good		
Deficiency	No deficiencies recorded		
· · · · · ·			

Building Condition Assessment Survey 2023 - 2024

Question	Response		
SECURITY	Inspected		
Intrusion Alarm System	Inspected		
Siren/Strobe			
Condition	1 - Good		
Deficiency	No deficiencies recorded		
Lighting - Security	Inaccessible		
SERVICE SWITCH	Inspected		
Instance	Electrical Room		
Instance Condition	3 - Fair		
Instance Quantity	1		
Instance Quantity Uom	EACH		
Instance Manufacturer	Federal Pacific Electric		
Equipment	Main Service Switch		
Capacity/Size Quantity	1,600		
Capacity/Size UOM	Amps		
Source of Capacity/Size	Nameplate		
Installation Year	1967		
Source of Installation	Inspector Estimate		
Deficiency	No deficiencies recorded		
SWITCHBOARD	Inspected		
Number of Spares	0		
Fused Disconnect Switch Type	Inspected		
Instance	Electrical Room		
Instance Condition	3 - Fair		
Instance Quantity	1		
Instance Quantity Uom	EACH		
Instance Manufacturer	Federal Pacific Electric		
Equipment	N/A		
Capacity/Size Quantity	1,600		
Capacity/Size UOM	Amps Total		
Capacity/Size2 Quantity	2		
Capacity/Size2 UOM	Section(S)		
Source of Capacity/Size	Service Switch Size		
Installation Year	1967		
Source of Installation	Inspector Estimate		
Deficiency	No deficiencies recorded		
Fused Knife Switch Type	Does not Exist		
Molded Case Circuit Breaker Type	Does not Exist		
TELEPHONE SYSTEM	Inspected		
PBX/Intercom	Inspected		
Condition	2 - Between Good and Fair		
Deficiency	No deficiencies recorded		
Standard	Inspected		
Condition	2 - Between Good and Fair		
Deficiency	No deficiencies recorded		
TRANSFORMER	Does not Exist		