Building Condition Assessment Survey 2023 - 2024

Inspection I	d Inspection	Гуре				Time In		Last Edited
EE : Q1	72 Electrical					2024-03-	-13 8:04 AM	2024-06-21 10:00 A
Asset Data								
Question					Answer			
Type of Servi	ice				Below Gro	und		
	ive Whiteboard (Γ	WB) Exist?			Yes			
	ation in Electrical				No			
Have any Sys	stems/Major Build	ing Components	been upgraded?		Yes			
	-				Systems:	Gymnasium (Sco	oreboard)	
					Years:	2023		
					Systems:	LAN		
					Years:	2021		
					Systems:	Partial Emergen	cy Lights (Non	Battery Type)
					Years:	2020		
					Systems:	Security Lights		
					Years:	2019		
					Systems:	Auditorium (Loc	al Sound Syste	m)
					Years:	2016		
					Systems:			Except (Auditorium, ce Prep Room 306), LED
					Years:	2015		
					Systems:	Cafeteria (Local	Sound System))
					Years:	2011		
					Systems:	Auditorium (Flu System)	orescent Lightin	ng, Theater Lighting
					Years:	2008		
					Systems:	Science Lab, Sci	ence Prep Roor	n 306
					Years:	2004		
					Systems:	Service Switch,	Switchboard	
					Years:	2001, 2013		
					Systems:	Emergency Ligh	t/Exit Light Par	nel
					Years:	2001		
					Systems:	Intrusion Alarm	System	
					Years:	1999		
					Systems:	Molded Case Cir	cuit Breaker T	ype Panel Board
					Years:	1998, 2001, 200	4, 2013, 2016, 2	2021
					Systems:	Public Address S	System (Amplif	ïer, Tuner)
					Years:	1998		
DEDICATE	D INTERCOMS	IN FIRE RESC	CUE AREAS					
Question					Response			
and/or Holdi	y Life Rescue Assing Rooms in your	building?			Yes			
during a f	ire?		hese spaces for use		No			
Which	spaces do not ha	ve dedicated inte	ercoms?		Rooms 219	9, 319		
Priority Conditi								
Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
No	Fire Alarm System - Components Not Operational	N/A	FIRE ALARM SYSTEM Sprinkler Flow/Air Pressure Switch	Room B27	Peter Navetta	Custodian	Sent to DSF	

Building Condition Assessment Survey 2023 - 2024

Electrical Inspection Q172

Public Address N/A System - System Yes

Defective

PUBLIC ADDRESS SYSTEM

General Office - Peter Navetta Room 127

Sent to DSF

pection	
Question	Response
Electrical	
AUDITORIUM	Inspected
Instance on 1st Floor	Inspected
House Lighting	Inspected
Does a Chandelier exist?	No
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Surface Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor	Inspected
Pendant Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Recessed Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Local Sound System	Inspected
Instance on 1st Floor	Inspected
Installation Year	2016
Source of Installation	Custodial Staff
Condition	4 - Between Fair and Poor
Deficiency	AMPLIFIER NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2

Print Date: 6/25/2024

Building Condition Assessment Survey 2023 - 2024

Hear Inspection		V -
estion	Response	
AUDITORIUM		
Local Sound System		
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
Projection System	Inspected	
Is the projector on a cart or installed on the ceiling?	Ceiling	
Instance on 1st Floor	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Theater Lighting System	Inspected	
Instance on 1st Floor	Inspected	
Dimming System	•	
Instance on 1st Floor	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Theater Lighting		
Instance on 1st Floor	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
AFETERIA	Inspected	
Instance on Basement	Inspected	
Lighting	Inspected	
Instance on Basement	Inspected	
Lighting Fixture - Fluorescent	· · · · · ·	
Instance on Basement	Inspected	
Pendant Mounted	Does not Exist	
Instance on Basement	Does not Exist	
Surface Mounted	Does not Exist	
Instance on Basement	Does not Exist	
Recessed Mounted		
Instance on Basement	Inspected	
Condition	Inspected 2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID	ino deficiencies recorded	
Instance on Basement	Does not Exist	
Lighting Fixture - Incandescent	Does not Exist	
Instance on Basement	Does not Exist	
-	Does not Exist	
Lighting Fixture - LED Instance on Basement	Does not Exist	
Local Sound System	Inspected	
Instance on Basement	Inspected	
Installation Year	2011	
Source of Installation	Custodial Staff	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Projection System	Does not Exist	
Instance on Basement	Does not Exist	
Theater Lighting System	Does not Exist	
Instance on Basement	Does not Exist	

Building Condition Assessment Survey 2023 - 2024

arear mspection		•
uestion	Response	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected	
Lighting	Inspected	
Does a Chandelier exist?	No	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE	
Deficiency Quantity	3	
Quantity Uom	EACH	
Potential Action	REPLACE BALLAST	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
Surface Mounted	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID	Does not Exist	
Lighting Fixture - Incandescent	Does not Exist	
Lighting Fixture - LED	Inspected	
Pendant Mounted	Does not Exist	
Surface Mounted	Does not Exist	
Recessed Mounted	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
COMPUTER LAB	Inspected	
Instance on Rooms 217, 234	Inspected	
Power Panel	Yes	
Lighting	Inspected	
Instance on Rooms 217, 234	Inspected	
Lighting Fixture - Fluorescent		
Instance on Rooms 217, 234	Inspected	
Pendant Mounted		
Instance on Rooms 217, 234	Inspected Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Does not Exist	
Instance on Rooms 217, 234	Does not Exist	
Recessed Mounted	Does not Exist	
Instance on Rooms 217, 234	Does not Exist Does not Exist	
	DOGS HOLEAIST	
Lighting Fixture - HID	Description of Pairs	
Instance on Rooms 217, 234	Does not Exist	
Lighting Fixture - Incandescent		
Instance on Rooms 217, 234	Does not Exist	
Lighting Fixture - LED		
Instance on Rooms 217, 234	Does not Exist	

Building Condition Assessment Survey 2023 - 2024

Response
Inspected
Inspected
3 - Fair
No deficiencies recorded
Inspected
Inspected
Inspected
Inspected
Does not Exist
Does not Exist
Does not Exist
Inspected
Does not Exist
Inspected
Inspected
2 - Between Good and Fair
No deficiencies recorded
Inspected
Inspected
1954
Documented
5 - Poor
AMPLIFIER NOT OPERATIONAL
1
EACH
REPLACE SYSTEM
PRIORITY 2
LEVEL 2
No photo recorded
No violations recorded.
Does not Exist
Does not Exist
Inspected
Inspected
1 - Good
No deficiencies recorded
D (F.)
Does not Exist
Does not Exist
Does not Exist Inspected
Does not Exist

Building Condition Assessment Survey 2023 - 2024

Question	Response
KITCHEN	
Lighting	
Instance on Basement	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement	Inspected
Pendant Mounted	Does not Exist
Instance on Basement	Does not Exist
Surface Mounted	Inspected
Instance on Basement	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Instance on Basement	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Basement	Does not Exist
Lighting Fixture - Incandescent	
Instance on Basement	Does not Exist
Lighting Fixture - LED	
Instance on Basement	Does not Exist
LIBRARY	Inspected
Instance on Room 231	Inspected
Lighting	Inspected
Instance on Room 231	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 231	Inspected
Pendant Mounted	Does not Exist
Instance on Room 231	Does not Exist
Surface Mounted	Inspected
Instance on Room 231	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Instance on Room 231	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Room 231	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 231	Does not Exist
Lighting Fixture - LED	
Instance on Room 231	Does not Exist
Raceway With Receptacles	Does not Exist
Instance on Room 231	Does not Exist Does not Exist
	Does not Exist Does not Exist
Projection System Instance on Room 231	Does not Exist Does not Exist
	_
LOCKER ROOM Instance on Recompant, Roya Recompant, Circle	Inspected
Instance on Basement - Boys, Basement - Girls	Inspected

Building Condition Assessment Survey 2023 - 2024

near inspection		Ų.
nestion	Response	
LOCKER ROOM		
Alternative use	No	
Lighting	Inspected	
Instance on Basement - Boys, Basement - Girls	Inspected	
Lighting Fixture - Fluorescent		
Instance on Basement - Boys, Basement - Girls	Inspected	
Pendant Mounted	Does not Exist	
Instance on Basement - Boys, Basement - Girls	Does not Exist	
Surface Mounted	Inspected	
Instance on Basement - Boys, Basement - Girls	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not Exist	
Instance on Basement - Boys, Basement - Girls	Does not Exist	
Lighting Fixture - HID		
Instance on Basement - Boys, Basement - Girls	Does not Exist	
Lighting Fixture - Incandescent		
Instance on Basement - Boys, Basement - Girls	Does not Exist	
Lighting Fixture - LED		
Instance on Basement - Boys, Basement - Girls	Does not Exist	
MULTIPURPOSE ROOM	Does not Exist	
SCIENCE DEMO ROOM	Inspected	
Instance on Rooms 101, 105, 201, 205, 301	Inspected	
Power Panel	No	
Alternative use	No	
Instance on Room 305	Inspected	
Power Panel Alternative use	No Yes	
Lighting	Inspected	
Instance on Room 305	Inspected	
Instance on Rooms 101, 105, 201, 205, 301	Inspected	
Lighting Fixture - Fluorescent	•	
Instance on Room 305	Inspected	
Instance on Rooms 101, 105, 201, 205, 301	Inspected	
Pendant Mounted	Inspected	
Instance on Room 305	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on Rooms 101, 105, 201, 205, 301	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Does not Exist	
Instance on Room 305	Does not Exist	
Instance on Rooms 101, 105, 201, 205, 301	Does not Exist	
Recessed Mounted	Does not Exist Does not Exist	
Instance on Room 305	Does not Exist Does not Exist	
Instance on Rooms 101, 105, 201, 205, 301	Does not Exist	
Lighting Fixture - HID		
Instance on Room 305	Does not Exist	

Building Condition Assessment Survey 2023 - 2024

incar hispection	•
nestion	Response
SCIENCE DEMO ROOM	
Lighting	
Lighting Fixture - HID	
Instance on Rooms 101, 105, 201, 205, 301	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 305	Does not Exist
Instance on Rooms 101, 105, 201, 205, 301	Does not Exist
Lighting Fixture - LED	
Instance on Room 305	Does not Exist
Instance on Rooms 101, 105, 201, 205, 301	Does not Exist
Emergency Gas Shut-Off Valve	Does not Exist
Instance on Room 305	Does not Exist
Instance on Rooms 101, 105, 201, 205, 301	Does not Exist
Emergency Shut-Off Power	Does not Exist
Instance on Room 305	Does not Exist
Instance on Rooms 101, 105, 201, 205, 301	Does not Exist
Power Supply	Does not Exist
Instance on Room 305	Does not Exist Does not Exist
Instance on Rooms 101, 105, 201, 205, 301	Does not Exist
	Does not Exist Does not Exist
Projection System Instance on Room 305	Does not Exist Does not Exist
Instance on Rooms 101, 105, 201, 205, 301	Does not Exist
SCIENCE LAB	Inspected
Instance on Room 304 Power Panel	Inspected
Alternative use	No No
Lighting	Inspected
Instance on Room 304	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 304	Inspected
Pendant Mounted	Inspected
Instance on Room 304	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Instance on Room 304	Does not Exist
Recessed Mounted	Does not Exist
Instance on Room 304	Does not Exist
Lighting Fixture - HID	
Instance on Room 304	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 304	Inspected
Pendant Mounted	Does not Exist
Instance on Room 304	Does not Exist
Surface Mounted	Inspected
Instance on Room 304	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Recessed Mounted	

Building Condition Assessment Survey 2023 - 2024

icai inspection	
estion	Response
CIENCE LAB	
Lighting	Inspected
Lighting Fixture - Incandescent	
Recessed Mounted	
Instance on Room 304	Does not Exist
Lighting Fixture - LED	
Instance on Room 304	Does not Exist
Emergency Gas Shut-Off Valve	Inspected
Instance on Room 304	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	Inspected
Instance on Room 304	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Power Supply	Inspected
Instance on Room 304	Inspected
Instructor Unit	
Instance on Room 304	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Meter Demonstration Unit	
Instance on Room 304	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Student Unit	
Instance on Room 304	Does not Exist
Projection System	Does not Exist
Instance on Room 304	Does not Exist
CIENCE PREP ROOM	Inspected
Instance on Room 146	Inspected
Power Panel Alternative use	No Yes
Instance on Room 306	Inspected
Power Panel	Yes
Alternative use	No
Instance on Rooms 103, 203, 303	Inspected
Power Panel Alternative use	No No
Lighting	Inspected
Instance on Rooms 103, 203, 303	Inspected
Instance on Room 306	Inspected
Instance on Room 146	
	Inspected
Lighting Fixture - Fluorescent	
Instance on Rooms 103, 203, 303	Inspected
Instance on Room 306	Inspected
Instance on Room 146	Inspected
Pendant Mounted	Does not Exist
Instance on Rooms 103, 203, 303	Does not Exist

Building Condition Assessment Survey 2023 - 2024

uestion	Response
SCIENCE PREP ROOM	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 146	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Instance on Rooms 103, 203, 303	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 306	Does not Exist
Instance on Room 146	Does not Exist
Recessed Mounted	Does not Exist
Instance on Rooms 103, 203, 303	Does not Exist
Instance on Room 306	Does not Exist
Instance on Room 146	Does not Exist
Lighting Fixture - HID	
Instance on Rooms 103, 203, 303	Does not Exist
Instance on Room 306	Does not Exist
Instance on Room 146	Does not Exist
Lighting Fixture - Incandescent	DOGS HOL EXIST
Instance on Rooms 103, 203, 303	Does not Exist
	
Instance on Room 306	Does not Exist
Instance on Room 146	Does not Exist
Lighting Fixture - LED	
Instance on Rooms 103, 203, 303	Does not Exist
Instance on Room 306	Does not Exist
Instance on Room 146	Does not Exist
Emergency Gas Shut-Off Valve	Does not Exist
Instance on Rooms 103, 203, 303	Does not Exist
Instance on Room 306	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 146	Does not Exist
Emergency Shut-Off Power	Does not Exist
Instance on Rooms 103, 203, 303	Does not Exist
Instance on Room 306	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 146	Does not Exist
Power Supply	Does not Exist
Instance on Rooms 103, 203, 303	Does not Exist
Instance on Room 306	Does not Exist
Instance on Room 146	Does not Exist
SWIMMING POOL	Does not Exist
TOILET ROOM - STAFF	Inspected
(D)	Pose 10 of 16

Building Condition Assessment Survey 2023 - 2024

Question	Response
TOILET ROOM - STAFF	
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted Condition	Inspected
Deficiency	2 - Between Good and Fair No deficiencies recorded
Surface Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Replacement Quantity	134,000
Replacement Uom	S.F.
Condition	3 - Fair
Deficiency EMERCENCY DO STANDBY BATTERBY ROWER	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not Exist
EMERGENCY GENERATOR SET	Does not Exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	3 - Fair
Deficiency EMERICAN A LIGHTING	No deficiencies recorded
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	3 - Fair
Deficiency	BATTERY NOT OPERATIONAL
Deficiency Location/Instance	Auditorium
Deficiency Quantity	2 FACH
Quantity Uom	EACH DEDLACE DATTEDV
Potential Action	REPLACE BATTERY PRIORITY 5
Urgency of Action Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Non Battery Pack	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded Pere 11 of 16 Print Potes 6/05/2024

Building Condition Assessment Survey 2023 - 2024

Question	Response
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Does not Exist
EXIT/EMERGENCY LIGHT	Does not Exist
FIRE ALARM SYSTEM	Inspected
Replacement Quantity	134,000
Replacement Uom	S.F.
Bell/Horn	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Strobe	Does not Exist
Manual Pull Station	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Does not Exist
Duct Smoke Detector	Does not Exist
Area Smoke Detector	Does not Exist
CO Detector	Does not Exist
Heat Detector	Does not Exist
Elevator Recall	Does not Exist
	Does not Exist
Magnetic Door Holder/Contactor	
Fused Cutout Panel	Inspected 3 - Fair
Condition	
Deficiency Fire Alarm Digital Communicator	No deficiencies recorded
Main Panel	Does not Exist Inspected
Bell At Panel	Inspected
Condition	3 - Fair
Deficiency Fire Alarm Control Panel (Electronic)	No deficiencies recorded Does not Exist
Fire Alarm Control Panel (Standard)	Inspected Boiler Room B30
Instance Instance Condition	3 - Fair
Instance Quantity	1 FACH
Instance Quantity Uom	EACH
Instance Manufacturer	ACME
Equipment	Fire Alarm
Installation Year	1954
Source of Installation	Documented
Deficiency	No deficiencies recorded
Sub-Panel	Inspected
Bell At Panel	Inspected
Condition	3 - Fair
Deficiency Fine Alexer Control Bond (Floringia)	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Does not Exist
Fire Alarm Control Panel (Standard)	Inspected P. I. P.
Instance (D) Page 12 of 16	Boiler Room B30

Building Condition Assessment Survey 2023 - 2024

arear mspection		QI/
nestion	Response	
FIRE ALARM SYSTEM		
Sub-Panel		
Fire Alarm Control Panel (Standard)		
Instance Condition	3 - Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Instance Manufacturer	ACME	
Equipment	Register Panel	
Installation Year	1954	
Source of Installation	Documented	
Deficiency	No deficiencies recorded	
Instance	Boiler Room B30	
Instance Condition	3 - Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Instance Manufacturer	ACME	
Equipment	Sprinkler Panel	
Installation Year	1954	
Source of Installation	Documented	
Deficiency	No deficiencies recorded	
Remote Annunciator	Inspected	
Display Monitor	Does not Exist	
Panel	Does not Exist	
Printer	Does not Exist	
Punch Register	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Sprinkler Flow/Air Pressure Switch	Inspected	
Condition	5 - Poor	
Deficiency	SWITCH NOT OPERATIONAL	
Deficiency Location/Instance	Room B27	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
Tamper Flow Switch/Chain	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
GROUNDING SYSTEM	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
INTERCOM SYSTEM	Does not Exist	
LAN	Inspected	
Local Distribution Frame (I/LDF)	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	

Building Condition Assessment Survey 2023 - 2024

Question	Response
LAN	Inspected
Main Equipment Rack (MDF)	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not Exist
MOTOR CONTROLLER	Inspected
Motor Control Center	Does not Exist
Motor Starter/Contactor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Does not Exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	3 - Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Fused Knife Switch Type	Inspected
Condition	3 - Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Room B34, Boiler Room, Mechanical Room B12
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Fused Toggle Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
PUBLIC ADDRESS SYSTEM	Inspected
Replacement Quantity	134,000
Replacement Uom	S.F.
Instance	General Office
Instance Condition	4 - Between Fair and Poor
Instance Quantity	1
Instance Quantity Uom	EACH
Model	N/A
Installation Year	1954
Source of Installation	Documented
Deficiency	SYSTEM DEFECTIVE

Building Condition Assessment Survey 2023 - 2024

Question	Response
PUBLIC ADDRESS SYSTEM	
Deficiency Location/Instance	General Office - Room 127
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE SYSTEM
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
SECURITY	Inspected
IPDVS/CCTV System	Under Construction
Intrusion Alarm System	
	Inspected
Replacement Quantity	134,000
Replacement Uom	S.F.
Central Control Panel	Inspected
Instance	Closet Room 135
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	N/A
Installation Year	1999
Source of Installation	Documented
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3 - Fair
Deficiency	SIREN/STROBE NOT OPERATIONAL
Deficiency Location/Instance	Exterior Wall facing 257th Street
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Lighting - Security	Inaccessible
SERVICE SWITCH	Inspected
Instance	Electrical Room B25
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Instance Quantity Uom	EACH
mounte Quantity Colli	Li CII

Building Condition Assessment Survey 2023 - 2024

Question	Response
SERVICE SWITCH	
Instance Manufacturer	All City Switchboard
Equipment	Service Switch #1
Capacity/Size Quantity	2,500
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2013
Source of Installation	Documented
Deficiency	No deficiencies recorded
SWITCHBOARD	Inspected
Number of Spares	3
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room B25
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	All City Switchboard
Equipment	N/A
Capacity/Size Quantity	2,500
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	5
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Service Switch Size
Installation Year	2013
Source of Installation	Documented
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Does not Exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
TRANSFORMER	Does not Exist