

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Architectural Inspection

Q197

Asset: P.S. 197 - QUEENS, 825 HICKSVILLE ROAD, New York, 11691

Inspection Id	Inspection Type	Time In	Last Edited
SA : Q197	Architectural - Senior	2024-05-01 8:09 AM	2024-05-07 4:32 PM
AA : Q197	Architectural - Associate	2024-05-01 7:53 AM	2024-05-10 4:46 PM

Asset Data

Question	Answer
Was the building fully accessible for inspection	No
Inspection Access Comment	1st Floor Locker Room, 1st Floor Shower Room (Storage)
Building Square Footage	77,000
Comments on the Area (for Athletic Field, Playing Surfaces, Leased Spaces)	None
Comments on the Stories (Floors) plus Basements	3+B
Comments on the Number of Classrooms	36
Comments on the Year Built	1963
Student Population	419
Staff Population	60
Weather	Fair
Principal(s) Information	
Principal Name	Christina Villavicencio
Organization	P.S. 197 - Queens
Did you meet with this Principal?	No
Did this Principal provide feedback?	Yes
Summary of Principal's Feedback	A Principal questionnaire form was returned with the following comments: 1. The ventilation system is not working properly. 2. The Students and Staff Toilet Rooms need to be upgraded.
Custodian	Steven Olmsted
Fireman	Ali Omar
Facade Photo	




Corner of Beach 9th Street and Hicksville Road - Northeast view

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q197

Main Entrance Photo



Facade A - Hicksville Road

Roof Photo



Roof 1 - East view

Have any Systems/Major Building Components been upgraded?

Yes

Systems: Floor Structure - repairs

Year: 2023

Systems: Leaders/Gutters/Downspouts, Roof Drains, Roof Hatch, Roofing - replacement; Chimney - repairs; Skylight - covered

Year: 2020

Systems: Exterior Walls - repairs

Year: 2013

Systems: Exterior Doors and Frames - repairs

Year: 1998

Systems: Exterior Guards, Windows - replacement

Year: 1996

Have there been any Building Additions?

No

Tandem Schools?

No

Leased Space?

No



Priority Condition

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	PhotoImage
-------------------------------------	-------------------	-----------------------	--------------------	----------------------	--------------------	-----------------	------------

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Architectural Inspection

Q197

No	Tripping Hazard	Severely Heaving Concrete Flag is a tripping Hazard Condition	SITE PAVING DOT Sidewalk Concrete	Beach 8th Street, Beach 9th Street	Ali Omar	Fireman	
Yes	Potential Falling Debris	Severely Damaged and leaning Brick wall, next to Playground Retaining Wall	SITE SITE WALLS (NOT RETAINING WALLS)	South of Building (Between Play Ground and NYC Park)	Ali Omar	Fireman	

Structural Engineer Required

Structural Condition Type	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	PhotoImage
No condition recorded						

Programmatic Accessibility

Programmatic Accessibility Status Question	Response
Is the primary or secondary entrance on an accessible route?	No

Physical Breakdown Structure	Exists	Required	Complies	Deficiency	Assistive Listening System	Fire Alarm Strobe
------------------------------	--------	----------	----------	------------	----------------------------	-------------------

PROGRAMMATIC ACCESSIBILITY						
Exterior Routes						
Exterior Entrances & Exits			No	Saddle height > 1/2"		
Exterior H/C Lifts		No	No			
Exterior Ramps and Railings		No	Yes			
Interior Routes						
Corridor and Lobby H/C Lifts		No	Yes			
Interior Corridor Doors and Hardware		Yes	Yes			
Interior Corridors and Lobbies			No	Change in Elevation		
Interior Elevators		No				
Interior Lobby Doors and Hardware			Yes			
Interior Ramps		No				
Rooms & Spaces						
Art Rooms	Room 302	Yes	No	Not on Accessible Route		
Auditorium	1st Floor	Yes	No	No Stage Access	No	No
Cafeteria	Basement	Yes	No	Not on Accessible Route	No	No
Classrooms	None on Accessible Route	Yes	No	Not on Accessible Route		
Computer Rooms	Room 317	Yes	No	Not on Accessible Route		
Gymnasium	1st Floor	Yes	No	Not on Accessible Route	No	No
Library	Room 209	Yes	No	Not on Accessible Route		
Main Office	Room 120	Yes	No	Not on Accessible Route		
Multi-purpose Room		No				
Nurse's Room	Room 124	Yes	No	Not on Accessible Route		
Pool		No				


NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Architectural Inspection

Q197


Physical Breakdown Structure	Exists	Required	Complies	Deficiency	Assistive Listening System	Fire Alarm Strobe
Rooms & Spaces						
Science Lab	Room 217	Yes	No	Not on Accessible Route		
Toilet Rooms (Boys)	None on Accessible Route	Yes	No	Not on Accessible Route		
Toilet Rooms (Girls)	None on Accessible Route	Yes	No	Not on Accessible Route		
Toilet Rooms (Staff)	None on Accessible Route	Yes	No	Not on Accessible Route		

Building Template



Inspection

Question	Response
Architectural	
EXTERIOR	Inspected
AREAWAY	Does not Exist
AWNINGS AND CANOPIES	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
CHIMNEY	Inspected
Material Type(s)	Masonry
Condition	3 - Fair
Deficiency	BRICK: DETERIORATED LADDER
Roof Plan reference	






Deficiency Quantity

1

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q197

Question	Response
EXTERIOR	
CHIMNEY	
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Roof 1 - Chimney No violations recorded.
COPING	Does not Exist
CORNICE	Does not Exist
DOORS	Inspected
DOORS AND FRAMES	Inspected
Condition	5 - Poor
Deficiency	METAL: DETERIORATED DOOR AND FRAME - MAJOR DETERIORATION
Roof Plan reference	
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Facade F No violations recorded.

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q197

Question	Response
----------	----------

EXTERIOR


DOORS

DOORS AND FRAMES

Deficiency

METAL CLAD: DETERIORATED DOOR AND FRAME - MAJOR DETERIORATION

Roof Plan reference



Deficiency Quantity

9

Quantity Uom

EACH

Potential Action

REPLACE


Urgency of Action

PRIORITY 4

Purpose of Action

LEVEL 2

Deficiency Photo1



Facade H

Violations

No violations recorded.

DOOR HARDWARE

Inspected

Condition

3 - Fair

Deficiency

No deficiencies recorded

LINTELS

Inspected

Condition

2 - Between Good and Fair

Deficiency

No deficiencies recorded

TRANSOM/SIDE LIGHT

Inspected

Condition

2 - Between Good and Fair

Deficiency

No deficiencies recorded

EXTERIOR WALLS

Inspected

Material Type(s)

Masonry, Concrete

Replacement Quantity

35,000

Replacement Uom

S.F.

Instance on All Facades

Inspected

Instance Condition

3 - Fair

Instance Quantity

35,000

Instance Quantity Uom

S.F.

Deficiency

BRICK: CRACKS/DISPLACED/SPALLED BRICK AT BUILDING CORNERS


Question

Response


EXTERIOR

EXTERIOR WALLS

Roof Plan reference



Elevation



Deficiency Quantity

20

Quantity Uom

S.F.

Potential Action

REMOVE AND REBUILD


Urgency of Action

PRIORITY 4

Purpose of Action

LEVEL 2

Deficiency Photo1



Facade C


No violations recorded.

Violations

Deficiency

BRICK: EFFLORESCENCE

Roof Plan reference



**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q197

Question

Response

EXTERIOR

EXTERIOR WALLS

Elevation



Deficiency Quantity

100

Quantity Uom

S.F.

Potential Action

MAINTENANCE

Urgency of Action

PRIORITY 1

Purpose of Action

LEVEL 1

Deficiency Photo1

No photo recorded


Violations

No violations recorded.


Deficiency

BRICK: MINOR CRACKS AND SPALLING

Roof Plan reference



Elevation



Deficiency Quantity

10

Quantity Uom

S.F.

Potential Action

RESTITCH

Urgency of Action

PRIORITY 3

Purpose of Action

LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q197

Question

Response

EXTERIOR

EXTERIOR WALLS

Deficiency Photo1



Facade H


No violations recorded.

Violations


Deficiency

CERAMIC TILE: CHIPPED, SPALLED, BROKEN PIECES

Roof Plan reference



Elevation



Deficiency Quantity

10

Quantity Uom

S.F.

Potential Action

REPLACE


Urgency of Action

PRIORITY 3

Purpose of Action

LEVEL 2

Deficiency Photo1



Facade H

No violations recorded.

Violations

Deficiency

BRICK: DETERIORATED MASONRY SILLS - MAJOR

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q197


Question

Response


EXTERIOR

EXTERIOR WALLS

Roof Plan reference



Elevation



Deficiency Quantity

20

Quantity Uom

L.F.

Potential Action

REMOVE AND REPLACE

Urgency of Action

PRIORITY 4

Purpose of Action

LEVEL 2

Deficiency Photo1



Facade H

No violations recorded.

Violations

EXTERIOR SOFFITS

Does not Exist

LOADING DOCK

Does not Exist

LOUVER

Inspected

Condition

3 - Fair

Deficiency

BROKEN/ DENTED BLADES

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q197


Question

Response


EXTERIOR

LOUVER

Roof Plan reference




Elevation



Deficiency Quantity
Quantity Uom
Potential Action
Urgency of Action
Purpose of Action
Deficiency Photo1

10
S.F.
REPLACE
PRIORITY 4
LEVEL 2



Facade C
No violations recorded.

Violations

PARAPETS

Does not Exist

PLAZA DECK

Does not Exist

ROOF

Inspected

Roofing

Inspected

Replacement Quantity

35,000

Replacement Uom

S.F.

ROOF HATCH/SMOKE HATCH

Inspected

Condition

1 - Good

Deficiency

No deficiencies recorded

LEADERS, GUTTERS, DOWNSPOUTS, SCUPPERS

Inspected

Condition

1 - Good

Deficiency

No deficiencies recorded



ROOF BARRIER/FENCE

Does not Exist

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Architectural Inspection

Q197

Question	Response
EXTERIOR	
ROOF	
Roofing	
ROOF BARRIER/FENCE	Does not Exist
ROOF CAGE	Does not Exist
ROOFING	Inspected
Instance on Modified Bitumen: All Roofs	Inspected
Instance Condition	3 - Fair
Instance Photo	
	Roof 1
Instance Quantity	35,000
Instance Quantity Uom	S.F.
Does the roof have major mechanical equipment sitting on Dunnage Steel less than 18" above the Roofing?	No
Does this roof instance have a Sustainable Roof System?	Yes
Sustainable Roof Type	White Roof
Sustainable Roof Location (Roof Number)	All Roofs
Do solar panels exist on these roofs?	No
Is/Are the roof(s) suitable for Solar Panel installation?	Yes
Installation Year	2020
Source of Installation	Custodial Staff
Deficiency	MODIFIED BITUMEN: ROOFING: MAJOR ACTIVE ROOF LEAKS IN INSTRUCTIONAL SPACE
Roof Plan reference	
Deficiency Quantity	200
Quantity Uom	S.F.
Potential Action	REPLACE ROOFING WITHOUT MAJOR EQUIPMENT REMOVAL
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q197

Question	Response
----------	----------

EXTERIOR

ROOF

Roofing

ROOFING

Deficiency Photo1

Inspected



Roof 3 - Corridor near Room 130 (Gymnasium) - two locations

No violations recorded.

Violations

ROOFING DRAINS

Inspected

Condition

1 - Good

Deficiency

No deficiencies recorded

Specialties

Inspected

BULKHEAD/PENTHOUSE

Does not Exist

CUPOLA/ SPIRES/ TOWERS

Does not Exist

DORMER

Does not Exist

DUNNAGE STEEL

Does not Exist

SKYLIGHT/ROOF VENT

Inspected

Material Type(s)

Other


Condition

3 - Fair

Deficiency

SHAFT VENTS DAMAGED

Roof Plan reference



Deficiency Quantity

1

Quantity Uom

EACH

Potential Action

MAINTENANCE

Urgency of Action

PRIORITY 3



Purpose of Action

LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection


Q197


Question	Response
EXTERIOR	
ROOF	
Specialties	
SKYLIGHT/ROOF VENT	Inspected
Deficiency Photo1	
	Roof 1
Violations	No violations recorded.
ROOF/GRAVITY TANK	Does not Exist
STAIRS/RAMPS: EXTERIOR	Inspected
BUILDING CHEEK/FLANK WALLS	Does not Exist
RAILINGS	Does not Exist
STAIRS/RAMPS	Inspected
Condition	4 - Between Fair and Poor
Deficiency	STONE: DETERIORATED SUBSTRATE
Roof Plan reference	
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE SUBSTRATE AND RESET
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Facade H
Violations	No violations recorded.
Deficiency	STONE: DETERIORATED JOINTS

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q197

Question	Response
EXTERIOR	
STAIRS/RAMPS: EXTERIOR	
STAIRS/RAMPS	
Roof Plan reference	
Deficiency Quantity	10
Quantity Uom	L.F.
Potential Action	REPOINT
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Facade H No violations recorded.
WINDOWS	Inspected
Replacement Quantity	6,600
Replacement Uom	S.F.
EXTERIOR GUARDS	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
LINTELS	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
WINDOWS	Inspected
Material Type(s)	Aluminum
Instance on Aluminum - Double Hung: All Facades	Inspected
Instance Condition	3 - Fair
Instance Quantity	6,600
Instance Quantity Uom	S.F.
Are these windows insulated	No
Installation Year	1996
Source of Installation	Custodial Staff
Deficiency	ALUMINUM - DOUBLE HUNG: INOPERABLE BALANCE



10
L.F.
REPOINT
PRIORITY 4
LEVEL 2



Facade H
No violations recorded.

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Architectural Inspection

Q197

Question	Response
INTERIOR	
AUDITORIUM	
Ceiling	
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Door(s)	
Instance on 1st Floor (425 Seats)	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Fixed H/C Lift	
Instance on 1st Floor (425 Seats)	Does not Exist
Fixed Seating	
Instance on 1st Floor (425 Seats)	Inspected
Condition	4 - Between Fair and Poor
Deficiency	DAMAGED/BROKEN/INOPERABLE
Deficiency Location/Instance	Seats A/2, B/2, E/101, F/2, O/4, and others
Deficiency Quantity	35
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	No violations recorded.
Floor Finish	
Instance on 1st Floor (425 Seats)	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Sliding-folding Partition	
Instance on 1st Floor (425 Seats)	Does not Exist
Stage	
Instance on 1st Floor (425 Seats)	Inspected
Stage	
Instance on 1st Floor (425 Seats)	Inspected
Condition	2 - Between Good and Fair
Deficiency	DAMAGED STEPS
Deficiency Location/Instance	Front
Deficiency Quantity	20
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q197

Question	Response
----------	----------

INTERIOR

AUDITORIUM

Stage

Stage

Deficiency Photo1



Front

Violations

No violations recorded.

Stage Curtain Rigging

Inspected

Instance on 1st Floor (425 Seats)

Inspected

Condition

2 - Between Good and Fair

Deficiency

No deficiencies recorded

Stage Curtains

Inspected

Instance on 1st Floor (425 Seats)

Inspected

Condition

2 - Between Good and Fair

Deficiency

No deficiencies recorded

Walls

Instance on 1st Floor (425 Seats)

Inspected

Condition

2 - Between Good and Fair

Deficiency

No deficiencies recorded

Window Curtains/Shades/Blinds

Instance on 1st Floor (425 Seats)

Does not Exist

CAFETERIA

Inspected

Instance on Basement

Inspected

Ceiling

Instance on Basement

Inspected

Condition

2 - Between Good and Fair

Deficiency

PLASTER: CRACKS/SPALLING

Deficiency Location/Instance

Near Windows

Deficiency Quantity

10

Quantity Uom

S.F.

Potential Action

REPLACE

Urgency of Action

PRIORITY 3

Purpose of Action

LEVEL 2



Deficiency Photo1



**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q197

Question	Response
INTERIOR	
CAFETERIA	
Ceiling	
Violations	Near Windows No violations recorded.
Deficiency	ACOUSTIC TILES ON PLASTER: DAMAGED/MISSING
Deficiency Location/Instance	Near Center, Windows, Serving Area
Deficiency Quantity	80
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Near Serving Area No violations recorded.
Door(s)	
Instance on Basement	Inspected
Condition	4 - Between Fair and Poor
Deficiency	METAL: DETERIORATED DOOR AND FRAME
Deficiency Location/Instance	Entrance
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Entrance No violations recorded.
Fixed Equipment	
Instance on Basement	Does not Exist
Floor Finish	
Instance on Basement	Inspected
Condition	2 - Between Good and Fair
Deficiency	VINYL TILES: BROKEN/DETERIORATED/MISSING TILES

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q197

Question	Response
INTERIOR	
CAFETERIA	
Floor Finish	
Deficiency Location/Instance	Near Entrance
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Near Entrance No violations recorded.
Sliding-folding Partition	
Instance on Basement	Does not Exist
Stage	
Instance on Basement	Does not Exist
Walls	
Instance on Basement	Inspected
Condition	2 - Between Good and Fair
Deficiency	GLAZED BLOCK: CRACKS/SPALLING
Deficiency Location/Instance	Drinking Fountain Area
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Near Drinking Fountain Area No violations recorded.
Deficiency	PLASTER: CRACKS/SPALLING
Deficiency Location/Instance	Near Windows
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q197

Question	Response
INTERIOR	
CAFETERIA	
Walls	
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Near Windows
Violations	No violations recorded.
Window Curtains/Shades/Blinds	
Instance on Basement	Does not Exist
CLASSROOMS/CORRIDORS/ADMIN SPACES	
Ceiling	
Condition	Inspected
	2 - Between Good and Fair
Deficiency	ACOUSTIC TILES ON PLASTER: DAMAGED/MISSING
Deficiency Location/Instance	Room 108, Corridor near Rooms 203, 204, 205, 210, and others
Deficiency Quantity	200
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Corridor near Room 220
Violations	No violations recorded.
Deficiency	ACOUSTIC TILES: DAMAGED/MISSING - ACTIVE LEAK
Deficiency Location/Instance	Corridor near Room 130
Deficiency Quantity	40
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q197

Question	Response
----------	----------

INTERIOR

CLASSROOMS/CORRIDORS/ADMIN SPACES

Ceiling

Deficiency Photo1



Corridor near Room 130

Violations

No violations recorded.

Deficiency

ACOUSTIC TILES: DAMAGED/MISSING

Deficiency Location/Instance

Room 307

Deficiency Quantity

20

Quantity Uom

S.F.

Potential Action

REPLACE

Urgency of Action

PRIORITY 3

Purpose of Action

LEVEL 2

Deficiency Photo1



Room 307

Violations

No violations recorded.

Door(s)

Inspected

Condition

5 - Poor

Deficiency

WOOD: DETERIORATED DOOR

Deficiency Location/Instance

Rooms 106, 201, 213, 307, 322, and others

Deficiency Quantity

15

Quantity Uom

EACH

Potential Action

MAINTENANCE


Urgency of Action

PRIORITY 3

Purpose of Action

LEVEL 2



Deficiency Photo1



**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q197

Question	Response
INTERIOR	
CLASSROOMS/CORRIDORS/ADMIN SPACES	
Door(s)	Inspected
	Room 322
Violations	No violations recorded.
Floor Finish	Inspected
Condition	3 - Fair
Deficiency	TERRAZZO: CRACKS
Deficiency Location/Instance	Main Entrance lobby
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Main Entrance lobby No violations recorded.
Deficiency	VINYL TILES: BROKEN/DETERIORATED/MISSING TILES
Deficiency Location/Instance	Rooms 103, 115, 303, 304, 317, and others
Deficiency Quantity	1,300
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Room 115 No violations recorded.
Walls	Inspected
Condition	2 - Between Good and Fair
Deficiency	BRICK: CRACKS/SPALLING
Deficiency Location/Instance	Corridor near Rooms B19, 128
Deficiency Quantity	20
Quantity Uom	S.F.
Potential Action	REPLACE

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q197

Question	Response
----------	----------

INTERIOR

CLASSROOMS/CORRIDORS/ADMIN SPACES

Walls

Urgency of Action
Purpose of Action
Deficiency Photo1

PRIORITY 3
LEVEL 2




Corridor near Room B19
No violations recorded.

Violations

Deficiency
Deficiency Location/Instance
Deficiency Quantity
Quantity Uom
Potential Action
Urgency of Action
Purpose of Action
Deficiency Photo1

CERAMIC TILE: BROKEN/ MISSING
Corridor near Room 128
10
S.F.
REPLACE
PRIORITY 3
LEVEL 2



Corridor near Room 128
No violations recorded.

Violations

Deficiency
Deficiency Location/Instance
Deficiency Quantity
Quantity Uom
Potential Action
Urgency of Action
Purpose of Action
Deficiency Photo1



GLAZED BLOCK: CRACKS/SPALLING
Corridor near Rooms 210, 215
10
S.F.
REPLACE
PRIORITY 3
LEVEL 2



NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Architectural Inspection

Q197

Question	Response
INTERIOR	
CLASSROOMS/CORRIDORS/ADMIN SPACES	
Walls	
Violations	Corridor near Room 215 No violations recorded.
Deficiency	PLASTER: CRACKS/SPALLING
Deficiency Location/Instance	Room 108, 306, Corridor near Rooms 306, 312, 320, and others
Deficiency Quantity	200
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Corridor near Room 320 No violations recorded.
Specialties	Does not Exist
GYMNASIUM	
Instance on 1st Floor	Inspected
Ceiling	Inspected
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	PLASTER: CRACKS/SPALLING
Deficiency Location/Instance	Storage Room
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Storage Room No violations recorded.
Door(s)	
Instance on 1st Floor	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q197

Question	Response
INTERIOR	
GYMNASIUM	
Door(s)	
Condition	5 - Poor
Deficiency	WOOD: DETERIORATED DOOR
Deficiency Location/Instance	Entrances, Storage Room
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Entrance No violations recorded.
Fixed Equipment	
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Floor Finish	
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	VINYL TILES: BROKEN/DETERIORATED/MISSING TILES
Deficiency Location/Instance	Near Center, Windows, Drinking Fountain Area
Deficiency Quantity	30
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Near Drinking Fountain Area No violations recorded.
Seating	
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection



Q197

Question	Response
INTERIOR	
GYMNASIUM	
Seating	
Deficiency	No deficiencies recorded
Sliding-folding Partition	
Instance on 1st Floor	Does not Exist
Stage	
Instance on 1st Floor	Does not Exist
Walls	
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	GLAZED BLOCK: CRACKS/SPALLING
Deficiency Location/Instance	Near center, Windows
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Near center No violations recorded.
Window Curtains/Shades/Blinds	
Instance on 1st Floor	Does not Exist
INTERIOR DOOR HARDWARE	
Condition	3 - Fair
Deficiency	No deficiencies recorded
INTERIOR GUARDS	
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
KITCHEN	
Instance on Basement	Inspected
Ceiling	
Instance on Basement	Inspected
Condition	2 - Between Good and Fair
Deficiency	PLASTER: CRACKS/SPALLING
Deficiency Location/Instance	Storage Room
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Architectural Inspection

Q197

Question	Response
INTERIOR	
KITCHEN	
Ceiling	
Deficiency Photo1	
Violations	Storage Room No violations recorded.
Door(s)	
Instance on Basement	Inspected
Condition	5 - Poor
Deficiency	WOOD: DETERIORATED DOOR
Deficiency Location/Instance	Room B13
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Room B13 No violations recorded.
Deficiency	METAL: DETERIORATED DOOR AND FRAME
Deficiency Location/Instance	Mop Room, Storage Room
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q197

Question	Response
----------	----------

INTERIOR

KITCHEN

Door(s)

Deficiency Photo1



Mop Room

Violations

No violations recorded.

Floor Finish

Instance on Basement	Inspected
----------------------	-----------

Condition	5 - Poor
-----------	----------

Deficiency	CONCRETE: CRACKS
------------	------------------

Deficiency Location/Instance	Storage Rooms B6, B8
------------------------------	----------------------

Deficiency Quantity	60
---------------------	----

Quantity Uom	S.F.
--------------	------

Potential Action	REPLACE
------------------	---------

Urgency of Action	PRIORITY 3
-------------------	------------

Purpose of Action	LEVEL 2
-------------------	---------

Deficiency Photo1



Outside Storage Room

Violations

No violations recorded.

Deficiency	CERAMIC TILE: BROKEN/MISSING TILES
------------	------------------------------------

Deficiency Location/Instance	Near Center, Serving Area, Mop Area
------------------------------	-------------------------------------

Deficiency Quantity	100
---------------------	-----

Quantity Uom	S.F.
--------------	------

Potential Action	REPLACE
------------------	---------



Urgency of Action	PRIORITY 3
-------------------	------------

Purpose of Action	LEVEL 2
-------------------	---------

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q197

Question	Response
INTERIOR	
KITCHEN	
Floor Finish	
Deficiency Photo1	
Violations	Near Serving Area No violations recorded.
Walls	
Instance on Basement	Inspected
Condition	2 - Between Good and Fair
Deficiency	CERAMIC TILE: BROKEN/ MISSING
Deficiency Location/Instance	Columns, Near Entrance, Mop Room, Sink Area
Deficiency Quantity	30
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Near Serving Area No violations recorded.
LIBRARY	
Instance on Room 209	Inspected
Built-in Furnishing	
Instance on Room 209	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Ceiling	
Instance on Room 209	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Door(s)	
Instance on Room 209	Inspected
Condition	3 - Fair
Deficiency	WOOD: DETERIORATED DOOR
Deficiency Location/Instance	Entrance

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection


Q197

Question	Response
INTERIOR	
LIBRARY	
Door(s)	
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Entrance
Violations	No violations recorded.
Floor Finish	
Instance on Room 209	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Walls	
Instance on Room 209	Inspected
Condition	2 - Between Good and Fair
Deficiency	PLASTER: CRACKS/SPALLING
Deficiency Location/Instance	Near Entrance, Windows
Deficiency Quantity	20
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Near Windows
Violations	No violations recorded.
LOCKER ROOM	
Instance on 1st Floor	Inaccessible
MULTI-PURPOSE ROOM	
	Does not Exist
SCIENCE DEMO ROOM	
	Does not Exist
SCIENCE LAB	
Instance on Room 217	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q197

Question	Response
INTERIOR	
SCIENCE LAB	
Alternative use	No
Fixed Equipment	
Instance on Room 217	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
SCIENCE PREP ROOM	
Does not Exist	
SHOWER ROOM	
Inspected	
Instance on 1st Floor	Inaccessible
STAIRS/RAMPS: INTERIOR	
Inspected	
Do Letter Stair Signs Exist?	No
Ceiling	Inspected
Condition	2 - Between Good and Fair
Deficiency	ACOUSTIC TILES: DAMAGED/MISSING
Deficiency Location/Instance	Stair EF/2
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Stair EF/2
Violations	No violations recorded.
Door(s)	
Inspected	
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Partition	
Does not Exist	
Railings	
Inspected	
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Stairs and Landings	
Inspected	
Condition	4 - Between Fair and Poor
Deficiency	STONE: BROKEN/MISSING
Deficiency Location/Instance	Stairs G/Basement, 1, 2, EF/1, 2, and others
Deficiency Quantity	210
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q197

Question

Response

INTERIOR

STAIRS/RAMPS: INTERIOR

Stairs and Landings

Deficiency Photo1



Stair G/Basement

No violations recorded.

Violations

Deficiency

TERRAZZO: CRACKS

Deficiency Location/Instance

Main Entrance Vestibule, Near Cafeteria, Stair G/Vestibule

Deficiency Quantity

50

Quantity Uom

S.F.

Potential Action

REPLACE


Urgency of Action

PRIORITY 3

Purpose of Action

LEVEL 2

Deficiency Photo1



Main Entrance Vestibule

No violations recorded.

Violations

Deficiency

VINYL TILES: BROKEN/DETERIORATED/MISSING TILES

Deficiency Location/Instance

Stair D/3

Deficiency Quantity

10

Quantity Uom

S.F.

Potential Action

REPLACE

Urgency of Action

PRIORITY 3

Purpose of Action

LEVEL 2

Deficiency Photo1



Stair D/3

No violations recorded.

Violations

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection


Q197

Question	Response
INTERIOR	
STAIRS/RAMPS: INTERIOR	
Walls	Inspected
Condition	2 - Between Good and Fair
Deficiency	GLAZED BLOCK: CRACKS/SPALLING
Deficiency Location/Instance	Stairs D/1, EF/1, G/1, 2
Deficiency Quantity	30
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Stair G/1 No violations recorded.
TOILET ROOMS - STAFF	
Ceiling	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Door(s)	Inspected
Condition	5 - Poor
Deficiency	WOOD: DETERIORATED DOOR
Deficiency Location/Instance	Rooms B13 (Kitchen), 126, 128, 223, 323
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Room 323 No violations recorded.
Floor Finish	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Stalls	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection



Q197

Question	Response
INTERIOR	
TOILET ROOMS - STAFF	
Stalls	
Condition	5 - Poor
Deficiency	RUST - MAJOR
Deficiency Location/Instance	Rooms 126, 128, 223
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Room 126 No violations recorded.
Walls	
Condition	Inspected 2 - Between Good and Fair
Deficiency	PLASTER: CRACKS/SPALLING
Deficiency Location/Instance	Rooms 126, 128, 223, 323
Deficiency Quantity	40
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Room 223 No violations recorded.
Deficiency	CERAMIC TILE: BROKEN/ MISSING
Deficiency Location/Instance	Rooms 223, 323
Deficiency Quantity	20
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q197

Question	Response
INTERIOR	
TOILET ROOMS - STAFF	
Walls	
Deficiency Photo1	
Violations	Room 223 No violations recorded.
TOILET ROOMS - STUDENTS	
Ceiling	Inspected
Condition	2 - Between Good and Fair
Deficiency	ACOUSTIC TILES ON PLASTER: DAMAGED/MISSING
Deficiency Location/Instance	Room 106
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Room 106 No violations recorded.
Door(s)	
Condition	5 - Poor
Deficiency	METAL: DETERIORATED DOOR AND FRAME
Deficiency Location/Instance	Rooms B14, B16
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q197

Question	Response
----------	----------

INTERIOR

TOILET ROOMS - STUDENTS

Door(s)

Deficiency Photo1



Room B14

No violations recorded.

Violations

Deficiency

WOOD: DETERIORATED DOOR

Deficiency Location/Instance

Rooms 106, 110, 210, 310, 314, and others

Deficiency Quantity

10

Quantity Uom

EACH

Potential Action

MAINTENANCE


Urgency of Action

PRIORITY 3

Purpose of Action

LEVEL 2

Deficiency Photo1



Room 314

No violations recorded.

Violations

Floor Finish

Inspected

Condition

2 - Between Good and Fair

Deficiency

CERAMIC TILE: BROKEN/MISSING TILES

Deficiency Location/Instance

Rooms 110, 114, 210, 214, 314, and others

Deficiency Quantity

70

Quantity Uom

S.F.

Potential Action

REPLACE


Urgency of Action

PRIORITY 3

Purpose of Action

LEVEL 2



Deficiency Photo1



**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q197

Question	Response
INTERIOR	
TOILET ROOMS - STUDENTS	
Floor Finish	Inspected
	Room 214
Violations	No violations recorded.
Stalls	Inspected
Condition	4 - Between Fair and Poor
Deficiency	RUST - MAJOR
Deficiency Location/Instance	Gymnasium - Boys and Girls
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Gymnasium - Boys No violations recorded.
Walls	Inspected
Condition	2 - Between Good and Fair
Deficiency	PLASTER: CRACKS/SPALLING
Deficiency Location/Instance	Rooms 214, 310
Deficiency Quantity	20
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Room 310 No violations recorded.
Deficiency	CERAMIC TILE: BROKEN/ MISSING
Deficiency Location/Instance	Rooms 106, 110, 114, 310, 314, and others
Deficiency Quantity	50
Quantity Uom	S.F.
Potential Action	REPLACE

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q197

Question	Response
INTERIOR	
TOILET ROOMS - STUDENTS	
Walls	
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Gymnasium - Girls
Violations	No violations recorded.
LIFE SAFETY	Inspected
F.D. HOLDING AREA	Does not Exist
STEEL STAIRS	Does not Exist
SITE	Inspected
CONTAINERIZATION	Inspected
Condition	5 - Poor
Deficiency	CONCRETE PAD MISSING
Deficiency Location/Instance	Beach 8th Street
Deficiency Quantity	500
Quantity Uom	S.F.
Potential Action	INSTALL NEW
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	FENCING MISSING
Deficiency Location/Instance	Beach 8th Street
Deficiency Quantity	1,050
Quantity Uom	S.F.
Potential Action	INSTALL NEW
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	CONTAINER DAMAGED
Deficiency Location/Instance	Beach 8th Street
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Architectural Inspection

Q197

Question	Response
SITE	
CONTAINERIZATION	
Deficiency Photo1	
Violations	Beach 8th Street No violations recorded.
Drainage System for Asphalt	Inspected
Catch Basins/Manhole - Surrounded by asphalt	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Culverts - Asphalt Covering	Does not Exist
Drainage System for Concrete	Inspected
Catch Basins/Manhole - Surrounded by concrete	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Culverts - Concrete Covering	Does not Exist
Drainage System for Soil	Inspected
Catch Basins/Manhole - Surrounded by Soil	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Culverts - Soil Covering	Does not Exist
DRINKING FOUNTAINS	Does not Exist
FENCES	Inspected
Condition	3 - Fair
Deficiency	CHAIN LINK: DAMAGED POST/RAIL
Deficiency Location/Instance	Beach 8th Street, Beach 9th Street, Hicksville Road
Deficiency Quantity	270
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Beach 8th Street No violations recorded.

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection


Q197

Question	Response
SITE	
FENCES	
Deficiency	CONCRETE CURB: DAMAGED/DETERIORATED
Deficiency Location/Instance	Beach 8th Street, Beach 9th Street, Hicksville Road
Deficiency Quantity	175
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Beach 8th Street
Violations	No violations recorded.
IRRIGATION SYSTEM	
	Does not Exist
PAVING	
	Inspected
Student Non-Use	
Gravel Exists?	No
Asphalt	
	Does not Exist
Concrete	
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Pavers	
	Does not Exist
Student Use	
Gravel Exists?	No
Asphalt	
Condition	3 - Fair
Deficiency	CRACKS - MAJOR
Deficiency Location/Instance	Near Center, Exit 10, NYC Park
Deficiency Quantity	200
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Near Exit 10

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection


Q197

Question	Response
SITE	
PAVING	
Student Use	
Asphalt	Inspected
Violations	No violations recorded.
Concrete	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Pavers	Does not Exist
Site Sidewalks & Walkways	Inspected
Asphalt	Does not Exist
Concrete	Inspected
Condition	3 - Fair
Deficiency	DAMAGED/DETERIORATED/MISSING SECTIONS
Deficiency Location/Instance	Near Exits 1, 5, Playground
Deficiency Quantity	225
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Near Exit 1 No violations recorded.
Pavers	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
DOT Sidewalk	Inspected
Asphalt	Does not Exist
Concrete	Inspected
Condition	4 - Between Fair and Poor
Deficiency	HEAVING
Deficiency Location/Instance	Beach 8th Street, Beach 9th Street
Deficiency Quantity	100
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q197

Question	Response
SITE	
PAVING	Inspected
DOT Sidewalk	
Concrete	Inspected
Violations	No violations recorded.
Pavers	Does not Exist
PLAYGROUNDS	Inspected
Instance on South of building	Inspected
Benches	
Instance on South of building	Does not Exist
Fence	
Instance on South of building	Does not Exist
Pavement	
Instance on South of building	Does not Exist
Play Equipment	
Instance on South of building	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Safety Surfacing	
Instance on South of building	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Unpaved Area	
Instance on South of building	Does not Exist
PLAYING SURFACE	Does not Exist
RETAINING WALLS	Inspected
Are there any Retaining Walls 6' OR higher facing public street/sidewalk?	Yes
Condition	3 - Fair
Deficiency	CAST IN PLACE CONCRETE: DETERIORATED COPING STONE
Deficiency Location/Instance	Near Main Entrance, Hicksville Road
Deficiency Quantity	20
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Near Main Entrance
Violations	No violations recorded.
Deficiency	CAST IN PLACE CONCRETE: DETERIORATED CONTROL/EXPANSION JOINT
Deficiency Location/Instance	Between Playground and NYC Park

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q197

Question	Response
SITE	
RETAINING WALLS	
Deficiency Quantity	30
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Between Playground and NYC Park No violations recorded.
Deficiency	CAST IN PLACE CONCRETE: CRACKS/SPALLING - MAJOR
Deficiency Location/Instance	Hicksville Road, Playground, Beach 9th Street, Schoolyard
Deficiency Quantity	150
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Playground No violations recorded.
SEATING	Does not Exist
SITE WALLS (NOT RETAINING WALLS)	Inspected
Condition	4 - Between Fair and Poor
Deficiency	BRICK: CRACKS/SPALLING - MAJOR
Deficiency Location/Instance	South of Building (Between Play Ground Floor - Boys and NYC Park)
Deficiency Quantity	400
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection


Q197

Question	Response
----------	----------

SITE

SITE WALLS (NOT RETAINING WALLS)

Deficiency Photo1



South of Building (Between Play Ground Floor - Boys and NYC Park)

35671764P

Violations

STAIRS/RAMPS: EXTERIOR

Inspected

Railings

Inspected

Condition

4 - Between Fair and Poor

Deficiency

MISSING

Deficiency Location/Instance

Entrance Playground

Deficiency Quantity

20

Quantity Uom

L.F.

Potential Action

REPLACE


Urgency of Action

PRIORITY 5

Purpose of Action

LEVEL 6

Deficiency Photo1



Entrance Playground

No violations recorded.

Violations

Site Cheek/flank Walls

Inspected

Condition

2 - Between Good and Fair

Deficiency

No deficiencies recorded

Stairs/ramps

Inspected

Condition

2 - Between Good and Fair

Deficiency

No deficiencies recorded

ARTWORK

Inspected

Instance

Exterior - Side Entrance - Beach 9th Street - 11765

Instance Photo







Side Entrance - Beach 9th Street

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q197

Question	Response
ARTWORK	
Instance ID Artwork exist at stated location?	11765 Yes
Instance Instance Photo	Exterior - Entrance Wall - 21011 
	Entrance Wall
Instance ID Artwork exist at stated location?	21011 Yes
Instance Instance Photo	Exterior - Rear Entrance - 21012 
	Rear Entrance
Instance ID Artwork exist at stated location?	21012 Yes
Instance	Interior - Adjacent to Entrance - 21013
Instance ID Artwork exist at stated location?	21013 No
Instance Instance Photo	Exterior - Entrance - 11137 
	Entrance
Instance ID Artwork exist at stated location?	11137 Yes
Instance Instance Photo	Exterior - Rear Wall - 21622 
	Rear Wall
Instance ID Artwork exist at stated location?	21622 Yes