

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

Q208

Asset: P.S./I.S. 208 - QUEENS, 74-30 COMMONWEALTH BLVD, New York, 11426

Inspection Id	Inspection Type	Time In	Last Edited
EE : Q208	Electrical	2024-03-22 7:30 AM	2024-04-08 1:53 PM

Asset Data

Question	Answer
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration in Electrical Room?	No
Have any Systems/Major Building Components been upgraded?	Yes
	Systems: Motor Controller (Variable Frequency Drive), Retrofitted Security Lights (Pole Lights), Retrofitted LED Lighting (Kitchen Serving Area)
	Years: 2023
	Systems: Fire Alarm System (Magnetic Door Holder/Contactor)
	Years: 2023
	Systems: Retrofitted LED Lighting (Auditorium, Gymnasium), Intrusion Alarm System (Panic Switch)
	Years: 2022
	Systems: Fire Alarm System (Printer), LAN
	Years: 2020
	Systems: Students Cafeteria (Local Sound System)
	Years: 2019
	Systems: IPDVS/CCTV System
	Years: 2011
	Systems: Security Lights
	Years: 2003, 2019
	Systems: All Other Electrical Systems and Components
	Years: 2003

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	Yes
Are dedicated intercoms available in all of these spaces for use during a fire?	Yes
Are all dedicated intercoms operational?	Yes

Priority Condition

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
Yes	Water Leaks onto Electrical Equipment	N/A	Lighting Fixture	Stair A - Bulkhead	Andrew Robles	Fireman	Sent to DSF	
Yes	Intercom - Not Connected to Remote Monitoring Station	N/A	INTERCOM SYSTEM Elevator	Elevator - Device IDs :4P10663, 4P10664	Andrew Robles	Fireman	Sent to DSF	
Yes	Fire Alarm System - Defective	N/A	FIRE ALARM SYSTEM Main Panel Fire Alarm Control Panel (Electronic)	Main Entrance Lobby	Andrew Robles	Fireman	Sent to DSF	

Inspection

Question	Response
Electrical	

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

Q208

Question	Response
AUDITORIUM	Inspected
Instance on 1st Floor	Inspected
House Lighting	Inspected
Does a Chandelier exist?	No
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor	Inspected
Pendant Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Recessed Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Local Sound System	Inspected
Instance on 1st Floor	Inspected
Installation Year	2003
Source of Installation	Documented
Condition	3 - Fair
Deficiency	MICROPHONE / JACK NOT OPERATIONAL
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Projection System	Inspected
Is the projector on a cart or installed on the ceiling?	Ceiling
Instance on 1st Floor	Inspected
Condition	5 - Poor
Deficiency	VIDEO PROJECTOR IS NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Theater Lighting System	Inspected

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

Q208

Question	Response
AUDITORIUM	
Theater Lighting System	
Instance on 1st Floor	Inspected
Dimming System	
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Theater Lighting	
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
CAFETERIA	
	Inspected
Instance on 1st Floor - Staff	Inspected
Instance on 1st Floor - Students	Inspected
Lighting	
	Inspected
Instance on 1st Floor - Students	Inspected
Instance on 1st Floor - Staff	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor - Students	Inspected
Instance on 1st Floor - Staff	Inspected
Pendant Mounted	
	Does not Exist
Instance on 1st Floor - Students	Does not Exist
Instance on 1st Floor - Staff	Does not Exist
Surface Mounted	
	Does not Exist
Instance on 1st Floor - Students	Does not Exist
Instance on 1st Floor - Staff	Does not Exist
Recessed Mounted	
	Inspected
Instance on 1st Floor - Students	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on 1st Floor - Staff	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor - Students	Does not Exist
Instance on 1st Floor - Staff	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor - Students	Does not Exist
Instance on 1st Floor - Staff	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor - Students	Does not Exist
Instance on 1st Floor - Staff	Does not Exist
Local Sound System	
	Inspected
Instance on 1st Floor - Students	Inspected
Installation Year	2019
Source of Installation	Custodial Staff
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on 1st Floor - Staff	Does not Exist

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

Q208

Question	Response
CAFETERIA	
Projection System	Does not Exist
Instance on 1st Floor - Students	Does not Exist
Instance on 1st Floor - Staff	Does not Exist
Theater Lighting System	Does not Exist
Instance on 1st Floor - Students	Does not Exist
Instance on 1st Floor - Staff	Does not Exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	Inspected
Does a Chandelier exist?	No
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Surface Mounted	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	17
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Does not Exist
Recessed Mounted	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Lighting Fixture - LED	Does not Exist
COMPUTER LAB	
Lighting	Inspected
Instance on Room 210	Inspected
Power Panel	Yes
Lighting Fixture - Fluorescent	Inspected
Instance on Room 210	Inspected

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

Q208

Question	Response
COMPUTER LAB	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	Does not Exist
Instance on Room 210	Does not Exist
Surface Mounted	Does not Exist
Instance on Room 210	Does not Exist
Recessed Mounted	Inspected
Instance on Room 210	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Room 210	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 210	Does not Exist
Lighting Fixture - LED	
Instance on Room 210	Does not Exist
Raceway With Receptacles	
Instance on Room 210	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
GYMNASIUM	
Instance on 1st Floor	Inspected
Lighting	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Surface Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Recessed Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor	Inspected
Pendant Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Recessed Mounted	Does not Exist
Instance on 1st Floor	Does not Exist

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

Q208

Question	Response
GYMNASIUM	
Local Sound System	Inspected
Instance on 1st Floor	Inspected
Installation Year	2003
Source of Installation	Documented
Condition	3 - Fair
Deficiency	No deficiencies recorded
Projection System	Does not Exist
Instance on 1st Floor	Does not Exist
Scoreboard	Inspected
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Theater Lighting System	Does not Exist
Instance on 1st Floor	Does not Exist
KITCHEN	Inspected
Instance on 1st Floor	Inspected
Lighting	Inspected
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Surface Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Recessed Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor	Inspected
Pendant Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Surface Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Recessed Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
LIBRARY	Inspected
Instance on Room 213	Inspected
Lighting	Inspected
Instance on Room 213	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 213	Inspected

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

Q208

Question	Response
LIBRARY	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	Does not Exist
Instance on Room 213	Does not Exist
Surface Mounted	Does not Exist
Instance on Room 213	Does not Exist
Recessed Mounted	Inspected
Instance on Room 213	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Room 213	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 213	Does not Exist
Lighting Fixture - LED	
Instance on Room 213	Does not Exist
Raceway With Receptacles	Inspected
Instance on Room 213	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Projection System	Does not Exist
Instance on Room 213	Does not Exist
LOCKER ROOM	Inspected
Instance on 1st Floor - Boys, 1st Floor - Girls	Inspected
Alternative use	Yes
Lighting	Inspected
Instance on 1st Floor - Boys, 1st Floor - Girls	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor - Boys, 1st Floor - Girls	Inspected
Pendant Mounted	Does not Exist
Instance on 1st Floor - Boys, 1st Floor - Girls	Does not Exist
Surface Mounted	Does not Exist
Instance on 1st Floor - Boys, 1st Floor - Girls	Does not Exist
Recessed Mounted	Inspected
Instance on 1st Floor - Boys, 1st Floor - Girls	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor - Boys, 1st Floor - Girls	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor - Boys, 1st Floor - Girls	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor - Boys, 1st Floor - Girls	Does not Exist
MULTIPURPOSE ROOM	Does not Exist
SCIENCE DEMO ROOM	Does not Exist
SCIENCE LAB	Inspected
Instance on Room 315	Inspected
Power Panel	No
Alternative use	No

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

Q208

Question	Response
SCIENCE LAB	
Instance on Room 319	Inspected
Power Panel	Yes
Alternative use	Yes
Instance on Room 323	Inspected
Power Panel	No
Alternative use	No
Lighting	Inspected
Instance on Room 323	Inspected
Instance on Room 319	Inspected
Instance on Room 315	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 323	Inspected
Instance on Room 319	Inspected
Instance on Room 315	Inspected
Pendant Mounted	
Instance on Room 323	Does not Exist
Instance on Room 319	Does not Exist
Instance on Room 315	Does not Exist
Surface Mounted	
Instance on Room 323	Does not Exist
Instance on Room 319	Does not Exist
Instance on Room 315	Does not Exist
Recessed Mounted	
Instance on Room 323	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 319	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 315	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Room 323	Does not Exist
Instance on Room 319	Does not Exist
Instance on Room 315	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 323	Does not Exist
Instance on Room 319	Does not Exist
Instance on Room 315	Does not Exist
Lighting Fixture - LED	
Instance on Room 323	Does not Exist
Instance on Room 319	Does not Exist
Instance on Room 315	Does not Exist
Emergency Gas Shut-Off Valve	
Instance on Room 323	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

Q208

Question	Response
SCIENCE LAB	
Emergency Gas Shut-Off Valve	
Instance on Room 319	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 315	Does not Exist
Emergency Shut-Off Power	
Instance on Room 323	Does not Exist
Instance on Room 319	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 315	Does not Exist
Power Supply	
Instance on Room 323	Inspected
Instance on Room 319	Inspected
Instance on Room 315	Does not Exist
Instructor Unit	
Instance on Room 323	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 319	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Meter Demonstration Unit	
Instance on Room 323	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 319	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Student Unit	
Instance on Room 323	Does not Exist
Instance on Room 319	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Projection System	
Instance on Room 323	Does not Exist
Instance on Room 319	Does not Exist
Instance on Room 315	Does not Exist
SCIENCE PREP ROOM	
Instance on Rooms 315A, 321	Inspected
Power Panel	No
Alternative use	No
Lighting	
Instance on Rooms 315A, 321	Inspected
Lighting Fixture - Fluorescent	
Instance on Rooms 315A, 321	Inspected
Pendant Mounted	
Instance on Rooms 315A, 321	Does not Exist
Surface Mounted	
	Does not Exist

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

Q208

Question	Response
SCIENCE PREP ROOM	
Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	Does not Exist
Instance on Rooms 315A, 321	Does not Exist
Recessed Mounted	Inspected
Instance on Rooms 315A, 321	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Rooms 315A, 321	Does not Exist
Lighting Fixture - Incandescent	
Instance on Rooms 315A, 321	Does not Exist
Lighting Fixture - LED	
Instance on Rooms 315A, 321	Does not Exist
Emergency Gas Shut-Off Valve	Does not Exist
Instance on Rooms 315A, 321	Does not Exist
Emergency Shut-Off Power	Does not Exist
Instance on Rooms 315A, 321	Does not Exist
Power Supply	Does not Exist
Instance on Rooms 315A, 321	Does not Exist
SWIMMING POOL	Does not Exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Does not Exist
Recessed Mounted	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Does not Exist
Recessed Mounted	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Replacement Quantity	111,000
Replacement Uom	S.F.
Condition	3 - Fair

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

Q208

Question	Response
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not Exist
EMERGENCY GENERATOR SET	Inspected
Automatic Transfer Switch (ATS)	Inspected
Instance	ATS Room C5
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	ASCO
Equipment	Fire Alarm Automatic Transfer SW.
Capacity/Size Quantity	30
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2003
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	ATS Room C5
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	ASCO
Equipment	ATS
Capacity/Size Quantity	800
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2003
Source of Installation	Documented
Deficiency	No deficiencies recorded
Battery Charger	Inspected
Instance	Roof - Outdoor Generator Enclosure
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	La Marche
Equipment	Battery Charger
Capacity/Size Quantity	10
Capacity/Size UOM	AmpsDC
Capacity/Size2 Quantity	24
Capacity/Size2 UOM	VDC
Source of Capacity/Size	Inspector Estimate
Installation Year	2003
Source of Installation	Documented
Deficiency	No deficiencies recorded
Emergency Distribution Board	Inspected
Number of Spares	5
Fused Disconnect Switch Type	Inspected
Instance	ATS Room C5
Instance Condition	3 - Fair

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

Q208

Question	Response
EMERGENCY GENERATOR SET	Inspected
Emergency Distribution Board	
Fused Disconnect Switch Type	
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Electrotech
Equipment	EMDBHV SECT.1, 2
Capacity/Size Quantity	600
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	2
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Emergency Distribution Board Mains Size
Installation Year	2003
Source of Installation	Documented
Deficiency	No deficiencies recorded
Molded Case Circuit Breaker Type	Does not Exist
Diesel	Inspected
Instance	Roof - Outdoor Generator Enclosure
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Caterpillar
Equipment	Emergency Generator
Capacity/Size Quantity	625
Capacity/Size UOM	KVA
Capacity/Size2 Quantity	500
Capacity/Size2 UOM	KW
Capacity/Size3Quantity	752
Capacity/Size3 UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2003
Source of Installation	Documented
Deficiency	No deficiencies recorded
Natural Gas	Does not Exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not Exist
EMERGENCY LIGHTING	Inspected
Battery Pack	Does not Exist
Non Battery Pack	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	3 - Fair
Deficiency	FIXTURE LAMP NOT OPERATIONAL
Deficiency Location/Instance	Kitchen
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

Q208

Question	Response
EXIT LIGHT	
Battery Pack	
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	FIXTURE NOT OPERATIONAL
Deficiency Location/Instance	Corridor by Rooms (223, 318), Electrical Room C3, Rooms (C1, C10)
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 4
Deficiency Photo1	No photo recorded
Violations	35654953J, 35671981L
Non Battery Pack	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
EXIT/EMERGENCY LIGHT	
Does not Exist	
FIRE ALARM SYSTEM	
Inspected	
Replacement Quantity	111,000
Replacement Uom	S.F.
Bell/Horn	
Inspected	
Condition	3 - Fair
Deficiency	No deficiencies recorded
Strobe	
Inspected	
Condition	3 - Fair
Deficiency	No deficiencies recorded
Manual Pull Station	
Inspected	
Condition	3 - Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	
Inspected	
Condition	3 - Fair
Deficiency	No deficiencies recorded
Duct Smoke Detector	
Inspected	
Condition	3 - Fair
Deficiency	No deficiencies recorded
Area Smoke Detector	
Inspected	
Condition	3 - Fair
Deficiency	No deficiencies recorded
CO Detector	
Does not Exist	
Heat Detector	
Inspected	
Condition	3 - Fair
Deficiency	No deficiencies recorded
Elevator Recall	
Inspected	
Condition	3 - Fair
Deficiency	No deficiencies recorded
Magnetic Door Holder/Contactor	
Inspected	
Condition	1 - Good
Deficiency	No deficiencies recorded
Fused Cutout Panel	
Inspected	

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

Q208

Question	Response
FIRE ALARM SYSTEM	
Fused Cutout Panel	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Inspected
Instance	Auditorium Stage - Telecom Closet 151D
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Ademco
Equipment	Fire Alarm Communicator
Installation Year	2003
Source of Installation	Documented
Deficiency	No deficiencies recorded
Main Panel	Inspected
Bell At Panel	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Main Entrance Lobby
Instance Condition	4 - Between Fair and Poor
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Cerberus Pyrotronics
Equipment	Fire Alarm Control Panel
Model	MXL
Installation Year	2003
Source of Installation	Documented
Deficiency	SYSTEM DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR SYSTEM
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Fire Alarm Control Panel (Standard)	Does not Exist
Sub-Panel	Inspected
Bell At Panel	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Auditorium Stage
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Notifier
Equipment	Deluge Control Panel
Model	RP - 1001

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

Q208

Question	Response
FIRE ALARM SYSTEM	
Sub-Panel	
Fire Alarm Control Panel (Electronic)	
Installation Year	2003
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Auditorium Stage
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Siemens
Equipment	Emergency Control Panel
Model	MXL
Installation Year	2003
Source of Installation	Documented
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Does not Exist
Remote Annunciator	Inspected
Display Monitor	Does not Exist
Panel	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Printer	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Punch Register	Does not Exist
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Tamper Flow Switch/Chain	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Inspected
Elevator	Inspected
Condition	3 - Fair
Deficiency	NOT CONNECTED TO REMOTE MONITORING STATION
Deficiency Location/Instance	Elevator - Device IDs :4P10663, 4P10664
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	INSTALL CONNECTION
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Holding Area	Does not Exist
LAN	Inspected

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

Q208

Question	Response
LAN	
Local Distribution Frame (I/LDF)	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
MOTOR CONTROLLER	Inspected
Motor Control Center	Inspected
Instance	Air Handling Room C10
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Square D
Equipment	MCC-EQ C HV
Capacity/Size Quantity	600
Capacity/Size UOM	Amps
Capacity/Size2 Quantity	5
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Nameplate
Installation Year	2003
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Penthouse Mechanical Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Square D
Equipment	MCC-HVACPHV 600A MLO
Capacity/Size Quantity	600
Capacity/Size UOM	Amps
Capacity/Size2 Quantity	7
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Nameplate
Installation Year	2003
Source of Installation	Documented
Deficiency	No deficiencies recorded
Motor Starter/Contactor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	3 - Fair

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

Q208

Question	Response
PANEL BOARD	
Fused Disconnect Switch Type	Inspected
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not Exist
Fused Toggle Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Inspected
Condition	3 - Fair
Deficiency	NO SPARE
Deficiency Location/Instance	Room 318
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL NEW PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
PUBLIC ADDRESS SYSTEM	Inspected
Replacement Quantity	111,000
Replacement Uom	S.F.
Instance	Telecommunication Room 402
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Rauland Telecenter
Installation Year	2003
Source of Installation	Documented
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Classrooms and Corridors
Deficiency Quantity	11
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
SECURITY	Inspected
IPDVS/CCTV System	Inspected
Replacement Quantity	111,000
Replacement Uom	S.F.
Installation Year	2011
Source of Installation	Custodial Staff
Condition	3 - Fair
Deficiency	No deficiencies recorded
Intrusion Alarm System	Inspected
Replacement Quantity	111,000
Replacement Uom	S.F.
Central Control Panel	Inspected
Instance	Custodian's Office
Instance Condition	4 - Between Fair and Poor

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

Q208

Question	Response
SECURITY	
Intrusion Alarm System	
Central Control Panel	
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista-128B
Installation Year	2003
Source of Installation	Documented
Deficiency	PANEL NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Infrared Sensor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Lighting - Security	Inspected
Replacement Uom	EACH
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
SERVICE SWITCH	
Instance	Electrical Room C3
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Electrotech
Equipment	N/A
Capacity/Size Quantity	4,000
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2003
Source of Installation	Documented
Deficiency	No deficiencies recorded
SWITCHBOARD	
Number of Spares	6
Fused Disconnect Switch Type	
Instance	Electrical Room C3
Instance Condition	3 - Fair

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

Q208

Question	Response
SWITCHBOARD	
Fused Disconnect Switch Type	
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Electrotech
Equipment	N/A
Capacity/Size Quantity	4,000
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	2
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Service Switch Size
Installation Year	2003
Source of Installation	Documented
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Does not Exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
TRANSFORMER	Inspected
Instance	ATS Room C5
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Olsun Electric
Equipment	Transformer
Capacity/Size Quantity	150
Capacity/Size UOM	KVA
Source of Capacity/Size	Nameplate
Installation Year	2003
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room C3
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Olsun Electric
Equipment	750KVA XFMR
Capacity/Size Quantity	750
Capacity/Size UOM	KVA
Source of Capacity/Size	Nameplate
Installation Year	2003
Source of Installation	Documented
Deficiency	No deficiencies recorded