

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

Q229

Asset: P.S. 229 - QUEENS, 67-25 51 ROAD, New York, 11377

| Inspection Id | Inspection Type | Time In | Last Edited |
|---------------|-----------------|--------------------|--------------------|
| EE : Q229 | Electrical | 2024-02-12 7:42 AM | 2024-06-13 8:44 AM |

Asset Data

| Question | Answer |
|---|--|
| Type of Service | Below Ground |
| Does Interactive Whiteboard (IWB) Exist? | Yes |
| Water Penetration in Electrical Room? | Yes |
| Have any Systems/Major Building Components been upgraded? | Yes |
| | Systems: Fire Alarm System |
| | Years: Under Construction |
| | Systems: LAN, Transformer |
| | Years: 2021 |
| | Systems: Auditorium (Local Sound System, Projection System), Exit Lights |
| | Years: 2019 |
| | Systems: Interior Lighting - Except (New Wing, Library - Fluorescent Lighting), IPDVS/CCTV system |
| | Years: 2016 |
| | Systems: Library (Fluorescent Lighting) |
| | Years: 2009 |
| | Systems: Auditorium (Theater Lighting System) |
| | Years: 2008 |
| | Systems: Partial Fused Disconnect Switch Type Panel Board |
| | Years: 2007 |
| | Systems: Intrusion Alarm System |
| | Years: 2006 |
| | Systems: Security Lights |
| | Years: 1999, 2013, 2022 |
| | Systems: Fluorescent Lighting (New Wing), Emergency Light/Exit Light Panel, Public Address System, Partial Service Switch, Partial Switchboard |
| | Years: 1999 |
| | Systems: Most Molded Case Circuit Breaker Type Panel Board |
| | Years: 1987, 1999, 2003, 2007, 2019, 2021 |

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

| Question | Response |
|---|----------|
| Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building? | No |

Priority Condition

| Priority Condition Exist Last Year? | Priority Category | Condition Description | Component Affected | Location Description | Person(s) Notified | Person(s) Title | Status | PhotoImage |
|-------------------------------------|---------------------------------------|-----------------------|----------------------|--------------------------------|--------------------|-----------------|-------------|------------|
| No | Water Penetration in Electrical Room | N/A | Electrical Equipment | Electrical Room G14 | Richard Gallino | Fireman | Sent to DSF | |
| No | Water Leaks onto Electrical Equipment | N/A | Electric Conduit | 1st Floor Corridor by Room 124 | Richard Gallino | Fireman | Sent to DSF | |

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Q229

Electrical Inspection

| | | | | | | |
|-----|--|-----|-----------------------------------|---|-------------------------|-------------|
| Yes | Emergency Lighting - Battery Not Operational | N/A | EMERGENCY LIGHTING Battery Pack | Auditorium, Cafeteria, Gymnasium, Multipurpose Room, Main Entrance Lobby, Main Entrance Vestibule, Ground Floor (Staircase D, Exit 7 Vestibule, Exit 8 Vestibule), 1st Floor - Exit 1/2 Vestibule, Staircase A at (Ground, 1st and 2nd Floors), Corridors by Rooms (G13, G16, G23, G29) | Richard Gallino Fireman | Sent to DSF |
|-----|--|-----|-----------------------------------|---|-------------------------|-------------|

Inspection

| Question | Response |
|--|---------------------------|
| Electrical | |
| AUDITORIUM | Inspected |
| Instance on Ground Floor | Inspected |
| House Lighting | Inspected |
| Does a Chandelier exist? | No |
| Instance on Ground Floor | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on Ground Floor | Inspected |
| Pendant Mounted | Does not Exist |
| Instance on Ground Floor | Does not Exist |
| Surface Mounted | Inspected |
| Instance on Ground Floor | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Recessed Mounted | Does not Exist |
| Instance on Ground Floor | Does not Exist |
| Lighting Fixture - HID | |
| Instance on Ground Floor | Does not Exist |
| Lighting Fixture - Incandescent | |
| Instance on Ground Floor | Does not Exist |
| Lighting Fixture - LED | |
| Instance on Ground Floor | Inspected |
| Pendant Mounted | Inspected |
| Instance on Ground Floor | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Surface Mounted | Does not Exist |
| Instance on Ground Floor | Does not Exist |
| Recessed Mounted | Inspected |
| Instance on Ground Floor | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Local Sound System | Inspected |

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

Q229

| Question | Response |
|---|---------------------------|
| AUDITORIUM | |
| Local Sound System | |
| Instance on Ground Floor | Inspected |
| Installation Year | 2019 |
| Source of Installation | Custodial Staff |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Projection System | |
| Is the projector on a cart or installed on the ceiling? | Ceiling |
| Instance on Ground Floor | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| Theater Lighting System | |
| Instance on Ground Floor | Inspected |
| Dimming System | |
| Instance on Ground Floor | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Theater Lighting | |
| Instance on Ground Floor | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| CAFETERIA | |
| Instance on Ground Floor - Staff | Inspected |
| Instance on Ground Floor - Students | Inspected |
| Lighting | |
| Instance on Ground Floor - Students | Inspected |
| Instance on Ground Floor - Staff | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on Ground Floor - Students | Does not Exist |
| Instance on Ground Floor - Staff | Inspected |
| Pendant Mounted | |
| Instance on Ground Floor - Staff | Does not Exist |
| Surface Mounted | |
| Instance on Ground Floor - Staff | Does not Exist |
| Recessed Mounted | |
| Instance on Ground Floor - Staff | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Lighting Fixture - HID | |
| Instance on Ground Floor - Students | Does not Exist |
| Instance on Ground Floor - Staff | Does not Exist |
| Lighting Fixture - Incandescent | |
| Instance on Ground Floor - Students | Does not Exist |
| Instance on Ground Floor - Staff | Does not Exist |
| Lighting Fixture - LED | |
| Instance on Ground Floor - Students | Inspected |
| Instance on Ground Floor - Staff | Does not Exist |
| Pendant Mounted | |
| | Does not Exist |

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

Q229

| Question | Response |
|--|------------------------------------|
| CAFETERIA | |
| Lighting | |
| Lighting Fixture - LED | |
| Pendant Mounted | Does not Exist |
| Instance on Ground Floor - Students | Does not Exist |
| Surface Mounted | Inspected |
| Instance on Ground Floor - Students | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Recessed Mounted | Inspected |
| Instance on Ground Floor - Students | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Local Sound System | Inspected |
| Instance on Ground Floor - Students | Inspected |
| Installation Year | 1999 |
| Source of Installation | Documented |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Instance on Ground Floor - Staff | Does not Exist |
| Projection System | Does not Exist |
| Instance on Ground Floor - Students | Does not Exist |
| Instance on Ground Floor - Staff | Does not Exist |
| Theater Lighting System | Does not Exist |
| Instance on Ground Floor - Students | Does not Exist |
| Instance on Ground Floor - Staff | Does not Exist |
| CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE | |
| Lighting | Inspected |
| Does a Chandelier exist? | No |
| Lighting Fixture - Fluorescent | Inspected |
| Pendant Mounted | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | LIGHTING FIXTURE BALLAST DEFECTIVE |
| Deficiency Quantity | 2 |
| Quantity Uom | EACH |
| Potential Action | REPLACE BALLAST |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Surface Mounted | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | LIGHTING FIXTURE BALLAST DEFECTIVE |
| Deficiency Quantity | 2 |
| Quantity Uom | EACH |
| Potential Action | REPLACE BALLAST |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

Q229

| Question | Response |
|--|------------------------------------|
| CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE | |
| Lighting | |
| Lighting Fixture - Fluorescent | |
| Surface Mounted | Inspected |
| Violations | No violations recorded. |
| Recessed Mounted | Inspected |
| Condition | 3 - Fair |
| Deficiency | LIGHTING FIXTURE BALLAST DEFECTIVE |
| Deficiency Quantity | 3 |
| Quantity Uom | EACH |
| Potential Action | REPLACE BALLAST |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Lighting Fixture - HID | Does not Exist |
| Lighting Fixture - Incandescent | Does not Exist |
| Lighting Fixture - LED | Inspected |
| Pendant Mounted | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Surface Mounted | Does not Exist |
| Recessed Mounted | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| COMPUTER LAB | |
| Instance on Room 225 | Inspected |
| Power Panel | Yes |
| Instance on Room 258 | Inspected |
| Power Panel | Yes |
| Lighting | Inspected |
| Instance on Room 258 | Inspected |
| Instance on Room 225 | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on Room 258 | Inspected |
| Instance on Room 225 | Inspected |
| Pendant Mounted | Does not Exist |
| Instance on Room 258 | Does not Exist |
| Instance on Room 225 | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Surface Mounted | Does not Exist |
| Instance on Room 258 | Does not Exist |
| Instance on Room 225 | Does not Exist |
| Recessed Mounted | Inspected |
| Instance on Room 258 | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Instance on Room 225 | Does not Exist |

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

Q229

| Question | Response |
|--|------------------------------------|
| COMPUTER LAB | |
| Lighting | |
| Lighting Fixture - HID | |
| Instance on Room 258 | Does not Exist |
| Instance on Room 225 | Does not Exist |
| Lighting Fixture - Incandescent | |
| Instance on Room 258 | Does not Exist |
| Instance on Room 225 | Does not Exist |
| Lighting Fixture - LED | |
| Instance on Room 258 | Does not Exist |
| Instance on Room 225 | Does not Exist |
| Raceway With Receptacles | Inspected |
| Instance on Room 258 | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Instance on Room 225 | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| GYMNASIUM | Inspected |
| Instance on Ground Floor | Inspected |
| Lighting | Inspected |
| Instance on Ground Floor | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on Ground Floor | Does not Exist |
| Lighting Fixture - HID | |
| Instance on Ground Floor | Does not Exist |
| Lighting Fixture - Incandescent | |
| Instance on Ground Floor | Does not Exist |
| Lighting Fixture - LED | |
| Instance on Ground Floor | Inspected |
| Pendant Mounted | Does not Exist |
| Instance on Ground Floor | Does not Exist |
| Surface Mounted | Inspected |
| Instance on Ground Floor | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | LIGHTING FIXTURE BALLAST DEFECTIVE |
| Deficiency Quantity | 2 |
| Quantity Uom | EACH |
| Potential Action | REPLACE BALLAST |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo | No photo recorded |
| Violations | No violations recorded. |
| Recessed Mounted | Does not Exist |
| Instance on Ground Floor | Does not Exist |
| Local Sound System | Inspected |
| Instance on Ground Floor | Inspected |
| Installation Year | 1999 |
| Source of Installation | Documented |

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

Q229

| Question | Response |
|--|---------------------------|
| GYMNASIUM | |
| Local Sound System | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Projection System | Does not Exist |
| Instance on Ground Floor | Does not Exist |
| Scoreboard | Does not Exist |
| Instance on Ground Floor | Does not Exist |
| Theater Lighting System | Does not Exist |
| Instance on Ground Floor | Does not Exist |
| KITCHEN | |
| Instance on Ground Floor | Inspected |
| Lighting | Inspected |
| Instance on Ground Floor | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on Ground Floor | Inspected |
| Pendant Mounted | Does not Exist |
| Instance on Ground Floor | Does not Exist |
| Surface Mounted | Does not Exist |
| Instance on Ground Floor | Does not Exist |
| Recessed Mounted | Inspected |
| Instance on Ground Floor | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Lighting Fixture - HID | |
| Instance on Ground Floor | Does not Exist |
| Lighting Fixture - Incandescent | |
| Instance on Ground Floor | Does not Exist |
| Lighting Fixture - LED | |
| Instance on Ground Floor | Does not Exist |
| LIBRARY | |
| Instance on Room 223 | Inspected |
| Lighting | Inspected |
| Instance on Room 223 | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on Room 223 | Inspected |
| Pendant Mounted | Inspected |
| Instance on Room 223 | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Surface Mounted | Does not Exist |
| Instance on Room 223 | Does not Exist |
| Recessed Mounted | Does not Exist |
| Instance on Room 223 | Does not Exist |
| Lighting Fixture - HID | |
| Instance on Room 223 | Does not Exist |
| Lighting Fixture - Incandescent | |
| Instance on Room 223 | Does not Exist |
| Lighting Fixture - LED | |

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

Q229

| Question | Response |
|--|---------------------------|
| LIBRARY | |
| Lighting | |
| Lighting Fixture - LED | |
| Instance on Room 223 | Inspected |
| Pendant Mounted | Does not Exist |
| Instance on Room 223 | Does not Exist |
| Surface Mounted | Does not Exist |
| Instance on Room 223 | Does not Exist |
| Recessed Mounted | Inspected |
| Instance on Room 223 | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Raceway With Receptacles | Does not Exist |
| Instance on Room 223 | Does not Exist |
| Projection System | Does not Exist |
| Instance on Room 223 | Does not Exist |
| LOCKER ROOM | Does not Exist |
| MULTIPURPOSE ROOM | Inspected |
| Instance on Ground Floor | Inspected |
| Lighting | Inspected |
| Instance on Ground Floor | Inspected |
| Lighting Fixture - Fluorescent | |
| Instance on Ground Floor | Inspected |
| Pendant Mounted | Does not Exist |
| Instance on Ground Floor | Does not Exist |
| Surface Mounted | Does not Exist |
| Instance on Ground Floor | Does not Exist |
| Recessed Mounted | Inspected |
| Instance on Ground Floor | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Lighting Fixture - HID | |
| Instance on Ground Floor | Does not Exist |
| Lighting Fixture - Incandescent | |
| Instance on Ground Floor | Does not Exist |
| Lighting Fixture - LED | |
| Instance on Ground Floor | Does not Exist |
| Local Sound System | Does not Exist |
| Instance on Ground Floor | Does not Exist |
| Projection System | Does not Exist |
| Instance on Ground Floor | Does not Exist |
| Theater Lighting System | Does not Exist |
| Instance on Ground Floor | Does not Exist |
| SCIENCE DEMO ROOM | Does not Exist |
| SCIENCE LAB | Does not Exist |
| SCIENCE PREP ROOM | Does not Exist |
| SWIMMING POOL | Does not Exist |
| TOILET ROOM - STAFF | Inspected |
| Lighting | Inspected |

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q229

| Question | Response |
|---|---|
| TOILET ROOM - STAFF | |
| Lighting | |
| Lighting Fixture - Fluorescent | Inspected |
| Pendant Mounted | Does not Exist |
| Surface Mounted | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Recessed Mounted | Does not Exist |
| Lighting Fixture - HID | Does not Exist |
| Lighting Fixture - Incandescent | Does not Exist |
| Lighting Fixture - LED | Does not Exist |
| TOILET ROOM - STUDENT | Inspected |
| Lighting | Inspected |
| Lighting Fixture - Fluorescent | Inspected |
| Pendant Mounted | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Surface Mounted | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Recessed Mounted | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Lighting Fixture - HID | Does not Exist |
| Lighting Fixture - Incandescent | Does not Exist |
| Lighting Fixture - LED | Does not Exist |
| AUXILIARY SIGNAL/BELL SYSTEM | Inspected |
| Replacement Quantity | 110,000 |
| Replacement Uom | S.F. |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| EMERGENCY DC STANDBY BATTERY POWER | Does not Exist |
| EMERGENCY GENERATOR SET | Does not Exist |
| EMERGENCY LIGHT/EXIT LIGHT PANEL | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| EMERGENCY LIGHTING | Inspected |
| Battery Pack | Inspected |
| Condition | 4 - Between Fair and Poor |
| Deficiency | BATTERY NOT OPERATIONAL |
| Deficiency Location/Instance | Auditorium, Cafeteria, Gymnasium, Multipurpose Room, Main Entrance Lobby, Main Entrance Vestibule, Ground Floor (Staircase D, Exit 7 Vestibule, Exit 8 Vestibule), 1st Floor - Exit 1/2 Vestibule, Staircase A at (Ground, 1st and 2nd Floors), Corridors by Rooms (G13, G16, G23, G29) |
| Deficiency Quantity | 20 |
| Quantity Uom | EACH |
| Potential Action | REPLACE BATTERY |
| Urgency of Action | PRIORITY 5 |
| Purpose of Action | LEVEL 6 |

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

Q229

| Question | Response |
|---|------------------------------------|
| EMERGENCY LIGHTING | |
| Battery Pack | |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Deficiency | FIXTURE NOT OPERATIONAL |
| Deficiency Location/Instance | Main Entrance Lobby |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 5 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Deficiency | FIXTURE LENS MISSING |
| Deficiency Location/Instance | 2nd Floor - Staircase A, Gymnasium |
| Deficiency Quantity | 2 |
| Quantity Uom | EACH |
| Potential Action | INSTALL LENS |
| Urgency of Action | PRIORITY 5 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Non Battery Pack | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| EXIT LIGHT | |
| | Inspected |
| Battery Pack | |
| Condition | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| Non Battery Pack | |
| | Does not Exist |
| EXIT/EMERGENCY LIGHT | |
| | Does not Exist |
| FIRE ALARM SYSTEM | |
| | Under Construction |
| GROUNDING SYSTEM | |
| | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| INTERCOM SYSTEM | |
| | Inspected |
| Elevator | |
| | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Holding Area | |
| | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| LAN | |
| | Inspected |
| Local Distribution Frame (I/LDF) | |
| | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |
| Main Equipment Rack (MDF) | |
| | Inspected |
| Condition | 1 - Good |
| Deficiency | No deficiencies recorded |

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

Q229

| Question | Response |
|---|---|
| LIGHTNING PROTECTION | Does not Exist |
| MOTOR CONTROLLER | Inspected |
| Motor Control Center | Does not Exist |
| Motor Starter/Contactor | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Variable Frequency Drive | Does not Exist |
| PANEL BOARD | Inspected |
| Fused Disconnect Switch Type | Inspected |
| Condition | 3 - Fair |
| Deficiency | PANEL BOARD BEYOND USEFUL LIFE |
| Deficiency Location/Instance | Boiler Room, Mechanical Room 126 |
| Deficiency Quantity | 3 |
| Quantity Uom | EACH |
| Potential Action | REPLACE-UPGRADE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Fused Knife Switch Type | Does not Exist |
| Fused Toggle Switch Type | Inspected |
| Condition | 3 - Fair |
| Deficiency | PANEL BOARD BEYOND USEFUL LIFE |
| Deficiency Location/Instance | Electrical Room G14 |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE-UPGRADE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Molded Case Circuit Breaker Type | Inspected |
| Condition | 3 - Fair |
| Deficiency | PANEL BOARD COVER IS MISSING |
| Deficiency Location/Instance | Auditorium Stage |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Deficiency | PANEL BOARD BEYOND USEFUL LIFE |
| Deficiency Location/Instance | Gymnasium, Cafeteria, Kitchen, Corridors by Rooms (G1, G13, G25, 103, 109, 121, 122, 129, 201A, 222, 225, 303, 322) |
| Deficiency Quantity | 16 |
| Quantity Uom | EACH |
| Potential Action | REPLACE-UPGRADE |
| Urgency of Action | PRIORITY 1 |

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

Q229

| Question | Response |
|---|----------------------------------|
| PANEL BOARD | |
| Molded Case Circuit Breaker Type | |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Deficiency | NO SPARE |
| Deficiency Location/Instance | 2nd Floor - Electrical Closet |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | INSTALL NEW PANEL BOARD |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Deficiency | NO SPARE |
| Deficiency Location/Instance | 1st Floor Corridor by Room 125 |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE PANEL BOARD |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Deficiency | PANEL BOARD DOOR LOCK IS MISSING |
| Deficiency Location/Instance | Electrical Room G14 |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | MAINTENANCE |
| Urgency of Action | PRIORITY 2 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| PUBLIC ADDRESS SYSTEM | Inspected |
| Replacement Quantity | 110,000 |
| Replacement Uom | S.F. |
| Instance | General Office |
| Instance Condition | 3 - Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Model | Rauland Telecenter |
| Installation Year | 1999 |
| Source of Installation | Documented |
| Deficiency | CLOCK NOT OPERATIONAL |
| Deficiency Location/Instance | Corridors and Classrooms |
| Deficiency Quantity | 9 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

Q229

| Question | Response |
|-------------------------------|------------------------------------|
| PUBLIC ADDRESS SYSTEM | Inspected |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| SECURITY | Inspected |
| IPDVS/CCTV System | Inspected |
| Replacement Quantity | 110,000 |
| Replacement Uom | S.F. |
| Installation Year | 2016 |
| Source of Installation | Inspector Estimate |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Intrusion Alarm System | Inspected |
| Replacement Quantity | 110,000 |
| Replacement Uom | S.F. |
| Central Control Panel | Inspected |
| Instance | Custodian's Office |
| Instance Condition | 3 - Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Model | Vista-128B |
| Installation Year | 2006 |
| Source of Installation | Inspector Estimate |
| Deficiency | No deficiencies recorded |
| Infrared Sensor | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Panic Switch | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Remote Annunciator | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Siren/Strobe | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Lighting - Security | Inspected |
| Replacement Uom | EACH |
| Condition | 2 - Between Good and Fair |
| Deficiency | LIGHTING FIXTURE BALLAST DEFECTIVE |
| Deficiency Location/Instance | Roof facing 67th Street |
| Deficiency Quantity | 3 |
| Quantity Uom | EACH |
| Potential Action | REPLACE BALLAST |
| Urgency of Action | PRIORITY 2 |
| Purpose of Action | LEVEL 3 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| SERVICE SWITCH | Inspected |
| Instance | Electrical Room G14 |

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

Q229

| Question | Response |
|-------------------------------------|--------------------------|
| SERVICE SWITCH | |
| Instance Condition | 3 - Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Instance Manufacturer | Lexington |
| Equipment | Main Switch 1600A Fuses |
| Capacity/Size Quantity | 1,600 |
| Capacity/Size UOM | Amps |
| Source of Capacity/Size | Fuse Size |
| Installation Year | 1967 |
| Source of Installation | Documented |
| Deficiency | No deficiencies recorded |
| Instance | Electrical Room G45D |
| Instance Condition | 3 - Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Instance Manufacturer | Square D |
| Equipment | Service Disconnect |
| Capacity/Size Quantity | 1,200 |
| Capacity/Size UOM | Amps |
| Source of Capacity/Size | Nameplate |
| Installation Year | 1999 |
| Source of Installation | Documented |
| Deficiency | No deficiencies recorded |
| SWITCHBOARD | Inspected |
| Number of Spares | 4 |
| Fused Disconnect Switch Type | Inspected |
| Instance | Electrical Room G14 |
| Instance Condition | 3 - Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Instance Manufacturer | Lexington |
| Equipment | N/A |
| Capacity/Size Quantity | 1,600 |
| Capacity/Size UOM | Amps Total |
| Capacity/Size2 Quantity | 2 |
| Capacity/Size2 UOM | Section(S) |
| Source of Capacity/Size | Nameplate |
| Installation Year | 1967 |
| Source of Installation | Documented |
| Deficiency | No deficiencies recorded |
| Instance | Electrical Room G45D |
| Instance Condition | 3 - Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Instance Manufacturer | Square D |
| Equipment | N/A |
| Capacity/Size Quantity | 1,200 |
| Capacity/Size UOM | Amps Total |

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

Q229

| Question | Response |
|---|--------------------------|
| SWITCHBOARD | |
| Fused Disconnect Switch Type | |
| Capacity/Size2 Quantity | 1 |
| Capacity/Size2 UOM | Section(S) |
| Source of Capacity/Size | Nameplate |
| Installation Year | 1999 |
| Source of Installation | Documented |
| Deficiency | No deficiencies recorded |
| Fused Knife Switch Type | |
| | Does not Exist |
| Molded Case Circuit Breaker Type | |
| | Does not Exist |
| TELEPHONE SYSTEM | |
| | Inspected |
| PBX/Intercom | |
| | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Standard | |
| | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| TRANSFORMER | |
| | Inspected |
| Instance | Room G12 |
| Instance Condition | 1 - Good |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Instance Manufacturer | Hammond Power Solutions |
| Equipment | Solar Transformer |
| Capacity/Size Quantity | 113 |
| Capacity/Size UOM | KVA |
| Source of Capacity/Size | Nameplate |
| Installation Year | 2021 |
| Source of Installation | Custodial Staff |
| Deficiency | No deficiencies recorded |