

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q266

**Asset:** P.S./I.S. 266 - QUEENS, 74-10 COMMONWEALTH BLVD, New York, 11426

Inspection Id	Inspection Type	Time In	Last Edited
SA : Q266	Architectural - Senior	2024-03-21 7:32 AM	2024-06-17 9:26 AM
AA : Q266	Architectural - Associate	2024-03-21 7:38 AM	2024-04-02 4:31 PM

**Asset Data**

Question	Answer
Was the building fully accessible for inspection	Yes
Building Square Footage	100,000
Comments on the Area (for Athletic Field, Playing Surfaces, Leased Spaces)	None
Comments on the Stories (Floors) plus Basements	3+B+PH
Comments on the Number of Classrooms	40
Comments on the Year Built	2003
Student Population	553
Staff Population	118
Weather	Fair
Principal(s) Information	

Principal Name	Ayanna Greenidge
Organization	P.S./I.S. 266 - Queens
Did you meet with this Principal?	No
Did this Principal provide feedback?	Yes
Summary of Principal's Feedback	Unit Coordinator Laurie Phillips provided comments on behalf of the Principal as follows: 1. The ductwork condensation drips into classrooms. 2. The HVAC system needs to be balanced. 3. Site fencing is in need of repairs. 4. An LED lighting upgrade is needed.

Principal Name	Jamie Allen
Organization	P224Q (District 75) - Queens
Did you meet with this Principal?	No
Did this Principal provide feedback?	Yes
Summary of Principal's Feedback	Assistant Principal Paul Winter provided comments on behalf of the Principal as follows: 1. The playground cracked surfaces need to be repaired. 2. The elevator cabs keep breaking down and need to be repaired or replaced. 3. The Fire Alarm panels are in trouble mode.

Custodian  
Fireman  
Facade Photo



**NYC Department of Education  
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q266

Main Entrance Photo

Facades A and J - North view



Roof Photo

Facade A - South view



Roof 1 - Northwest view

Have any Systems/Major Building Components been upgraded?

Yes  
 Systems: Exterior Doors - replacement (partial)  
 Year: 2023  
 Systems: Bulkhead - repairs (roofing)  
 Year: 2018  
 Systems: Roofing - repairs  
 Year: 2015  
 Systems: Roofing - repairs  
 Year: 2013  
 Systems: Exterior Walls - repairs  
 Year: 2012

Have there been any Building Additions?

No

Tandem Schools?

No

Leased Space?

No

**Priority Condition**

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	PhotoImage
-------------------------------------	-------------------	-----------------------	--------------------	----------------------	--------------------	-----------------	------------

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q266

No condition recorded

**Structural Engineer Required**

Structural Condition Type	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	PhotoImage
---------------------------	-----------------------	--------------------	----------------------	--------------------	-----------------	------------

No condition recorded

**Programmatic Accessibility**

Programmatic Accessibility Status Question	Response
Is the primary or secondary entrance on an accessible route?	Yes
Is the building a multi-story building?	Yes
Are all floors of the building accessible through compliant means?	Yes
Accessible classrooms exists on each floor?	Yes
Boys and Girls or Unisex accessible toilets exist on at least every other floor?	Yes
If the following spaces exist, are they ALL accessible? Art Room, Auditorium, Cafeteria, Computer, Gymnasiums, Library, Multipurpose Room, Science Labs	Yes

Physical Breakdown Structure	Exists	Required	Complies	Deficiency	Assistive Listening System	Fire Alarm Strobe
------------------------------	--------	----------	----------	------------	----------------------------	-------------------

**PROGRAMMATIC ACCESSIBILITY**

**Exterior Routes**

Exterior Entrances & Exits			Yes			
Exterior H/C Lifts	No	No				
Exterior Ramps and Railings	No	No				

**Interior Routes**

Corridor and Lobby H/C Lifts	No	No				
Interior Corridor Doors and Hardware	Yes		Yes			
Interior Corridors and Lobbies			Yes			
Interior Elevators	Yes		Yes			
Interior Lobby Doors and Hardware			Yes			
Interior Ramps	Yes		Yes			

**Rooms & Spaces**

Art Rooms	Room 315	Yes	Yes			
Auditorium	1st Floor	Yes	Yes		FM System	Yes
Cafeteria	1st Floor - Students, 1st Floor - Staff	Yes	Yes		FM System	Yes
Classrooms	1st-3rd Floor	Yes	Yes			
Computer Rooms	Room 212	Yes	Yes			
Gymnasium	1st Floor	Yes	Yes		FM System	Yes
Library	Room 215	Yes	Yes			
Main Office	Room 113A (P.S./I.S. 266), Room 134 (P224Q - District 75)	Yes	Yes			
Multi-purpose Room		No				
Nurse's Room	Room 128	Yes	Yes			
Pool		No				
Science Lab	Rooms 321, 325	Yes	Yes			
Toilet Rooms (Boys)	1st-3rd Floor	Yes	Yes			
Toilet Rooms (Girls)	1st-3rd Floor	Yes	Yes			
Toilet Rooms (Staff)	1st-3rd Floor	Yes	Yes			

**NYC Department of Education  
Building Condition Assessment Survey 2023 - 2024**


Architectural Inspection

Q266


Physical Breakdown Structure	Exists	Required	Complies	Deficiency	Assistive Fire Listening System	Fire Alarm Strobe
------------------------------	--------	----------	----------	------------	---------------------------------	-------------------

Building Template

**Q266**






Inspection

Question	Response
<b>Architectural</b>	
<b>EXTERIOR</b>	Inspected
<b>AREAWAY</b>	Inspected
Instance on AW1-AW10	Inspected
Instance Condition	3 - Fair
Instance Quantity	10
Instance Quantity Uom	EACH
Deficiency	AREAWAY WALLS: CRACKS AND SPALLING
Roof Plan reference	<b>Q266</b>
	
Deficiency Quantity	30
Quantity Uom	S.F.
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education  
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection




Q266

Question	Response
<b>EXTERIOR</b>	
<b>AREAWAY</b>	
Deficiency Photo1	
Violations	Facade A - AW1 No violations recorded.
<b>AWNINGS AND CANOPIES</b>	
Condition	Inspected
Deficiency	2 - Between Good and Fair No deficiencies recorded
<b>CHIMNEY</b>	
Material Type(s)	Inspected Metal
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>COPING</b>	
Condition	Inspected 3 - Fair
Deficiency	CAST STONE: DETERIORATED TRANSVERSE JOINTS
Roof Plan reference	Q266
	
Deficiency Quantity	50
Quantity Uom	L.F.
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Roof 2 No violations recorded.
<b>CORNICE</b>	
	Does not Exist

**NYC Department of Education  
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q266

Question	Response
<b>EXTERIOR</b>	
<b>DOORS</b>	Inspected
<b>DOORS AND FRAMES</b>	Inspected
Condition	4 - Between Fair and Poor
Deficiency	METAL: DETERIORATED DOOR AND FRAME - MAJOR DETERIORATION
Roof Plan reference	<p><b>Q266</b></p> 
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	<p>Facade E</p> <p>No violations recorded.</p>
Deficiency	METAL: DETERIORATED DOOR AND FRAME - MINOR DETERIORATION
Roof Plan reference	<p><b>Q266</b></p> 
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.



**NYC Department of Education  
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q266

Question	Response
----------	----------

**EXTERIOR**

**DOORS**

**DOOR HARDWARE**

Inspected

Condition

3 - Fair

Deficiency

No deficiencies recorded

**LINTELS**

Inspected

Condition

2 - Between Good and Fair

Deficiency

No deficiencies recorded

**TRANSOM/SIDE LIGHT**

Inspected

Condition

2 - Between Good and Fair

Deficiency

No deficiencies recorded

**EXTERIOR WALLS**

Inspected

Material Type(s)

Masonry

Replacement Quantity

50,000

Replacement Uom

S.F.

Instance on All Facades

Inspected

Instance Condition

3 - Fair

Instance Quantity

50,000

Instance Quantity Uom


S.F.

Deficiency

BRICK: MINOR CRACKS AND SPALLING

Roof Plan reference

Q266



Elevation



Deficiency Quantity

30

Quantity Uom

S.F.

Potential Action

RESTITCH

Urgency of Action

PRIORITY 3

Purpose of Action

LEVEL 2

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q266

**Question**

**Response**

**EXTERIOR**

**EXTERIOR WALLS**

Deficiency Photo1



Facade C

Violations


No violations recorded.

Deficiency

**BRICK: RELIEVING ANGLES - MAJOR DETERIORATION**

Roof Plan reference

**Q266**



Elevation



Deficiency Quantity

20

Quantity Uom

L.F.

Potential Action

REPLACE


Urgency of Action

PRIORITY 4

Purpose of Action

LEVEL 2

Deficiency Photo1



Facade F

Violations

No violations recorded.



**NYC Department of Education  
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q266

**Question**

**Response**

**EXTERIOR**


**EXTERIOR WALLS**

Deficiency


BRICK: CRACKS/DISPLACED/SPALLED BRICK AT BUILDING CORNERS

Roof Plan reference

**Q266**



Elevation



Deficiency Quantity

10

Quantity Uom

S.F.

Potential Action

REMOVE AND REBUILD


Urgency of Action

PRIORITY 4

Purpose of Action

LEVEL 2

Deficiency Photo1



Facade B

No violations recorded.

Violations

**EXTERIOR SOFFITS**

Inspected

Condition

2 - Between Good and Fair

Deficiency

CONCRETE: MINOR CRACKS/SPALLING

**NYC Department of Education  
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q266

**Question**


**Response**

**EXTERIOR**


**EXTERIOR SOFFITS**

Roof Plan reference

**Q266**



Elevation



Deficiency Quantity

30

Quantity Uom

S.F.

Potential Action

REPAIR

Urgency of Action

PRIORITY 3

Purpose of Action

LEVEL 2

Deficiency Photo1



Facade E

No violations recorded.

Violations

**LOADING DOCK**

Does not Exist

**LOUVER**

Inspected

Condition

2 - Between Good and Fair

Deficiency

No deficiencies recorded

**PARAPETS**

Inspected

Material Type(s)

Masonry

Replacement Quantity

8,000

Replacement Uom

C.F.

Instance on All Facades

Inspected

Instance Condition

4 - Between Fair and Poor

Instance Quantity

8,000

Instance Quantity Uom

C.F.

Deficiency

BRICK: MINOR CRACKS, SPALLING

**NYC Department of Education  
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q266

**Question**


**Response**

**EXTERIOR**

**PARAPETS**

Roof Plan reference

**Q266**



Deficiency Quantity

50

Quantity Uom

S.F.

Potential Action

REPAIR

Urgency of Action

PRIORITY 3

Purpose of Action

LEVEL 2

Deficiency Photo1



Roof 2

Violations


No violations recorded.

Deficiency

**BRICK: DETERIORATED JOINTS**

Roof Plan reference

**Q266**



Deficiency Quantity

100

Quantity Uom

S.F.

Potential Action

REPOINT

Urgency of Action

PRIORITY 4

Purpose of Action

LEVEL 2

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q266


**Question**

**Response**

**EXTERIOR**

**PARAPETS**

Deficiency Photo1



Roof 2

No violations recorded.


Violations

Deficiency

**BRICK: DETERIORATED JOINTS**

Roof Plan reference

**Q266**



Deficiency Quantity

10

Quantity Uom

S.F.

Potential Action

REPOINT


Urgency of Action

PRIORITY 3

Purpose of Action

LEVEL 2

Deficiency Photo1



Roof 8

No violations recorded.

Violations

Deficiency

**BRICK: EFFLORESCENCE**

**NYC Department of Education  
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q266


**Question**

**Response**

**EXTERIOR**

**PARAPETS**

Roof Plan reference



Deficiency Quantity  
Quantity Uom  
Potential Action  
Urgency of Action  
Purpose of Action  
Deficiency Photo  
Violations

1,000  
S.F.  
MAINTENANCE  
PRIORITY 1  
LEVEL 1  
No photo recorded  
No violations recorded.

**PLAZA DECK**

Does not Exist

**ROOF**

Inspected

**Roofing**

Inspected

Replacement Quantity

45,000

Replacement Uom

S.F.

**ROOF HATCH/SMOKE HATCH**

Inspected

Condition


5 - Poor

Deficiency

WATER INFILTRATION

Roof Plan reference

Q266



Deficiency Quantity  
Quantity Uom  
Potential Action  
Urgency of Action  
Purpose of Action

2  
EACH  
REPAIR  
PRIORITY 5  
LEVEL 2

**NYC Department of Education  
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q266




Question	Response
<b>EXTERIOR</b>	
<b>ROOF</b>	
<b>Roofing</b>	
<b>ROOF HATCH/SMOKE HATCH</b>	Inspected
Deficiency Photo1	
	Roof 1 - Bulkhead 1
Violations	No violations recorded.
<b>LEADERS, GUTTERS, DOWNSPOUTS, SCUPPERS</b>	Does not Exist
<b>ROOF BARRIER/FENCE</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>ROOF CAGE</b>	Does not Exist
<b>ROOFING</b>	Inspected
Instance on IRMA: All Roofs except Roof 4	Inspected
Instance Condition	3 - Fair
Instance Photo	
	Roof 1
Instance Quantity	40,000
Instance Quantity Uom	S.F.
Does the roof have major mechanical equipment sitting on Dunnage Steel less than 18" above the Roofing?	No
Does this roof instance have a Sustainable Roof System?	No
Do solar panels exist on these roofs?	No
Is/Are the roof(s) suitable for Solar Panel installation?	No
Installation Year	2003
Source of Installation	Custodial Staff
Deficiency	IRMA: FLASHING: CAP FLASHING MISSING
Roof Plan reference	<b>Q266</b> 
Deficiency Quantity	20



**NYC Department of Education  
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q266

Question	Response
<b>EXTERIOR</b>	
<b>ROOF</b>	
<b>Roofing</b>	
<b>ROOFING</b>	
Quantity Uom Potential Action Urgency of Action Purpose of Action Deficiency Photo1	L.F. INSTALL NEW PRIORITY 4 LEVEL 2 
Violations	Roof 7 No violations recorded.
Deficiency	IRMA: ROOFING: DAMAGED INSULATION
Roof Plan reference	Q266 
Deficiency Quantity Quantity Uom Potential Action Urgency of Action Purpose of Action Deficiency Photo1	20 S.F. REPLACE PRIORITY 4 LEVEL 2 
Violations	Roof 2 No violations recorded.
Deficiency	IRMA: FLASHING: CAP FLASHING DAMAGED

**NYC Department of Education  
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q266

**Question**

**Response**

**EXTERIOR**


**ROOF**

**Roofing**

**ROOFING**


Roof Plan reference

**Q266**



Deficiency Quantity  
Quantity Uom  
Potential Action  
Urgency of Action  
Purpose of Action  
Deficiency Photo1

10  
L.F.  
REPLACE  
PRIORITY 4  
LEVEL 2



Roof 2  
No violations recorded.


Violations

Deficiency

IRMA: FLASHING: PITCH POCKET DETERIORATED - MAJOR

Roof Plan reference

**Q266**



Deficiency Quantity  
Quantity Uom  
Potential Action  
Urgency of Action  
Purpose of Action

1  
EACH  
REPLACE  
PRIORITY 4  
LEVEL 2

**NYC Department of Education  
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q266

**Question**

**Response**

**EXTERIOR**

**ROOF**

**Roofing**

**ROOFING**

Deficiency Photo1



Roof 8

Violations


No violations recorded.

Deficiency

**IRMA: ROOFING: MAJOR ACTIVE ROOF LEAKS IN INSTRUCTIONAL SPACE**

Roof Plan reference

**Q266**



Deficiency Quantity

200

Quantity Uom

S.F.

Potential Action

**REPLACE ROOFING WITHOUT MAJOR EQUIPMENT REMOVAL**

Urgency of Action

**PRIORITY 5**

Purpose of Action

**LEVEL 2**

Deficiency Photo1



Roof 8 - Room 311, Stair C/3

Violations

No violations recorded.

Instance on Metal: Roof 4

Inspected

Instance Condition

2 - Between Good and Fair

**NYC Department of Education  
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q266

Question	Response
----------	----------


**EXTERIOR**

**ROOF**

**Roofing**

**ROOFING**

Instance Photo



Roof 4

Instance Quantity

5,000

Instance Quantity Uom

S.F.

Does the roof have major mechanical equipment sitting on Dunnage Steel less than 18" above the Roofing?

No

Does this roof instance have a Sustainable Roof System?

No

Do solar panels exist on these roofs?

No

Is/Are the roof(s) suitable for Solar Panel installation?

No

Installation Year

2003

Source of Installation

Custodial Staff

Deficiency

No deficiencies recorded

**ROOFING DRAINS**

Inspected

Condition


4 - Between Fair and Poor

Deficiency

DETERIORATED

Roof Plan reference

Q266



Deficiency Quantity

2

Quantity Uom

EACH

Potential Action

REPLACE

Urgency of Action

PRIORITY 4

Purpose of Action

LEVEL 2

Deficiency Photo1



Roof 2

Violations

No violations recorded.




**Specialties**

Inspected

**NYC Department of Education  
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q266

Question	Response
<b>EXTERIOR</b>	
<b>ROOF</b>	
<b>Specialties</b>	
<b>BULKHEAD/PENTHOUSE</b>	Inspected
Condition	3 - Fair
Deficiency	BULKHEAD/PENTHOUSE WALLS/INTERIOR: GYPSUM BOARD DAMAGED/DETERIORATED
Roof Plan reference	Q266
	
Deficiency Quantity	30
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Roof 1 - Bulkhead 1 No violations recorded.
Deficiency	BULKHEAD/PENTHOUSE WALLS/EXTERIOR: EFFLORESCENCE
Roof Plan reference	Q266
	
Deficiency Quantity	30
Quantity Uom	S.F.
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 1
Deficiency Photo1	No photo recorded

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q266



Question	Response
<b>EXTERIOR</b>	
<b>ROOF</b>	
<b>Specialties</b>	
<b>BULKHEAD/PENTHOUSE</b>	Inspected
Violations	No violations recorded.
<b>CUPOLA/ SPIRES/ TOWERS</b>	Does not Exist
<b>DORMER</b>	Does not Exist
<b>DUNNAGE STEEL</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>SKYLIGHT/ROOF VENT</b>	Does not Exist
<b>ROOF/GRAVITY TANK</b>	Does not Exist
<b>STAIRS/RAMPS: EXTERIOR</b>	Does not Exist
<b>WINDOWS</b>	Inspected
Replacement Quantity	5,500
Replacement Uom	S.F.
<b>EXTERIOR GUARDS</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>LINTELS</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>WINDOWS</b>	Inspected
Material Type(s)	Aluminum
Instance on Aluminum - Double Hung: All Facades	Inspected
Instance Condition	3 - Fair
Instance Quantity	5,400
Instance Quantity Uom	S.F.
Are these windows insulated	No
Installation Year	2003
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded
Instance on Aluminum - Other: Facade E	Inspected
Instance Condition	3 - Fair
Instance Quantity	100
Instance Quantity Uom	S.F.
Are these windows insulated	No
Installation Year	2003
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded
<b>INTERIOR</b>	Inspected
<b>POOLS</b>	Does not Exist
<b>STRUCTURAL</b>	Inspected
<b>COLUMNS/BEAMS/BEARING WALLS</b>	Inspected
Condition	3 - Fair
Deficiency	STEEL COLUMNS/BEAMS: DETERIORATED/MISSING SPRAY-ON FIREPROOFING
Deficiency Location/Instance	Mechanical Room 401, Basement- Crawl Space, Basement- Electrical Panel Room



**NYC Department of Education  
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection



Q266

Question	Response
<b>INTERIOR</b>	
<b>STRUCTURAL</b>	
<b>COLUMNS/BEAMS/BEARING WALLS</b>	
Deficiency Quantity	30
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 5
Deficiency Photo1	
	Mechanical Room 401
Violations	No violations recorded.
<b>FLOOR STRUCTURE</b>	
Condition	Inspected
	3 - Fair
Deficiency	CONCRETE SLAB ON GRADE: THRU CRACKS
Deficiency Location/Instance	Basement - Room C2
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 5
Deficiency Photo1	
	Basement - Room C2
Violations	No violations recorded.
Deficiency	METAL DECK AND CONCRETE: DETERIORATED
Deficiency Location/Instance	Basement - Crawl Space
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPAIR
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 5

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q266

Question	Response
<b>INTERIOR</b>	
<b>STRUCTURAL</b>	
<b>FLOOR STRUCTURE</b>	
Deficiency Photo1	
Violations	Basement - Crawl Space No violations recorded.
<b>FOUNDATION WALLS</b>	
Material Type(s)	Inspected Concrete
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>ROOF STRUCTURE</b>	
Condition	Inspected 3 - Fair
Deficiency	STEEL COLUMNS/BEAMS: DETERIORATED/MISSING SPRAY-ON FIREPROOFING
Deficiency Location/Instance	Roof 7 - Elevator Machine Room, Chiller Room 403
Deficiency Quantity	30
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 5
Deficiency Photo1	
Violations	Roof 7 - Elevator Machine Room No violations recorded.
<b>VAULTS-BUNKERS</b>	
	Does not Exist
<b>AUDITORIUM</b>	
Instance on 1st Floor (365 Seats)	Inspected Inspected
<b>Ceiling</b>	
Instance on 1st Floor (365 Seats)	Inspected
Condition	2 - Between Good and Fair
Deficiency	GYP SUM BOARD: DAMAGED/DETERIORATED
Deficiency Location/Instance	Near Room 141F
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE

**NYC Department of Education  
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q266

Question	Response
<b>INTERIOR</b>	
<b>AUDITORIUM</b>	
<b>Ceiling</b>	
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Near Room 141F
Violations	No violations recorded.
<b>Door(s)</b>	
Instance on 1st Floor (365 Seats)	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Fixed H/C Lift</b>	
Instance on 1st Floor (365 Seats)	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Fixed Seating</b>	
Instance on 1st Floor (365 Seats)	Inspected
Condition	3 - Fair
Deficiency	DAMAGED/BROKEN/INOPERABLE
Deficiency Location/Instance	Seats D/102, 113, J/113, 126, E/5, and others
Deficiency Quantity	14
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Seat D/102
Violations	No violations recorded.
<b>Floor Finish</b>	
Instance on 1st Floor (365 Seats)	Inspected
Condition	2 - Between Good and Fair
Deficiency	SHEET VINYL: BROKEN/DETERIORATED
Deficiency Location/Instance	Near Room 141G

**NYC Department of Education  
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q266

Question	Response
<b>INTERIOR</b>	
<b>AUDITORIUM</b>	
<b>Floor Finish</b>	
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Near Room 141G
Violations	No violations recorded.
<b>Sliding-folding Partition</b>	
Instance on 1st Floor (365 Seats)	Does not Exist
<b>Stage</b>	
Instance on 1st Floor (365 Seats)	Inspected
<b>Stage</b>	
Instance on 1st Floor (365 Seats)	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Stage Curtain Rigging</b>	
Instance on 1st Floor (365 Seats)	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Stage Curtains</b>	
Instance on 1st Floor (365 Seats)	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Walls</b>	
Instance on 1st Floor (365 Seats)	Inspected
Condition	2 - Between Good and Fair
Deficiency	MASONRY: CRACKS/SPALLING
Deficiency Location/Instance	Near Exit 9
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education  
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection



Q266

Question	Response
<b>INTERIOR</b>	
<b>AUDITORIUM</b>	
<b>Walls</b>	
Deficiency Photo1	
	Near Exit 9
Violations	No violations recorded.
Deficiency	BRICK: CRACKS/SPALLING
Deficiency Location/Instance	Near Exit 10
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Near Exit 10
Violations	No violations recorded.
<b>Window Curtains/Shades/Blinds</b>	
Instance on 1st Floor (365 Seats)	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>CAFETERIA</b>	
Instance on 1st Floor - Staff (500 SF)	Inspected
Instance on 1st Floor - Students	Inspected
<b>Ceiling</b>	
Instance on 1st Floor - Staff (500 SF)	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on 1st Floor - Students	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Door(s)</b>	
Instance on 1st Floor - Students	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q266

Question	Response
<b>INTERIOR</b>	
<b>CAFETERIA</b>	
<b>Door(s)</b>	
Instance on 1st Floor - Staff (500 SF)	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Fixed Equipment</b>	
Instance on 1st Floor - Staff (500 SF)	Does not Exist
Instance on 1st Floor - Students	Does not Exist
<b>Floor Finish</b>	
Instance on 1st Floor - Staff (500 SF)	Inspected
Condition	2 - Between Good and Fair
Deficiency	VINYL TILES: BROKEN/DETERIORATED/MISSING TILES
Deficiency Location/Instance	Near center, Entrance
Deficiency Quantity	30
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Near center No violations recorded.
Instance on 1st Floor - Students	Inspected
Condition	2 - Between Good and Fair
Deficiency	VINYL TILES: BROKEN/DETERIORATED/MISSING TILES
Deficiency Location/Instance	Near Entrance, Center, Columns, Windows
Deficiency Quantity	50
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Near center No violations recorded.



**NYC Department of Education  
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q266



Question	Response
<b>INTERIOR</b>	
<b>CAFETERIA</b>	
<b>Sliding-folding Partition</b>	
Instance on 1st Floor - Students	Does not Exist
Instance on 1st Floor - Staff (500 SF)	Does not Exist
<b>Stage</b>	
Instance on 1st Floor - Staff (500 SF)	Does not Exist
Instance on 1st Floor - Students	Does not Exist
<b>Walls</b>	
Instance on 1st Floor - Students	Inspected
Condition	2 - Between Good and Fair
Deficiency	GLAZED BLOCK: CRACKS/SPALLING
Deficiency Location/Instance	Column
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Column	
Violations	No violations recorded.
Instance on 1st Floor - Staff (500 SF)	Inspected
Condition	2 - Between Good and Fair
Deficiency	MASONRY: CRACKS/SPALLING
Deficiency Location/Instance	Near Entrance
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Near Entrance	
Violations	No violations recorded.

**Window Curtains/Shades/Blinds**

**NYC Department of Education  
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection



Q266

Question	Response
<b>INTERIOR</b>	
<b>CAFETERIA</b>	Inspected
<b>Window Curtains/Shades/Blinds</b>	
Instance on 1st Floor - Students	Does not Exist
Instance on 1st Floor - Staff (500 SF)	Does not Exist
<b>CLASSROOMS/CORRIDORS/ADMIN SPACES</b>	Inspected
<b>Ceiling</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	ACOUSTIC TILES: DAMAGED/MISSING - ACTIVE LEAK
Deficiency Location/Instance	Room 311
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Room 311 No violations recorded.
Deficiency	ACOUSTIC TILES: DAMAGED/MISSING
Deficiency Location/Instance	Room 101, 104, 129, 302, 312, and others
Deficiency Quantity	200
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Room 104 No violations recorded.
Deficiency	GYPSUM BOARD: DAMAGED/DETERIORATED
Deficiency Location/Instance	Corridor Near Elevator A/1, Stair B/3
Deficiency Quantity	20
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3

**NYC Department of Education  
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q266

Question	Response
<b>INTERIOR</b>	
<b>CLASSROOMS/CORRIDORS/ADMIN SPACES</b>	Inspected
<b>Ceiling</b>	Inspected
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Corridor Near Elevator A/1 No violations recorded.
<b>Door(s)</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Floor Finish</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	VINYL TILES: BROKEN/DETERIORATED/MISSING TILES
Deficiency Location/Instance	Room 101, Corridor near Room 212
Deficiency Quantity	20
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Room 101 No violations recorded.
<b>Walls</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	GLAZED BLOCK: CRACKS/SPALLING
Deficiency Location/Instance	Corridor near Room 311
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education  
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection


Q266

Question	Response
<b>INTERIOR</b>	
<b>CLASSROOMS/CORRIDORS/ADMIN SPACES</b>	
<b>Walls</b>	
Deficiency Photo1	
Violations	Corridor near Room 311 No violations recorded.
Deficiency	MASONRY: CRACKS/SPALLING
Deficiency Location/Instance	Room 321
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Room 321 No violations recorded.
<b>Specialties</b>	Inspected
<b>Classroom Locker(s)</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Fixed Seating</b>	Does not Exist
<b>GYMNASIUM</b>	Inspected
Instance on 1st Floor	Inspected
<b>Ceiling</b>	Inspected
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Door(s)</b>	Inspected
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Fixed Equipment</b>	Inspected
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair

**NYC Department of Education  
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q266

Question	Response
<b>INTERIOR</b>	
<b>GYMNASIUM</b>	
<b>Fixed Equipment</b>	
Deficiency	No deficiencies recorded
<b>Floor Finish</b>	
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Seating</b>	
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	DAMAGED BLEACHERS
Deficiency Location/Instance	Near Exits 7, 8, Center
Deficiency Quantity	30
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Near Exit 7 No violations recorded.
<b>Sliding-folding Partition</b>	
Instance on 1st Floor	Does not Exist
<b>Stage</b>	
Instance on 1st Floor	Does not Exist
<b>Walls</b>	
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	WALL PADDING: DETERIORATED
Deficiency Location/Instance	Near Exit 8
Deficiency Quantity	80
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education  
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q266

Question	Response
<b>INTERIOR</b>	
<b>GYMNASIUM</b>	
<b>Walls</b>	
Deficiency Photo1	
	Near Exit 8
Violations	No violations recorded.
<b>Window Curtains/Shades/Blinds</b>	
Instance on 1st Floor	Does not Exist
<b>INTERIOR DOOR HARDWARE</b>	
Condition	Inspected
Deficiency	3 - Fair
Deficiency	No deficiencies recorded
<b>INTERIOR GUARDS</b>	
Condition	Inspected
Deficiency	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>KITCHEN</b>	
Instance on 1st Floor	Inspected
<b>Ceiling</b>	
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	ACOUSTIC TILES: DAMAGED/MISSING
Deficiency Location/Instance	Rooms 106E, 106C
Deficiency Quantity	20
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Room 106E
Violations	No violations recorded.
<b>Door(s)</b>	
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	METAL: DETERIORATED DOOR AND FRAME
Deficiency Location/Instance	Room 106H



**NYC Department of Education  
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q266

Question	Response
----------	----------

**INTERIOR**

**KITCHEN**

**Door(s)**

Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	




Room 106H

Violations	No violations recorded.
------------	-------------------------

**Floor Finish**

Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	QUARRY TILE: BROKEN/MISSING TILES
Deficiency Location/Instance	Serving Area, Prep Area
Deficiency Quantity	30
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	



Serving Area

Violations	No violations recorded.
------------	-------------------------

**Walls**

Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	MASONRY: CRACKS/SPALLING
Deficiency Location/Instance	Room 106E
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education  
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q266

Question	Response
<b>INTERIOR</b>	
<b>KITCHEN</b>	
<b>Walls</b>	
Deficiency Photo1	
	Room 106E
Violations	No violations recorded.
Deficiency	CERAMIC TILE: BROKEN/ MISSING
Deficiency Location/Instance	Serving Area, Near Windows
Deficiency Quantity	20
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Serving Area
Violations	No violations recorded.
<b>LIBRARY</b>	Inspected
Instance on Room 215	Inspected
<b>Built-in Furnishing</b>	
Instance on Room 215	Does not Exist
<b>Ceiling</b>	
Instance on Room 215	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Door(s)</b>	
Instance on Room 215	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Floor Finish</b>	
Instance on Room 215	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Walls</b>	
Instance on Room 215	Inspected

**NYC Department of Education  
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection


Q266

Question	Response
<b>INTERIOR</b>	
<b>LIBRARY</b>	Inspected
<b>Walls</b>	
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>LOCKER ROOM</b>	Inspected
Instance on 1st Floor - Boys (252 Lockers, 800 SF)	Inspected
Alternative use	Yes
Instance on 1st Floor - Girls (236 Lockers, 800 SF)	Inspected
Alternative use	Yes
<b>Ceiling</b>	
Instance on 1st Floor - Boys (252 Lockers, 800 SF)	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on 1st Floor - Girls (236 Lockers, 800 SF)	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Door(s)</b>	
Instance on 1st Floor - Girls (236 Lockers, 800 SF)	Inspected
Condition	3 - Fair
Deficiency	METAL: DAMAGED LOUVER
Deficiency Location/Instance	Entrance
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Entrance	Entrance
Violations	No violations recorded.
<b>Floor Finish</b>	
Instance on 1st Floor - Girls (236 Lockers, 800 SF)	Inspected
Condition	2 - Between Good and Fair
Deficiency	CERAMIC TILE: BROKEN/MISSING TILES
Deficiency Location/Instance	Near center
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education  
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q266

Question	Response
<b>INTERIOR</b>	
<b>LOCKER ROOM</b>	Inspected
<b>Floor Finish</b>	
Deficiency Photo1	
Violations	Near center No violations recorded.
<b>Locker Room Lockers</b>	
Instance on 1st Floor - Boys (252 Lockers, 800 SF)	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on 1st Floor - Girls (236 Lockers, 800 SF)	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Walls</b>	
Instance on 1st Floor - Boys (252 Lockers, 800 SF)	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on 1st Floor - Girls (236 Lockers, 800 SF)	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>MULTI-PURPOSE ROOM</b>	Does not Exist
<b>SCIENCE DEMO ROOM</b>	Does not Exist
<b>SCIENCE LAB</b>	Inspected
Instance on Room 321	Inspected
Alternative use	No
Instance on Room 325	Inspected
Alternative use	No
<b>Fixed Equipment</b>	
Instance on Room 321	Inspected
Condition	3 - Fair
Deficiency	CABINETRY: MISSING/DAMAGED
Deficiency Location/Instance	Room 321
Deficiency Quantity	10
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education  
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection



Q266

Question	Response
<b>INTERIOR</b>	
<b>SCIENCE LAB</b>	
<b>Fixed Equipment</b>	
Deficiency Photo1	
	Room 321
Violations	No violations recorded.
<b>SCIENCE PREP ROOM</b>	
	Inspected
Instance on Room 323	Inspected
Alternative use	Yes
<b>Fixed Equipment</b>	
Instance on Room 323	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>SHOWER ROOM</b>	
	Inspected
Instance on 1st Floor - Boys	Inspected
Alternative use	Yes
Instance on 1st Floor - Girls	Inspected
Alternative use	Yes
<b>Ceiling</b>	
Instance on 1st Floor - Girls	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on 1st Floor - Boys	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Door(s)</b>	
Instance on 1st Floor - Boys	Does not Exist
Instance on 1st Floor - Girls	Does not Exist
<b>Floor Finish</b>	
Instance on 1st Floor - Boys	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on 1st Floor - Girls	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Walls</b>	
Instance on 1st Floor - Girls	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on 1st Floor - Boys	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded

**NYC Department of Education  
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q266

Question	Response
<b>INTERIOR</b>	
<b>STAIRS/RAMPS: INTERIOR</b>	Inspected
Do Letter Stair Signs Exist?	Yes
<b>Ceiling</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	GYPSUM BOARD: DAMAGED/DETERIORATED
Deficiency Location/Instance	Stair A/1, 2
Deficiency Quantity	20
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Stair A/2 No violations recorded.
Deficiency	GYPSUM BOARD: DAMAGED/DETERIORATED - ACTIVE LEAK
Deficiency Location/Instance	Stair C/3
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Stair C/3 No violations recorded.
<b>Door(s)</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Partition</b>	Does not Exist
<b>Railings</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Stairs and Landings</b>	Inspected

**NYC Department of Education  
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q266



Question	Response
<b>INTERIOR</b>	
<b>STAIRS/RAMPS: INTERIOR</b>	
<b>Stairs and Landings</b>	
Condition	2 - Between Good and Fair
Deficiency	TERRAZZO: CRACKS
Deficiency Location/Instance	Stair C/2
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Stair C/2
Violations	No violations recorded.
<b>Walls</b>	
Condition	2 - Between Good and Fair
Deficiency	GLAZED BLOCK: CRACKS/SPALLING
Deficiency Location/Instance	Stair B/1
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Stair B/1
Violations	No violations recorded.
Deficiency	GYPSUM BOARD: DETERIORATED
Deficiency Location/Instance	Stair A/2
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2



**NYC Department of Education  
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q266

Question	Response
<b>INTERIOR</b>	
<b>STAIRS/RAMPS: INTERIOR</b>	
<b>Walls</b>	
Deficiency Photo1	
Violations	Stair A/2 No violations recorded.
<b>TOILET ROOMS - STAFF</b>	Inspected
<b>Ceiling</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Door(s)</b>	Inspected
Condition	4 - Between Fair and Poor
Deficiency	METAL CLAD WOOD: DETERIORATED DOOR
Deficiency Location/Instance	Room 126
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Room 126 No violations recorded.
<b>Floor Finish</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Stalls</b>	Does not Exist
<b>Walls</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>TOILET ROOMS - STUDENTS</b>	Inspected
<b>Ceiling</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	ACOUSTIC TILES: DAMAGED/MISSING
Deficiency Location/Instance	Rooms 124, 205

**NYC Department of Education  
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection



Q266

Question	Response
<b>INTERIOR</b>	
<b>TOILET ROOMS - STUDENTS</b>	
<b>Ceiling</b>	
Deficiency Quantity	20
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Room 124 No violations recorded.
<b>Door(s)</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Floor Finish</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Stalls</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Walls</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	CERAMIC TILE: BROKEN/ MISSING
Deficiency Location/Instance	Room 122
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Room 122 No violations recorded.
<b>LIFE SAFETY</b>	Inspected
<b>F.D. HOLDING AREA</b>	Does not Exist

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q266

Question	Response
<b>LIFE SAFETY</b>	Inspected
<b>STEEL STAIRS</b>	Does not Exist
<b>SITE</b>	Not Required
<b>ARTWORK</b>	Inspected
Instance	Interior- Entrance Lobby - 30057
Instance Photo	
	Entrance Lobby
Instance ID	30057
Artwork exist at stated location?	Yes
Instance	Interior - Library - 10023
Instance Photo	
	Library
Instance ID	10023
Artwork exist at stated location?	Yes