Building Condition Assessment Survey 2023 - 2024

Electrical Inspection Q321 Asset: PRE-K CENTER @ 70-24 47TH AVENUE - QUEENS, 70-24 47TH AVENUE, New York, 11377 Last Edited Inspection Id Inspection Type Time In EE: 0321 Electrical 2024-02-13 11:05 AM 2024-06-20 1:15 PM Asset Data Question Answer Type of Service Below Ground Does Interactive Whiteboard (IWB) Exist? Yes Water Penetration in Electrical Room? No Have any Systems/Major Building Components been upgraded? Yes Interior Fluorescent Lighting, LED Lighting, Auxiliary Systems: Signal/Bell System, Partial Emergency Lighting (Battery Pack), LAN, Telephone System, Public Address System, Molded Case Circuit Breaker Type Panel Board, Motor Controller (Motor Starter/Contactor), Fire Alarm System, IPDVS/CCTV System, Intrusion Alarm System Years: 2017 HID Lighting Systems: 2005 Years: DEDICATED INTERCOMS IN FIRE RESCUE AREAS Question Response Are there any Life Rescue Assistance Areas, Fire Rescue Areas, Yes and/or Holding Rooms in your building? No Are dedicated intercoms available in all of these spaces for use during a fire? Which spaces do not have dedicated intercoms? Room 111 Priority Condition Priority Priority Condition Component Location Person(s) Person(s) Title Status PhotoImage **Condition Exist Category** Description Affected Description Notified Last Year? No condition recorded Inspection Question Response Electrical **AUDITORIUM** Does not Exist CAFETERIA Does not Exist CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE Inspected Lighting Inspected Does a Chandelier exist? Yes **Lighting Fixture - Fluorescent** Inspected Pendant Mounted Inspected Condition 2 - Between Good and Fair Deficiency No deficiencies recorded Surface Mounted Inspected Condition 2 - Between Good and Fair Deficiency No deficiencies recorded **Recessed Mounted** Inspected Condition 2 - Between Good and Fair Deficiency No deficiencies recorded Lighting Fixture - HID Does not Exist **Lighting Fixture - Incandescent** Inspected Pendant Mounted Inspected

Condition

3 - Fair

Building Condition Assessment Survey 2023 - 2024

uestion	Response	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE		
Lighting		
Lighting Fixture - Incandescent		
Pendant Mounted		
Deficiency	No deficiencies recorded	
Surface Mounted	Does not Exist	
Recessed Mounted	Does not Exist	
Lighting Fixture - LED	Inspected	
Pendant Mounted	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
COMPUTER LAB	Does not Exist	
GYMNASIUM	Inspected	
Instance on 1st Floor	Inspected	
Lighting	Inspected	
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Does not Exist	
Lighting Fixture - HID		
Instance on 1st Floor	Inspected	
Pendant Mounted	Inspected	
Instance on 1st Floor	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Does not Exist	
Instance on 1st Floor	Does not Exist	
Recessed Mounted	Does not Exist	
Instance on 1st Floor	Does not Exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not Exist	
Lighting Fixture - LED		
Instance on 1st Floor	Inspected	
Pendant Mounted	Does not Exist	
Instance on 1st Floor	Does not Exist Does not Exist	
Surface Mounted	Inspected	
Instance on 1st Floor	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not Exist	
Instance on 1st Floor	Does not Exist	
Local Sound System	Does not Exist	
Instance on 1st Floor	Does not Exist	
Projection System	Does not Exist	

(P)

Building Condition Assessment Survey 2023 - 2024

uestion	Response	
GYMNASIUM		
Projection System	Does not Exist	
Instance on 1st Floor	Does not Exist	
Scoreboard	Inspected	
Instance on 1st Floor	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Theater Lighting System	Does not Exist	
Instance on 1st Floor	Does not Exist	
KITCHEN	Inspected	
Instance on 1st Floor	Inspected	
Lighting	Inspected	
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Does not Exist	
Lighting Fixture - HID		
Instance on 1st Floor	Does not Exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not Exist	
Lighting Fixture - LED		
Instance on 1st Floor	Inspected	
Pendant Mounted	Does not Exist	
Instance on 1st Floor	Does not Exist	
Surface Mounted	Does not Exist	
Instance on 1st Floor	Does not Exist	
Recessed Mounted	Inspected	
Instance on 1st Floor	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
LIBRARY	Does not Exist	
LOCKER ROOM	Does not Exist	
MULTIPURPOSE ROOM	Does not Exist	
SCIENCE DEMO ROOM	Does not Exist	
SCIENCE LAB	Does not Exist	
SCIENCE PREP ROOM	Does not Exist	
SWIMMING POOL	Does not Exist	
TOILET ROOM - STAFF	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Does not Exist	
Surface Mounted		
	Inspected 2 - Between Good and Fair	
	2 - Between Good and Fair No deficiencies recorded	
Deficiency Recessed Mounted	Does not Exist	
Lighting Fixture - HID	Does not Exist	
Lighting Fixture - Incandescent	Does not Exist	
Lighting Fixture - LED	Does not Exist	

Building Condition Assessment Survey 2023 - 2024

uestion	Response	
TOILET ROOM - STUDENT		
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Does not Exist	
Surface Mounted	Does not Exist	
Recessed Mounted	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID	Does not Exist	
Lighting Fixture - Incandescent	Does not Exist	
Lighting Fixture - LED	Does not Exist	
AUXILIARY SIGNAL/BELL SYSTEM	Inspected	
Replacement Quantity	10,000	
Replacement Uom	S.F.	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
EMERGENCY DC STANDBY BATTERY POWER	Does not Exist	
EMERGENCY GENERATOR SET	Does not Exist	
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not Exist	
EMERGENCY LIGHTING	Inspected	
Battery Pack	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Non Battery Pack	Does not Exist	
EXIT LIGHT	Does not Exist	
EXIT/EMERGENCY LIGHT	Inspected	
Condition	3 - Fair	
Deficiency	FIXTURE LENS MISSING	
Deficiency Location/Instance	Gymnasium	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	INSTALL LENS	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 2	
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
FIRE ALARM SYSTEM	Inspected	
Replacement Quantity	10,000	
Replacement Uom	S.F.	
Bell/Horn		
Condition	Inspected 2 - Between Good and Fair	
	2 - Between Good and Fair No deficiencies recorded	
Deficiency Strobe	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
	Inspected	
Manual Pull Station	Inspected 2 - Between Good and Fair	
	Inspected 2 - Between Good and Fair No deficiencies recorded	

Building Condition Assessment Survey 2023 - 2024

uestion	Response	
FIRE ALARM SYSTEM		
Duct Smoke Detector	Does not Exist	
Area Smoke Detector	Does not Exist	
CO Detector	Does not Exist	
Heat Detector	Does not Exist	
Elevator Recall	Does not Exist	
Magnetic Door Holder/Contactor	Does not Exist	
Fused Cutout Panel	Does not Exist	
Fire Alarm Digital Communicator	Does not Exist	
Main Panel	Does not Exist	
Sub-Panel	Does not Exist	
Remote Annunciator	Inspected	
Display Monitor	Does not Exist	
Panel	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Printer	Does not Exist	
Punch Register	Does not Exist	
Sprinkler Flow/Air Pressure Switch	Does not Exist	
Tamper Flow Switch/Chain	Does not Exist	
GROUNDING SYSTEM	Does not Exist	
INTERCOM SYSTEM	Does not Exist	
LAN	Inspected	
Local Distribution Frame (I/LDF)	Does not Exist	
Main Equipment Rack (MDF)	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
LIGHTNING PROTECTION	Does not Exist	
MOTOR CONTROLLER	Inspected	
Motor Control Center	Does not Exist	
Motor Starter/Contactor	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Variable Frequency Drive	Does not Exist	
PANEL BOARD	Inspected	
Fused Disconnect Switch Type	Does not Exist	
Fused Knife Switch Type	Does not Exist	
Fused Toggle Switch Type	Does not Exist	
Molded Case Circuit Breaker Type	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
PUBLIC ADDRESS SYSTEM	Inspected	
Replacement Quantity	10,000	
Replacement Uom	S.F.	
Instance	Custodian's Office	
Instance Condition	2 - Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	

Building Condition Assessment Survey 2023 - 2024

uestion	Response	
PUBLIC ADDRESS SYSTEM	*	
Model	Telecor XL	
Installation Year	2017	
Source of Installation	Documented	
Deficiency	No deficiencies recorded	
SECURITY	Inspected	
IPDVS/CCTV System	Inspected	
Replacement Quantity	10,000	
Replacement Uom	S.F.	
Installation Year	2017	
Source of Installation	Documented	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Intrusion Alarm System	Inspected	
Replacement Quantity	10,000	
Replacement Uom	S.F.	
Central Control Panel	Inspected	
Instance	Custodian's Office	
Instance Condition	2 - Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Model	Vista-128BPT	
Installation Year	2017	
Source of Installation	Documented	
Deficiency	No deficiencies recorded	
Infrared Sensor	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Panic Switch	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Remote Annunciator	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Siren/Strobe	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting - Security	Does not Exist	
SERVICE SWITCH	Does not Exist	
SWITCHBOARD	Does not Exist	
TELEPHONE SYSTEM	Inspected	
PBX/Intercom	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Standard	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	

(P)