Building Condition Assessment Survey 2023 - 2024

Mechanical Inspection

Inspection Id Inspection Type		Time In	Last Edited
ME : Q322 Mechanical		2024-03-21 10:32 AM	2024-04-03 5:57 Pl
sset Data			
Question	Answei		
Are there fuel tanks?	No		
Total # of water main service entries to the asset	1		
MERs/Fan Rooms Locations	None		
Are there any spaces with Missing or Defective CO Detectors?	No		
Are there any Emergency Stop Switches with Missing Hammers?	No		
Are there any Painted/Obstructed Sprinkler Heads?	No		
Have any Systems/Major Building Components been upgraded?	Yes		
	System		MER
	Years:	2023	
	System		
	Years:	2022	Service and (DV Selit
	System	System)	equipment (DX Split
	Years:	2018	
	System		ater
	Years:	2017	
riority Condition			
	escription Person(s) Notified	Person(s) Title Status	PhotoImage
No condition recorded			
No condition recorded			
No condition recorded			
	Resp	onse	
spection	Resp	onse	
Question	Resp		
Question Mechanical	Inspe		
Question Question Mechanical AIR CONDITIONING	Inspe Does	cted	
Question Question Mechanical AIR CONDITIONING Chilled Water System	Inspe Does Does	cted not Exist	
Question Question Mechanical AIR CONDITIONING Chilled Water System Condenser Water Distribution: Piping, Pumps and Auxiliaries	Inspe Does Does Does	cted not Exist not Exist	
Question Question Mechanical AIR CONDITIONING Chilled Water System Condenser Water Distribution: Piping, Pumps and Auxiliaries Cooling Coil in Ductwork Cooling Tower	Inspe Does Does Does Does	cted not Exist not Exist not Exist not Exist	
AIR CONDITIONING Chilled Water System Condenser Water Distribution: Piping, Pumps and Auxiliaries Cooling Coil in Ductwork Cooling Tower DX Split System	Inspe Does Does Does Does Inspe	cted not Exist not Exist not Exist not Exist cted	
aspection Question Mechanical AIR CONDITIONING Chilled Water System Condenser Water Distribution: Piping, Pumps and Auxiliaries Cooling Coil in Ductwork Cooling Tower DX Split System Indoor Unit	Inspe Does Does Does Does Inspe Inspe	cted not Exist not Exist not Exist not Exist cted cted	
All Condenser Water Distribution: Piping, Pumps and Auxiliaries Cooling Coil in Ductwork Cooling Tower DX Split System Indoor Unit Condition	Inspe Does Does Does Does Inspe Inspe 1 - G	cted not Exist not Exist not Exist not Exist cted cted cted	
All Condenser Water Distribution: Piping, Pumps and Auxiliaries Cooling Coil in Ductwork Cooling Tower DX Split System Indoor Unit Condition Deficiency	Inspe Does Does Does Does Inspe Inspe 1 - G No de	cted not Exist not Exist not Exist not Exist cted cted cted ood eficiencies recorded	
Aspection Question Question Mechanical AIR CONDITIONING Chilled Water System Condenser Water Distribution: Piping, Pumps and Auxiliaries Cooling Coil in Ductwork Cooling Tower DX Split System Indoor Unit Condition Deficiency Outdoor Unit	Inspe Does Does Does Does Inspe Inspe Inspe I - G No de Inspe	cted not Exist not Exist not Exist not Exist cted cted cted ood eficiencies recorded cted	
All CONDITIONING Chilled Water System Condenser Water Distribution: Piping, Pumps and Auxiliaries Cooling Coil in Ductwork Cooling Tower DX Split System Indoor Unit Condition Deficiency Outdoor Unit Condition	Inspe Does Does Does Does Inspe Inspe 1 - G No de Inspe 1 - G	cted not Exist not Exist not Exist not Exist cted cted cted ood efficiencies recorded cted ood	
All Condenser Water Distribution: Piping, Pumps and Auxiliaries Cooling Coil in Ductwork Cooling Tower DX Split System Indoor Unit Condition Deficiency Outdoor Unit Condition Deficiency	Inspe Does Does Does Does Inspe Inspe 1 - G No de Inspe 1 - G No de Inspe	cted not Exist not Exist not Exist not Exist cted cted cted ood eficiencies recorded cted ood eficiencies recorded	
Aspection Question Mechanical AIR CONDITIONING Chilled Water System Condenser Water Distribution: Piping, Pumps and Auxiliaries Cooling Coil in Ductwork Cooling Tower DX Split System Indoor Unit Condition Deficiency Outdoor Unit Condition Deficiency Dry Cooler	Inspe Does Does Does Does Inspe Inspe I - G No de Inspe I - G No de Inspe	cted not Exist not Exist not Exist not Exist cted cted cted cood efficiencies recorded cted ood efficiencies recorded not Exist	
All Condenser Water Distribution: Piping, Pumps and Auxiliaries Cooling Coil in Ductwork Cooling Tower DX Split System Indoor Unit Condition Deficiency Outdoor Unit Condition Deficiency Dry Cooler Packaged / Rooftop Unit	Inspe Does Does Does Does Inspe Inspe I - G No de Inspe I - G No de Does Does Does	cted not Exist not Exist not Exist not Exist cted cted cted cted cted cted cted cte	
Question Mechanical AIR CONDITIONING Chilled Water System Condenser Water Distribution: Piping, Pumps and Auxiliaries Cooling Coil in Ductwork Cooling Tower DX Split System Indoor Unit Condition Deficiency Outdoor Unit Condition Deficiency Dry Cooler Packaged / Rooftop Unit Packaged Terminal A/C	Inspe Does Does Does Does Inspe Inspe I - G No de Inspe I - G No de Does Does Does	cted not Exist not Exist not Exist not Exist cted cted cood efficiencies recorded cted ood efficiencies recorded not Exist not Exist not Exist	
All R CONDITIONING	Inspe Does Does Does Does Inspe Inspe I - G No de Inspe I - G No de Does Does Does Does	cted not Exist not Exist not Exist not Exist cted cted cted cted cted cted cted cte	
All Condenser Water Distribution: Piping, Pumps and Auxiliaries Cooling Coil in Ductwork Cooling Tower DX Split System Indoor Unit Condition Deficiency Outdoor Unit Condition Deficiency Dry Cooler Packaged / Rooftop Unit Packaged Terminal A/C Refrigerant Leak Detection System	Inspe Does Does Does Does Inspe Inspe I - G No da Inspe I - G No da Does Does Does Does Does	cted not Exist not Exist not Exist not Exist cted cted cted cted cood efficiencies recorded cted ood efficiencies recorded not Exist not Exist not Exist not Exist not Exist cted	
All R CONDITIONING Question Mechanical AIR CONDITIONING Chilled Water System Condenser Water Distribution: Piping, Pumps and Auxiliaries Cooling Coil in Ductwork Cooling Tower DX Split System Indoor Unit Condition Deficiency Outdoor Unit Condition Deficiency Dry Cooler Packaged / Rooftop Unit Packaged Terminal A/C Refrigerant Leak Detection System Refrigerant Piping Condition	Inspe Does Does Does Does Does Inspe Inspe I - G No de Inspe I - G No de Does Does Does Does Inspe I - G	cted not Exist not Exist not Exist not Exist cted cted cood efficiencies recorded cted ood efficiencies recorded not Exist not Exist not Exist not Exist cted ood	
All Condenser Water Distribution: Piping, Pumps and Auxiliaries Cooling Coil in Ductwork Cooling Tower DX Split System Indoor Unit Condition Deficiency Outdoor Unit Condition Deficiency Dry Cooler Packaged / Rooftop Unit Packaged Terminal A/C Refrigerant Leak Detection System	Inspe Does Does Does Does Inspe I - G No de Inspe I - G No de Does Does Does Does Inspe I - G No de Does No de Does No de Does No de No de	cted not Exist not Exist not Exist not Exist cted cted cted cted cood efficiencies recorded cted ood efficiencies recorded not Exist not Exist not Exist not Exist not Exist cted	

uestion	Response	
CLIMATE CONTROL SYSTEM	Inspected	
BMS	Does not Exist	
Pneumatic System	Does not Exist	
Hybrid System	Does not Exist	
Electric System	Inspected	
Instance	Throughout (Zone Control)	
Instance Condition	3 - Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Building Area Covered by Operational System	81-100%	
Deficiency	No deficiencies recorded	
COMPACTOR	Does not Exist	_
CONVEYING	Inspected	
Dumbwaiter	Does not Exist	
Elevator	Inspected	
Are all the existing elevators operable?	Yes	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Escalator	Does not Exist	
Non-auditorium Handicap Lift - Vertical	Does not Exist	
Non-auditorium Handicap Lift - Stair	Does not Exist	_
Ash Hoist	Does not Exist	
Sidewalk Elevator	Does not Exist	
DOMESTIC WATER SYSTEM	Inspected	
Domestic Cold Water System	Inspected	
Gravity System	Does not Exist	
Pressure Booster System	Does not Exist	
Water Service	Inspected	
Instance	Boiler Room	
Instance Condition	3 - Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Deficiency	WATER MAIN: DEFECTIVE/LEAKS	
Deficiency Location/Instance	Boiler Room	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
Domestic Hot Water System	Inspected	
Domestic Hot Water Remote Storage Tank	Does not Exist	
Domestic Water Heat Exchanger	Does not Exist	
Electric Domestic Water Heater	Does not Exist	
Heat Pump Domestic Water Heater	Does not Exist	
Gas Fired Domestic Water Heater	Inspected Boiler Room	

uestion	Response
DOMESTIC WATER SYSTEM	
Domestic Hot Water System	
Gas Fired Domestic Water Heater	
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	A.O. Smith
Equipment	N/A
Capacity/Size Quantity	275
Capacity/Size UOM	MBH Input
Capacity/Size2 Quantity	100
Capacity/Size2 UOM	Gallons
Source of Capacity/Size	Documented
Installation Year	2017
Source of Installation	Inspector Estimate
Deficiency	No deficiencies recorded
Oil Fired Domestic Water Heater	Does not Exist
Domestic Water Distribution Piping	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
DRAIN/WASTE/VENT AND STORM SYSTEM	Inspected
Interior Storm Piping	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Sewage/Waste/Vent Piping	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Sewage Ejector Pump	Does not Exist
Sump Pump	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Does not Exist
FIXTURES	Inspected
Staff And Other	Inspected
Janitor Sink	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Lavatory/Sink	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Toilet	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Urinal	Does not Exist
Student	Inspected
Drinking Fountain	Inspected
Condition	3 - Fair
Deficiency	DEFECTIVE AUXILIARY (FAUCET, SHUT OFF VALVE,ET
Deficiency Location/Instance	Boys Toilet Room 105, Girls Toilet Room 215

uestion	Response
FIXTURES	
Student	
Drinking Fountain	
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Lavatory/Sink	Inspected
Condition	2 - Between Good and Fair
Deficiency	DEFECTIVE AUXILIARY (FAUCET, SHUT OFF VALVE, ET
Deficiency Location/Instance	Student's Toilet Room 102
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Locker Room Shower	Does not Exist
Sink And Fountain Combo Unit	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Toilet	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Urinal	Inspected
Condition	3 - Fair
Deficiency	CRACKED/PHYSICAL DAMAGE
Deficiency Location/Instance	Boys Toilet Room B12
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
GAS FIRED FURNACE	Does not Exist
GAS SERVICE	Inspected
Gas Distribution Piping	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Gas Meter Room Exhaust Fan	Does not Exist
Gas Meter Room Vent	Does not Exist
Gas Pressure Booster	Does not Exist
CO/Gas Leak Detection	Does not Exist
HEATING	Inspected

Building Condition Assessment Survey 2023 - 2024

nanical Inspection	Decronso
estion	Response
IEATING	
Heating Coil In Ductwork	Does not Exist
Hydronic Heating	Does not Exist
Radiator/Convector/Fin Tube	Inspected
Condition	3 - Fair
Deficiency	RADIATOR/CONVECTOR: DEFECTIVE
Deficiency Location/Instance	Toilet Room inside Room 207, Girls Toilet Room 213, Boys To Room 215
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Steam Heating	Inspected
F&T/Steam Drip Trap	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
MER Steam and Condensate Piping	Does not Exist
Steam Condensate Return Piping	Inspected
Condition	3 - Fair
Deficiency	DEFECTIVE/LEAKS
Deficiency Location/Instance	Girls Toilet Rooms117, 213, Boys Toilet Room 215/ Leaks affect walls in Toilet Rooms
Deficiency Quantity	40
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Steam Condensate Return Pumping System	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Steam Piping	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Terminal Unit Thermostatic Trap	Inspected
Condition	3 - Fair
Deficiency	DEFECTIVE/DETERIORATED
Deficiency Location/Instance	Girls Toilet Room 213, Boys Toilet Room 215
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Steen applied by External Courses	Doos not Evist

Steam supplied by External Sources

Does not Exist

Building Condition Assessment Survey 2023 - 2024

uestion	Response	
HEATING	Inspected	
Unit Heater/Cabinet Heater	Does not Exist	
HEATING PLANT	Inspected	
Replacement Quantity	1,322	
Replacement Uom	MBH Net	
Instance on Basement	Inspected	
Burner Type	Gas	
Heating Plant Oil Number	N/A	
Is there a water meter on the boiler make-up water piping? Burner Exists?	No Yes	
Burner Manufacturer	Power Flame	
Burner Model Number	C2-G-20B-HBS-9	
Boiler Auxiliaries	Inspected	
Instance on Basement	Inspected	
Boiler Auxiliary Piping		
Instance on Basement	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Boiler Emergency Stop Switch		
Instance on Basement	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Boiler Feedwater System		
Instance on Basement	Does not Exist	
Boiler Feedwater Treatment(Automatic)		
Instance on Basement	Does not Exist	
Boiler Flue Exhaust		
Instance on Basement	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Boiler Make-up Water Backflow Preventer		
Instance on Basement	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Boiler Room Steam And Condensate Piping		
Instance on Basement	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Boiler Safety Valve		
Instance on Basement	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Boiler System	Inspected	
Instance on Basement	Inspected	
Coal-fired Boiler		
Instance on Basement	Does not Exist	
Hot Water Boiler		
Instance on Basement	Does not Exist	
Modular Boiler		

Steam Boiler

uestion	Response
HEATING PLANT	Inspected
Boiler System	•
Steam Boiler	
Instance on Basement	Inspected
Instance	Boiler Room
Instance Condition	3 - Fair
Instance Quantity	1,322
Instance Quantity Uom	MBH Net
Cast Iron Boiler?	Yes
Instance Manufacturer	H. B. Smith Co., Inc.
Equipment	83103-05
Capacity/Size Quantity	1,322
Capacity/Size UOM	MBH Net
Source of Capacity/Size	Documented
Installation Year	2000
Source of Installation	Documented
Deficiency	No deficiencies recorded
Fuel System	Inspected
Instance on Basement	Inspected
Boiler Fresh Air Louver/Damper	
Do Boiler Combustion Air Louvers exist?	Yes
Туре	Automatic
Instance on Basement	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Burner/Burner Control Panel	
Instance on Basement	Inspected
Condition	3 - Fair
Deficiency	BURNER CONTROL PANEL: DEFECTIVE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Fuel Oil Storage/Supply System	
Instance on Basement	Does not Exist
Gas Trains And Vent At The Boiler	
Instance on Basement	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Enclosed IDF Room	Does not Exist
KITCHEN	Inspected
Instance on Basement	Inspected
CO Detector	Inspected
Instance on Basement	Inspected
Condition	3 - Fair

uestion	Response	
KITCHEN		
Gas System	Inspected	
Instance on Basement	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Grease Trap	Inspected	
Instance on Basement	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Hood	Inspected	
Instance on Basement	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Hood Exhaust Ductwork	Inspected	
Instance on Basement	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Hood Exhaust Fan	Inspected	
Instance on Basement	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Hood Fire Suppression System	Inspected	
Instance on Basement	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Hot Water Temperature Booster	Inspected	
Instance on Basement	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Kitchen Sink	Inspected	
Instance on Basement	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
MDF Room	Inspected	
Instance on Room 317	Inspected	
Dedicated A/C Equipment		
Instance on Room 317	Inspected Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
SCIENCE DEMO ROOM	Does not Exist	
SCIENCE LAB	Does not Exist	
SCIENCE PREP ROOM	Does not Exist	
SPRINKLERS, STANDPIPE, FIRE SYSTEM	Does not Exist	
SWIMMING POOL	Does not Exist	
VENTILATION	Inspected	
Is the building mechanically ventilated?	No	
Exhaust Fan	Inspected	
Approximate Total # of Fans	1-25	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	

Building Condition Assessment Survey 2023 - 2024

Mechanical Inspection

hanical Inspection		Q322
uestion	Response	
VENTILATION		
Heating And Ventilating Unit	Does not Exist	
Metal Ductwork	Inspected	
Are there any uninsulated ductwork by design in Mechanical		
Rooms?	No	
Are there chain operated dampers?	No	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Supply Fan	Does not Exist	
Unit Ventilator	Does not Exist	