Building Condition Assessment Survey 2023 - 2024

Inspection Id Inspection T	ype				Time In	Last Edited
EE: Q338 Electrical					2024-02-13 9:55 AM	2024-02-27 2:54 PM
sset Data						
Question				Answer		
Type of Service				Below Gro	ound	
Does Interactive Whiteboard (IW	VB) Exist?			Yes		
Water Penetration in Electrical R				No		
Have any Systems/Major Buildin	ng Components	been upgraded?		Yes		
				Systems:	Fire Alarm System	
				Years:	2023 All Other Electrical Systems and	d Components
				Systems: Years:	2022	u Components
DEDICATED INTERCOMS I	N FIRE RESC	TIE AREAS		1 cars.	2022	
Question	IVIIIE RESC	CE TIKETO		Response		
Are there any Life Rescue Assis and/or Holding Rooms in your b		re Rescue Areas,		No		
riority Condition						
·	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title Status	PhotoImage
No condition recorded						
spection						
Question				Respon	se	
Electrical						
AUDITORIUM				Does no	t Exist	
CAFETERIA				Does no	t Exist	
CLASSROOM/CORRIDOR/A	DMINISTRA	TIVE SPACE		Inspecte	ed	
Lighting				Inspecte	ed	
Does a Chandelier exi	ist?			No		
Lighting Fixture - Fluores	cent			Does no	t Exist	
Lighting Fixture - HID				Does no	t Exist	
Lighting Fixture - Incande	escent			Does no	t Exist	
Lighting Fixture - LED				Inspecte	ed	
Pendant Mounted				Inspecte	ed	
Condition				1 - Good	d	
Deficiency				No defic	ciencies recorded	
Surface Mounted				Inspecte		
Condition				1 - Good	d	
Deficiency					ciencies recorded	
Recessed Mounted				Inspecte		
Condition				1 - Good		
Deficiency					ciencies recorded	
COMPUTER LAB				Does no		
GYMNASIUM				Does no		
KITCHEN				Inspecte		
Instance on 1st Floor				Inspecte		
Lighting				Inspecte	ed	
Instance on 1st Floor				Inspecte	ed	

Building Condition Assessment Survey 2023 - 2024

urcai mspection		QUU
uestion	Response	
KITCHEN		
Lighting		
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Does not Exist	
Lighting Fixture - HID		
Instance on 1st Floor	Does not Exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not Exist	
Lighting Fixture - LED		
Instance on 1st Floor	Inspected	
Pendant Mounted	Does not Exist	
Instance on 1st Floor	Does not Exist	
Surface Mounted	Does not Exist	
Instance on 1st Floor	Does not Exist	
Recessed Mounted	Inspected	
Instance on 1st Floor	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
LIBRARY	Does not Exist	
LOCKER ROOM	Does not Exist	
MULTIPURPOSE ROOM	Inspected	
Instance on 1st Floor	Inspected	
Lighting	Inspected	
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Does not Exist	
Lighting Fixture - HID		
Instance on 1st Floor	Does not Exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not Exist	
Lighting Fixture - LED		
Instance on 1st Floor	T 1	
Pendant Mounted	Inspected	
I chaunt intounted	Inspected	
Instance on 1st Floor		
	Inspected	
Instance on 1st Floor	Inspected Inspected	
Instance on 1st Floor Condition	Inspected Inspected 1 - Good	
Instance on 1st Floor Condition Deficiency	Inspected Inspected 1 - Good No deficiencies recorded	
Instance on 1st Floor Condition Deficiency Surface Mounted	Inspected Inspected 1 - Good No deficiencies recorded Does not Exist	
Instance on 1st Floor Condition Deficiency Surface Mounted Instance on 1st Floor	Inspected Inspected 1 - Good No deficiencies recorded Does not Exist Does not Exist	
Instance on 1st Floor Condition Deficiency Surface Mounted Instance on 1st Floor Recessed Mounted	Inspected Inspected 1 - Good No deficiencies recorded Does not Exist Does not Exist Does not Exist	
Instance on 1st Floor Condition Deficiency Surface Mounted Instance on 1st Floor Recessed Mounted Instance on 1st Floor	Inspected Inspected 1 - Good No deficiencies recorded Does not Exist Does not Exist Does not Exist Does not Exist	
Instance on 1st Floor Condition Deficiency Surface Mounted Instance on 1st Floor Recessed Mounted Instance on 1st Floor Local Sound System	Inspected Inspected 1 - Good No deficiencies recorded Does not Exist	
Instance on 1st Floor Condition Deficiency Surface Mounted Instance on 1st Floor Recessed Mounted Instance on 1st Floor Local Sound System Instance on 1st Floor	Inspected Inspected 1 - Good No deficiencies recorded Does not Exist	
Instance on 1st Floor Condition Deficiency Surface Mounted Instance on 1st Floor Recessed Mounted Instance on 1st Floor Local Sound System Instance on 1st Floor Projection System Instance on 1st Floor	Inspected Inspected 1 - Good No deficiencies recorded Does not Exist	
Instance on 1st Floor Condition Deficiency Surface Mounted Instance on 1st Floor Recessed Mounted Instance on 1st Floor Local Sound System Instance on 1st Floor Projection System	Inspected Inspected 1 - Good No deficiencies recorded Does not Exist	
Instance on 1st Floor Condition Deficiency Surface Mounted Instance on 1st Floor Recessed Mounted Instance on 1st Floor Local Sound System Instance on 1st Floor Projection System Instance on 1st Floor Theater Lighting System Instance on 1st Floor	Inspected Inspected 1 - Good No deficiencies recorded Does not Exist Does not Exist	
Instance on 1st Floor Condition Deficiency Surface Mounted Instance on 1st Floor Recessed Mounted Instance on 1st Floor Local Sound System Instance on 1st Floor Projection System Instance on 1st Floor Theater Lighting System	Inspected Inspected 1 - Good No deficiencies recorded Does not Exist Does not Exist	

Building Condition Assessment Survey 2023 - 2024

Question	Response
SWIMMING POOL	Does not Exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Does not Exist
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Does not Exist
Recessed Mounted	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Does not Exist
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Does not Exist
Recessed Mounted	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Replacement Quantity	9,000
Replacement Uom	S.F.
Condition	1 - Good
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not Exist
EMERGENCY GENERATOR SET	Does not Exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not Exist
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Non Battery Pack	Does not Exist
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Non Battery Pack	Does not Exist
EXIT/EMERGENCY LIGHT	Does not Exist
FIRE ALARM SYSTEM	Inspected
Replacement Quantity	9,000
Replacement Uom	S.F.
Bell/Horn	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded

Building Condition Assessment Survey 2023 - 2024

near mspection		Qu
estion	Response	
IRE ALARM SYSTEM		
Strobe	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Manual Pull Station	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Fan Shutdown Control	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Duct Smoke Detector	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Area Smoke Detector	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
CO Detector	Does not Exist	
Heat Detector	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Elevator Recall	Does not Exist	
Magnetic Door Holder/Contactor	Does not Exist	
Fused Cutout Panel	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Fire Alarm Digital Communicator	Does not Exist	
Main Panel	Inspected	
Bell At Panel	Does not Exist	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Main Entrance Lobby	
Instance Condition	1 - Good	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Instance Quantity Com Instance Manufacturer	Mircom	
Equipment	Fire Alarm Control Panel	
Model	FleX-Net	
Installation Year	2023	
Source of Installation	Documented Documented	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Standard)	Does not Exist	
Sub-Panel	Does not Exist	
Remote Annunciator	Inspected	
Display Monitor	Does not Exist	
Panel	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Printer	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Punch Register	Does not Exist	

Building Condition Assessment Survey 2023 - 2024

Question	Response
FIRE ALARM SYSTEM	Inspected
Remote Annunciator	Inspected
Punch Register	
Sprinkler Flow/Air Pressure Switch	Does not Exist
Tamper Flow Switch/Chain	Does not Exist
GROUNDING SYSTEM	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Does not Exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Does not Exist
Main Equipment Rack (MDF)	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not Exist
MOTOR CONTROLLER	Inspected
Motor Control Center	Does not Exist
Motor Starter/Contactor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Variable Frequency Drive	Does not Exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Does not Exist
Fused Knife Switch Type	Does not Exist
Fused Toggle Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
PUBLIC ADDRESS SYSTEM	Inspected
Replacement Quantity	9,000
Replacement Uom	S.F.
Instance	MDF Room 116
Instance Condition	1 - Good
Instance Quantity	1
Instance Quantity Uom	EACH
Model	N/A
Installation Year	2022
Source of Installation	Documented
Deficiency	No deficiencies recorded
SECURITY	Inspected
IPDVS/CCTV System	Inspected
Replacement Quantity	9,000
Replacement Uom	S.F.
Installation Year	2022
Source of Installation	Documented
Condition	1 - Good
Deficiency	No deficiencies recorded
Intrusion Alarm System	Inspected
Replacement Quantity	9,000
(D) Page 5 of 7	Print Data: 6/25/2024

Building Condition Assessment Survey 2023 - 2024

icai inspection	V-
estion	Response
ECURITY	
Intrusion Alarm System	
Replacement Uom	S.F.
Central Control Panel	Inspected
Instance	Custodian's Office
Instance Condition	1 - Good
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista-128BPT
Installation Year	2022
Source of Installation	Documented
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	1 - Good
Deficiency	SIREN/STROBE NOT ACTIVE
Deficiency Location/Instance	Exterior Wall - By Main Entrance, Corridor - By Rooms 102, 10 106, 114, 121
Deficiency Quantity	7
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Lighting - Security	Inspected
Replacement Uom	EACH
Condition	1 - Good
Deficiency ERVICE SWITCH	No deficiencies recorded Inspected
	*
Instance Instance Condition	Electrical Room 120 1 - Good
Instance Quantity	1 EACH
Instance Quantity Uom	EACH
Instance Manufacturer	General Electric
Equipment	N/A
Capacity/Size Quantity	600
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2022
Source of Installation	Documented

Building Condition Assessment Survey 2023 - 2024

uestion	Response Inspected 0	
SWITCHBOARD		
Number of Spares		
Fused Disconnect Switch Type	Inspected	
Instance	Electrical Room 120	
Instance Condition	1 - Good	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Instance Manufacturer	All City Switchboard	
Equipment	MDP	
Capacity/Size Quantity	600	
Capacity/Size UOM	Amps Total	
Capacity/Size2 Quantity	1	
Capacity/Size2 UOM	Section(S)	
Source of Capacity/Size	Nameplate	
Installation Year	2022	
Source of Installation	Documented	
Deficiency	No deficiencies recorded	
Fused Knife Switch Type	Does not Exist	
Molded Case Circuit Breaker Type	Does not Exist	
TELEPHONE SYSTEM	Inspected	
PBX/Intercom	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Standard	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
TRANSFORMER	Does not Exist	