	Q370
	T 4 E P4 . 1
	Last Edited
2024-01-02 12:52 PM	2024-01-12 5:30 PM
<b></b>	
No	
No	
No	
No	
Person(s) Person(s) Title Status Notified	PhotoImage
Response	
*	
Does not Exist	
Inspected	
MER 223	
1 - Good	
2	
EACH	
Electric	
*	
Inspected  1 - Good	
L - COOR	
No deficiencies recorded  Does not Exist	
	No N

Inspected Throughout 1 - Good 1 EACH 81-100% 2023 Documented No deficiencies recorded Does not Exist
Throughout 1 - Good 1 EACH 81-100% 2023 Documented No deficiencies recorded
1 - Good  1  EACH 81-100% 2023 Documented No deficiencies recorded
1 EACH 81-100% 2023 Documented No deficiencies recorded
EACH 81-100% 2023 Documented No deficiencies recorded
81-100% 2023 Documented No deficiencies recorded
2023 Documented No deficiencies recorded
Documented  No deficiencies recorded
No deficiencies recorded
Does not Exist
Does not Exist
Does not Exist
Does not Exist
Inspected
Does not Exist
Inspected
Yes
1 - Good
No deficiencies recorded
Does not Exist
Inspected
Does not Exist
Inspected
Does not Exist
Does not Exist
Inspected
1 - Good
No deficiencies recorded
Does not Exist
Does not Exist
Does not Exist
Inspected
1 - Good
No deficiencies recorded
Inspected
Inspected
1 - Good
No deficiencies recorded
Inspected
1 - Good
No deficiencies recorded
Does not Exist

chanical Inspection		Q37
uestion	Response	
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Does not Exist	
FIXTURES	Inspected	
Staff And Other	Inspected	
Janitor Sink	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Lavatory/Sink	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Toilet	Inspected	
Condition	1 - Good	
Deficiency	DEFECTIVE FLUSHOMETER VALVE	
Deficiency Location/Instance	Toilet Room 229 (Flushometer Sensor)	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
Urinal	Does not Exist	
Student	Inspected	
Drinking Fountain	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Lavatory/Sink	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Locker Room Shower	Does not Exist	
Sink And Fountain Combo Unit	Does not Exist	
Toilet	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Urinal	Does not Exist	
GAS FIRED FURNACE	Does not Exist	
GAS SERVICE	Does not Exist	
HEATING	Inspected	
Heating Coil In Ductwork	Does not Exist	
Hydronic Heating	Does not Exist	
Radiator/Convector/Fin Tube	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Steam Heating	Does not Exist	
Steam supplied by External Sources	Does not Exist	
Unit Heater/Cabinet Heater	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	-
HEATING PLANT	Does not Exist	

hanical Inspection		Q370
uestion	Response	
Enclosed IDF Room	Does not Exist	
KITCHEN	Inspected	
Instance on 2nd Floor	Inspected	
CO Detector	Not Required	
Instance on 2nd Floor	Not Required	
Gas System	Does not Exist	
Instance on 2nd Floor	Does not Exist	
Grease Trap	Inspected	
Instance on 2nd Floor	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Hood	Does not Exist	
Instance on 2nd Floor	Does not Exist	
Hood Exhaust Ductwork	Does not Exist	
Instance on 2nd Floor	Does not Exist	
Hood Exhaust Fan	Does not Exist	
Instance on 2nd Floor	Does not Exist	
Hood Fire Suppression System	Does not Exist	
Instance on 2nd Floor	Does not Exist	
Hot Water Temperature Booster	Does not Exist	
Instance on 2nd Floor	Does not Exist  Does not Exist	
Kitchen Sink		
Instance on 2nd Floor	Inspected	
Condition	Inspected  1 - Good	
Deficiency	No deficiencies recorded	
MDF Room	Inspected	
Instance on Room 209	Inspected	
Dedicated A/C Equipment  Instance on Room 209	Inspected	
Condition	Inspected 1 - Good	
Deficiency	No deficiencies recorded	
SCIENCE DEMO ROOM	Does not Exist	
SCIENCE LAB	Does not Exist  Does not Exist	
SCIENCE PREP ROOM	Does not Exist	
SPRINKLERS, STANDPIPE, FIRE SYSTEM	Inspected	
Dry Sprinkler Alarm Valve Assembly	Does not Exist	
Wet Sprinkler Alarm Valve Assembly	Does not Exist	
Fire Booster Pump Assembly	Does not Exist	
Roof Tank	Does not Exist	
Siamese Connection	Does not Exist	
Sprinkler Head	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Sprinkler Piping	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Standpipe System	Inspected	
Hose Valve Assembly	Inspected	

#### **Building Condition Assessment Survey 2023 - 2024**

Q376 Mechanical Inspection Question Response SPRINKLERS, STANDPIPE, FIRE SYSTEM Standpipe System Hose Valve Assembly Inspected Deficiency No deficiencies recorded **Piping** Inspected Condition 1 - Good Deficiency No deficiencies recorded Water Gong Does not Exist SWIMMING POOL Does not Exist VENTILATION Inspected Is the building mechanically ventilated? Yes **Exhaust Fan** Inspected 1-25 Approximate Total # of Fans Condition 1 - Good Deficiency No deficiencies recorded **Heating And Ventilating Unit** Does not Exist **Metal Ductwork** Inspected Are there any uninsulated ductwork by design in Mechanical No Are there chain operated dampers? No Condition 1 - Good Deficiency No deficiencies recorded **Supply Fan** Does not Exist **Unit Ventilator** Does not Exist