Building Condition Assessment Survey 2023 - 2024

Inspection Id	Inspection Ty	ype				Time In	Last Edited
EE: Q381	Electrical					2024-02-15 12:53 PM	2024-02-26 12:23 PM
Asset Data							
Question					Answer		
Type of Service					Below Gro	ound	
Does Interactive					Yes		
Water Penetration			1 1 10		No		
Have any System	is/Major Buildin	ig Components	been upgraded?		Yes Systems:	Retrofitted LED Lighting (Base	amant)
					Years:	2023	ement)
					Systems:	All Other Electrical Systems ar	nd Components
					Years:	2015	1
DEDICATED II	NTERCOMS II	N FIRE RESC	UE AREAS				
Question					Response		
Are there any Li and/or Holding I			e Rescue Areas,		No		
Priority Condition							
Priority Pr Condition Exist Ca Last Year?		Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title Status	PhotoImage
No condition recorde	ed						
Inspection							
Question					Respons	se	
Electrical							
AUDITORIUM					Does no	t Exist	
CAFETERIA					Does no	t Exist	
CLASSROOM/	CORRIDOR/A	DMINISTRAT	TIVE SPACE		Inspecte	d	
Lighting					Inspecte	d	
Does a	a Chandelier exi	st?			No		
Lighting Fix	kture - Fluoresc	ent			Inspecte	d	
Pendant N	Mounted				Inspecte	d	
Condition	on				2 - Betw	een Good and Fair	
Defici	ency				No defic	ciencies recorded	
Surface M	Iounted				Inspecte		
Condition						een Good and Fair	
Defici	-					ciencies recorded	
Recessed					Inspecte		
Condition						reen Good and Fair	
Defici	-				Does no	ciencies recorded	
Lighting Fix							
	xture - Incande	scent			Does no		
Lighting Fix					Inspecte		
Pendant M					Inspecte		
Condition						reen Good and Fair	
Defici-						ciencies recorded	
Surface M					Inspecte		
Condition	Ш					een Good and Fair	
Defici	am ar :				XT 1 €	ciencies recorded	

Building Condition Assessment Survey 2023 - 2024

uestion	Response	
COMPUTER LAB	Does not Exist	
GYMNASIUM	Does not Exist	
KITCHEN	Inspected	
Instance on 1st Floor	Inspected	
Lighting	Inspected	
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Inspected	
Pendant Mounted	Does not Exist	
Instance on 1st Floor	Does not Exist	
Surface Mounted	Does not Exist	
Instance on 1st Floor	Does not Exist	
Recessed Mounted	Inspected	
Instance on 1st Floor	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on 1st Floor	Does not Exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not Exist	
Lighting Fixture - LED		
Instance on 1st Floor	Does not Exist	
LIBRARY	Does not Exist	
LOCKER ROOM	Does not Exist	
MULTIPURPOSE ROOM	Inspected	
Instance on 1st Floor	Inspected	
Lighting	Inspected	
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Inspected	
Pendant Mounted	Does not Exist	
Instance on 1st Floor	Does not Exist	
Surface Mounted	Does not Exist	
Instance on 1st Floor	Does not Exist	
Recessed Mounted	Inspected	
Instance on 1st Floor	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on 1st Floor	Does not Exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not Exist	
Lighting Fixture - LED		
Instance on 1st Floor	Inspected	
Pendant Mounted	Does not Exist	
Instance on 1st Floor	Does not Exist	
Surface Mounted	Inspected	
Instance on 1st Floor	Inspected	

Condition

2 - Between Good and Fair

Building Condition Assessment Survey 2023 - 2024

Question	Response
MULTIPURPOSE ROOM	
Lighting	Inspected
Lighting Fixture - LED	
Surface Mounted	Inspected
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Local Sound System	Does not Exist
Instance on 1st Floor	Does not Exist
Projection System	Does not Exist
Instance on 1st Floor	Does not Exist
Theater Lighting System	Does not Exist
Instance on 1st Floor	Does not Exist
SCIENCE DEMO ROOM	Does not Exist
SCIENCE LAB	Does not Exist
SCIENCE PREP ROOM	Does not Exist
SWIMMING POOL	Does not Exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Does not Exist
Recessed Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Does not Exist
Recessed Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Replacement Quantity	12,000
Replacement Uom	S.F.
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not Exist
EMERGENCY GENERATOR SET	Does not Exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not Exist
EMERGENCY LIGHTING	Inspected
	•

Building Condition Assessment Survey 2023 - 2024

Question	Response
EMERGENCY LIGHTING	
Battery Pack	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Does not Exist
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Does not Exist
EXIT/EMERGENCY LIGHT	Does not Exist
FIRE ALARM SYSTEM	Inspected
Replacement Quantity	12,000
Replacement Uom	S.F.
Bell/Horn	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Manual Pull Station	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Duct Smoke Detector	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Area Smoke Detector	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
CO Detector	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Heat Detector	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Elevator Recall	Does not Exist
Magnetic Door Holder/Contactor	Does not Exist
Fused Cutout Panel	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Does not Exist
Main Panel	Inspected
Bell At Panel	Does not Exist
Fire Alarm Control Panel (Electronic)	Inspected Main Entrance Lobby
Instance Instance Condition	Main Entrance Lobby
Instance Condition	2 - Between Good and Fair
Instance Quantity (D) Page 4 of 7	1 Print Data: 6/05/2004

Building Condition Assessment Survey 2023 - 2024

arical hispection		Qsos
uestion	Response	
FIRE ALARM SYSTEM		
Main Panel		
Fire Alarm Control Panel (Electronic)		
Instance Quantity Uom	EACH	
Instance Manufacturer	Mircom	
Equipment	Fire Alarm Control	
Model	FX - 2000	
Installation Year	2015	
Source of Installation	Documented	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Standard)	Does not Exist	
Sub-Panel	Does not Exist	
Remote Annunciator	Inspected	
Display Monitor	Does not Exist	
Panel	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Printer	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Punch Register	Does not Exist	
Sprinkler Flow/Air Pressure Switch	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Tamper Flow Switch/Chain	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
GROUNDING SYSTEM	Does not Exist	
INTERCOM SYSTEM	Does not Exist	
LAN	Inspected	
Local Distribution Frame (I/LDF)	Does not Exist	
Main Equipment Rack (MDF)	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
LIGHTNING PROTECTION	Does not Exist	
MOTOR CONTROLLER	Inspected	
Motor Control Center	Does not Exist	
Motor Starter/Contactor	Does not Exist	
Variable Frequency Drive	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
PANEL BOARD	Inspected	
Fused Disconnect Switch Type	Does not Exist	
	Does not Exist Does not Exist	
Fused Knife Switch Type		
Fused Toggle Switch Type	Does not Exist	
Molded Case Circuit Breaker Type	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	NO SPARE	
Deficiency Location/Instance	Rooms (103, 104), Boiler Room	

Building Condition Assessment Survey 2023 - 2024

Question	Response		
PANEL BOARD			
Molded Case Circuit Breaker Type			
Deficiency Quantity	3		
Quantity Uom	EACH		
Potential Action	INSTALL NEW PANEL BOARD		
Urgency of Action	PRIORITY 3		
Purpose of Action	LEVEL 2		
Deficiency Photo1	No photo recorded		
Violations	No violations recorded.		
PUBLIC ADDRESS SYSTEM	Inspected		
Replacement Quantity	12,000		
Replacement Uom	S.F.		
Instance	Telecom Room 117		
Instance Condition	2 - Between Good and Fair		
Instance Quantity	1		
Instance Quantity Uom	EACH		
Model	Bogen Quantum Multicom IP		
Installation Year	2015		
Source of Installation	Documented		
Deficiency	No deficiencies recorded		
SECURITY	Inspected		
IPDVS/CCTV System	Inspected		
Replacement Quantity	12,000		
Replacement Uom	S.F.		
Installation Year	2015		
Source of Installation	Documented		
Condition	2 - Between Good and Fair		
Deficiency	No deficiencies recorded		
Intrusion Alarm System	Inspected		
Replacement Quantity	12,000		
Replacement Uom	S.F.		
Central Control Panel	Inspected		
Instance	Custodian's Office		
Instance Condition	2 - Between Good and Fair		
Instance Quantity	1		
Instance Quantity Uom	EACH		
Model	Vista-128BP		
Installation Year	2015		
Source of Installation	Documented		
Deficiency	No deficiencies recorded		
Infrared Sensor	Inspected		
Condition	2 - Between Good and Fair		
Deficiency	No deficiencies recorded		
Panic Switch	Inspected		
Condition	2 - Between Good and Fair		
Deficiency	No deficiencies recorded		
Remote Annunciator	Inspected		
Condition	2 - Between Good and Fair		
Deficiency	No deficiencies recorded		

Building Condition Assessment Survey 2023 - 2024

Question	Response	
SECURITY	Inspected	
Intrusion Alarm System	Inspected	
Siren/Strobe	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting - Security	Does not Exist	
SERVICE SWITCH	Inspected	
Instance	Electrical Room	
Instance Condition	2 - Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Instance Manufacturer	Siemens	
Equipment	Service Disconnect	
Capacity/Size Quantity	800	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	2015	
Source of Installation	Documented	
Deficiency	No deficiencies recorded	
SWITCHBOARD	Inspected	
Number of Spares	3	
Fused Disconnect Switch Type	Does not Exist	
Fused Knife Switch Type	Does not Exist	
Molded Case Circuit Breaker Type	Inspected	
Instance	Electrical Room	
Instance Condition	2 - Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Instance Manufacturer	Electrotech	
Equipment	N/A	
Capacity/Size Quantity	800	
Capacity/Size UOM	Amps Total	
Capacity/Size2 Quantity	1	
Capacity/Size2 UOM	Section(S)	
Source of Capacity/Size	Service Switch Size	
Installation Year	2015	
Source of Installation	Documented	
Deficiency	No deficiencies recorded	
TELEPHONE SYSTEM	Inspected	
PBX/Intercom	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Standard	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
TRANSFORMER	Does not Exist	