Building Condition Assessment Survey 2023 - 2024

Electrical Inspection Q382

Asset:	PRE-K CENTER @ 89-14 PARSONS BOULEVARD - QUEENS, 89-14 PARSONS
	ROLL EVADD Now York 11422

Inspection Id	Inspection Type		Time In	Last Edited
EE: Q382	Electrical		2023-11-29 12:13 PM	2023-12-26 12:40 PM
Asset Data				
Question		Answer		
Type of Service		Below Gro	ound	
Does Interactive	Whiteboard (IWB) Exist?	Yes		
Water Penetration	n in Electrical Room?	No		
Have any System	s/Major Building Components been upgraded?	Yes		
		Systems:	All Electrical Systems and Comp	onents
		Years:	2015	
DEDICATED II	NTERCOMS IN FIRE RESCUE AREAS			
Question		Response		
•	fe Rescue Assistance Areas, Fire Rescue Areas, Rooms in your building?	No		

Priority Condition

Priority Condition Exis Last Year?	Priority t Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
No	Fire Alarm System - Defective	N/A	FIRE ALARM SYSTEM Main Panel Fire Alarm Control Panel (Electronic)	Main Entrance a Lobby	Drew Brooks	Handyman	Sent to DSF	

uestion	Response	
lectrical		
AUDITORIUM	Does not Exist	
CAFETERIA	Does not Exist	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected	
Lighting	Inspected	
Does a Chandelier exist?	No	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID	Does not Exist	
Lighting Fixture - Incandescent	Does not Exist	
Lighting Fixture - LED	Inspected	
Pendant Mounted	Does not Exist	
Surface Mounted	Does not Exist	
Recessed Mounted	Inspected	
Condition	2 - Between Good and Fair	

Building Condition Assessment Survey 2023 - 2024

Question	Response
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	
Lighting Fixture - LED	
Recessed Mounted	
Deficiency	No deficiencies recorded
COMPUTER LAB	Does not Exist
GYMNASIUM	Does not Exist
KITCHEN	Inspected
Instance on 1st Floor	Inspected
Lighting	Inspected
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Surface Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Recessed Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not Exist
LIBRARY	Does not Exist
LOCKER ROOM	Does not Exist
MULTIPURPOSE ROOM	Inspected
Instance on 1st Floor	Inspected
Lighting	Inspected
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Surface Mounted	Does not Exist
Instance on 1st Floor	Does not Exist Does not Exist
Recessed Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not Exist
(D) Page 2 of 7	Dulat Data: 6/25/2024

Building Condition Assessment Survey 2023 - 2024

Question	Response
MULTIPURPOSE ROOM	
Local Sound System	Does not Exist
Instance on 1st Floor	Does not Exist
Projection System	Does not Exist
Instance on 1st Floor	Does not Exist
Theater Lighting System	Does not Exist
Instance on 1st Floor	Does not Exist
SCIENCE DEMO ROOM	Does not Exist
SCIENCE LAB	Does not Exist
SCIENCE PREP ROOM	Does not Exist
SWIMMING POOL	Does not Exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Does not Exist
Recessed Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Does not Exist
Recessed Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Replacement Quantity	10,000
Replacement Uom	S.F.
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not Exist
EMERGENCY GENERATOR SET	Does not Exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not Exist
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Does not Exist
EXIT LIGHT	Inspected
Battery Pack	Inspected
(D) Page 2 of 7	Drint Date: 6/25/2024

Building Condition Assessment Survey 2023 - 2024

•
Response
Inspected
Inspected
2 - Between Good and Fair
No deficiencies recorded
Does not Exist
Does not Exist
Inspected
10,000
S.F.
Inspected
2 - Between Good and Fair
No deficiencies recorded
Inspected
2 - Between Good and Fair
No deficiencies recorded
Inspected
2 - Between Good and Fair
No deficiencies recorded
Inspected
2 - Between Good and Fair
No deficiencies recorded
Inspected
2 - Between Good and Fair
No deficiencies recorded
Inspected
2 - Between Good and Fair
No deficiencies recorded
Inspected
2 - Between Good and Fair
No deficiencies recorded
Does not Exist
Does not Exist
Does not Exist
Inspected
2 - Between Good and Fair
No deficiencies recorded
Does not Exist
Inspected
Does not Exist
Inspected
Main Entrance Lobby
3 - Fair
3 - 1 an
1
1
1 EACH
1 EACH Gamewell
1 EACH Gamewell Fire Alarm Control Panel with D.A.C.T
1 EACH Gamewell

Building Condition Assessment Survey 2023 - 2024

Question	Response	
FIRE ALARM SYSTEM		
Main Panel		
Fire Alarm Control Panel (Electronic)		
Deficiency	SYSTEM DEFECTIVE	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPAIR SYSTEM	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 6	
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	

Fire Alarm Control Panel (Standard)	Does not Exist
Sub-Panel	Does not Exist
Remote Annunciator	Inspected
Display Monitor	Does not Exist
Panel	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Printer	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Punch Register	Does not Exist
Sprinkler Flow/Air Pressure Switch	Does not Exist
Tamper Flow Switch/Chain	Does not Exist
GROUNDING SYSTEM	Does not Exist
NTERCOM SYSTEM	Does not Exist
AN	Inspected
Local Distribution Frame (I/LDF)	Does not Exist
Main Equipment Rack (MDF)	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
IGHTNING PROTECTION	Does not Exist
MOTOR CONTROLLER	Inspected
Motor Control Center	Does not Exist
Motor Starter/Contactor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
ANEL BOARD	Inspected
Fused Disconnect Switch Type	Does not Exist
Fused Knife Switch Type	Does not Exist
Fused Toggle Switch Type	Does not Exist

Building Condition Assessment Survey 2023 - 2024

uestion	Response
PANEL BOARD	Inspected
Molded Case Circuit Breaker Type	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
PUBLIC ADDRESS SYSTEM	Inspected
Replacement Quantity	10,000
Replacement Uom	S.F.
Instance	MDF Room 112
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Bogen Quantum Multicom IP
Installation Year	2015
Source of Installation	Documented
Deficiency	No deficiencies recorded
SECURITY	Inspected
IPDVS/CCTV System	Inspected
Replacement Quantity	10,000
Replacement Uom	S.F.
Installation Year	2015
Source of Installation	Documented
Condition	3 - Fair
Deficiency	SYSTEM DEFECTIVE
Deficiency Location/Instance	MDF Room 112
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR SYSTEM
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Intrusion Alarm System	Inspected
Replacement Quantity	10,000
Replacement Uom	S.F.
Central Control Panel	Inspected
Instance	Custodian's Office
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH V. 1200DD
Model	Vista-128BP
Installation Year	2015
Source of Installation	Documented
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	2 - Between Good and Fair
Deficiency Desir Series	No deficiencies recorded
Panic Switch	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded

Building Condition Assessment Survey 2023 - 2024

uestion	Response		
SECURITY			
Intrusion Alarm System			
Remote Annunciator	Inspected		
Condition	2 - Between Good and Fair		
Deficiency	No deficiencies recorded		
Siren/Strobe	Inspected		
Condition	2 - Between Good and Fair		
Deficiency	No deficiencies recorded		
Lighting - Security	Does not Exist		
SERVICE SWITCH	Inaccessible		
SWITCHBOARD	Inspected		
Number of Spares	3		
Fused Disconnect Switch Type	Inspected		
Instance	Electrical Room 115		
Instance Condition	2 - Between Good and Fair		
Instance Quantity	1		
Instance Quantity Uom	EACH		
Instance Manufacturer	Siemens		
Equipment	PANEL MDB		
Capacity/Size Quantity	800		
Capacity/Size UOM	Amps Total		
Capacity/Size2 Quantity	1		
Capacity/Size2 UOM	Section(S)		
Source of Capacity/Size	Nameplate		
Installation Year	2015		
Source of Installation	Documented		
Deficiency	No deficiencies recorded		
Fused Knife Switch Type	Does not Exist		
Molded Case Circuit Breaker Type	Does not Exist		
FELEPHONE SYSTEM	Inspected		
PBX/Intercom	Inspected		
Condition	2 - Between Good and Fair		
Deficiency	No deficiencies recorded		
Standard	Inspected		
Condition	2 - Between Good and Fair		
Deficiency	No deficiencies recorded		
TRANSFORMER	Does not Exist		