#### **Building Condition Assessment Survey 2023 - 2024**

# Mechanical Inspection

Inspection Id Inspection Type	Time In	Last Edited
ME : Q382 Mechanical	2023-11-29 12:09 PM	2024-01-18 3:15 PM
Asset Data		
Question	Answer	
Are there fuel tanks?	No	
Total # of water main service entries to the asset	0	
MERs/Fan Rooms Locations	MER 111	
Are there any spaces with Missing or Defective CO Detectors?	No	
Are there any Emergency Stop Switches with Missing Hammers?	No	
Are there any Painted/Obstructed Sprinkler Heads? Have any Systems/Major Building Components been upgraded?	No No	
	10	
Priority Condition		
PriorityPriorityConditionComponentLocationCondition ExistCategoryDescriptionAffectedDescriptionLastYear?	Person(s) Person(s) Title Status Notified	PhotoImage
No condition recorded		
Inspection		
Question	Response	
Mechanical		
AIR CONDITIONING	Inspected	
Chilled Water System	Does not Exist	
Condenser Water Distribution: Piping, Pumps and Auxiliaries	Does not Exist	
Cooling Coil in Ductwork	Does not Exist	
Cooling Tower	Does not Exist	
DX Split System	Inspected	
Indoor Unit	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Outdoor Unit	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Dry Cooler	Does not Exist	
Packaged / Rooftop Unit	Does not Exist	
Packaged Terminal A/C	Does not Exist	
Refrigerant Leak Detection System	Does not Exist	
Refrigerant Piping	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Return Fan	Does not Exist	
CENTRAL ACID WASTE NEUTRALIZING TANK	Does not Exist	
CLIMATE CONTROL SYSTEM	Inspected	
BMS	Inspected	
Instance	Throughout	
Instance Condition	2 - Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Building Area Covered by Operational System	81-100%	
Installation Year	2015	

# **Building Condition Assessment Survey 2023 - 2024**

Response         Documented         No deficiencies recorded         Does not Exist         Does not Exist
No deficiencies recorded         Does not Exist         Inspected         Does not Exist         Inspected         Does not Exist
No deficiencies recorded         Does not Exist         Inspected         Does not Exist         Inspected         Does not Exist
Does not Exist         Does not Exist         Does not Exist         Does not Exist         Inspected         Does not Exist         Inspected         Does not Exist
Does not Exist         Does not Exist         Does not Exist         Inspected         Does not Exist         Inspected         Does not Exist
Does not Exist         Does not Exist         Inspected         Does not Exist         Inspected         Does not Exist         Does not Exist         Does not Exist         Does not Exist
Does not Exist         Does not Exist         Inspected         Does not Exist         Inspected         Does not Exist         Does not Exist
Does not Exist         Inspected         Does not Exist         Does not Exist         Does not Exist
Inspected Does not Exist Inspected Does not Exist Does not Exist
Does not Exist         Inspected         Does not Exist         Does not Exist
Inspected Does not Exist Does not Exist
Does not Exist Does not Exist
Does not Exist Does not Exist
Does not Exist
Inspected
2 - Between Good and Fair
No deficiencies recorded
Does not Exist
Does not Exist
Does not Exist
Inspected
1 - Good
No deficiencies recorded
Inspected
Inspected
1 - Good
No deficiencies recorded
Inspected
1 - Good
No deficiencies recorded
Does not Exist
Does not Exist
Does not Exist
Inspected
Inspected
Inspected
2 - Between Good and Fair
No deficiencies recorded
Inspected
2 - Between Good and Fair
No deficiencies recorded
Inspected
2 - Between Good and Fair No deficiencies recorded
Does not Exist
Inspected
Inspected

#### **Building Condition Assessment Survey 2023 - 2024**

uestion	Response	
FIXTURES		
Student		
Drinking Fountain	Inspected	
Deficiency	No deficiencies recorded	
Lavatory/Sink	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Locker Room Shower	Does not Exist	
Sink And Fountain Combo Unit	Does not Exist	
Toilet	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Urinal	Does not Exist	
GAS FIRED FURNACE	Does not Exist	
GAS SERVICE	Does not Exist	
HEATING	Inspected	
Heating Coil In Ductwork	Does not Exist	
Hydronic Heating	Inspected	
Hydronic Hot Water Distribution: Piping, Pumps and Auxiliaries Condition	Inspected 1 - Good	
Deficiency	No deficiencies recorded	
Backflow Preventer		
Condition	Inspected 2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Hot Water Heat Exchanger	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Radiator/Convector/Fin Tube	Does not Exist	
Steam Heating	Does not Exist	
Steam supplied by External Sources	Does not Exist	
Unit Heater/Cabinet Heater	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
HEATING PLANT	Does not Exist	
	Does not Exist	
Enclosed IDF Room		
KITCHEN	Inspected	
Instance on 1st Floor	Inspected	
CO Detector	Not Required	
Instance on 1st Floor	Not Required	
Gas System	Does not Exist	
Instance on 1st Floor	Does not Exist	
Grease Trap	Inspected	
Instance on 1st Floor	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Hood	Does not Exist	
Instance on 1st Floor	Does not Exist	
Hood Exhaust Ductwork	Does not Exist	

# **Building Condition Assessment Survey 2023 - 2024**

Response	
<b>X</b>	
Does not Exist	
Does not Exist	
Does not Exist	
-	
Inspected	
*	
Does not Exist	
Does not Exist	
Does not Exist	
Inspected	
Does not Exist	
-	
Inspected	
2 - Between Good and Fair	
No deficiencies recorded	
	Does not Exist         Inspected         Inspected         2 - Between Good and Fair         MISSING AIR GAP         Kitchen         1         EACH         MAINTENANCE         PRIORITY 3         LEVEL 2         No photo recorded         No violations recorded.         Inspected         Inspected         Inspected         Inspected         Inspected         Inspected         Does not Exist         Does not Exist

#### **Building Condition Assessment Survey 2023 - 2024**

#### Mechanical Inspection

	Q382
Response	
Does not Exist	
Inspected	
No	
No	
1 - Good	
No deficiencies recorded	
Does not Exist	
Does not Exist	
	Does not Exist Inspected No No 1 - Good No deficiencies recorded Does not Exist

(P)