Building Condition Assessment Survey 2023 - 2024 Electrical Inspection Asset: PRE-K CENTER @ 44-15 JUDGE STREET - QUEENS, 44-15 JUDGE STREET, New York, 11373 Last Edited Time In Inspection Id Inspection Type EE: 0391 Electrical 2024-04-18 12:43 PM 2024-04-25 3:43 PM Asset Data Question Answer Type of Service Below Ground Does Interactive Whiteboard (IWB) Exist? Yes Water Penetration in Electrical Room? No Have any Systems/Major Building Components been upgraded? Yes Systems: Security Lights Years: 2024 Multipurpose Room (Retrofitted LED Lighting) Systems: Years: 2021 Systems: Service Switch, Switchboard, Public Address System, Intrusion Alarm System, IPDVS/CCTV System, Fire Alarm System (Fused Cutout Panel), Fluorescent Lighting - Except (Multipurpose Room), Auxiliary Signal/Bell System, Exit Lights (Battery Pack), Emergency Lighting (Battery Pack), Exit/Emergency Light, Grounding System, LAN, Telephone System Years: 2015 Most Molded Case Circuit Breaker Type Panel Board Systems: 2000, 2015, 2021 Years: Systems: Multipurpose Room (Fluorescent Lighting) 2000 Years: DEDICATED INTERCOMS IN FIRE RESCUE AREAS Question Response Are there any Life Rescue Assistance Areas, Fire Rescue Areas, No and/or Holding Rooms in your building? **Priority Condition** Condition Location Person(s) Title Status Priority Priority Component Person(s) **PhotoImage** Condition Exist Category Description Description Notified Affected Last Year? No condition recorded Inspection Question Response Electrical AUDITORIUM Does not Exist CAFETERIA Does not Exist CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE Inspected Lighting Inspected Does a Chandelier exist? No **Lighting Fixture - Fluorescent** Inspected Pendant Mounted Inspected Condition 2 - Between Good and Fair Deficiency No deficiencies recorded Surface Mounted Inspected Condition 2 - Between Good and Fair Deficiency No deficiencies recorded **Recessed Mounted** Inspected

Condition

(P)

Deficiency

Lighting Fixture - HID

2 - Between Good and Fair

No deficiencies recorded

Does not Exist

| uestion | Response | |
|---|---|--|
| CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE | | |
| Lighting | | |
| Lighting Fixture - HID | | |
| Lighting Fixture - Incandescent | Does not Exist | |
| Lighting Fixture - LED | Does not Exist | |
| COMPUTER LAB | Does not Exist | |
| GYMNASIUM | Does not Exist | |
| KITCHEN | Inspected | |
| Instance on 1st Floor | Inspected | |
| Lighting | Inspected | |
| Instance on 1st Floor | Inspected | |
| Lighting Fixture - Fluorescent | 1 | |
| Instance on 1st Floor | Inspected | |
| Pendant Mounted | Does not Exist | |
| Instance on 1st Floor | Does not Exist | |
| Surface Mounted | Does not Exist | |
| Instance on 1st Floor | Does not Exist | |
| Recessed Mounted | Inspected | |
| Instance on 1st Floor | Inspected | |
| Condition | 2 - Between Good and Fair | |
| Deficiency | No deficiencies recorded | |
| Lighting Fixture - HID | | |
| Instance on 1st Floor | Does not Exist | |
| Lighting Fixture - Incandescent | | |
| Instance on 1st Floor | Does not Exist | |
| Lighting Fixture - LED | Doos not Lank | |
| Instance on 1st Floor | Does not Exist | |
| LIBRARY | Does not Exist | |
| | | |
| LOCKER ROOM | Does not Exist | |
| MULTIPURPOSE ROOM | Inspected | |
| Instance on Basement | Inspected | |
| Lighting | Inspected | |
| Instance on Basement | Inspected | |
| Lighting Fixture - Fluorescent | | |
| Instance on Basement | Inspected | |
| Pendant Mounted | Inspected | |
| Instance on Basement | Inspected | |
| Condition | 3 - Fair | |
| Deficiency | No deficiencies recorded | |
| Surface Mounted | Inspected | |
| Instance on Basement | Inspected | |
| Condition | 3 - Fair No deficiencies recorded | |
| Deficiency Recessed Mounted | No deficiencies recorded Does not Exist | |
| Instance on Basement | Does not Exist Does not Exist | |
| | DOES HOU EXIST | |
| Lighting Fixture - HID | Doos not Evict | |
| Instance on Basement | Does not Exist | |
| Lighting Fixture - Incandescent | | |
| Instance on Basement | Does not Exist | |

| ctrical Inspection | | |
|-------------------------|-------------------------------------|--|
| uestion | Response | |
| MULTIPURPOSE ROOM | | |
| Lighting | | |
| Lighting Fixture - LED | | |
| Instance on Basement | Inspected | |
| Pendant Mounted | Does not Exist | |
| Instance on Basement | Does not Exist | |
| Surface Mounted | Inspected | |
| Instance on Basement | Inspected | |
| Condition | 2 - Between Good and Fair | |
| Deficiency | No deficiencies recorded | |
| Recessed Mounted | Does not Exist | |
| Instance on Basement | Does not Exist | |
| Local Sound System | Inspected | |
| Instance on Basement | Inspected | |
| Installation Year | 2000 | |
| Source of Installation | Inspector Estimate | |
| Condition | 3 - Fair | |
| Deficiency | No deficiencies recorded | |
| Projection System | Does not Exist | |
| Instance on Basement | Does not Exist | |
| Theater Lighting System | Inspected | |
| Instance on Basement | Inspected | |
| Dimming System | | |
| Instance on Basement | Does not Exist | |
| Theater Lighting | | |
| Instance on Basement | Inspected | |
| Condition | 3 - Fair | |
| Deficiency | LIGHTING FIXTURE NOT OPERATIONAL | |
| Deficiency Quantity | 28 | |
| Quantity Uom | EACH | |
| Potential Action | REPLACE | |
| Urgency of Action | PRIORITY 3 | |
| Purpose of Action | LEVEL 2 | |
| Deficiency Photo1 | No photo recorded | |
| Violations | No violations recorded. | |
| | | |
| Deficiency | LIGHTING FIXTURE BEYOND USEFUL LIFE | |
| Deficiency Quantity | 110 | |
| Quantity Uom | EACH | |
| Potential Action | REPLACE-UPGRADE | |
| Urgency of Action | PRIORITY 1 | |
| Purpose of Action | LEVEL 2 | |
| Deficiency Photo1 | No photo recorded | |
| Violations | No violations recorded. | |
| SCIENCE DEMO ROOM | Does not Exist | |
| SCIENCE LAB | Does not Exist | |
| SCIENCE PREP ROOM | Does not Exist | |
| SWIMMING POOL | Does not Exist | |
| TOILET ROOM - STAFF | Inspected | |
| | Inspected | |

| uestion | Response | |
|---|---------------------------|--|
| TOILET ROOM - STAFF | | |
| Lighting | | |
| Lighting Fixture - Fluorescent | Inspected | |
| Pendant Mounted | Does not Exist | |
| Surface Mounted | Inspected | |
| Condition | 2 - Between Good and Fair | |
| Deficiency | No deficiencies recorded | |
| Recessed Mounted | Does not Exist | |
| Lighting Fixture - HID | Does not Exist | |
| Lighting Fixture - Incandescent | Does not Exist | |
| Lighting Fixture - LED | Does not Exist | |
| TOILET ROOM - STUDENT | Inspected | |
| Lighting | Inspected | |
| Lighting Fixture - Fluorescent | Inspected | |
| Pendant Mounted | Inspected | |
| | 2 - Between Good and Fair | |
| Deficiency | No deficiencies recorded | |
| Surface Mounted | Does not Exist | |
| Recessed Mounted | Does not Exist | |
| Lighting Fixture - HID | Does not Exist | |
| Lighting Fixture - Incandescent | Does not Exist | |
| | | |
| Lighting Fixture - LED | Does not Exist | |
| AUXILIARY SIGNAL/BELL SYSTEM | Inspected | |
| Replacement Quantity | 12,000 | |
| Replacement Uom | S.F. | |
| Condition | 2 - Between Good and Fair | |
| Deficiency EMERGENCY DC STANDBY BATTERY POWER | No deficiencies recorded | |
| | Does not Exist | |
| EMERGENCY GENERATOR SET | Does not Exist | |
| EMERGENCY LIGHT/EXIT LIGHT PANEL | Does not Exist | |
| EMERGENCY LIGHTING | Inspected | |
| Battery Pack | Inspected | |
| Condition | 2 - Between Good and Fair | |
| Deficiency | No deficiencies recorded | |
| Non Battery Pack | Does not Exist | |
| EXIT LIGHT | Inspected | |
| Battery Pack | Inspected | |
| Condition | 2 - Between Good and Fair | |
| Deficiency | No deficiencies recorded | |
| Non Battery Pack | Does not Exist | |
| EXIT/EMERGENCY LIGHT | Inspected | |
| Condition | 2 - Between Good and Fair | |
| Deficiency EIDE ALADM SYSTEM | No deficiencies recorded | |
| FIRE ALARM SYSTEM | Inspected 12,000 | |
| Replacement Quantity | 12,000 | |
| Replacement Uom | S.F. | |
| Bell/Horn | Inspected | |

Building Condition Assessment Survey 2023 - 2024

| uestion | Response | |
|---------------------------------------|---------------------------|--|
| FIRE ALARM SYSTEM | | |
| Bell/Horn | Inspected | |
| Deficiency | No deficiencies recorded | |
| Strobe | Does not Exist | |
| Manual Pull Station | Inspected | |
| Condition | 3 - Fair | |
| Deficiency | No deficiencies recorded | |
| Fan Shutdown Control | Does not Exist | |
| Duct Smoke Detector | Does not Exist | |
| Area Smoke Detector | Does not Exist | |
| CO Detector | Does not Exist | |
| Heat Detector | Does not Exist | |
| Elevator Recall | Does not Exist | |
| Magnetic Door Holder/Contactor | Does not Exist | |
| Fused Cutout Panel | Inspected | |
| | 2 - Between Good and Fair | |
| Deficiency | No deficiencies recorded | |
| Fire Alarm Digital Communicator | Does not Exist | |
| Main Panel | Inspected | |
| Bell At Panel | - | |
| Condition | Inspected 3 - Fair | |
| Deficiency | No deficiencies recorded | |
| Fire Alarm Control Panel (Electronic) | Does not Exist | |
| Fire Alarm Control Panel (Standard) | Inspected | |
| Instance | Boiler Room | |
| Instance Condition | 3 - Fair | |
| Instance Quantity | 1 | |
| Instance Quantity Uom | EACH | |
| Instance Manufacturer | Edwards | |
| | Fire Alarm Control Panel | |
| Equipment | 1951 | |
| Source of Installation | Documented | |
| Deficiency | No deficiencies recorded | |
| Sub-Panel | Does not Exist | |
| Remote Annunciator | Does not Exist | |
| Sprinkler Flow/Air Pressure Switch | Does not Exist | |
| Tamper Flow Switch/Chain | Does not Exist | |
| | | |
| GROUNDING SYSTEM | Inspected | |
| Condition | 2 - Between Good and Fair | |
| Deficiency | No deficiencies recorded | |
| INTERCOM SYSTEM | Does not Exist | |
| | Inspected | |
| Local Distribution Frame (I/LDF) | Does not Exist | |
| Main Equipment Rack (MDF) | Inspected | |
| Condition | 2 - Between Good and Fair | |
| Deficiency | No deficiencies recorded | |
| LIGHTNING PROTECTION | Does not Exist | |

(P)

| iestion | Response |
|----------------------------------|--------------------------------|
| MOTOR CONTROLLER | |
| Motor Control Center | Does not Exist |
| Motor Starter/Contactor | Inspected |
| Condition | 3 - Fair |
| Deficiency | No deficiencies recorded |
| Variable Frequency Drive | Does not Exist |
| PANEL BOARD | |
| | Inspected |
| Fused Disconnect Switch Type | Does not Exist |
| Fused Knife Switch Type | Does not Exist |
| Fused Toggle Switch Type | Does not Exist |
| Molded Case Circuit Breaker Type | Inspected |
| Condition | 2 - Between Good and Fair |
| Deficiency | PANEL BOARD BEYOND USEFUL LIFE |
| Deficiency Location/Instance | Slop sink across Room 107B |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE-UPGRADE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| Deficiency | NO SPARE |
| Deficiency Location/Instance | Boiler Room |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | INSTALL NEW PANEL BOARD |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Deficiency Photo1 | No photo recorded |
| Violations | No violations recorded. |
| | |
| PUBLIC ADDRESS SYSTEM | Inspected 12,000 |
| Replacement Quantity | 12,000 |
| Replacement Uom | S.F. |
| Instance | MDF Room 103A |
| Instance Condition | 2 - Between Good and Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Model | Telecor XL |
| Installation Year | 2015 |
| Source of Installation | Documented |
| Deficiency | No deficiencies recorded |
| SECURITY | Inspected |
| IPDVS/CCTV System | Inspected |
| Replacement Quantity | 12,000 |
| Replacement Uom | S.F. |
| Installation Year | 2015 |
| Source of Installation | Documented |
| Condition | 2 - Between Good and Fair |
| Deficiency | No deficiencies recorded |

| lestion | Response | |
|------------------------------|---------------------------|--|
| SECURITY | · · · · · | |
| Intrusion Alarm System | Inspected | |
| Replacement Quantity | 12,000 | |
| Replacement Uom | S.F. | |
| Central Control Panel | Inspected | |
| Instance | Custodian's Office | |
| Instance Condition | 2 - Between Good and Fair | |
| Instance Quantity | 1 | |
| Instance Quantity Uom | EACH | |
| Model | Vista-128BPT | |
| Installation Year | 2015 | |
| Source of Installation | Documented | |
| Deficiency | No deficiencies recorded | |
| Infrared Sensor | Inspected | |
| Condition | 2 - Between Good and Fair | |
| Deficiency | No deficiencies recorded | |
| Panic Switch | Inspected | |
| Condition | 2 - Between Good and Fair | |
| Deficiency | No deficiencies recorded | |
| Remote Annunciator | Inspected | |
| Condition | 2 - Between Good and Fair | |
| Deficiency | No deficiencies recorded | |
| Siren/Strobe | Inspected | |
| Condition | 2 - Between Good and Fair | |
| Deficiency | No deficiencies recorded | |
| Lighting - Security | Inspected | |
| Replacement Uom | EACH | |
| Condition | 1 - Good | |
| Deficiency | No deficiencies recorded | |
| SERVICE SWITCH | Inspected | |
| Instance | Boiler Room | |
| Instance Condition | 2 - Between Good and Fair | |
| Instance Quantity | 1 | |
| Instance Quantity Uom | EACH | |
| Instance Manufacturer | Square D | |
| Equipment | Main Switch | |
| Capacity/Size Quantity | 800 | |
| Capacity/Size UOM | Amps | |
| Source of Capacity/Size | Nameplate | |
| Installation Year | 2015 | |
| Source of Installation | Documented | |
| Deficiency | No deficiencies recorded | |
| SWITCHBOARD | Inspected | |
| Number of Spares | 4 | |
| Fused Disconnect Switch Type | Inspected | |
| Instance | Boiler Room | |
| Instance Condition | 2 - Between Good and Fair | |
| Instance Quantity | 1 | |
| Instance Quantity Uom | EACH | |

Building Condition Assessment Survey 2023 - 2024

Q391 **Electrical Inspection** Question Response SWITCHBOARD Fused Disconnect Switch Type Equipment N/A Capacity/Size Quantity 800 Capacity/Size UOM Amps Total Capacity/Size2 Quantity 1 Capacity/Size2 UOM Section(S) Nameplate Source of Capacity/Size 2015 Installation Year Source of Installation Documented Deficiency No deficiencies recorded Fused Knife Switch Type Does not Exist Molded Case Circuit Breaker Type Does not Exist TELEPHONE SYSTEM Inspected PBX/Intercom Inspected Condition 2 - Between Good and Fair Deficiency No deficiencies recorded Standard Inspected Condition 2 - Between Good and Fair No deficiencies recorded Deficiency TRANSFORMER Does not Exist

Page 8 of 8