Building Condition Assessment Survey 2023 - 2024

Inspection Id	Inspection Type					Time In	Last Edited
EE: Q399	Electrical					2023-11-16 12:52 PM	2024-01-05 11:23 AN
sset Data							
Question					Answer		
Type of Service					Below Gro	ound	
Does Interactive W	hiteboard (IWB) Ex	xist?			Yes		
Water Penetration i	in Electrical Room?				No		
Have any Systems/	Major Building Con	nponents	been upgraded?		Yes		
					Systems:	All Electrical Systems and Com (Intercom System - Elevator)	ponents - Except
					Years:	2023	
Ouestion	TERCOMS IN FIR	E RESC	CUE AREAS		Dogwongo		
Are there any Life	Rescue Assistance A	Areas, Fi	re Rescue Areas,		No No		
riority Condition							
Priority Prio Condition Exist Cate Last Year?			Component Affected	Location Description	Person(s) Notified	Person(s) Title Status	PhotoImage
No condition recorded							
nspection							
Question					Respons	se	
Electrical							
AUDITORIUM					Does no	t Exist	
CAFETERIA					Does no	t Exist	
CLASSROOM/C	ORRIDOR/ADMIN	NISTRA	TIVE SPACE		Inspecte	d	
Lighting					Inspecte	d	
Does a C	Chandelier exist?				No		
Lighting Fixt	ure - Fluorescent				Does no	t Exist	
Lighting Fixtu	ure - HID				Does no	t Exist	
Lighting Fixt	ure - Incandescent				Does no	t Exist	
Lighting Fixtu	ure - LED				Inspecte	d	
Pendant Mo	ounted				Inspecte	d	
Condition					1 - Good	1	
Deficien	ісу				No defic	riencies recorded	
Surface Mo	unted				Inspecte	d	
Condition					1 - Good		
Deficien					No defic	riencies recorded	
Recessed M					Inspecte		
Condition					1 - Good		
Deficien						riencies recorded	
COMPUTER LAI	В				Does no	t Exist	
GYMNASIUM					Does no	t Exist	
KITCHEN					Inspecte		
	on Basement				Inaccess	ible	
					Does no	t Exist	
LIBRARY							
	Ī				Does no	t Exist	

Building Condition Assessment Survey 2023 - 2024

arical hispection		Q57
uestion	Response	
MULTIPURPOSE ROOM		
Lighting	Inspected	
Instance on 2nd Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 2nd Floor	Does not Exist	
Lighting Fixture - HID		
Instance on 2nd Floor	Does not Exist	
Lighting Fixture - Incandescent		
Instance on 2nd Floor	Does not Exist	
Lighting Fixture - LED		
Instance on 2nd Floor	Inspected	
Pendant Mounted	Does not Exist	
Instance on 2nd Floor	Does not Exist	
Surface Mounted	Does not Exist	
Instance on 2nd Floor	Does not Exist	
Recessed Mounted	Inspected	
Instance on 2nd Floor	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Local Sound System	Does not Exist	
Instance on 2nd Floor	Does not Exist	
Projection System	Does not Exist	
Instance on 2nd Floor	Does not Exist	
Theater Lighting System	Does not Exist	
Instance on 2nd Floor	Does not Exist	
SCIENCE DEMO ROOM	Does not Exist	
SCIENCE LAB	Does not Exist	
SCIENCE PREP ROOM	Does not Exist	
SWIMMING POOL	Does not Exist	
TOILET ROOM - STAFF	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Does not Exist	
Lighting Fixture - HID	Does not Exist	
Lighting Fixture - Incandescent	Does not Exist	
Lighting Fixture - LED	Inspected	
Pendant Mounted	Does not Exist	
Surface Mounted		
	Does not Exist	
Recessed Mounted Condition	Inspected	
	1 - Good	
Deficiency TOILET ROOM - STUDENT	No deficiencies recorded	
	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Does not Exist	
Lighting Fixture - HID	Does not Exist	
Lighting Fixture - Incandescent	Does not Exist	
Lighting Fixture - LED	Inspected	
Lighting Fixture - LED Pendant Mounted	Inspected Does not Exist	

Building Condition Assessment Survey 2023 - 2024

Question	Response
TOILET ROOM - STUDENT	Inspected
Lighting	
Lighting Fixture - LED	
Recessed Mounted	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Replacement Quantity	5,400
Replacement Uom	S.F.
Condition	1 - Good
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not Exist
EMERGENCY GENERATOR SET	Does not Exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not Exist
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Non Battery Pack	Does not Exist
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Non Battery Pack	Does not Exist
EXIT/EMERGENCY LIGHT	Does not Exist
FIRE ALARM SYSTEM	Inspected
Replacement Quantity	5,400
Replacement Uom	S.F.
Bell/Horn	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Manual Pull Station	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Fan Shutdown Control	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Duct Smoke Detector	Inspected
Condition	1 - Good
Deficiency Area Smoke Detector	No deficiencies recorded
Condition	Inspected 1 - Good
Deficiency CO Detector	No deficiencies recorded Does not Exist
Heat Detector Condition	Inspected
Condition Deficiency	1 - Good No deficiencies recorded
(P)	Page 3 of 7 Print Date: 6/25/2024

Building Condition Assessment Survey 2023 - 2024

iteal hispection		QUI
estion	Response	
FIRE ALARM SYSTEM		
Elevator Recall	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Magnetic Door Holder/Contactor	Does not Exist	
Fused Cutout Panel	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Fire Alarm Digital Communicator	Does not Exist	
Main Panel	Inspected	
Bell At Panel	Does not Exist	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Main Entrance Lobby	
Instance Condition	1 - Good	
Instance Quantity	1	
Instance Quantity Uom	ЕАСН	
Instance Manufacturer	Edwards System Technology	
Equipment	Fire Alarm Control Panel	
Model	EST 3	
Installation Year	2023	
Source of Installation	Documented	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Standard)	Does not Exist	
Sub-Panel	Does not Exist	
Remote Annunciator	Inspected	
Display Monitor	Does not Exist	
Panel	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Printer	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Punch Register	Does not Exist	
Sprinkler Flow/Air Pressure Switch	Does not Exist	
Tamper Flow Switch/Chain	Does not Exist	
GROUNDING SYSTEM	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
NTERCOM SYSTEM	Inspected	
Elevator	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Holding Area	Does not Exist	
AN	Inspected	
Local Distribution Frame (I/LDF)	Does not Exist	
Main Equipment Rack (MDF)	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
LIGHTNING PROTECTION	Does not Exist	

Building Condition Assessment Survey 2023 - 2024

Question	Response	
MOTOR CONTROLLER	Inspected	
Motor Control Center	Does not Exist	
Motor Starter/Contactor	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Variable Frequency Drive	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
PANEL BOARD	Inspected	
Fused Disconnect Switch Type	Does not Exist	
Fused Knife Switch Type	Does not Exist	
Fused Toggle Switch Type	Does not Exist	
Molded Case Circuit Breaker Type	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
PUBLIC ADDRESS SYSTEM	Inspected	
Replacement Quantity	5,400	
Replacement Uom	S.F.	
Instance	Telecoms Room 104	
Instance Condition	1 - Good	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Model	Telecor XL	
Installation Year	2023	
Source of Installation	Documented	
Deficiency	No deficiencies recorded	
SECURITY	Inspected	
IPDVS/CCTV System	Inspected	
Replacement Quantity	5,400	
Replacement Uom	S.F.	
Installation Year	2023	
Source of Installation	Documented	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Intrusion Alarm System	Inspected	
Replacement Quantity	5,400	
Replacement Uom	S.F.	
Central Control Panel	Inspected	
Instance	Custodian's Office	
Instance Condition	1 - Good	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Model	Vista-128BPT	
Installation Year	2023	
Source of Installation	Documented	
AODICE OF HISTARIANON	Documented	
	No deficiencies recorded	
Deficiency	No deficiencies recorded Inspected	
	No deficiencies recorded Inspected 1 - Good	

Building Condition Assessment Survey 2023 - 2024

uestion	Response		
SECURITY			
Intrusion Alarm System			
Panic Switch	Inspected		
Condition	1 - Good		
Deficiency	No deficiencies recorded		
Remote Annunciator	Inspected		
Condition	1 - Good		
Deficiency	No deficiencies recorded		
Siren/Strobe	Inspected		
Condition	1 - Good		
Deficiency	No deficiencies recorded		
Lighting - Security	Inspected		
Replacement Uom	EACH		
Condition	1 - Good		
Deficiency	No deficiencies recorded		
SERVICE SWITCH	Inspected		
Instance	Electrical Room C08		
Instance Condition	1 - Good		
Instance Quantity	1		
Instance Quantity Uom	EACH		
Instance Manufacturer	All City Switchboard		
Equipment	N/A		
Capacity/Size Quantity	1,200		
Capacity/Size UOM	Amps		
Source of Capacity/Size	Nameplate		
Installation Year	2023		
Source of Installation	Documented		
Deficiency	No deficiencies recorded		
SWITCHBOARD	Inspected		
Number of Spares	3		
Fused Disconnect Switch Type	Inspected		
Instance	Electrical Room C08		
Instance Condition	1 - Good		
Instance Quantity	1		
Instance Quantity Uom	EACH		
Instance Manufacturer	All City Switchboard		
Equipment	N/A		
Capacity/Size Quantity	1,200		
Capacity/Size UOM	Amps Total		
Capacity/Size2 Quantity	2		
Capacity/Size2 UOM	Section(S)		
Source of Capacity/Size	Nameplate		
Installation Year	2023		
Source of Installation	Documented		
Deficiency	No deficiencies recorded		
Fused Knife Switch Type	Does not Exist		
Molded Case Circuit Breaker Type	Does not Exist		
TELEPHONE SYSTEM	Inspected		

Building Condition Assessment Survey 2023 - 2024

uestion	Response	
TELEPHONE SYSTEM		
PBX/Intercom	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Standard	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
FRANSFORMER	Does not Exist	