

**NYC Department of Education  
Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

**Q415**

**Asset: BENJAMIN N. CARDOZO HS - Q, 57-00 223 STREET, New York, 11364**

Inspection Id	Inspection Type	Time In	Last Edited
EE : Q415	Electrical	2023-11-20 8:16 AM	2023-12-08 3:33 PM

**Asset Data**

Question	Answer
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration in Electrical Room?	No
Have any Systems/Major Building Components been upgraded?	Yes
	Systems: Fire Alarm System (CO Detector, Electronic Sub-Panel), Motor Controller (Variable Frequency Drive)
	Years: Under Construction
	Systems: Toilet Room (LED Lighting)
	Years: 2023
	Systems: Computer Lab - Room B37 (Raceway With Receptacles), Partial Emergency Lighting (Battery Pack), Partial Fused Disconnect Switch Type Panel Board
	Years: 2021
	Systems: Exit/Emergency Light
	Years: 2020
	Systems: Library (Raceway With Receptacles), Intercom System (Elevator)
	Years: 2017
	Systems: Gymnasium (LED Lighting)
	Years: 2015
	Systems: Most Exit Lights (Battery Pack), Intrusion Alarm System (Except Panic Switch)
	Years: 2014
	Systems: Emergency Generator Set (Automatic Transfer Switch, Battery Charger), Fire Alarm System
	Years: 2010
	Systems: IPDVS/CCTV System
	Years: 2007
	Systems: Auditorium (Theater Lighting System), Local Sound System, Public Address System
	Years: 2005
	Systems: Emergency Light/Exit Light Panel
	Years: 2000
	Systems: Fire Alarm System (Fused Cutout Panel, Remote Annunciator Panel)
	Years: 1997, 2010
	Systems: Security Lights
	Years: 1995, 2004, 2010
	Systems: Incandescent Lighting (Science Demo Room B33, Science Lab - Rooms B35, B39)
	Years: 1995
	Systems: Partial Molded Case Circuit Breaker Type Panel Board
	Years: 1990, 2002, 2007, 2017

**DEDICATED INTERCOMS IN FIRE RESCUE AREAS**

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	Yes
Are dedicated intercoms available in all of these spaces for use during a fire?	No
Which spaces do not have dedicated intercoms?	Rooms 207, 241, 307, 325

**Priority Condition**

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q415

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
Yes	Fire Alarm System - Components Not Operational	N/A	FIRE ALARM SYSTEM   Strobe	Exterior Wall by Exit 16 (Facing TCU), Students Toilet Room (Inside Room B66 - Girls Locker Room)	Scott Kruse	Custodian	Sent to DSF	

Inspection

Question	Response
<b>Electrical</b>	
<b>AUDITORIUM</b>	Inspected
Instance on 1st Floor	Inaccessible
<b>CAFETERIA</b>	Inspected
Instance on 1st Floor	Inspected
<b>Lighting</b>	Inspected
Instance on 1st Floor	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 1st Floor	Inspected
<b>Pendant Mounted</b>	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Surface Mounted</b>	Inspected
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	11
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Recessed Mounted</b>	Inspected
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	131
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q415

Question	Response
<b>CAFETERIA</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Recessed Mounted</b>	
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Lighting Fixture - HID</b>	
Instance on 1st Floor	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 1st Floor	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on 1st Floor	Does not Exist
<b>Local Sound System</b>	
	Inspected
Instance on 1st Floor	Inspected
Installation Year	2005
Source of Installation	Custodial Staff
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Projection System</b>	
	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Theater Lighting System</b>	
	Does not Exist
Instance on 1st Floor	Does not Exist
<b>CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE</b>	
	Inspected
<b>Lighting</b>	
	Inspected
Does a Chandelier exist?	No
<b>Lighting Fixture - Fluorescent</b>	
	Inspected
<b>Pendant Mounted</b>	
	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	231
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Surface Mounted</b>	
	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	15
Quantity Uom	EACH

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

**Q415**

**Question**

**Response**

**CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE**

**Lighting**

**Lighting Fixture - Fluorescent**

**Surface Mounted**

Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.

Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	2,250
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.

**Recessed Mounted**

Inspected

Condition	3 - Fair
-----------	----------

Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	570
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.

Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.

**Lighting Fixture - HID**

Does not Exist

**Lighting Fixture - Incandescent**

Inspected

**Pendant Mounted**

Inspected

Condition	3 - Fair
-----------	----------

Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	33
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.

**Surface Mounted**

Inspected

Condition	3 - Fair
-----------	----------

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q415

Question	Response
<b>CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Incandescent</b>	
<b>Surface Mounted</b>	
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	20
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Recessed Mounted</b>	
Condition	Inspected
Deficiency	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	25
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Lighting Fixture - LED</b>	
	Does not Exist
<b>COMPUTER LAB</b>	
	Inspected
Instance on Room 150	Inspected
Power Panel	No
Instance on Room 243	Inspected
Power Panel	Yes
Instance on Room 346	Inspected
Power Panel	Yes
Instance on Room 347	Inspected
Power Panel	Yes
Instance on Room 348	Inspected
Power Panel	No
Instance on Room B37	Inaccessible
Instance on Rooms 265, 353	Inspected
Power Panel	Yes
<b>Lighting</b>	
	Inspected
Instance on Rooms 265, 353	Inspected
Instance on Room 348	Inspected
Instance on Room 347	Inspected
Instance on Room 346	Inspected
Instance on Room 243	Inspected
Instance on Room 150	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Rooms 265, 353	Inspected
Instance on Room 348	Inspected
Instance on Room 347	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q415

Question	Response
<b>COMPUTER LAB</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 346	Inspected
Instance on Room 243	Inspected
Instance on Room 150	Inspected
<b>Pendant Mounted</b>	
Instance on Rooms 265, 353	Does not Exist
Instance on Room 348	Does not Exist
Instance on Room 347	Does not Exist
Instance on Room 346	Does not Exist
Instance on Room 243	Does not Exist
Instance on Room 150	Does not Exist
<b>Surface Mounted</b>	
Instance on Rooms 265, 353	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	36
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room 348	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	21
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room 347	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

**Q415**

<b>Question</b>	<b>Response</b>
<b>COMPUTER LAB</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Surface Mounted</b>	
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	26
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room 346	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	24
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room 243	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	20
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room 150	Does not Exist
<b>Recessed Mounted</b>	Does not Exist
Instance on Rooms 265, 353	Does not Exist
Instance on Room 348	Does not Exist
Instance on Room 347	Does not Exist
Instance on Room 346	Does not Exist
Instance on Room 243	Does not Exist
Instance on Room 150	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	16
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

**Q415**

<b>Question</b>	<b>Response</b>
<b>COMPUTER LAB</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Recessed Mounted</b>	
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Lighting Fixture - HID</b>	
Instance on Rooms 265, 353	Does not Exist
Instance on Room 348	Does not Exist
Instance on Room 347	Does not Exist
Instance on Room 346	Does not Exist
Instance on Room 243	Does not Exist
Instance on Room 150	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Rooms 265, 353	Does not Exist
Instance on Room 348	Does not Exist
Instance on Room 347	Does not Exist
Instance on Room 346	Does not Exist
Instance on Room 243	Does not Exist
Instance on Room 150	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Rooms 265, 353	Does not Exist
Instance on Room 348	Does not Exist
Instance on Room 347	Does not Exist
Instance on Room 346	Does not Exist
Instance on Room 243	Does not Exist
Instance on Room 150	Does not Exist
<b>Raceway With Receptacles</b>	Inspected
Instance on Rooms 265, 353	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 348	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 347	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 346	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 243	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 150	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>GYMNASIUM</b>	Inspected
Instance on 1st Floor - Boys	Inspected



**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q415

Question	Response
<b>GYMNASIUM</b>	
Instance on 1st Floor - Girls	Inspected
<b>Lighting</b>	Inspected
Instance on 1st Floor - Girls	Inspected
Instance on 1st Floor - Boys	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 1st Floor - Girls	Does not Exist
Instance on 1st Floor - Boys	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on 1st Floor - Girls	Does not Exist
Instance on 1st Floor - Boys	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 1st Floor - Girls	Does not Exist
Instance on 1st Floor - Boys	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on 1st Floor - Girls	Inspected
Instance on 1st Floor - Boys	Inspected
<b>Pendant Mounted</b>	Inspected
Instance on 1st Floor - Girls	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on 1st Floor - Boys	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Does not Exist
Instance on 1st Floor - Girls	Does not Exist
Instance on 1st Floor - Boys	Does not Exist
<b>Recessed Mounted</b>	Does not Exist
Instance on 1st Floor - Girls	Does not Exist
Instance on 1st Floor - Boys	Does not Exist
<b>Local Sound System</b>	Inspected
Instance on 1st Floor - Girls	Inspected
Installation Year	2005
Source of Installation	Custodial Staff
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on 1st Floor - Boys	Inspected
Installation Year	2005
Source of Installation	Custodial Staff
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Projection System</b>	Does not Exist
Instance on 1st Floor - Girls	Does not Exist
Instance on 1st Floor - Boys	Does not Exist
<b>Scoreboard</b>	Does not Exist
Instance on 1st Floor - Girls	Does not Exist
Instance on 1st Floor - Boys	Inspected
Condition	4 - Between Fair and Poor
Deficiency	NOT OPERATIONAL

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q415

Question	Response
<b>GYMNASIUM</b>	
<b>Scoreboard</b>	
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Theater Lighting System</b>	
	Does not Exist
Instance on 1st Floor - Girls	Does not Exist
Instance on 1st Floor - Boys	Does not Exist
<b>KITCHEN</b>	
	Inspected
Instance on 1st Floor	Inspected
<b>Lighting</b>	
	Inspected
Instance on 1st Floor	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 1st Floor	Inspected
<b>Pendant Mounted</b>	
	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Surface Mounted</b>	
	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Recessed Mounted</b>	
	Inspected
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	96
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Lighting Fixture - HID</b>	
Instance on 1st Floor	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 1st Floor	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on 1st Floor	Does not Exist
<b>LIBRARY</b>	
	Inspected
Instance on Room 216	Inspected
<b>Lighting</b>	
	Inspected
Instance on Room 216	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 216	Inspected
<b>Pendant Mounted</b>	
	Does not Exist
Instance on Room 216	Does not Exist
<b>Surface Mounted</b>	
	Inspected
Instance on Room 216	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q415

Question	Response
<b>LIBRARY</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Surface Mounted</b>	
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	32
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Recessed Mounted</b>	Inspected
Instance on Room 216	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	128
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Lighting Fixture - HID</b>	
Instance on Room 216	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 216	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Room 216	Does not Exist
<b>Raceway With Receptacles</b>	Inspected
Instance on Room 216	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Projection System</b>	Does not Exist
Instance on Room 216	Does not Exist
<b>LOCKER ROOM</b>	Inspected
Instance on 1st Floor - Visitors	Inaccessible
Instance on Room B55	Inspected
Alternative use	No
Instance on Room B57	Inspected
Alternative use	No
Instance on Room B59	Inspected
Alternative use	No
Instance on Room B66 - Girls	Inspected
Alternative use	No
Instance on Room B67 - Boys	Inspected
Alternative use	No
<b>Lighting</b>	Inspected

**NYC Department of Education  
Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q415

Question	Response
<b>LOCKER ROOM</b>	
<b>Lighting</b>	
Instance on Room B67 - Boys	Inspected
Instance on Room B66 - Girls	Inspected
Instance on Room B59	Inspected
Instance on Room B57	Inspected
Instance on Room B55	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room B67 - Boys	Inspected
Instance on Room B66 - Girls	Inspected
Instance on Room B59	Inspected
Instance on Room B57	Inspected
Instance on Room B55	Inspected
<b>Pendant Mounted</b>	
Instance on Room B67 - Boys	Does not Exist
Instance on Room B66 - Girls	Does not Exist
Instance on Room B59	Does not Exist
Instance on Room B57	Does not Exist
Instance on Room B55	Does not Exist
<b>Surface Mounted</b>	
Instance on Room B67 - Boys	Does not Exist
Instance on Room B66 - Girls	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	37
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room B59	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room B57	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	7
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q415

Question	Response
<b>LOCKER ROOM</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Surface Mounted</b>	
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room B55	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Recessed Mounted</b>	Inspected
Instance on Room B67 - Boys	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	27
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room B66 - Girls	Does not Exist
Instance on Room B59	Does not Exist
Instance on Room B57	Does not Exist
Instance on Room B55	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on Room B67 - Boys	Does not Exist
Instance on Room B66 - Girls	Does not Exist
Instance on Room B59	Does not Exist
Instance on Room B57	Does not Exist
Instance on Room B55	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room B67 - Boys	Inspected
Instance on Room B66 - Girls	Does not Exist
Instance on Room B59	Does not Exist
Instance on Room B57	Does not Exist
Instance on Room B55	Does not Exist
<b>Pendant Mounted</b>	Does not Exist
Instance on Room B67 - Boys	Does not Exist
<b>Surface Mounted</b>	Inspected
Instance on Room B67 - Boys	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q415

Question	Response
<b>LOCKER ROOM</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Incandescent</b>	
<b>Surface Mounted</b>	
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	10
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo	No photo recorded
Violations	No violations recorded.
<b>Recessed Mounted</b>	Does not Exist
Instance on Room B67 - Boys	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Room B67 - Boys	Does not Exist
Instance on Room B66 - Girls	Does not Exist
Instance on Room B59	Does not Exist
Instance on Room B57	Does not Exist
Instance on Room B55	Does not Exist
<b>MULTIPURPOSE ROOM</b>	Does not Exist
<b>SCIENCE DEMO ROOM</b>	Inspected
Instance on Room 260	Inspected
Power Panel	No
Alternative use	No
Instance on Room B33	Inspected
Power Panel	Yes
Alternative use	No
Instance on Rooms 244, 246, 264, 266, 270, 272	Inspected
Power Panel	No
Alternative use	No
Instance on Rooms 248, 262	Inspected
Power Panel	No
Alternative use	No
Instance on Room 250	Inspected
Power Panel	No
Alternative use	No
<b>Lighting</b>	Inspected
Instance on Room 250	Inspected
Instance on Rooms 248, 262	Inspected
Instance on Rooms 244, 246, 264, 266, 270, 272	Inspected
Instance on Room B33	Inspected
Instance on Room 260	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 250	Inspected
Instance on Rooms 248, 262	Inspected
Instance on Rooms 244, 246, 264, 266, 270, 272	Inspected
Instance on Room B33	Inspected
Instance on Room 260	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q415

Question	Response
<b>SCIENCE DEMO ROOM</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Pendant Mounted</b>	Does not Exist
Instance on Room 250	Does not Exist
Instance on Rooms 248, 262	Does not Exist
Instance on Rooms 244, 246, 264, 266, 270, 272	Does not Exist
Instance on Room B33	Does not Exist
Instance on Room 260	Does not Exist
<b>Surface Mounted</b>	Inspected
Instance on Room 250	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	24
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Rooms 248, 262	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	48
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Rooms 244, 246, 264, 266, 270, 272	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	138
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room B33	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q415

Question	Response
<b>SCIENCE DEMO ROOM</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Surface Mounted</b>	
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	41
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room 260	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	24
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Recessed Mounted</b>	Does not Exist
Instance on Room 250	Does not Exist
Instance on Rooms 248, 262	Does not Exist
Instance on Rooms 244, 246, 264, 266, 270, 272	Does not Exist
Instance on Room B33	Does not Exist
Instance on Room 260	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on Room 250	Does not Exist
Instance on Rooms 248, 262	Does not Exist
Instance on Rooms 244, 246, 264, 266, 270, 272	Does not Exist
Instance on Room B33	Does not Exist
Instance on Room 260	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 250	Inspected
Instance on Rooms 248, 262	Inspected
Instance on Rooms 244, 246, 264, 266, 270, 272	Inspected
Instance on Room B33	Inspected



**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

**Q415**

<b>Question</b>	<b>Response</b>
<b>SCIENCE DEMO ROOM</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 260	Inspected
<b>Pendant Mounted</b>	
Instance on Room 250	Does not Exist
Instance on Rooms 248, 262	Does not Exist
Instance on Rooms 244, 246, 264, 266, 270, 272	Does not Exist
Instance on Room B33	Does not Exist
Instance on Room 260	Does not Exist
<b>Surface Mounted</b>	
Instance on Room 250	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Rooms 248, 262	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Rooms 244, 246, 264, 266, 270, 272	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	18
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room B33	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 260	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	3
Quantity Uom	EACH

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q415

Question	Response
<b>SCIENCE DEMO ROOM</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Incandescent</b>	
<b>Surface Mounted</b>	
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo	No photo recorded
Violations	No violations recorded.
<b>Recessed Mounted</b>	
Instance on Room 250	Does not Exist
Instance on Rooms 248, 262	Does not Exist
Instance on Rooms 244, 246, 264, 266, 270, 272	Does not Exist
Instance on Room B33	Does not Exist
Instance on Room 260	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Room 250	Does not Exist
Instance on Rooms 248, 262	Does not Exist
Instance on Rooms 244, 246, 264, 266, 270, 272	Does not Exist
Instance on Room B33	Does not Exist
Instance on Room 260	Does not Exist
<b>Emergency Gas Shut-Off Valve</b>	
Instance on Room 250	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 248, 262	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 244, 246, 264, 266, 270, 272	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room B33	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 260	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Emergency Shut-Off Power</b>	
Instance on Room 250	Does not Exist
Instance on Rooms 248, 262	Does not Exist
Instance on Rooms 244, 246, 264, 266, 270, 272	Does not Exist
Instance on Room B33	Does not Exist
Instance on Room 260	Does not Exist
<b>Power Supply</b>	
Instance on Room 250	Inspected
Instance on Rooms 248, 262	Inspected
Instance on Rooms 244, 246, 264, 266, 270, 272	Inspected
Instance on Room B33	Inspected
Instance on Room 260	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q415

Question	Response
<b>SCIENCE DEMO ROOM</b>	
<b>Power Supply</b>	
<b>Instructor Unit</b>	
Instance on Room 250	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 248, 262	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 244, 246, 264, 266, 270, 272	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room B33	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 260	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Meter Demonstration Unit</b>	
Instance on Room 250	Does not Exist
Instance on Rooms 248, 262	Does not Exist
Instance on Rooms 244, 246, 264, 266, 270, 272	Does not Exist
Instance on Room B33	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 260	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Projection System</b>	
Instance on Room 250	Does not Exist
Instance on Rooms 248, 262	Does not Exist
Instance on Rooms 244, 246, 264, 266, 270, 272	Does not Exist
Instance on Room B33	Does not Exist
Instance on Room 260	Does not Exist
<b>SCIENCE LAB</b>	
Instance on Room 251	Inspected
Power Panel	Yes
Alternative use	No
Instance on Room 253	Inspected
Power Panel	Yes
Alternative use	No
Instance on Room 255	Inspected
Power Panel	Yes
Alternative use	No
Instance on Room 257	Inspected
Power Panel	Yes
Alternative use	No
Instance on Rooms B35, B39	Inaccessible
<b>Lighting</b>	
Instance on Room 257	Inspected
Instance on Room 255	Inspected

**NYC Department of Education  
Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

**Q415**

<b>Question</b>	<b>Response</b>
<b>SCIENCE LAB</b>	
<b>Lighting</b>	
Instance on Room 253	Inspected
Instance on Room 251	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 257	Inspected
Instance on Room 255	Inspected
Instance on Room 253	Inspected
Instance on Room 251	Inspected
<b>Pendant Mounted</b>	
	Does not Exist
Instance on Room 257	Does not Exist
Instance on Room 255	Does not Exist
Instance on Room 253	Does not Exist
Instance on Room 251	Does not Exist
<b>Surface Mounted</b>	
	Inspected
Instance on Room 257	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	32
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room 255	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	30
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q415

Question	Response
<b>SCIENCE LAB</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Surface Mounted</b>	
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room 253	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	30
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room 251	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	30
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Recessed Mounted</b>	Does not Exist
Instance on Room 257	Does not Exist
Instance on Room 255	Does not Exist
Instance on Room 253	Does not Exist
Instance on Room 251	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on Room 257	Does not Exist
Instance on Room 255	Does not Exist
Instance on Room 253	Does not Exist
Instance on Room 251	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 257	Inspected
Instance on Room 255	Inspected
Instance on Room 253	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q415

Question	Response
<b>SCIENCE LAB</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 251	Does not Exist
<b>Pendant Mounted</b>	
Instance on Room 257	Does not Exist
Instance on Room 255	Does not Exist
Instance on Room 253	Does not Exist
<b>Surface Mounted</b>	
Instance on Room 257	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room 255	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room 253	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Recessed Mounted</b>	
Instance on Room 257	Does not Exist
Instance on Room 255	Does not Exist
Instance on Room 253	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Room 257	Does not Exist
Instance on Room 255	Does not Exist
Instance on Room 253	Does not Exist
Instance on Room 251	Does not Exist
<b>Emergency Gas Shut-Off Valve</b>	
	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q415

Question	Response
<b>SCIENCE LAB</b>	
<b>Emergency Gas Shut-Off Valve</b>	
Instance on Room 257	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 255	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 253	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 251	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Emergency Shut-Off Power</b>	
Instance on Room 257	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 255	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 253	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 251	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Power Supply</b>	
Instance on Room 257	Inspected
Instance on Room 255	Inspected
Instance on Room 253	Inspected
Instance on Room 251	Inspected
<b>Instructor Unit</b>	
Instance on Room 257	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 255	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 253	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 251	Inspected
Condition	5 - Poor
Deficiency	UNIT NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE UNIT
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q415

Question	Response
<b>SCIENCE LAB</b>	
<b>Power Supply</b>	
<b>Instructor Unit</b>	
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Meter Demonstration Unit</b>	
Instance on Room 257	Does not Exist
Instance on Room 255	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 253	Does not Exist
Instance on Room 251	Does not Exist
<b>Student Unit</b>	
Instance on Room 257	Does not Exist
Instance on Room 255	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 253	Does not Exist
Instance on Room 251	Does not Exist
<b>Projection System</b>	
	Does not Exist
Instance on Room 257	Does not Exist
Instance on Room 255	Does not Exist
Instance on Room 253	Does not Exist
Instance on Room 251	Does not Exist
<b>SCIENCE PREP ROOM</b>	
	Inspected
Instance on Room 252	Inspected
Power Panel	Yes
Alternative use	No
Instance on Room 258	Inspected
Power Panel	No
Alternative use	No
<b>Lighting</b>	
	Inspected
Instance on Room 258	Inspected
Instance on Room 252	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 258	Inspected
Instance on Room 252	Inspected
<b>Pendant Mounted</b>	
	Does not Exist
Instance on Room 258	Does not Exist
Instance on Room 252	Does not Exist
<b>Surface Mounted</b>	
	Inspected
Instance on Room 258	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2



**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q415

Question	Response
<b>SCIENCE PREP ROOM</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Surface Mounted</b>	
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	58
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room 252	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	35
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Recessed Mounted</b>	
Instance on Room 258	Does not Exist
Instance on Room 252	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on Room 258	Does not Exist
Instance on Room 252	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 258	Inspected
Instance on Room 252	Inspected
<b>Pendant Mounted</b>	
Instance on Room 258	Does not Exist
Instance on Room 252	Does not Exist
<b>Surface Mounted</b>	
Instance on Room 258	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q415

Question	Response
<b>SCIENCE PREP ROOM</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Incandescent</b>	
<b>Surface Mounted</b>	
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room 252	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Recessed Mounted</b>	Does not Exist
Instance on Room 258	Does not Exist
Instance on Room 252	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Room 258	Does not Exist
Instance on Room 252	Does not Exist
<b>Emergency Gas Shut-Off Valve</b>	
Instance on Room 258	Inspected
Instance on Room 258	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 252	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Emergency Shut-Off Power</b>	
Instance on Room 258	Does not Exist
Instance on Room 252	Does not Exist
<b>Power Supply</b>	
Instance on Room 258	Inspected
Instance on Room 252	Inspected
<b>Instructor Unit</b>	
Instance on Room 258	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 252	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>SWIMMING POOL</b>	
Does not Exist	
<b>TOILET ROOM - STAFF</b>	
Inspected	

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

**Q415**

<b>Question</b>	<b>Response</b>
<b>TOILET ROOM - STAFF</b>	
<b>Lighting</b>	Inspected
<b>Lighting Fixture - Fluorescent</b>	Inspected
<b>Pendant Mounted</b>	Does not Exist
<b>Surface Mounted</b>	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Recessed Mounted</b>	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	13
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Lighting Fixture - HID</b>	Does not Exist
<b>Lighting Fixture - Incandescent</b>	Does not Exist
<b>Lighting Fixture - LED</b>	Inspected
<b>Pendant Mounted</b>	Does not Exist
<b>Surface Mounted</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>TOILET ROOM - STUDENT</b>	Inspected
<b>Lighting</b>	Inspected
<b>Lighting Fixture - Fluorescent</b>	Inspected
<b>Pendant Mounted</b>	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Surface Mounted</b>	Inspected
Condition	3 - Fair

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q415

Question	Response
<b>TOILET ROOM - STUDENT</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Surface Mounted</b>	
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	18
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Recessed Mounted</b>	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	16
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Lighting Fixture - HID</b>	Does not Exist
<b>Lighting Fixture - Incandescent</b>	Does not Exist
<b>Lighting Fixture - LED</b>	Inspected
<b>Pendant Mounted</b>	Does not Exist
<b>Surface Mounted</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>AUXILIARY SIGNAL/BELL SYSTEM</b>	Inspected
Replacement Quantity	284,000
Replacement Uom	S.F.
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>EMERGENCY DC STANDBY BATTERY POWER</b>	Does not Exist
<b>EMERGENCY GENERATOR SET</b>	Inspected
<b>Automatic Transfer Switch (ATS)</b>	Inspected
Instance	Electrical Room
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	GE Zenith Controls
Equipment	N/A
Capacity/Size Quantity	200
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q415

Question	Response
<b>EMERGENCY GENERATOR SET</b>	
<b>Automatic Transfer Switch (ATS)</b>	
Installation Year	2010
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded
Instance	Electrical Room
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	ASCO
Equipment	Fire Alarm ATS Switch
Capacity/Size Quantity	104
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2010
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded
<b>Battery Charger</b>	Inspected
Instance	Electrical Room
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	SENS
Equipment	Battery Charger
Capacity/Size Quantity	3
Capacity/Size UOM	AmpsDC
Capacity/Size2 Quantity	12
Capacity/Size2 UOM	VDC
Source of Capacity/Size	Nameplate
Installation Year	2010
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded
<b>Emergency Distribution Board</b>	Inspected
Number of Spares	2
<b>Fused Disconnect Switch Type</b>	Inspected
Instance	Electrical Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Federal Pacific Electric
Equipment	EMG. GEN. DIST
Capacity/Size Quantity	200
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	1
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Inspector Estimate
Installation Year	1967
Source of Installation	Documented
Deficiency	No deficiencies recorded

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

**Q415**

<b>Question</b>	<b>Response</b>
<b>EMERGENCY GENERATOR SET</b>	
<b>Emergency Distribution Board</b>	Inspected
<b>Molded Case Circuit Breaker Type</b>	Does not Exist
<b>Diesel</b>	Does not Exist
<b>Natural Gas</b>	Inspected
Instance	Generator Room (By Electrical Room)
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Cummins Onan
Equipment	Emergency Generator
Capacity/Size Quantity	50
Capacity/Size UOM	KVA
Capacity/Size2 Quantity	40
Capacity/Size2 UOM	KW
Capacity/Size3Quantity	139
Capacity/Size3 UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1967
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>EMERGENCY LIGHT/EXIT LIGHT PANEL</b>	Inspected
Condition	3 - Fair
Deficiency	LESS THAN 20% SPARE CIRCUIT BREAKERS
Deficiency Location/Instance	Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL NEW PANEL BOARD
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>EMERGENCY LIGHTING</b>	Inspected
<b>Battery Pack</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	BATTERY NOT OPERATIONAL
Deficiency Location/Instance	1st Floor Corridor by Room 121
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE BATTERY
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Non Battery Pack</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>EXIT LIGHT</b>	Inspected
<b>Battery Pack</b>	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q415

Question	Response
<b>EXIT LIGHT</b>	
<b>Battery Pack</b>	
Condition	2 - Between Good and Fair
Deficiency	FIXTURE NOT OPERATIONAL
Deficiency Location/Instance	Cafeteria
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Non Battery Pack</b>	
Condition	Inspected
Deficiency	No deficiencies recorded
<b>EXIT/EMERGENCY LIGHT</b>	
Condition	Inspected
Deficiency	No deficiencies recorded
<b>FIRE ALARM SYSTEM</b>	
Condition	Inspected
Replacement Quantity	284,000
Replacement Uom	S.F.
<b>Bell/Horn</b>	
Condition	Inspected
Deficiency	No deficiencies recorded
<b>Strobe</b>	
Condition	Inspected
Deficiency	2 - Between Good and Fair
Deficiency Location/Instance	STROBE NOT OPERATIONAL
Deficiency Quantity	Exterior Wall by Exit 16 (Facing TCU), Students Toilet Room (Inside Room B66 - Girls Locker Room)
Quantity Uom	2
Potential Action	EACH
Urgency of Action	REPLACE
Purpose of Action	PRIORITY 5
Deficiency Photo1	LEVEL 6
Violations	No photo recorded
Violations	No violations recorded.
<b>Manual Pull Station</b>	
Condition	Inspected
Deficiency	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Fan Shutdown Control</b>	
Condition	Inspected
Deficiency	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Duct Smoke Detector</b>	
Condition	Inspected
Deficiency	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Area Smoke Detector</b>	
Condition	Inspected
Deficiency	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>CO Detector</b>	
Condition	Under Construction
<b>Heat Detector</b>	
Condition	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q415

Question	Response
<b>FIRE ALARM SYSTEM</b>	
<b>Heat Detector</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Elevator Recall</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Magnetic Door Holder/Contactor</b>	Does not Exist
<b>Fused Cutout Panel</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Fire Alarm Digital Communicator</b>	Does not Exist
<b>Main Panel</b>	Inspected
<b>Bell At Panel</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Fire Alarm Control Panel (Electronic)</b>	Inspected
Instance	Main Entrance Lobby
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	General Electric
Equipment	Fire Alarm Control Panel
Model	EST 2
Installation Year	2010
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded
<b>Fire Alarm Control Panel (Standard)</b>	Does not Exist
<b>Sub-Panel</b>	Inspected
<b>Bell At Panel</b>	Does not Exist
<b>Fire Alarm Control Panel (Electronic)</b>	Under Construction
<b>Fire Alarm Control Panel (Standard)</b>	Does not Exist
<b>Remote Annunciator</b>	Inspected
<b>Display Monitor</b>	Does not Exist
<b>Panel</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Printer</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Punch Register</b>	Does not Exist
<b>Sprinkler Flow/Air Pressure Switch</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Tamper Flow Switch/Chain</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>GROUNDING SYSTEM</b>	Inspected
Condition	3 - Fair



**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

**Q415**

<b>Question</b>	<b>Response</b>
<b>GROUNDING SYSTEM</b>	Inspected
Deficiency	No deficiencies recorded
<b>INTERCOM SYSTEM</b>	Inspected
<b>Elevator</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Holding Area</b>	Does not Exist
<b>LAN</b>	Inspected
<b>Local Distribution Frame (I/LDF)</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Main Equipment Rack (MDF)</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>LIGHTNING PROTECTION</b>	Does not Exist
<b>MOTOR CONTROLLER</b>	Inspected
<b>Motor Control Center</b>	Does not Exist
<b>Motor Starter/Contactor</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Variable Frequency Drive</b>	Under Construction
<b>PANEL BOARD</b>	Inspected
<b>Fused Disconnect Switch Type</b>	Inspected
Condition	3 - Fair
Deficiency	PANEL BOARD DOOR LOCK IS MISSING
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL BOARD COVER IS MISSING
Deficiency Location/Instance	Boiler Room, Penthouse - Fan Rooms (A, B)
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room, Mechanical Room B20, 1st Floor - Fan Room C, Penthouse - Fan Rooms (A, B)
Deficiency Quantity	9
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

**Q415**

<b>Question</b>	<b>Response</b>
<b>PANEL BOARD</b>	
<b>Fused Disconnect Switch Type</b>	Inspected
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Fused Knife Switch Type</b>	Does not Exist
<b>Fused Toggle Switch Type</b>	Does not Exist
<b>Molded Case Circuit Breaker Type</b>	Inspected
Condition	3 - Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room, Kitchen, Gymnasiums, Rooms (B29, B33, 251, 252, 253, 255, 257, 317), Corridors by Rooms (B11, B18, B40, B60, 138, 140, 161, 169, 173, 175, 178, 233, 244, 261, 314, 322, 330, 343, 350)
Deficiency Quantity	37
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	NO SPARE
Deficiency Location/Instance	Corridors by Rooms 106, 135
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	INSTALL NEW PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	NO SPARE
Deficiency Location/Instance	Cafeteria, Kitchen, Library, Corridors by Rooms (154, 212, 252, 301, 341)
Deficiency Quantity	10
Quantity Uom	EACH
Potential Action	REPLACE PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL BOARD DOOR LOCK IS MISSING
Deficiency Location/Instance	1st Floor Corridor by Room 173
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL BOARD COVER IS MISSING
Deficiency Location/Instance	Basement Corridor by Room B40
Deficiency Quantity	1

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

**Q415**

<b>Question</b>	<b>Response</b>
<b>PANEL BOARD</b>	
<b>Molded Case Circuit Breaker Type</b>	
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL BOARD COVER IS MISSING
Deficiency Location/Instance	Kitchen
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	CIRCUIT BREAKER NOT OPERATIONAL
Deficiency Location/Instance	Boys Gymnasium
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE CIRCUIT BREAKER
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>PUBLIC ADDRESS SYSTEM</b>	Inspected
Replacement Quantity	284,000
Replacement Uom	S.F.
Instance	Room 105D
Instance Condition	4 - Between Fair and Poor
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Dukane 250
Installation Year	2005
Source of Installation	Custodial Staff
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Corridors and Classrooms
Deficiency Quantity	8
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	SYSTEM DEFECTIVE
Deficiency Location/Instance	Room 105D
Deficiency Quantity	1
Quantity Uom	EACH

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q415

Question	Response
<b>PUBLIC ADDRESS SYSTEM</b>	
Potential Action	REPAIR SYSTEM
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>SECURITY</b>	
	Inspected
<b>IPDVS/CCTV System</b>	
	Inspected
Replacement Quantity	284,000
Replacement Uom	S.F.
Installation Year	2007
Source of Installation	Custodial Staff
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Intrusion Alarm System</b>	
	Inspected
Replacement Quantity	284,000
Replacement Uom	S.F.
<b>Central Control Panel</b>	
	Inspected
Instance	Custodian's Office
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista-128BPT
Installation Year	2014
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded
<b>Infrared Sensor</b>	
	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Panic Switch</b>	
	Inspected
Condition	4 - Between Fair and Poor
Deficiency	SWITCH NOT OPERATIONAL
Deficiency Location/Instance	Kitchen - Office
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Remote Annunciator</b>	
	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Siren/Stroke</b>	
	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Lighting - Security</b>	
	Inspected
Replacement Uom	EACH
Condition	3 - Fair

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

**Q415**

<b>Question</b>	<b>Response</b>
<b>SECURITY</b>	Inspected
<b>Lighting - Security</b>	
Deficiency	No deficiencies recorded
<b>SERVICE SWITCH</b>	Inspected
Instance	Electrical Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Federal Pacific Electric
Equipment	5000A SW. 4000A Fuse Main Switch
Capacity/Size Quantity	4,000
Capacity/Size UOM	Amps
Source of Capacity/Size	Fuse Size
Installation Year	1967
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Federal Pacific Electric
Equipment	2500A SW. 2001A Fuse Sub Dist. Pnl.
Capacity/Size Quantity	2,001
Capacity/Size UOM	Amps
Source of Capacity/Size	Fuse Size
Installation Year	1967
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Federal Pacific Electric
Equipment	400A SW. 400A Fuse Kitchen Dist. Pnl.
Capacity/Size Quantity	400
Capacity/Size UOM	Amps
Source of Capacity/Size	Fuse Size
Installation Year	1967
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Federal Pacific Electric
Equipment	1200A SW. 1200A Fuse. Chiller Unit
Capacity/Size Quantity	1,200
Capacity/Size UOM	Amps
Source of Capacity/Size	Fuse Size

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q415

Question	Response
<b>SERVICE SWITCH</b>	Inspected
Installation Year	1967
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>SWITCHBOARD</b>	Inspected
Number of Spares	7
<b>Fused Disconnect Switch Type</b>	Inspected
Instance	Electrical Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Federal Pacific Electric
Equipment	N/A
Capacity/Size Quantity	4,000
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	5
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Service Switch Fuse Size
Installation Year	1967
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Federal Pacific Electric
Equipment	Kitchen Dist Panel
Capacity/Size Quantity	400
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	1
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Service Switch Fuse Size
Installation Year	1967
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Room B45
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Federal Pacific Electric
Equipment	MAIN DIS. 2500A
Capacity/Size Quantity	2,500
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	3
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Switchboard Mains Size
Installation Year	1967
Source of Installation	Documented
Deficiency	No deficiencies recorded

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

**Q415**

<b>Question</b>	<b>Response</b>
<b>SWITCHBOARD</b>	Inspected
<b>Fused Knife Switch Type</b>	Does not Exist
<b>Molded Case Circuit Breaker Type</b>	Does not Exist
<b>TELEPHONE SYSTEM</b>	Inspected
<b>PBX/Intercom</b>	Inspected
Condition	3 - Fair
Deficiency	TELEPHONE NOT OPERATIONAL
Deficiency Location/Instance	Locker Room B59
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE TELEPHONE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	TELEPHONE MISSING
Deficiency Location/Instance	Electrical Room B45
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL TELEPHONE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Standard</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>TRANSFORMER</b>	Does not Exist