Building Condition Assessment Survey 2023 - 2024

Inspection I			NS HS - Q, 143-1			Time In	Last Edited
EE : Q4						2024-04-15 8:09 AM	2024-04-24 11:07 AM
Asset Data							
Question					Answer		
Type of Servi	ice				Below Gro	ound	
	ive Whiteboard (I	WB) Exist?			Yes		
Water Penetra	ation in Electrical	Room?			No		
Have any Sys	stems/Major Build	ling Components	been upgraded?		Yes		
					Systems:	Most Security Lights, LAN	
					Years:	2024	
					Systems:	Gymnasium 1/2 (Scoreboard)	
					Years:	2022	
					Systems:	Partial Fused Disconnect Swit	ch Type Panel Board
					Years:	2021	• •
					Systems:	Most Emergency Lighting (Ba Lights (Battery Pack), IPDVS/	•
					Years:	2019	
					Systems:	Auditorium (Local Sound Syst System, Projection System, Su	
					Years:	2018	
					Systems:	Motor Controller (Variable Fre	equency Drive)
					Years:	2016	
					Systems:	Gymnasiums (LED Lighting)	
					Years:	2015	
					Systems:	Science Demo Room 208 (Lig	hting)
					Years:	2014	
					Systems:	Library	
					Years:	2010	
					Systems:	Science Lab - Rooms (103, 10 Rooms (103P, 307)	5, 308), Science Prep
					Years:	2009	
					Systems:	Emergency Generator Set, Fire	e Alarm System
					Years:	2008	
					Systems:	Public Address System, Local	Sound System
					Years:	2004	
					Systems:	Intrusion Alarm System	
					Years:	1999	
					Systems:	Partial Molded Case Circuit B	reaker Type Panel Board
					Years:	1993, 2002, 2008, 2016, 2021	
	D INTERCOMS	IN FIRE RESC	CUE AREAS				
Question	T.C.D. A	· ,	· D . A		Response		
and/or Holdi	y Life Rescue Ass ng Rooms in your	building?	these spaces for use		Yes No		
during a					Rooms 208	3 308	
		ve dedicated inte	ereoms.		Rooms 200	3, 300	
Priority Condit	ion						
Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title Status	PhotoImage
Yes	Fire Alarm System - Components Not Operational	N/A	FIRE ALARM SYSTEM Fan Shutdown Control	Mechanical Rooms (Auditorium, Gymnasium, Room B12)	Jose Chacone	Fireman Sent to DSF	

Building Condition Assessment Survey 2023 - 2024

iestion	Response
ectrical	
AUDITORIUM	Inspected
Instance on 1st Floor	Inspected
House Lighting	Inspected
Does a Chandelier exist?	No
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	Inspected
Instance on 1st Floor	Inspected
Pendant Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Surface Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair No deficiencies recorded
Deficiency	
Recessed Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Inspected
Pendant Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	16
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Surface Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Recessed Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	61
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Lighting Fixture - LED	Decree (F.1)
Instance on 1st Floor	Does not Exist Inspected

Building Condition Assessment Survey 2023 - 2024

estion	Response
UDITORIUM	
Local Sound System	
Instance on 1st Floor	Inspected
Installation Year	2018
Source of Installation	Custodial Staff
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Projection System	Inspected
Is the projector on a cart or installed on the ceiling?	Ceiling
Instance on 1st Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Theater Lighting System	Inspected
Instance on 1st Floor	Inspected
Dimming System	
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Theater Lighting	
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
AFETERIA	Inspected
Instance on 1st Floor - Students	Inspected
Instance on 1st Floor - Staff	Inspected
Lighting	Inspected
Instance on 1st Floor - Staff	Inspected
Instance on 1st Floor - Students	
	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor - Staff	Inspected
Instance on 1st Floor - Students	Inspected
Pendant Mounted	Does not Exist
Instance on 1st Floor - Staff	Does not Exist
Instance on 1st Floor - Students	Does not Exist
Surface Mounted	Does not Exist
Instance on 1st Floor - Staff	Does not Exist
Instance on 1st Floor - Students	Does not Exist
Recessed Mounted	Inspected
Instance on 1st Floor - Staff	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	13
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on 1st Floor - Students	Inspected

Building Condition Assessment Survey 2023 - 2024

estion	Response
AFETERIA	
Lighting	
Lighting Fixture - Fluorescent	
Recessed Mounted	
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	69
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Lighting Fixture - HID	
Instance on 1st Floor - Staff	Does not Exist
Instance on 1st Floor - Students	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor - Staff	Does not Exist
Instance on 1st Floor - Students	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor - Staff	Does not Exist
Instance on 1st Floor - Students	Does not Exist
Local Sound System	Does not Exist
Instance on 1st Floor - Staff	Does not Exist
Instance on 1st Floor - Students	Inspected
Installation Year	2004
Source of Installation	Inspector Estimate
Condition	3 - Fair
Deficiency	No deficiencies recorded
Projection System	Does not Exist
Instance on 1st Floor - Staff	Does not Exist
Instance on 1st Floor - Students	Does not Exist
Theater Lighting System	Does not Exist
Instance on 1st Floor - Staff	Does not Exist
Instance on 1st Floor - Students	Does not Exist
LASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected
Lighting Does a Chandelier exist?	Inspected No
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	
Condition	Inspected 3 - Fair
Deficiency Deficiency Quantity	LIGHTING FIXTURE BALLAST DEFECTIVE 8
Quantity Uom	8 EACH
Quantity Uom Potential Action	
	REPLACE BALLAST PRIORITY 3
Urgency of Action	LEVEL 2
Purpose of Action Deficiency Photo1	No photo recorded
Deficiency Photo1	

Building Condition Assessment Survey 2023 - 2024

stion	Response	
LASSROOM/CORRIDOR/ADMINISTRATIVE SPACE		
Lighting		
Lighting Fixture - Fluorescent		
Pendant Mounted	LIGHTING FIVTUDE DEVOND LIGHTILL HE	
Deficiency Deficiency Operation	LIGHTING FIXTURE BEYOND USEFUL LIFE	
Deficiency Quantity	1,455	
Quantity Uom	EACH DEDI ACE LIBORADE	
Potential Action Urgency of Action	REPLACE-UPGRADE PRIORITY I	
Purpose of Action	LEVEL 2	
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
Surface Mounted	Inspected	
Condition	3 - Fair	_
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE	_
Deficiency Quantity	488	
Quantity Uom	EACH	
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE	_
Deficiency Quantity	3	
Quantity Uom	EACH	
Potential Action	REPLACE BALLAST	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
Recessed Mounted	Inspected	
Condition	3 - Fair	_
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE	_
Deficiency Quantity	6	
Quantity Uom	EACH	
Potential Action	REPLACE BALLAST	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE	_
Deficiency Quantity	668	
Quantity Uom	EACH	
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
Lighting Fixture - HID	Does not Exist	

Building Condition Assessment Survey 2023 - 2024

urear inspection	Y
uestion	Response
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	
Lighting Fixture - Incandescent	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	8
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Recessed Mounted	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	8
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Lighting Fixture - LED	Does not Exist
COMPUTER LAB	Inspected
Instance on Room 124	Inspected
Power Panel	Yes
Lighting	Inspected
Instance on Room 124	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 124	Inspected
Pendant Mounted	Inspected
Instance on Room 124	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	20
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Surface Mounted	Does not Exist
	Does not Exist
Instance on Room 124	Does not Exist
Recessed Mounted	Inspected

Building Condition Assessment Survey 2023 - 2024

near inspection	
estion	Response
COMPUTER LAB	
Lighting	
Lighting Fixture - Fluorescent	
Recessed Mounted	
Deficiency Quantity	9
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Lighting Fixture - HID	
Instance on Room 124	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 124	Does not Exist
Lighting Fixture - LED	
Instance on Room 124	Does not Exist
Raceway With Receptacles	
Instance on Room 124	Inspected Inspected
Condition	3 - Fair
	No deficiencies recorded
Deficiency SYMNASIUM	
	Inspected
Instance on 1st Floor - Gymnasium 1/2	Inspected
Instance on 2nd Floor - Gymnasium 3, 2nd Floor - Gymnasium 4	Inspected
Lighting	Inspected
Instance on 2nd Floor - Gymnasium 3, 2nd Floor - Gymnasium 4	Inspected
Instance on 1st Floor - Gymnasium 1/2	Inspected
Lighting Fixture - Fluorescent	
Instance on 2nd Floor - Gymnasium 3, 2nd Floor - Gymnasium 4	Does not Exist
Instance on 1st Floor - Gymnasium 1/2	Inspected
Pendant Mounted	Does not Exist
Instance on 1st Floor - Gymnasium 1/2	Does not Exist
Surface Mounted	Inspected
Instance on 1st Floor - Gymnasium 1/2	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Potential Action Urgency of Action	REPLACE-UPGRADE PRIORITY 1
Potential Action Urgency of Action Purpose of Action	REPLACE-UPGRADE PRIORITY 1 LEVEL 2
Potential Action Urgency of Action Purpose of Action Deficiency Photo1	REPLACE-UPGRADE PRIORITY 1 LEVEL 2 No photo recorded
Potential Action Urgency of Action Purpose of Action Deficiency Photo1 Violations	REPLACE-UPGRADE PRIORITY 1 LEVEL 2 No photo recorded No violations recorded.
Potential Action Urgency of Action Purpose of Action Deficiency Photo1 Violations Recessed Mounted	REPLACE-UPGRADE PRIORITY 1 LEVEL 2 No photo recorded No violations recorded. Does not Exist
Potential Action Urgency of Action Purpose of Action Deficiency Photo1 Violations Recessed Mounted Instance on 1st Floor - Gymnasium 1/2	REPLACE-UPGRADE PRIORITY 1 LEVEL 2 No photo recorded No violations recorded.
Potential Action Urgency of Action Purpose of Action Deficiency Photo1 Violations Recessed Mounted	REPLACE-UPGRADE PRIORITY 1 LEVEL 2 No photo recorded No violations recorded. Does not Exist
Potential Action Urgency of Action Purpose of Action Deficiency Photo1 Violations Recessed Mounted Instance on 1st Floor - Gymnasium 1/2	REPLACE-UPGRADE PRIORITY 1 LEVEL 2 No photo recorded No violations recorded. Does not Exist

Building Condition Assessment Survey 2023 - 2024

stion	Response
YMNASIUM	
Lighting	
Lighting Fixture - Incandescent	
Instance on 2nd Floor - Gymnasium 3, 2nd Floor - Gymnasium 4	Does not Exist
Instance on 1st Floor - Gymnasium 1/2	Does not Exist
Lighting Fixture - LED	
Instance on 2nd Floor - Gymnasium 3, 2nd Floor - Gymnasium 4	Inspected
Instance on 1st Floor - Gymnasium 1/2	Inspected
Pendant Mounted	Inspected
Instance on 2nd Floor - Gymnasium 3, 2nd Floor - Gymnasium 4	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on 1st Floor - Gymnasium 1/2	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Instance on 2nd Floor - Gymnasium 3, 2nd Floor - Gymnasium 4	Does not Exist
Instance on 1st Floor - Gymnasium 1/2	Does not Exist
Recessed Mounted	
	Does not Exist Does not Exist
Instance on 2nd Floor - Gymnasium 3, 2nd Floor - Gymnasium 4	
Instance on 1st Floor - Gymnasium 1/2	Does not Exist
Local Sound System	Inspected
Instance on 2nd Floor - Gymnasium 3, 2nd Floor - Gymnasium 4	Inspected
Installation Year	2004
Source of Installation	Inspector Estimate
Condition	4 - Between Fair and Poor
Deficiency	AMPLIFIER NOT OPERATIONAL
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on 1st Floor - Gymnasium 1/2	Inspected
Installation Year	2004
Source of Installation	Inspector Estimate
Condition	4 - Between Fair and Poor
Deficiency	AMPLIFIER NOT OPERATIONAL
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Projection System	Does not Exist
Instance on 2nd Floor - Gymnasium 3, 2nd Floor - Gymnasium 4	Does not Exist Does not Exist
Instance on 1st Floor - Gymnasium 1/2	Does not Exist

Building Condition Assessment Survey 2023 - 2024

hartin	Domongo
uestion CNA	Response
GYMNASIUM	
Scoreboard	Does not Exist
Instance on 2nd Floor - Gymnasium 3, 2nd Floor - Gymnasium 4	Does not Exist
Instance on 1st Floor - Gymnasium 1/2	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Theater Lighting System	Does not Exist
Instance on 2nd Floor - Gymnasium 3, 2nd Floor - Gymnasium 4	Does not Exist
Instance on 1st Floor - Gymnasium 1/2	Does not Exist
KITCHEN	Inspected
Instance on 1st Floor	Inspected
Lighting	Inspected
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Surface Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Recessed Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	64
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Y. Let Et a YHD	
Lighting Fixture - HID	D. (F.)
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not Exist
LIBRARY	Inspected
Instance on Room 236	Inspected
Lighting	Inspected
Instance on Room 236	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 236	Inspected
Pendant Mounted	Inspected
Instance on Room 236	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Instance on Room 236	Inspected
Condition	3 - Fair

Building Condition Assessment Survey 2023 - 2024

ricai inspection	
estion	Response
LIBRARY	
Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	Inspected
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Instance on Room 236	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	D
Instance on Room 236	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 236	Does not Exist
Lighting Fixture - LED	
Instance on Room 236	Does not Exist
Raceway With Receptacles	Inspected
Instance on Room 236	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Projection System	Does not Exist
Instance on Room 236	Does not Exist
OCKER ROOM	Inspected
Instance on 1st Floor - Boys	Inspected
Alternative use	No
Instance on 1st Floor - Girls	Inspected
Alternative use	No
Instance on Basement - Home	Inspected
Alternative use	No
Instance on Basement - Visitors	Inspected
Alternative use	No
Lighting	Inspected
Instance on Basement - Visitors	Inspected
Instance on Basement - Home	Inspected
Instance on 1st Floor - Girls	Inspected
Instance on 1st Floor - Boys	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement - Visitors	Inspected
Instance on Basement - Home	Inspected
Instance on 1st Floor - Girls	Inspected
Instance on 1st Floor - Boys	Inspected
Pendant Mounted	Does not Exist
Instance on Basement - Visitors	Does not Exist
Instance on Basement - Home	Does not Exist
Instance on 1st Floor - Girls	Does not Exist
Instance on 1st Floor - Boys	Does not Exist
Surface Mounted	Inspected
Instance on Basement - Visitors	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE

Building Condition Assessment Survey 2023 - 2024

cal Inspection	Q4
tion	Response
OCKER ROOM	
Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	
Deficiency Quantity	16
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Basement - Home	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	42
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on 1st Floor - Girls	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1 Violations	No photo recorded No violations recorded.
Violations	ino violations recorded.
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	36
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on 1st Floor - Boys	Inspected
Condition	3 - Fair

Building Condition Assessment Survey 2023 - 2024

LIGHTING FIXTURE BALLAST DEFECTIVE 3 EACH REPLACE BALLAST PRIORITY 3 LEVEL 2 No photo recorded No violations recorded. LIGHTING FIXTURE BEYOND USEFUL LIFE 44 EACH
3 EACH REPLACE BALLAST PRIORITY 3 LEVEL 2 No photo recorded No violations recorded. LIGHTING FIXTURE BEYOND USEFUL LIFE 44
3 EACH REPLACE BALLAST PRIORITY 3 LEVEL 2 No photo recorded No violations recorded. LIGHTING FIXTURE BEYOND USEFUL LIFE 44
3 EACH REPLACE BALLAST PRIORITY 3 LEVEL 2 No photo recorded No violations recorded. LIGHTING FIXTURE BEYOND USEFUL LIFE 44
EACH REPLACE BALLAST PRIORITY 3 LEVEL 2 No photo recorded No violations recorded. LIGHTING FIXTURE BEYOND USEFUL LIFE 44
REPLACE BALLAST PRIORITY 3 LEVEL 2 No photo recorded No violations recorded. LIGHTING FIXTURE BEYOND USEFUL LIFE 44
PRIORITY 3 LEVEL 2 No photo recorded No violations recorded. LIGHTING FIXTURE BEYOND USEFUL LIFE 44
LEVEL 2 No photo recorded No violations recorded. LIGHTING FIXTURE BEYOND USEFUL LIFE 44
No photo recorded No violations recorded. LIGHTING FIXTURE BEYOND USEFUL LIFE 44
No violations recorded. LIGHTING FIXTURE BEYOND USEFUL LIFE 44
LIGHTING FIXTURE BEYOND USEFUL LIFE 44
44
FACH
LACII
REPLACE-UPGRADE
PRIORITY 1
LEVEL 2
No photo recorded
No violations recorded.
Does not Exist
Does not Exist
Inspected
Inspected
Does not Exist
Inspected
Inspected
3 - Fair
LIGHTING FIXTURE BEYOND USEFUL LIFE
8
EACH
REPLACE-UPGRADE
PRIORITY 1

Building Condition Assessment Survey 2023 - 2024

icai hispection		V
stion	Response	
OCKER ROOM		
Lighting		
Lighting Fixture - Incandescent		
Surface Mounted		
Violations	No violations recorded.	
Instance on Basement - Home	Inspected	
Condition	3 - Fair	
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE	
Deficiency Quantity	8	
Quantity Uom	EACH	
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
Recessed Mounted	Does not Exist	
Instance on Basement - Visitors	Does not Exist	
Instance on Basement - Home	Does not Exist	
Lighting Fixture - LED		
Instance on Basement - Visitors	Does not Exist	
Instance on Basement - Home	Does not Exist	
Instance on 1st Floor - Girls	Does not Exist	
Instance on 1st Floor - Boys	Does not Exist	
ULTIPURPOSE ROOM	Does not Exist	
CIENCE DEMO ROOM	Inspected	
Instance on Rooms 202, 206	Inspected	
Power Panel	No	
Alternative use	No	
Instance on Room 204	Inspected	
Power Panel	No	
Alternative use	No	
Instance on Room 208	Inspected	
Power Panel Alternative use	No No	
Instance on Rooms 302, 306	Inspected	
Power Panel	No	
Alternative use	No	
Instance on Room 303	Inspected	
Power Panel	No	
Alternative use	No	
Instance on Room 304	Inspected	
Power Panel Alternative use	No No	
Instance on Room 305	Inspected	
Power Panel	No	
Alternative use	Yes	
Lighting	Inspected	
Instance on Room 305	Inspected	
instance on room 505		
Instance on Room 304	Inspected	
	Inspected Inspected	

Building Condition Assessment Survey 2023 - 2024

stion	Response
CIENCE DEMO ROOM	
Lighting	
Instance on Room 208	Inspected
Instance on Room 204	Inspected
Instance on Rooms 202, 206	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 305	Inspected
Instance on Room 304	Inspected
Instance on Room 303	Inspected
Instance on Rooms 302, 306	Inspected
Instance on Room 208	Inspected
Instance on Room 204	Inspected
Instance on Rooms 202, 206	Inspected
Pendant Mounted	Inspected
Instance on Room 305	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	20
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room 304	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	20
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room 303	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	20
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Rooms 302, 306	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	40
Quantity Uom	EACH

Building Condition Assessment Survey 2023 - 2024

icai inspection	· ·
stion	Response
CIENCE DEMO ROOM	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room 208	Does not Exist
Instance on Room 204	Does not Exist
Instance on Rooms 202, 206	Does not Exist
Surface Mounted	Does not Exist
Instance on Room 305	Does not Exist
Instance on Room 304	Does not Exist
Instance on Room 303	Does not Exist
Instance on Rooms 302, 306	Does not Exist
Instance on Room 208	Does not Exist
Instance on Room 204	Does not Exist
Instance on Rooms 202, 206	Does not Exist
Recessed Mounted	Does not Exist
Instance on Room 305	Does not Exist
Instance on Room 304	Does not Exist
Instance on Room 303	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Rooms 302, 306	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	12
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room 208	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 204	Inspected
Condition	3 - Fair

Building Condition Assessment Survey 2023 - 2024

tion	Response
IENCE DEMO ROOM	
Lighting	
Lighting Fixture - Fluorescent Recessed Mounted	
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	20
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Rooms 202, 206	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	52
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Lighting Fixture - HID	
Instance on Room 305	Does not Exist
Instance on Room 304	Does not Exist
Instance on Room 303	Does not Exist
Instance on Rooms 302, 306	Does not Exist
Instance on Room 208	Does not Exist
Instance on Room 204	Does not Exist
Instance on Rooms 202, 206	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 305	Inspected
Instance on Room 304	Inspected
Instance on Room 303	Inspected
Instance on Rooms 302, 306	Inspected
Instance on Room 208	Does not Exist
Instance on Room 204	Inspected
Instance on Rooms 202, 206	Inspected
Pendant Mounted	Does not Exist
Instance on Room 305	Does not Exist
Instance on Room 304	Does not Exist
Instance on Room 303	Does not Exist
Instance on Rooms 302, 306	Does not Exist
Instance on Room 204	Does not Exist
Instance on Rooms 202, 206	Does not Exist
Surface Mounted Instance on Room 305	Inspected Inspected

Building Condition Assessment Survey 2023 - 2024

ion	Response
ENCE DEMO ROOM	
ghting	
Lighting Fixture - Incandescent	
Surface Mounted	LIGHTING FIVELIDE DEVOND LIGERIA LIFE
Deficiency Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	1 FACH
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room 304	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room 303	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Rooms 302, 306	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room 204	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1

Building Condition Assessment Survey 2023 - 2024

Electrical Inspection Q420

tion	Response
IENCE DEMO ROOM	
ighting	
Lighting Fixture - Incandescent	
Surface Mounted	
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Rooms 202, 206	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Recessed Mounted	Does not Exist
Instance on Room 305	Does not Exist
Instance on Room 304	Does not Exist
Instance on Room 303	Does not Exist
Instance on Rooms 302, 306	Does not Exist
Instance on Room 204	Does not Exist
Instance on Rooms 202, 206	Does not Exist
Lighting Fixture - LED	
Instance on Room 305	Does not Exist
Instance on Room 304	Does not Exist
Instance on Room 303	Does not Exist
Instance on Rooms 302, 306	Does not Exist
Instance on Room 208	Does not Exist
Instance on Room 204	Does not Exist
Instance on Rooms 202, 206	Does not Exist
Emergency Gas Shut-Off Valve	Inspected
Instance on Room 305	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 304	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 303	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 302, 306	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 208	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 204	Inspected

Print Date: 6/25/2024

Building Condition Assessment Survey 2023 - 2024

stion	Response	
ZIENCE DEMO ROOM	кезропя	
Emergency Gas Shut-Off Valve		
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Instance on Rooms 202, 206	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Emergency Shut-Off Power	Inspected	
Instance on Room 305	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Instance on Room 304	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Instance on Room 303		
Condition	Inspected 3 - Fair	
	No deficiencies recorded	
Deficiency Lecture of Reserve 202, 206		
Instance on Rooms 302, 306	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Instance on Room 208	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Instance on Room 204	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Instance on Rooms 202, 206	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Power Supply	Inspected	
Instance on Room 305	Inspected	
Instance on Room 304	Inspected	
Instance on Room 303	Inspected	
Instance on Rooms 302, 306	Inspected	
Instance on Room 208	Inspected	
Instance on Room 204	Inspected	
Instance on Rooms 202, 206	Inspected	
	inspected	
Instructor Unit		
Instance on Room 305	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Instance on Room 304	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Instance on Room 303	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
	I	
Instance on Rooms 302, 306 Condition	Inspected 3 - Fair	

Building Condition Assessment Survey 2023 - 2024

No. Power Supply	duestion	Response
Instance on Room 208	SCIENCE DEMO ROOM	
Inspected Countries	Power Supply	
Condition	Instructor Unit	
Deficiency	Instance on Room 208	Inspected
Instance on Room 204	Condition	3 - Fair
Condition	Deficiency	No deficiencies recorded
Deficiency	Instance on Room 204	Inspected
Instance on Rooms 202, 206	Condition	3 - Fair
Deficiency	Deficiency	No deficiencies recorded
Deficiency	Instance on Rooms 202, 206	Inspected
Instance on Room 305	Condition	3 - Fair
Instance on Room 305	Deficiency	No deficiencies recorded
Condition 3 - Fair	Meter Demonstration Unit	
Deficiency	Instance on Room 305	Inspected
Instance on Room 304	Condition	3 - Fair
Condition 3 - Fair Deficiency No deficiencies recorded Instance on Room 303 Inspected Condition 3 - Fair Deficiency No deficiencies recorded Instance on Rooms 302, 306 Inspected Condition 3 - Fair Deficiency No deficiencies recorded Instance on Room 208 Inspected Condition 3 - Fair Deficiency No deficiencies recorded Instance on Room 204 Inspected Condition 3 - Fair Deficiency No deficiencies recorded Instance on Rooms 202, 206 Inspected Condition 3 - Fair Deficiency No deficiencies recorded Instance on Room 302, 206 Inspected Projection System Does not Exist Instance on Room 305 Does not Exist Instance on Room 304 Does not Exist Instance on Room 303 Does not Exist Instance on Room 304 Does not Exist Instance on Room 204 Does not Exist Insta	Deficiency	No deficiencies recorded
Deficiency No deficiencies recorded Instance on Room 303 Inspected Condition 3 - Fair Deficiency No deficiencies recorded Instance on Rooms 302, 306 Inspected Condition 3 - Fair Deficiency No deficiencies recorded Instance on Room 208 Inspected Condition 3 - Fair Deficiency No deficiencies recorded Instance on Room 204 Inspected Condition 3 - Fair Deficiency No deficiencies recorded Instance on Rooms 202, 206 Inspected Condition 3 - Fair Deficiency No deficiencies recorded Projection System Does not Exist Instance on Room 305 Does not Exist Instance on Room 304 Does not Exist Instance on Room 303 Does not Exist Instance on Room 304 Does not Exist Instance on Room 208 Does not Exist Instance on Room 208 Does not Exist Instance on Room 208 Does not Exist	Instance on Room 304	Inspected
Instance on Room 303 Inspected Condition 3 - Fair Deficiency No deficiencies recorded Instance on Rooms 302, 306 Inspected Condition 3 - Fair Deficiency No deficiencies recorded Instance on Room 208 Inspected Condition 3 - Fair Deficiency No deficiencies recorded Instance on Room 204 Inspected Condition 3 - Fair Deficiency No deficiencies recorded Instance on Rooms 202, 206 Inspected Condition 3 - Fair Deficiency No deficiencies recorded Instance on Rooms 202, 206 Inspected Projection System Does not Exist Instance on Room 305 Does not Exist Instance on Room 304 Does not Exist Instance on Room 303 Does not Exist Instance on Room 304 Does not Exist Instance on Room 308 Does not Exist Instance on Room 309 Does not Exist Instance on Room 208 Does not Exist	Condition	3 - Fair
Condition	Deficiency	No deficiencies recorded
Deficiency Instance on Rooms 302, 306 Inspected Condition 3 - Fair Deficiency Instance on Room 208 Inspected Condition 3 - Fair Deficiency Instance on Room 208 Inspected Condition 3 - Fair Deficiency No deficiencies recorded Instance on Room 204 Inspected Condition 3 - Fair Deficiency No deficiencies recorded Instance on Room 204 Inspected Condition 3 - Fair Deficiency No deficiencies recorded Instance on Rooms 202, 206 Inspected Condition 3 - Fair Deficiency No deficiencies recorded Instance on Room 302, 206 Inspected Condition 3 - Fair Deficiency No deficiencies recorded Instance on Room 305 Does not Exist Instance on Room 305 Does not Exist Instance on Room 305 Does not Exist Instance on Room 304 Does not Exist Instance on Room 303 Does not Exist Instance on Room 302, 306 Does not Exist Instance on Room 208 Does not Exist Instance on Room 208 Does not Exist Instance on Room 208 Does not Exist Instance on Room 209 Instance on Room 204 Does not Exist Instance on Room 209 Instance on Room 204 Does not Exist Instance on Room 204 Does not Exist Instance on Room 204 Does not Exist Instance on Room 208 Inspected Power Panel Alternative use No Inspected Power Panel Alternative use No	Instance on Room 303	Inspected
Instance on Rooms 302, 306	Condition	3 - Fair
No deficiency No deficiencies recorded	Deficiency	No deficiencies recorded
Deficiency	Instance on Rooms 302, 306	Inspected
Instance on Room 208	Condition	3 - Fair
Condition	Deficiency	No deficiencies recorded
Deficiency No deficiencies recorded Instance on Room 204 Inspected Condition 3 - Fair Deficiency No deficiencies recorded Instance on Rooms 202, 206 Inspected Condition 3 - Fair Deficiency No deficiencies recorded Instance on Rooms 202, 206 Inspected Condition 3 - Fair Deficiency No deficiencies recorded Projection System Does not Exist Instance on Room 305 Does not Exist Instance on Room 304 Does not Exist Instance on Room 304 Does not Exist Instance on Room 303 Does not Exist Instance on Rooms 302, 306 Does not Exist Instance on Room 208 Does not Exist Instance on Room 208 Does not Exist Instance on Room 204 Does not Exist Instance on Room 204 Does not Exist Instance on Room 202, 206 Does not Exist Instance on Room 201 Inspected Power Panel Yes Alternative use No Instance on Room 203 Inspected Power Panel Yes Alternative use No No	Instance on Room 208	Inspected
Instance on Room 204	Condition	3 - Fair
Condition 3 - Fair	Deficiency	No deficiencies recorded
Deficiency	Instance on Room 204	Inspected
Instance on Rooms 202, 206	Condition	3 - Fair
No deficiency No deficiencies recorded	Deficiency	No deficiencies recorded
Deficiency	Instance on Rooms 202, 206	Inspected
Does not Exist	Condition	3 - Fair
Instance on Room 305 Instance on Room 304 Instance on Room 303 Does not Exist Instance on Room 303 Does not Exist Instance on Rooms 302, 306 Does not Exist Instance on Room 208 Instance on Room 208 Does not Exist Instance on Room 204 Does not Exist Instance on Rooms 202, 206 Does not Exist Instance on Rooms 202, 206 Does not Exist Inspected Inspected Inspected Power Panel Alternative use No Inspected Power Panel Alternative use No Inspected Power Panel Alternative use No Inspected Power Panel Alternative use No Inspected Power Panel Alternative use No	Deficiency	No deficiencies recorded
Instance on Room 304 Does not Exist	Projection System	Does not Exist
Instance on Room 303	Instance on Room 305	Does not Exist
Instance on Rooms 302, 306 Instance on Room 208 Instance on Room 204 Instance on Rooms 202, 206 SCIENCE LAB Instance on Room 201 Instance on Room 201 Power Panel Alternative use Instance on Room 203 Inspected Power Panel Alternative use No Inspected Yes Alternative use No Inspected Yes Alternative use No Inspected No Inspected No Inspected No Inspected No Inspected No	Instance on Room 304	Does not Exist
Instance on Room 208 Does not Exist Instance on Room 204 Does not Exist Instance on Rooms 202, 206 Does not Exist Instance on Rooms 202, 206 SCIENCE LAB Inspected Instance on Room 201 Inspected Power Panel Alternative use Inspected Power Panel Alternative use Inspected Power Panel No Inspected Power Panel No	Instance on Room 303	Does not Exist
Instance on Room 204 Does not Exist Instance on Rooms 202, 206 Does not Exist SCIENCE LAB Inspected Instance on Room 201 Inspected Power Panel Yes Alternative use No Instance on Room 203 Inspected Power Panel Yes Alternative use No	Instance on Rooms 302, 306	Does not Exist
Instance on Room 204 Does not Exist Instance on Rooms 202, 206 Does not Exist SCIENCE LAB Inspected Instance on Room 201 Inspected Power Panel Alternative use Yes No Instance on Room 203 Inspected Power Panel Alternative use Yes No Alternative use No	Instance on Room 208	Does not Exist
Instance on Rooms 202, 206 Does not Exist SCIENCE LAB Inspected Instance on Room 201 Inspected Power Panel Yes Alternative use No Instance on Room 203 Inspected Power Panel Yes Alternative use No	Instance on Room 204	
SCIENCE LAB Inspected Instance on Room 201 Inspected Power Panel Yes Alternative use No Instance on Room 203 Inspected Power Panel Yes Alternative use No		
Instance on Room 201 Power Panel Alternative use Instance on Room 203 Inspected Power Panel Alternative use Yes Alternative use Yes Alternative use No		
Power Panel Alternative use No Instance on Room 203 Inspected Power Panel Alternative use No		
Alternative use No Instance on Room 203 Inspected Power Panel Yes Alternative use No		
Power Panel Yes Alternative use No		
Power Panel Yes Alternative use No	Instance on Room 203	Inspected
Alternative use No		
Instance on Room 301 Inspected	Alternative use	
	Instance on Room 301	Inspected

Building Condition Assessment Survey 2023 - 2024

near inspection	
estion	Response
CIENCE LAB	
Power Panel	Yes
Alternative use	No
Instance on Room 308	Inspected
Power Panel Alternative use	Yes No
Instance on Rooms 103, 105	Inspected
Power Panel	Yes
Alternative use	No
Lighting	Inspected
Instance on Rooms 103, 105	Inspected
Instance on Room 308	Inspected
Instance on Room 301	Inspected
Instance on Room 203	Inspected
Instance on Room 201	Inspected
Lighting Fixture - Fluorescent	
Instance on Rooms 103, 105	Inspected
Instance on Room 308	Inspected
Instance on Room 301	Inspected
Instance on Room 203	Inspected
Instance on Room 201	Inspected
Pendant Mounted	Does not Exist
Instance on Rooms 103, 105	Does not Exist
Instance on Room 308	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 301	Does not Exist
Instance on Room 203	Does not Exist
Instance on Room 201	Does not Exist
Surface Mounted	Does not Exist Does not Exist
Instance on Rooms 103, 105	Does not Exist Does not Exist
	Does not Exist Does not Exist
Instance on Room 308	
Instance on Room 301	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	1 EACH
Quantity Uom Potential Action	EACH REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room 203	Does not Exist
Instance on Room 201	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	1 EACH
Quantity Uom	EACH

Building Condition Assessment Survey 2023 - 2024

car inspection	· ·
tion	Response
IENCE LAB	
ighting	
Lighting Fixture - Fluorescent	
Surface Mounted	
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Recessed Mounted	Inspected
Instance on Rooms 103, 105	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 308	Does not Exist
Instance on Room 301	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	30
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room 203	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	29
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room 201	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	29
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Lighting Fixture - HID	
Instance on Rooms 103, 105	Does not Exist
Instance on Room 308	Does not Exist
	Descript Endet
Instance on Room 301	Does not Exist
Instance on Room 301 Instance on Room 203	Does not Exist Does not Exist

Building Condition Assessment Survey 2023 - 2024

ENCE LAB	
ghting	
Lighting Fixture - Incandescent	
Instance on Rooms 103, 105	Does not Exist
Instance on Room 308	Does not Exist
Instance on Room 301	Inspected
Instance on Room 203	Inspected
Instance on Room 201	Inspected
Pendant Mounted	Does not Exist
Instance on Room 301	Does not Exist
Instance on Room 203	Does not Exist
Instance on Room 201	Does not Exist
Surface Mounted	Inspected
Instance on Room 301	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room 203	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room 201	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Recessed Mounted	Does not Exist
Instance on Room 301	Does not Exist
Instance on Room 203	Does not Exist
Instance on Room 201	Does not Exist
Lighting Fixture - LED	

Building Condition Assessment Survey 2023 - 2024

stion	Response	
CIENCE LAB		
Lighting		
Lighting Fixture - LED		
Instance on Room 308	Does not Exist	
Instance on Room 301	Does not Exist	
Instance on Room 203	Does not Exist	
Instance on Room 201	Does not Exist	
Emergency Gas Shut-Off Valve	Inspected	
Instance on Rooms 103, 105	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Instance on Room 308	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Instance on Room 301	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Instance on Room 203	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Instance on Room 201	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Emergency Shut-Off Power	Inspected	
Instance on Rooms 103, 105	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Instance on Room 308	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Instance on Room 301	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Instance on Room 203	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Instance on Room 201	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Power Supply	Inspected	
Instance on Rooms 103, 105	Inspected	
Instance on Room 308	Inspected	
Instance on Room 301	Inspected	
Instance on Room 203	Inspected	
Instance on Room 201	Inspected	
Instructor Unit		
Instance on Rooms 103, 105	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Instance on Room 308	Inspected	

Building Condition Assessment Survey 2023 - 2024

uestion	Response
SCIENCE LAB	
Power Supply	
Instructor Unit	
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 301	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 203	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 201	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Meter Demonstration Unit	
Instance on Rooms 103, 105	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 308	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 301	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 203	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 201	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Student Unit	
Instance on Rooms 103, 105	Does not Exist
Instance on Room 308	Does not Exist
Instance on Room 301	Inspected
Condition	3 - Fair
	No deficiencies recorded
Deficiency Instance on Room 203	
Condition	Inspected 3 - Fair
	No deficiencies recorded
Deficiency Instance on Room 201	
	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Projection System	Does not Exist
Instance on Rooms 103, 105	Does not Exist
Instance on Room 308	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 301	Does not Exist
Instance on Room 203	Does not Exist

Building Condition Assessment Survey 2023 - 2024

stion	Response
CIENCE PREP ROOM	Inspected
Instance on Room 103P	Inspected
Power Panel Alternative use	No No
Instance on Rooms 201P, 307	Inaccessible
Instance on Room 203P	Inspected
Power Panel	No
Alternative use	No
Instance on Room 301P	Inspected
Power Panel Alternative use	Yes
	No
Lighting Instance on Recent 201B	Inspected
Instance on Room 301P	Inspected
Instance on Room 203P	Inspected
Instance on Room 103P	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 301P	Inspected
Instance on Room 203P	Inspected
Instance on Room 103P	Inspected
Pendant Mounted	Inspected
Instance on Room 301P	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	23
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1 Violations	No photo recorded No violations recorded.
-	
Instance on Room 203P	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	4 EACH
Quantity Uom Potential Action	EACH REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room 103P	Does not Exist
Surface Mounted	Does not Exist
Instance on Room 301P	Does not Exist Does not Exist
Instance on Room 203P	Does not Exist
Instance on Room 103P	Does not Exist
Recessed Mounted	Does not Exist
Instance on Room 301P	Does not Exist
Instance on Room 203P Condition	Inspected 3 - Fair

Building Condition Assessment Survey 2023 - 2024

stion	Response	
CIENCE PREP ROOM		
Lighting		
Lighting Fixture - Fluorescent		
Recessed Mounted		-
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE	
Deficiency Quantity	13	
Quantity Uom	EACH	
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
Instance on Room 103P	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on Room 301P	Does not Exist	
Instance on Room 203P	Does not Exist	
Instance on Room 103P	Does not Exist	
Lighting Fixture - Incandescent		
Instance on Room 301P	Does not Exist	
Instance on Room 203P	Does not Exist	
Instance on Room 103P	Does not Exist	
Lighting Fixture - LED		
Instance on Room 301P	Does not Exist	
Instance on Room 203P	Does not Exist	
Instance on Room 103P	Does not Exist	
Emergency Gas Shut-Off Valve	Inspected	
Instance on Room 301P	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Instance on Room 203P	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Instance on Room 103P	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Emergency Shut-Off Power	Inspected	
Instance on Room 301P	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Instance on Room 203P	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Instance on Room 103P	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Power Supply	Inspected	
Instance on Room 301P	Inspected	
Instance on Room 203P	Inspected	

Building Condition Assessment Survey 2023 - 2024

euestion	Response
SCIENCE PREP ROOM	
Power Supply	
Instance on Room 103P	Does not Exist
Instructor Unit	
Instance on Room 301P	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 203P	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
SWIMMING POOL	Does not Exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	15
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Recessed Mounted	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	23
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	7
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2

Building Condition Assessment Survey 2023 - 2024

· ·
Response
Inspected
No photo recorded
No violations recorded.
Inspected
3 - Fair
LIGHTING FIXTURE BEYOND USEFUL LIFE
12
EACH
REPLACE-UPGRADE
PRIORITY 1
LEVEL 2
No photo recorded
No violations recorded.
Inspected
3 - Fair
LIGHTING FIXTURE BEYOND USEFUL LIFE
47
EACH
REPLACE-UPGRADE
PRIORITY 1
LEVEL 2
No photo recorded
No violations recorded.
Does not Exist
Does not Exist
Does not Exist
Inspected
262,000
S.F.
3 - Fair
INDICATOR PANEL NOT OPERATIONAL
Custodian's Office, Boiler Room
2
EACH
REPLACE PANEL
PRIORITY 3
PRIORITY 3 LEVEL 2
LEVEL 2
LEVEL 2 No photo recorded
LEVEL 2 No photo recorded No violations recorded.
LEVEL 2 No photo recorded No violations recorded. Does not Exist Inspected
LEVEL 2 No photo recorded No violations recorded. Does not Exist
LEVEL 2 No photo recorded No violations recorded. Does not Exist Inspected Inspected
LEVEL 2 No photo recorded No violations recorded. Does not Exist Inspected Inspected Room next to Electrical Room B22

Building Condition Assessment Survey 2023 - 2024

nestion	Response
EMERGENCY GENERATOR SET	
Automatic Transfer Switch (ATS)	
Instance Manufacturer	ASCO
Equipment	NDPEM-TRANS SW
Capacity/Size Quantity	600
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2008
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded
Instance	Room next to Electrical Room B22
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	ASCO
Equipment	FA-TRANS SW
Capacity/Size Quantity	30
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2008
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded
Instance	Room next to Electrical Room B22
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	ASCO
Equipment	COMM-TRANS SW
Capacity/Size Quantity	30
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2008
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded
Battery Charger	Inspected
Instance	Outdoor Generator Enclosure (Loading Area)
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Generac
Equipment	Battery Charger
Capacity/Size Quantity	10
Capacity/Size UOM	AmpsDC
Capacity/Size2 Quantity	24
Capacity/Size2 UOM	VDC
Source of Capacity/Size	Nameplate
Installation Year	2008
Source of Installation	Documented
Deficiency	No deficiencies recorded

Building Condition Assessment Survey 2023 - 2024

•	
uestion	Response
EMERGENCY GENERATOR SET	
Emergency Distribution Board	Inspected
Number of Spares	0
Fused Disconnect Switch Type	Inspected
Instance	Room next to Electrical Room B22
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	All City Switchboard
Equipment	NDPEM
Capacity/Size Quantity	600
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	1
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Inspector Estimate
Installation Year	2008
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded
Molded Case Circuit Breaker Type	Does not Exist
Diesel	Inspected
Instance	Outdoor Generator Enclosure (Loading Area)
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Generac
Equipment	Emergency Generator
Capacity/Size Quantity	169
Capacity/Size UOM	KVA
Capacity/Size2 Quantity	135
Capacity/Size2 UOM	KW
Capacity/Size3Quantity	468
Capacity/Size3 UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2008
Source of Installation	Documented
Deficiency	No deficiencies recorded
Natural Gas	Does not Exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not Exist
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Non Battery Pack	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded

Building Condition Assessment Survey 2023 - 2024

V
Response
Inspected
Does not Exist
Does not Exist
Inspected
262,000
S.F.
Inspected
2 - Between Good and Fair
No deficiencies recorded
Inspected
2 - Between Good and Fair
No deficiencies recorded
Inspected
2 - Between Good and Fair
No deficiencies recorded
Inspected
4 - Between Fair and Poor
CONTROL NOT OPERATIONAL
Mechanical Rooms (Auditorium, Gymnasium, Room B12)
3
EACH
REPAIR
PRIORITY 5
LEVEL 6
No photo recorded
No violations recorded.
Inspected
2 - Between Good and Fair
No deficiencies recorded
Inspected
2 - Between Good and Fair
No deficiencies recorded
Does not Exist
Inspected
2 - Between Good and Fair
No deficiencies recorded
Inspected
2 - Between Good and Fair
No deficiencies recorded
Inspected
2 - Between Good and Fair
No deficiencies recorded
Inspected
2 - Between Good and Fair
No deficiencies recorded
Inspected
Main Entrance Lobby

Building Condition Assessment Survey 2023 - 2024

ilear inspection	Y
estion	Response
IRE ALARM SYSTEM	Inspected
Fire Alarm Digital Communicator	
Instance Manufacturer	Radionics
Equipment	Fire Alarm Communicator
Installation Year	2008
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded
Main Panel	Inspected
Bell At Panel	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Main Entrance Lobby
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Mircom
Equipment	N/A
Model	FX - 2000
Installation Year	2008
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Does not Exist
Sub-Panel	Does not Exist
Remote Annunciator	Inspected
Display Monitor	Does not Exist
Panel	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Printer	Inspected
Condition	5 - Poor
Deficiency	PRINTER NOT OPERATIONAL
Deficiency Location/Instance	Custodian's Office
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Punch Register	Does not Exist
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Tamper Flow Switch/Chain	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
ROUNDING SYSTEM	Inspected
Condition Condition	3 - Fair
CONGRESSION	2 Iuii

Building Condition Assessment Survey 2023 - 2024

nestion	Response
INTERCOM SYSTEM	Inspected
Elevator	Inspected
Condition	3 - Fair
Deficiency Holding Area	No deficiencies recorded Does not Exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not Exist
MOTOR CONTROLLER	Inspected
Motor Control Center	Does not Exist
Motor Starter/Contactor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	3 - Fair
Deficiency	PANEL BOARD DOOR LOCK IS MISSING
Deficiency Location/Instance	Gymnasiums Mechanical Room, Boiler Room
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room B22, Boiler Room, Mechanical Rooms (Gymnasiums Auditorium, Basement Field House, Room B12)
Deficiency Quantity	10
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Fused Knife Switch Type	Does not Exist
Fused Toggle Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Inspected
Condition	3 - Fair
Deficiency	NO SPARE
Deficiency Location/Instance	Room 301P
•	Room 301P

Building Condition Assessment Survey 2023 - 2024

stion	Response
NEL BOARD	
Molded Case Circuit Breaker Type	
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL NEW PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL BOARD COVER IS MISSING
Deficiency Location/Instance	Auditorium
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL BOARD DOOR LOCK IS MISSING
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL BOARD DOOR LOCK IS MISSING
Deficiency Location/Instance	Auditorium
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	NO SPARE
Deficiency Location/Instance	1st Floor Corridor - by Room 138
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Purpose of Action Deficiency Photo1	No photo recorded
Violations	No violations recorded.
	110 violations recorded.

Building Condition Assessment Survey 2023 - 2024

puestion	Response
PANEL BOARD	
Molded Case Circuit Breaker Type	
Deficiency Location/Instance	Corridors - by (Rooms 328, 322A, 308, 302, 229J, 220, 207, 202, 138 126J, 124S, 120, 110, 108, 102A, A10, B4, B7, Boys Locker Room), Rooms (201P, 119, B8, B7, B6), Auditorium, Gymnasiums, Kitchen, Students Cafeteria, Projection Room, Field House - Basement Mechanical Room, Electrical Closet - Field House, Boiler Room, Electrical Room B22
Deficiency Quantity	47
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
PUBLIC ADDRESS SYSTEM	Inspected
Replacement Quantity	262,000
Replacement Uom	S.F.
Instance	Room 102D
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Rauland Telecenter
Installation Year	2004
Source of Installation	Inspector Estimate
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Classrooms and Corridors
Deficiency Quantity	15
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
SECURITY	Inspected
IPDVS/CCTV System	Inspected
Replacement Quantity	262,000
Replacement Uom	S.F.
Installation Year	2019
Source of Installation	Custodial Staff
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Intrusion Alarm System	Inspected
Replacement Quantity	262,000
Replacement Uom	S.F.
Central Control Panel	Inspected
Instance	Custodian's Office
Instance Condition	3 - Fair
Instance Quantity	1

Building Condition Assessment Survey 2023 - 2024

uestion	Response
SECURITY	
Intrusion Alarm System	
Central Control Panel	Inspected
Model	Vista-128B
Installation Year	1999
Source of Installation	Inspector Estimate
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Lighting - Security	Inspected
Replacement Uom	EACH
Condition	2 - Between Good and Fair
	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency	
Deficiency Location/Instance	Main Entrance Canopy
Deficiency Quantity	17
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 3
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Location/Instance	Main Entrance Canopy
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 3
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
SERVICE SWITCH	
	Inspected
Instance	Electrical Room B22
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Federal Pacific Electric
Equipment	Main Switchboard Section "A"
Capacity/Size Quantity	3,000
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
(P)	Page 37 of 39 Print Date: 6/25/2024

Building Condition Assessment Survey 2023 - 2024

estion	Response
ERVICE SWITCH	
Installation Year	1965
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room B22
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Federal Pacific Electric
Equipment	Main Switchboard Section "B"
Capacity/Size Quantity	3,000
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1965
Source of Installation	Documented
Deficiency	No deficiencies recorded
VITCHBOARD	Inspected
Number of Spares	0
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room B22
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Federal Pacific Electric
Equipment	N/A
Capacity/Size Quantity	3,000
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	3
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Service Switch Size
Installation Year	1965
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room B22
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Federal Pacific Electric
Equipment	N/A
Capacity/Size Quantity	3,000
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	3
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Service Switch Size
Installation Year	1965
Source of Installation	Documented
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not Exist

Building Condition Assessment Survey 2023 - 2024

uestion	Response
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
TRANSFORMER	Does not Exist