Building Condition Assessment Survey 2023 - 2024

Inspection Id Inspection Type		Time In	Last Edited
EE: Q426 Electrical		2024-05-20 8:19 AM	2024-06-07 8:50 AM
sset Data			
Question	Answer		
Type of Service	Below Ground	i	
Does Interactive Whiteboard (IWB) Exist?	No		
Water Penetration in Electrical Room?	No		
Have any Systems/Major Building Components been upgraded?	Yes		
	Systems: I	Retrofitted LED Lighting	
	Years: 2	2024	
	Systems: S	Security Lights	
	Years:	1997, 2017	
		Incandescent Lighting, Fire Ala System	rm System, Public Addre
	Years:	1997	
	•	Molded Case Circuit Breaker Ty 1987, 1997	ype Panel Board
DEDICATED INTERCOMS IN FIRE RESCUE AREAS			
Question	Response		
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	No		
riority Condition			
Priority Priority Condition Component Locatic Condition Exist Category Description Affected Description Last Year?		Person(s) Title Status	PhotoImage
No condition recorded			
nspection			
Question	Response		
Electrical			
AUDITORIUM	Does not Ex	rist	
CAFETERIA	Does not Ex	xist	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected		
Lighting	Inspected		
Does a Chandelier exist?	No		
Lighting Fixture - Fluorescent	Does not Ex	rist	
Lighting Fixture - HID	Does not Ex	xist	
Lighting Fixture - Incandescent	Inspected		
Pendant Mounted	Does not Ex	xist	
Surface Mounted	Inspected		
Condition	3 - Fair		
Deficiency	No deficien	cies recorded	
Recessed Mounted	Does not Ex		
Lighting Fixture - LED	Inspected		
Pendant Mounted	Inspected		
Condition		Good and Fair	
Deficiency		cies recorded	
Surface Mounted	Inspected		
Condition		Good and Fair	
Deficiency		cies recorded	
Recessed Mounted	Inspected		
(SP (P)	Page 1 of 5		Print Date: 6/25/202

Building Condition Assessment Survey 2023 - 2024

Question	Response
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	
Lighting Fixture - LED	
Recessed Mounted	
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
COMPUTER LAB	Does not Exist
GYMNASIUM	Does not Exist
KITCHEN	Does not Exist
LIBRARY	Does not Exist
LOCKER ROOM	Does not Exist
MULTIPURPOSE ROOM	Does not Exist
SCIENCE DEMO ROOM	Does not Exist
SCIENCE LAB	Does not Exist
SCIENCE PREP ROOM	Does not Exist
SWIMMING POOL	Does not Exist
TOILET ROOM - STAFF	Does not Exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Does not Exist
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - Incandescent Lighting Fixture - LED	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Does not Exist
Recessed Mounted	Inspected 2 - Between Good and Fair
Condition Deficiency	No deficiencies recorded
AUXILIARY SIGNAL/BELL SYSTEM	Does not Exist
EMERGENCY DC STANDBY BATTERY POWER	Does not Exist
EMERGENCY GENERATOR SET	Does not Exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not Exist
EMERGENCY LIGHTING	Does not Exist
EXIT LIGHT	Inspected
Battery Pack	Does not Exist
Non Battery Pack	Inspected
Condition	3 - Fair
Deficiency EXIT/EMERGENCY LIGHT	No deficiencies recorded Does not Exist
FIRE ALARM SYSTEM Replacement Operative	Inspected 5.500
Replacement Ucm	5,500 S.F.
Replacement Uom	
Bell/Horn	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Strobe Condition	Inspected 3 - Fair
Deficiency	No deficiencies recorded
Deficiency	TWO deficiencies recolded

Building Condition Assessment Survey 2023 - 2024

rical hispection		Q-1.
estion	Response	
FIRE ALARM SYSTEM		
Manual Pull Station	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Fan Shutdown Control	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Duct Smoke Detector	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Area Smoke Detector	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
CO Detector	Does not Exist	
Heat Detector	Does not Exist	
Elevator Recall	Does not Exist	
Magnetic Door Holder/Contactor	Does not Exist	
Fused Cutout Panel	Does not Exist	
Fire Alarm Digital Communicator	Does not Exist	
Main Panel	Inspected	
Bell At Panel	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Poultry House	
Instance Condition	3 - Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Instance Manufacturer	Edwards System Technology	
Equipment	Fire Alarm Panel	
Model	EST	
Installation Year	1997	
Source of Installation	Documented	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Standard)	Does not Exist	
Sub-Panel	Does not Exist	
Remote Annunciator	Does not Exist	
Sprinkler Flow/Air Pressure Switch	Does not Exist	
Tamper Flow Switch/Chain	Does not Exist	
ROUNDING SYSTEM	Does not Exist	
NTERCOM SYSTEM	Does not Exist	
AN	Does not Exist	
IGHTNING PROTECTION	Does not Exist	
MOTOR CONTROLLER	Inspected	
Motor Control Center	Does not Exist	
Motor Starter/Contactor	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
	Does not Exist	

Building Condition Assessment Survey 2023 - 2024

Question	Response
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	3 - Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Greenhouse
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Fused Knife Switch Type	Does not Exist
Fused Toggle Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
PUBLIC ADDRESS SYSTEM	Inspected
Replacement Quantity	5,500
Replacement Uom	S.F.
Instance	Connected to Main Asset Q425
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	N/A
Installation Year	1997
Source of Installation	Documented
Deficiency	No deficiencies recorded
SECURITY	Inspected
IPDVS/CCTV System	Does not Exist
Intrusion Alarm System	Does not Exist
Lighting - Security	Inspected
Replacement Uom	EACH
Condition	2 - Between Good and Fair
Deficiency	LIGHTING FIXTURE PHOTOCELL NOT OPERATIONAL
Deficiency Location/Instance	Exterior Wall - by Poultry House Entrance
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 3
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
SERVICE SWITCH	Does not Exist
SWITCHBOARD	Does not Exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded

Building Condition Assessment Survey 2023 - 2024

Question	Response
TELEPHONE SYSTEM	Inspected
Standard	Does not Exist
TRANSFORMER	Does not Exist