#### **Building Condition Assessment Survey 2023 - 2024**

Inspection Id Inspection Type		Time In	Last Edited
EE: Q440 Electrical		2024-05-01 8:54 AM	2024-05-09 10:16 A
sset Data			
Question	Answer		
Type of Service	Below Gro	ound	
Does Interactive Whiteboard (IWB) Exist?	Yes		
Water Penetration in Electrical Room?	No		
Have any Systems/Major Building Components been upgraded?	Yes		
	Systems:	Gymnasium (Scoreboard), Motor Frequency Drive)	Controller (Variable
	Years:	Under Construction	
	Systems:	IPDVS/CCTV System, Emergen (Science Demo Rooms 340, 342, Lighting (Room 415)	
	Years:	2022	
	Systems:	Gymnasiums (LED Lighting), In (Infrared Sensor)	trusion Alarm System
	Years:	2020	
	Systems:	Science Prep Room 154A (LED	Lighting)
	Years:	2019	
	Systems:	Telephone System, LAN	
	Years:	2018	
	Systems:	Intrusion Alarm System (Remote Control Panel)	Annunciator, Central
	Years:	2014	
	Systems:	Library	
	Years:	2012	
	Systems:	Auditorium (Theater Lighting Sy System)	stem, Local Sound
	Years:	2010	
	Systems:	Security Lights	
	Years:	2009, 2019	
	Systems:	Interior Fluorescent Lighting - E Mounted, Kitchen, Toilet Rooms Cafeterias - Pendant Mounted)	
	Years:	2009	
	Systems:	Service Switch, Switchboard, Fu Type Panel Board, Fire Alarm Sy	
	Years:	2008	
	Systems:	Public Address System	
	Years:	2006	
	Systems:	Interior Fluorescent Lighting (Re Kitchen, Toilet Rooms, Auditori Mounted), Science Lab - Room Lighting)	ım, Cafeterias - Pendant
	Years:	2003	
	Systems:	Emergency Light/Exit Light Pan	el
	Years:	1997	
	Systems:	Most Molded Case Circuit Break	er Type Panel Board
	Years:	1985, 1999, 2008, 2011, 2019, 20	)22
DEDICATED INTERCOMS IN FIRE RESCUE AREAS			
Question	Response		
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	No		
riority Condition			

# **Building Condition Assessment Survey 2023 - 2024**

Electrical Insp	ection								Q440
Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage	
No	Fire Alarm System - Components Not Operational	N/A	FIRE ALARM SYSTEM   Strobe	Boys Gymnasium	David Pareti	Custodian	Sent to DSF		
Inspection									
Question					Respons	se			
Electrical									
AUDITORIU	J <b>M</b>				Inspected	 d			
Ins	tance on 1st Floo	r			Inspected	d			
House Ligh	hting				Inspected	 d			
	es a Chandelier e	exist?			No				
Ins	tance on 1st Floo	r			Inspected	d			
Lighting	Fixture - Fluore	escent							
Ins	tance on 1st Floo	r			Inspected	d			
Penda	nt Mounted				Does not	Exist			
Ins	stance on 1st Floo	r			Does not	Exist			
Surfac	e Mounted				Inspected	d			
Ins	stance on 1st Floo	r			Inspected	d			
Conc	dition				3 - Fair				
De	ficiency				No defic	iencies recorded			
Recess	ed Mounted				Does not	Exist			
Ins	tance on 1st Floo	r			Does not	Exist			
Lighting	Fixture - HID								
Ins	tance on 1st Floo	r			Does not	Exist			
Lighting	Fixture - Incand	descent							
Ins	stance on 1st Floo	r			Inspected	d			
Penda	nt Mounted				Does not	Exist			
Ins	stance on 1st Floo	r			Does not	Exist			
Surfac	e Mounted				Inspected	d			
Ins	stance on 1st Floo	r			Inspected				
Conc	dition				3 - Fair				
De	ficiency				LIGHTI	NG FIXTURE BEY	YOND USEFUI	LIFE	
D	eficiency Quantit	ty			2				
Q	uantity Uom				EACH				
P	otential Action				REPLAC	CE-UPGRADE			
U	rgency of Action				PRIORI'	ГҮ 1			
P	urpose of Action				LEVEL	2			
D	eficiency Photo1				No photo	recorded			
V	iolations				No viola	tions recorded.			
Recess	sed Mounted				Inspected	d			
Ins	tance on 1st Floo	r			Inspected				
Conc	dition				3 - Fair				
	ficiency					NG FIXTURE BEY	YOND USEFUI	LIFE	
	eficiency Quantit	ty			80				
	uantity Uom				EACH				
	otential Action				REPLAC	CE-UPGRADE			
IJ	rgency of Action				PRIORI'	ГҮ 1			

# **Building Condition Assessment Survey 2023 - 2024**

Response	
LEVEL 2	
No photo recorded	
No violations recorded.	
Does not Exist	
Inspected	
2010	
Inspector Estimate	
Does not Exist	
Does not Exist	
Inspected	
<u> </u>	
Inspected	
Inspected	
3 - Fair	
No deficiencies recorded	
Inspected	
Inspected	
mspected	
Inspected	
No deficiencies recorded	
T 1	
Inspected	
Inspected	
Inspected 3 - Fair	
Inspected	
	No photo recorded No violations recorded.  Does not Exist Inspected Inspected 2010 Inspector Estimate 3 - Fair No deficiencies recorded Does not Exist Does not Exist Inspected Inspected Inspected Inspected Inspected 3 - Fair No deficiencies recorded  Inspected

# **Building Condition Assessment Survey 2023 - 2024**

ireal hispection		Q T
estion	Response	
AFETERIA		
Lighting		
Lighting Fixture - Fluorescent		
Recessed Mounted		
Instance on Basement - Students	Does not Exist	
Instance on Basement - Staff	Does not Exist	
Lighting Fixture - HID		
Instance on Basement - Students	Does not Exist	
Instance on Basement - Staff	Does not Exist	
Lighting Fixture - Incandescent		
Instance on Basement - Students	Does not Exist	
Instance on Basement - Staff	Does not Exist	
Lighting Fixture - LED		
Instance on Basement - Students	Does not Exist	
Instance on Basement - Staff	Does not Exist	
Local Sound System	Inspected	
Instance on Basement - Students	Inspected	
Installation Year	2000	
Source of Installation	Inspector Estimate	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Instance on Basement - Staff	Does not Exist	
Projection System	Does not Exist	
Instance on Basement - Students	Does not Exist	
Instance on Basement - Staff	Does not Exist	
Theater Lighting System	Does not Exist	
Instance on Basement - Students	Does not Exist	
Instance on Basement - Staff	Does not Exist	
LASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected	
Lighting	Inspected	
Does a Chandelier exist?	Yes	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID	Does not Exist	
Lighting Fixture - Incandescent	Inspected	
Pendant Mounted	Does not Exist	
Surface Mounted	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not Exist	

# **Building Condition Assessment Survey 2023 - 2024**

Question	Response
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	
Lighting Fixture - LED	
Pendant Mounted	Does not Exist
Surface Mounted	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
COMPUTER LAB	Inspected
Instance on Rooms 211, 363, 366	Inspected
Power Panel	Yes
Lighting	Inspected
Instance on Rooms 211, 363, 366	Inspected
Lighting Fixture - Fluorescent	
Instance on Rooms 211, 363, 366	Inspected
Pendant Mounted	Inspected
Instance on Rooms 211, 363, 366	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Instance on Rooms 211, 363, 366	Does not Exist
Recessed Mounted	Does not Exist
Instance on Rooms 211, 363, 366	Does not Exist
Lighting Fixture - HID	
Instance on Rooms 211, 363, 366	Does not Exist
Lighting Fixture - Incandescent	
Instance on Rooms 211, 363, 366	Does not Exist
Lighting Fixture - LED	
Instance on Rooms 211, 363, 366	Does not Exist
Raceway With Receptacles	Inspected
Instance on Rooms 211, 363, 366	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
GYMNASIUM	Inspected
Instance on 1st Floor - Boys, 1st Floor - Girls	Inspected
Lighting	Inspected
Instance on 1st Floor - Boys, 1st Floor - Girls	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor - Boys, 1st Floor - Girls	Does not Exist
Lighting Fixture - HID	
Instance on 1st Floor - Boys, 1st Floor - Girls	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor - Boys, 1st Floor - Girls	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor - Boys, 1st Floor - Girls	Inspected
Pendant Mounted	Does not Exist
Instance on 1st Floor - Boys, 1st Floor - Girls	Does not Exist
Surface Mounted	Inspected
Instance on 1st Floor - Boys, 1st Floor - Girls	Inspected
·	

# **Building Condition Assessment Survey 2023 - 2024**

Response  Inspected  Inspected
·
·
Inspected
Inspected
<u> </u>
1 - Good
No deficiencies recorded
Does not Exist
Does not Exist
Inspected
Inspected
2000
Inspector Estimate
3 - Fair
No deficiencies recorded
Does not Exist
Does not Exist
Under Construction
Under Construction
Does not Exist
Does not Exist
Inspected
Inspected
Inspected
Inspected
Inspected
Inspected
Inspected
3 - Fair
No deficiencies recorded
Inspected
Inspected
3 - Fair
No deficiencies recorded
Does not Exist
Does not Exist
Does not Exist
Does not Exist
Does not Exist
Inspected
Inspected
Inspected
Inspected
mspected
Inspected

# **Building Condition Assessment Survey 2023 - 2024**

# **Building Condition Assessment Survey 2023 - 2024**

stion	Response	v
CIENCE DEMO ROOM	Response	
Power Panel	No	
Alternative use	No	
Instance on Rooms 151, 251	Inspected	
Power Panel Alternative use	Yes No	
Instance on Rooms 153, 214A, 253	Inspected	
Power Panel	No	
Alternative use	No	
Instance on Rooms 340, 342, 343, 344, 345	Inspected	
Power Panel Alternative use	No No	
Instance on Rooms 351, 353	Inspected	
Power Panel	No	
Alternative use	No	
Lighting	Inspected	
Instance on Rooms 351, 353	Inspected	
Instance on Rooms 340, 342, 343, 344, 345	Inspected	
Instance on Rooms 153, 214A, 253	Inspected	
Instance on Rooms 151, 251	Inspected	
Instance on Room 163	Inspected	
Lighting Fixture - Fluorescent		
Instance on Rooms 351, 353	Inspected	
Instance on Rooms 340, 342, 343, 344, 345	Inspected	
Instance on Rooms 153, 214A, 253	Inspected	_
Instance on Rooms 151, 251	Inspected	_
Instance on Room 163	Inspected	_
Pendant Mounted	Inspected	_
Instance on Rooms 351, 353	Inspected	_
Condition	3 - Fair	_
Deficiency	No deficiencies recorded	
Instance on Rooms 340, 342, 343, 344, 345	Inspected	
Condition	3 - Fair	_
Deficiency	No deficiencies recorded	
Instance on Rooms 153, 214A, 253	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Instance on Rooms 151, 251	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	_
Instance on Room 163	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Does not Exist	
Instance on Rooms 351, 353	Does not Exist	
Instance on Rooms 340, 342, 343, 344, 345	Does not Exist	
Instance on Rooms 153, 214A, 253	Does not Exist	
Instance on Rooms 151, 251	Does not Exist	
Instance on Room 163	Does not Exist	
Recessed Mounted	Does not Exist	

# **Building Condition Assessment Survey 2023 - 2024**

stion	Response	
IENCE DEMO ROOM		
ighting		
Lighting Fixture - Fluorescent		
Recessed Mounted		
Instance on Rooms 351, 353	Does not Exist	
Instance on Rooms 340, 342, 343, 344, 345	Does not Exist	
Instance on Rooms 153, 214A, 253	Does not Exist	
Instance on Rooms 151, 251	Does not Exist	
Instance on Room 163	Does not Exist	
Lighting Fixture - HID		
Instance on Rooms 351, 353	Does not Exist	
Instance on Rooms 340, 342, 343, 344, 345	Does not Exist	
Instance on Rooms 153, 214A, 253	Does not Exist	
Instance on Rooms 151, 251	Does not Exist	
Instance on Room 163	Does not Exist	
Lighting Fixture - Incandescent		
Instance on Rooms 351, 353	Does not Exist	
Instance on Rooms 340, 342, 343, 344, 345	Does not Exist	
Instance on Rooms 153, 214A, 253	Does not Exist	
Instance on Rooms 151, 251	Does not Exist	
Instance on Room 163	Does not Exist	
Lighting Fixture - LED	DOGS HOT LAIST	
Instance on Rooms 351, 353	Does not Exist	
Instance on Rooms 340, 342, 343, 344, 345	Does not Exist	
Instance on Rooms 153, 214A, 253	Does not Exist	
Instance on Rooms 151, 251	Does not Exist	
Instance on Rooms 163	Does not Exist	
Emergency Gas Shut-Off Valve	Inspected	
Instance on Rooms 351, 353	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Instance on Rooms 340, 342, 343, 344, 345	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Instance on Rooms 153, 214A, 253	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Instance on Rooms 151, 251	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Instance on Room 163	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Emergency Shut-Off Power	Does not Exist	
Instance on Rooms 351, 353	Does not Exist	
	Does not Exist	
Instance on Rooms 340, 342, 343, 344, 345		
Instance on Rooms 340, 342, 343, 344, 345  Instance on Rooms 153, 214A, 253  Condition	Inspected 3 - Fair	

# **Building Condition Assessment Survey 2023 - 2024**

	Q-
Response	
Inspected	
3 - Fair	
No deficiencies recorded	
Does not Exist	
Inspected	
Inspected	
No deficiencies recorded	
Inspected	
3 - Fair	
No deficiencies recorded	
Inspected	
3 - Fair	
No deficiencies recorded	
Inspected	
3 - Fair	
No deficiencies recorded	
Does not Exist	
Does not Exist	
Inspected	
3 - Fair	
No deficiencies recorded	
Inspected	
3 - Fair	
No deficiencies recorded	
Inspected	
3 - Fair	
No deficiencies recorded	
Does not Exist	
Inspected	
Inspected	
	Inspected  3 - Fair  No deficiencies recorded  Does not Exist  Inspected  3 - Fair  No deficiencies recorded  Does not Exist  Inspected  3 - Fair  No deficiencies recorded  Does not Exist  Does not Exist

# **Building Condition Assessment Survey 2023 - 2024**

tion	Response
IENCE LAB	
Instance on Room 162	Inspected
Power Panel Alternative use	Yes No
Instance on Rooms 152, 252	Inspected
Power Panel	Yes
Alternative use	No
Lighting	Inspected
Instance on Rooms 152, 252	Inspected
Instance on Room 162	Inspected
Instance on Room 111	Inspected
Lighting Fixture - Fluorescent	
Instance on Rooms 152, 252	Inspected
Instance on Room 162	Inspected
Instance on Room 111	Inspected
Pendant Mounted	Inspected
Instance on Rooms 152, 252	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 162	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 111	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Instance on Rooms 152, 252 Condition	Inspected 3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 162	Does not Exist
Instance on Room 111	Does not Exist
Recessed Mounted	Does not Exist
Instance on Rooms 152, 252	Does not Exist
Instance on Room 162	Does not Exist
Instance on Room 111	Does not Exist
Lighting Fixture - HID	Does not Daist
Instance on Rooms 152, 252	Does not Exist
Instance on Room 162	Does not Exist
Instance on Room 111	Does not Exist
Lighting Fixture - Incandescent	DOG NOT DAIST
Instance on Rooms 152, 252	Does not Exist
Instance on Room 162	Inspected
Instance on Room 111	
	Inspected
Pendant Mounted Instance on Room 162	Does not Exist  Does not Exist
Instance on Room 111	Inspected 5. Poor
Condition	5 - Poor
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL

trical Inspection		Ç
uestion	Response	
SCIENCE LAB		
Lighting		
Lighting Fixture - Incandescent		
Pendant Mounted		
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
Surface Mounted	Inspected	
Instance on Room 162	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Instance on Room 111	Does not Exist	
Recessed Mounted	Does not Exist	
Instance on Room 162	Does not Exist	
Instance on Room 111	Does not Exist	
Lighting Fixture - LED		
Instance on Rooms 152, 252	Does not Exist	
Instance on Room 162	Does not Exist	
Instance on Room 111	Does not Exist	
Emergency Gas Shut-Off Valve	Inspected	
Instance on Rooms 152, 252	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Instance on Room 162	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Instance on Room 111	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Emergency Shut-Off Power	Inspected	
Instance on Rooms 152, 252	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Instance on Room 162	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Instance on Room 111	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Power Supply	Inspected	
Instance on Rooms 152, 252	Inspected	
Instance on Room 162	Inspected	
Instance on Room 111	Does not Exist	

Inspected

No deficiencies recorded

3 - Fair

Instance on Rooms 152, 252

Condition

Deficiency

#### **Building Condition Assessment Survey 2023 - 2024**

icai inspection		
estion	Response	
CIENCE LAB		
Power Supply		
Instructor Unit		
Instance on Room 162	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Meter Demonstration Unit		
Instance on Rooms 152, 252	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Instance on Room 162	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Student Unit		
Instance on Rooms 152, 252	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Instance on Room 162	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Projection System	Does not Exist	
Instance on Rooms 152, 252	Does not Exist	
Instance on Room 162	Does not Exist	
Instance on Room 111	Does not Exist	
CIENCE PREP ROOM	Inspected	
Instance on Room 154A	Inspected	
Power Panel	No	
Alternative use	No	
Instance on Room 254	Inspected	
Power Panel	Yes	
Alternative use	No	
Instance on Room 356	Inspected	
Power Panel	No	
Alternative use	Yes	
Instance on Rooms 164, 352	Inspected	
Power Panel Alternative use	No Yes	
Instance on Room 352A	Inspected	
Power Panel Alternative use	Yes Yes	
Lighting	Inspected	
Instance on Room 352A	Inspected	
Instance on Rooms 164, 352	Inspected	
Instance on Room 356	Inspected	
Instance on Room 254	Inspected	
Instance on Room 154A	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 352A	Inspected	
Instance on Rooms 164, 352	Inspected	
Instance on Room 356	Inspected	
	· T · · · · · · ·	

# **Building Condition Assessment Survey 2023 - 2024**

tion	Response	
IENCE PREP ROOM		
ighting		
Lighting Fixture - Fluorescent		
Instance on Room 154A	Does not Exist	
Pendant Mounted	Inspected	
Instance on Room 352A	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Instance on Rooms 164, 352	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Instance on Room 356	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Instance on Room 254	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Does not Exist  Does not Exist	
Instance on Room 352A		
Instance on Rooms 164, 352	Does not Exist	
Instance on Room 356	Does not Exist	
Instance on Room 254	Does not Exist	
Recessed Mounted	Does not Exist	
Instance on Room 352A	Does not Exist	
Instance on Rooms 164, 352	Does not Exist	
Instance on Room 356	Does not Exist	
Instance on Room 254	Does not Exist	
Lighting Fixture - HID		
Instance on Room 352A	Does not Exist	
Instance on Rooms 164, 352	Does not Exist	
Instance on Room 356	Does not Exist	
Instance on Room 254	Does not Exist	
Instance on Room 154A	Does not Exist	
Lighting Fixture - Incandescent		
Instance on Room 352A	Does not Exist	
Instance on Rooms 164, 352	Does not Exist	
Instance on Room 356	Does not Exist	
Instance on Room 254	Does not Exist	
Instance on Room 154A	Does not Exist	
Lighting Fixture - LED	DOGS HOT LAIST	
Instance on Room 352A	Does not Exist	
	Does not Exist	
Instance on Rooms 164, 352		
Instance on Room 356	Does not Exist	
Instance on Room 254	Does not Exist	
Instance on Room 154A	Inspected	
Pendant Mounted	Inspected	
Instance on Room 154A	Inspected	

# **Building Condition Assessment Survey 2023 - 2024**

ileai ilispection		
estion	Response	
CCIENCE PREP ROOM		
Lighting		
Lighting Fixture - LED		
Pendant Mounted	Inspected	
Deficiency	No deficiencies recorded	
Surface Mounted	Does not Exist	
Instance on Room 154A	Does not Exist	
Recessed Mounted	Does not Exist	
Instance on Room 154A	Does not Exist	
Emergency Gas Shut-Off Valve	Does not Exist	
Instance on Room 352A	Does not Exist	
Instance on Rooms 164, 352	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Instance on Room 356	Does not Exist	
Instance on Room 254	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Instance on Room 154A	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Emergency Shut-Off Power	Does not Exist	
Instance on Room 352A	Does not Exist	
Instance on Rooms 164, 352	Does not Exist	
Instance on Room 356	Does not Exist	
Instance on Room 254	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Instance on Room 154A	Does not Exist	
Power Supply	Does not Exist	
Instance on Room 352A	Does not Exist	
Instance on Rooms 164, 352	Inspected	
Instance on Room 356	Does not Exist	
Instance on Room 254	Does not Exist	
Instance on Room 154A	Does not Exist	
Instructor Unit		
Instance on Rooms 164, 352	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
WIMMING POOL	Does not Exist	
COILET ROOM - STAFF	Inspected	
Lighting	Inspected	
<b>Lighting Fixture - Fluorescent</b>	Inspected	
Pendant Mounted	Does not Exist	
Surface Mounted	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not Exist	
Lighting Fixture - HID	Does not Exist	

#### **Building Condition Assessment Survey 2023 - 2024**

**Electrical Inspection O440** Ouestion Response TOILET ROOM - STAFF Inspected Lighting Inspected **Lighting Fixture - Incandescent** Does not Exist **Lighting Fixture - LED** Does not Exist **TOILET ROOM - STUDENT** Inspected Lighting Inspected **Lighting Fixture - Fluorescent** Inspected **Pendant Mounted** Inspected Condition 3 - Fair Deficiency No deficiencies recorded **Surface Mounted** Inspected Condition 3 - Fair Deficiency No deficiencies recorded Recessed Mounted Does not Exist **Lighting Fixture - HID** Does not Exist **Lighting Fixture - Incandescent** Does not Exist **Lighting Fixture - LED** Does not Exist AUXILIARY SIGNAL/BELL SYSTEM Inspected 256,000 Replacement Quantity Replacement Uom S.F. Condition 3 - Fair Deficiency No deficiencies recorded EMERGENCY DC STANDBY BATTERY POWER Does not Exist EMERGENCY GENERATOR SET Does not Exist EMERGENCY LIGHT/EXIT LIGHT PANEL Inspected Condition 3 - Fair Deficiency PANEL BOARD COVER IS MISSING Electrical Room B19 Deficiency Location/Instance Deficiency Quantity EACH Quantity Uom Potential Action MAINTENANCE PRIORITY 2 Urgency of Action Purpose of Action LEVEL 2 Deficiency Photo1 No photo recorded Violations No violations recorded. Deficiency LESS THAN 20% SPARE CIRCUIT BREAKERS Deficiency Location/Instance Electrical Rooms B19, B68 **Deficiency Quantity** Quantity Uom **EACH** INSTALL NEW PANEL BOARD Potential Action Urgency of Action PRIORITY 5 Purpose of Action LEVEL 2 Deficiency Photo1 No photo recorded Violations No violations recorded. **EMERGENCY LIGHTING** Inspected **Battery Pack** Inspected Condition 3 - Fair Deficiency BATTERY NOT OPERATIONAL

# **Building Condition Assessment Survey 2023 - 2024**

estion	Response
EMERGENCY LIGHTING	
Battery Pack	
Deficiency Location/Instance	Corridors - by Rooms (105, 135, 167), 1st Floor - Staircase D Vestibule
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE BATTERY
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Non Battery Pack	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	3 - Fair
Deficiency	FIXTURE NOT OPERATIONAL
Deficiency Location/Instance	3rd Floor Corridor - by Room 332
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Non Battery Pack	Does not Exist
EXIT/EMERGENCY LIGHT	Does not Exist
TIRE ALARM SYSTEM	Inspected
Replacement Quantity	256,000
Replacement Uom	S.F.
Bell/Horn	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Strobe	Inspected
Strobe Condition	Inspected 2 - Between Good and Fair
Condition	
Condition Deficiency	2 - Between Good and Fair STROBE NOT OPERATIONAL
Condition	2 - Between Good and Fair
Condition  Deficiency  Deficiency Location/Instance  Deficiency Quantity	2 - Between Good and Fair  STROBE NOT OPERATIONAL  Boys Gymnasium
Condition  Deficiency  Deficiency Location/Instance	2 - Between Good and Fair  STROBE NOT OPERATIONAL  Boys Gymnasium  1
Condition  Deficiency  Deficiency Location/Instance  Deficiency Quantity  Quantity Uom  Potential Action	2 - Between Good and Fair  STROBE NOT OPERATIONAL  Boys Gymnasium  1  EACH
Condition  Deficiency  Deficiency Location/Instance  Deficiency Quantity  Quantity Uom  Potential Action  Urgency of Action	2 - Between Good and Fair  STROBE NOT OPERATIONAL  Boys Gymnasium  1  EACH  REPLACE
Condition  Deficiency  Deficiency Location/Instance  Deficiency Quantity  Quantity Uom  Potential Action  Urgency of Action  Purpose of Action	2 - Between Good and Fair  STROBE NOT OPERATIONAL  Boys Gymnasium  1  EACH  REPLACE  PRIORITY 5  LEVEL 6
Condition  Deficiency  Deficiency Location/Instance  Deficiency Quantity  Quantity Uom  Potential Action  Urgency of Action	2 - Between Good and Fair  STROBE NOT OPERATIONAL  Boys Gymnasium  1  EACH  REPLACE  PRIORITY 5
Condition  Deficiency Deficiency Location/Instance Deficiency Quantity Quantity Uom Potential Action Urgency of Action Purpose of Action Deficiency Photo1 Violations	2 - Between Good and Fair  STROBE NOT OPERATIONAL  Boys Gymnasium  1  EACH  REPLACE  PRIORITY 5  LEVEL 6  No photo recorded  No violations recorded.
Condition  Deficiency Deficiency Location/Instance Deficiency Quantity Quantity Uom Potential Action Urgency of Action Purpose of Action Deficiency Photo1 Violations  Manual Pull Station	2 - Between Good and Fair  STROBE NOT OPERATIONAL  Boys Gymnasium  1  EACH  REPLACE  PRIORITY 5  LEVEL 6  No photo recorded  No violations recorded.  Inspected
Condition  Deficiency Deficiency Location/Instance Deficiency Quantity Quantity Uom Potential Action Urgency of Action Purpose of Action Deficiency Photo1 Violations  Manual Pull Station Condition	2 - Between Good and Fair  STROBE NOT OPERATIONAL  Boys Gymnasium  1  EACH  REPLACE  PRIORITY 5  LEVEL 6  No photo recorded  No violations recorded.  Inspected  2 - Between Good and Fair
Condition  Deficiency Deficiency Location/Instance Deficiency Quantity Quantity Uom Potential Action Urgency of Action Purpose of Action Deficiency Photo1 Violations  Manual Pull Station	2 - Between Good and Fair  STROBE NOT OPERATIONAL  Boys Gymnasium  1  EACH  REPLACE  PRIORITY 5  LEVEL 6  No photo recorded  No violations recorded.  Inspected

# **Building Condition Assessment Survey 2023 - 2024**

ilear inspection		Q+
estion	Response	
IRE ALARM SYSTEM		
Fan Shutdown Control	Inspected	
Deficiency	No deficiencies recorded	
Duct Smoke Detector	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Area Smoke Detector	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
CO Detector	Does not Exist	
Heat Detector	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Elevator Recall	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Magnetic Door Holder/Contactor	Does not Exist	
Fused Cutout Panel	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Digital Communicator	Does not Exist	
Main Panel	Inspected	
Bell At Panel	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Main Entrance Lobby	
Instance Condition	2 - Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Instance Manufacturer	General Electric	
Equipment	Fire Alarm Control Panel	
Model	EST 2	
Installation Year	2008	
Source of Installation	Inspector Estimate	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Standard)	Does not Exist	
Sub-Panel	Does not Exist	
Remote Annunciator	Inspected	
-	•	
Display Monitor	Does not Exist	
Panel	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Printer	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Punch Register	Does not Exist	
Sprinkler Flow/Air Pressure Switch	Does not Exist	
Tamper Flow Switch/Chain	Inspected	
Condition	2 - Between Good and Fair	

# **Building Condition Assessment Survey 2023 - 2024**

arrear inspection	
uestion	Response
FIRE ALARM SYSTEM	Inspected
Tamper Flow Switch/Chain	
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Inspected
Elevator	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Holding Area	Does not Exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not Exist
MOTOR CONTROLLER	Inspected
Motor Control Center	Does not Exist
Motor Starter/Contactor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Under Construction
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not Exist
Fused Toggle Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Inspected
Condition	2 - Between Good and Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Mechanical Rooms (B25, B49), 1st Floor - Room 162
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1 LEVEL 2
Purpose of Action	
Deficiency Photo1 Violations	No photo recorded  No violations recorded.
v ioiations	NO VIOIAHORS RECORDED.
PUBLIC ADDRESS SYSTEM	Inspected
Replacement Quantity	256,000
Replacement Uom	S.F.
Instance	PA Closet - Room 149
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH

#### **Building Condition Assessment Survey 2023 - 2024**

near inspection	_	Q44
estion	Response	
UBLIC ADDRESS SYSTEM		
Model	Rauland Telecenter	
Installation Year	2006	
Source of Installation	Inspector Estimate	
Deficiency	CLOCK NOT OPERATIONAL	
Deficiency Location/Instance	Boys Gymnasium	
Deficiency Quantity	2	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
ECURITY	Inspected	
IPDVS/CCTV System	Inspected	
Replacement Quantity	256,000	
Replacement Uom	S.F.	
Installation Year	2022	
Source of Installation	Custodial Staff	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Intrusion Alarm System	Inspected	
Replacement Quantity	256,000	
Replacement Uom	S.F.	
Central Control Panel	Inspected	
Instance	Custodian's Office	
Instance Condition	2 - Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Model	Vista-128BPT	
Installation Year	2014	
Source of Installation	Custodial Staff	
Deficiency	No deficiencies recorded	
Infrared Sensor	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Panic Switch	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Remote Annunciator	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Siren/Strobe	Inspected	
Condition	3 - Fair	
Deficiency	SIREN/STROBE NOT ACTIVE	
Deficiency Location/Instance	2nd Floor Corridor - by Room 258	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	

# **Building Condition Assessment Survey 2023 - 2024**

Question	Response
SECURITY	
Intrusion Alarm System	Inspected
Siren/Strobe	
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Lighting - Security	Inaccessible
SERVICE SWITCH	Inspected
Instance	Electrical Room B19
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Galaxy Switchgear
Equipment	Service "A"
Capacity/Size Quantity	2,500
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2008
Source of Installation	Inspector Estimate
Deficiency	No deficiencies recorded
Instance	Electrical Room B68
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Galaxy Switchgear
Equipment	Service "B"
Capacity/Size Quantity	2,500
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2008
Source of Installation	Inspector Estimate
Deficiency	No deficiencies recorded
SWITCHBOARD	Inspected
Number of Spares	6
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room B19
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Galaxy Switchgear
Equipment	Service "A"
Capacity/Size Quantity	2,500
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	3
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Service Switch Size
Installation Year	2008
Source of Installation	Inspector Estimate
Source of instantation	Page 21 of 22 Print Poto, 6/05/2024

#### **Building Condition Assessment Survey 2023 - 2024**

nestion	Response
SWITCHBOARD	
Fused Disconnect Switch Type	
Deficiency	No deficiencies recorded
Instance	Electrical Room B68
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Galaxy Switchgear
Equipment	Service "B"
Capacity/Size Quantity	2,500
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	3
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Service Switch Size
Installation Year	2008
Source of Installation	Inspector Estimate
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Does not Exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
FRANSFORMER	Does not Exist