Building Condition Assessment Survey 2023 - 2024

Inspection Id Inspection Type	Time In Last Edited	
EE: Q443 Electrical	2023-12-05 11:19 AM 2023-12-26 11	1:40 Al
Asset Data		
Question	Answer	
Type of Service	Below Ground	
Does Interactive Whiteboard (IWB) Exist?	Yes	
Water Penetration in Electrical Room?	No	
Have any Systems/Major Building Components been upgraded?	Yes	
	Systems: Fire Alarm System	
	Years: 2023 Systems: All Other Electrical Systems and Components	
	Years: 2022	
DEDICATED INTERCOMS IN FIRE RESCUE AREAS	10013. 2022	
Question	Response	
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	No	
Priority Condition		
Priority Priority Condition Component Location Condition Exist Category Description Affected Description Last Year?	Person(s) Person(s) Title Status PhotoImage Notified	
No condition recorded		
nspection		
Question	Response	
Electrical		
AUDITORIUM	Does not Exist	
CAFETERIA	Does not Exist	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected	
Lighting	Inspected	
Does a Chandelier exist?	No	
Lighting Fixture - Fluorescent	Does not Exist	
Lighting Fixture - HID	Does not Exist	
Lighting Fixture - Incandescent	Does not Exist	
Lighting Fixture - LED	Inspected	
Pendant Mounted	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Surface Mounted	Does not Exist	
Recessed Mounted	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
COMPUTER LAB	Does not Exist	
GYMNASIUM	Does not Exist	
KITCHEN	Inspected	
Instance on 1st Floor	Inspected	
	Inspected	
Lighting		
Lighting Instance on 1st Floor	Inspected	
	Inspected	

Building Condition Assessment Survey 2023 - 2024

inear hispection		Q T T
nestion	Response	
KITCHEN		
Lighting		
Lighting Fixture - HID		
Instance on 1st Floor	Does not Exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not Exist	
Lighting Fixture - LED		
Instance on 1st Floor	Inspected	
Pendant Mounted	Does not Exist	
Instance on 1st Floor	Does not Exist	
Surface Mounted	Does not Exist	
Instance on 1st Floor	Does not Exist	
Recessed Mounted	Inspected	
Instance on 1st Floor	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
LIBRARY	Does not Exist	
LOCKER ROOM	Does not Exist	
MULTIPURPOSE ROOM	Inspected	
Instance on 1st Floor - Room 116, 1st Floor - Room 124	Inspected	
Lighting	Inspected	
Instance on 1st Floor - Room 116, 1st Floor - Room 124	Inspected	
Lighting Fixture - Fluorescent		
Instance on 1st Floor - Room 116, 1st Floor - Room 124	Does not Exist	
Lighting Fixture - HID		
Instance on 1st Floor - Room 116, 1st Floor - Room 124	Does not Exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor - Room 116, 1st Floor - Room 124	Does not Exist	
Lighting Fixture - LED		
Instance on 1st Floor - Room 116, 1st Floor - Room 124	Inspected	
Pendant Mounted	Does not Exist	
Instance on 1st Floor - Room 116, 1st Floor - Room 124	Does not Exist	
Surface Mounted	Does not Exist	
Instance on 1st Floor - Room 116, 1st Floor - Room 124	Does not Exist	
Recessed Mounted	Inspected	
Instance on 1st Floor - Room 116, 1st Floor - Room 124	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Local Sound System	Does not Exist	
Instance on 1st Floor - Room 116, 1st Floor - Room 124	Does not Exist	
Projection System	Does not Exist	
Instance on 1st Floor - Room 116, 1st Floor - Room 124	Does not Exist	
Theater Lighting System	Does not Exist	
Instance on 1st Floor - Room 116, 1st Floor - Room 124	Does not Exist	
SCIENCE DEMO ROOM	Does not Exist	
SCIENCE LAB	Does not Exist	
SCIENCE LAB SCIENCE PREP ROOM	Does not Exist Does not Exist	

Building Condition Assessment Survey 2023 - 2024

Question	Response
TOILET ROOM - STAFF	
Lighting	Inspected
Lighting Fixture - Fluorescent	Does not Exist
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Does not Exist
Recessed Mounted	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Does not Exist
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Does not Exist
Recessed Mounted	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Replacement Quantity	23,000
Replacement Uom	S.F.
Condition	1 - Good
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not Exist
EMERGENCY GENERATOR SET	Does not Exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not Exist
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Non Battery Pack	Does not Exist
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Non Battery Pack	Does not Exist
EXIT/EMERGENCY LIGHT	Does not Exist
FIRE ALARM SYSTEM	Inspected
Replacement Quantity	23,000
Replacement Uom	S.F.
Bell/Horn	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Strobe	Inspected

Building Condition Assessment Survey 2023 - 2024

near mspection		Q-
estion	Response	
IRE ALARM SYSTEM		
Strobe	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Manual Pull Station	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Fan Shutdown Control	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Duct Smoke Detector	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Area Smoke Detector	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
CO Detector	Does not Exist	
Heat Detector	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Elevator Recall	Does not Exist	
Magnetic Door Holder/Contactor	Does not Exist	
Fused Cutout Panel	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Fire Alarm Digital Communicator	Does not Exist	
Main Panel	Inspected	
Bell At Panel	Does not Exist	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Main Entrance Lobby	
Instance Condition	1 - Good	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Instance Manufacturer	Edwards System Technology Fire Alarm Control Panel	
Equipment	EST3X	
Model Installation Year	2023	
Source of Installation	Documented	
	No deficiencies recorded	
Deficiency Fire Alarm Control Panel (Standard)	No deficiencies recorded Does not Exist	
Sub-Panel	Does not Exist	
Remote Annunciator	Inspected	
Display Monitor	Does not Exist	
Panel	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Printer	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Punch Register	Does not Exist	

Building Condition Assessment Survey 2023 - 2024

Question	Response
FIRE ALARM SYSTEM	
Remote Annunciator	Inspected
Punch Register	
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Tamper Flow Switch/Chain	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Does not Exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Does not Exist
Main Equipment Rack (MDF)	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not Exist
MOTOR CONTROLLER	Inspected
Motor Control Center	Does not Exist
Motor Starter/Contactor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Variable Frequency Drive	Does not Exist
PANEL BOARD	
	Inspected Does not Exist
Fused Disconnect Switch Type	
Fused Knife Switch Type	Does not Exist
Fused Toggle Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
PUBLIC ADDRESS SYSTEM	Inspected
Replacement Quantity	23,000
Replacement Uom	S.F.
Instance	Telecom Room 119
Instance Condition	1 - Good
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Telecor XL
Installation Year	2022
Source of Installation	Documented
Deficiency	No deficiencies recorded
SECURITY	Inspected
IPDVS/CCTV System	Inspected
Replacement Quantity	23,000
Replacement Uom	S.F.
Installation Year	2022
Source of Installation	Documented

Building Condition Assessment Survey 2023 - 2024

irical hispection		Q+
nestion	Response	
SECURITY		
IPDVS/CCTV System	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Intrusion Alarm System	Inspected	
Replacement Quantity	23,000	
Replacement Uom	S.F.	
Central Control Panel	Inspected	
Instance	Custodian's Office	
Instance Condition	1 - Good	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Model	Vista-128BPT	
Installation Year	2022	
Source of Installation	Documented	
Deficiency	No deficiencies recorded	
Infrared Sensor	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Panic Switch	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Remote Annunciator	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Siren/Strobe	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Lighting - Security	Inspected	
Replacement Uom	EACH	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
ERVICE SWITCH	Inspected	
Instance	Electrical Room 113	
Instance Condition	1 - Good	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Instance Manufacturer	All City Switchboard	
Equipment	Service Switch	
Capacity/Size Quantity	1,600	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	2022	
Source of Installation	Documented	
Deficiency	No deficiencies recorded	
WITCHBOARD	Inspected	
Number of Spares	0	
Fused Disconnect Switch Type	Does not Exist	
Fused Knife Switch Type	Does not Exist	
Molded Case Circuit Breaker Type	Inspected	Drint Data: 6/25/20

Building Condition Assessment Survey 2023 - 2024

Question	Response
SWITCHBOARD	
Molded Case Circuit Breaker Type	
Instance	Electrical Room 113
Instance Condition	1 - Good
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	All City Switchboard
Equipment	SSA
Capacity/Size Quantity	1,600
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	1
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Nameplate
Installation Year	2022
Source of Installation	Documented
Deficiency	No deficiencies recorded
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
TRANSFORMER	Does not Exist