Building Condition Assessment Survey 2023 - 2024

Electrical Inspection Q450

Inspection Id	Inspection Type		Time In	Last Edited
EE: Q450	Electrical		2023-12-01 8:00 AM	2024-06-21 2:33 PI
et Data				
Question		Answer		
Type of Service		Below Gro	und	
Does Interactive	Whiteboard (IWB) Exist?	Yes		
Water Penetration	n in Electrical Room?	Yes		
Have any Systems/Major Building Components been upgraded?		Yes		
		Systems:	Science Prep Room 310	
		Years:	Under Construction	
		Systems:	Public Address System, Local So (Auditorium), 2nd Floor - Gymn Alarm System (Electronic Sub-P Partial Fused Cutout Panel, Tam	asium (Scoreboard), Fi anel, Elevator Recall,
		Years:	2023	
		Systems:	Auditorium (Local Sound Syster Exit Lights (Battery Pack), Exit/ Telephone System	
		Years:	2018	
		Systems:	Interior Lighting, Most Emergen Pack)	cy Lighting (Non Batte
		Years:	2017	
		Systems:	Intrusion Alarm System (Central Annunciator)	Control Panel, Remote
		Years:	2013	
		Systems:	Fire Alarm System (Sprinkler Fl	ow Switch)
		Years:	2008	
		Systems:	Auditorium (Dimming System, M	Most Theater Lighting)
		Years:	2005	
		Systems:	Fused Disconnect Switch Type I Lights, Partial Service Switch, P	
		Years:	2002	
		Systems:	Emergency Light/Exit Light Pan	el
		Years:	1992, 2001	
		Systems:	Most Molded Case Circuit Break	er Type Panel Board
		Years:	1987, 2000, 2002, 2005, 2010, 2	022
DEDICATED IN	NTERCOMS IN FIRE RESCUE AREAS			
Question		Response		
	fe Rescue Assistance Areas, Fire Rescue Areas, Rooms in your building?	No		

Priority Condition

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
No	Fire Alarm System - Defective	The panel is defective due to defective relays and a wire wound resistor.	FIRE ALARM SYSTEM Sub- Panel Fire Alarm Control Panel (Standard)		Jamel Peebles	Fireman	Sent to DSF	
No	Fire Alarm System - Defective	The panel is defective due to a faulty phone line.	FIRE ALARM SYSTEM Sub- Panel Fire Alarm Control Panel (Electronic)	Sub-Basement - Room SB1	Jamel Peebles	Fireman	Sent to DSF	
Yes	Water Penetration in Electrical Room	N/A	Electrical Equipment	Electrical Room SB9	Jamel Peebles	Fireman	Sent to DSF	

Building Condition Assessment Survey 2023 - 2024

Q450 **Electrical Inspection**

> Intercom - Not N/A Connected to Remote Monitoring

Station

Yes

INTERCOM Elevator -SYSTEM | Elevator 4P114

Device ID:

Jamel Peebles Fireman Sent to DSF

ıi.	n
estion	Response
ectrical	
AUDITORIUM	Inspected
Instance on 1st Floor	Inspected
House Lighting	Inspected
Does a Chandelier exist?	No
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Surface Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor	Inspected
Pendant Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Surface Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Local Sound System	Inspected
Instance on 1st Floor	Inspected
Installation Year	2018
Source of Installation	Inspector Estimate
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Projection System	Inspected
Is the projector on a cart or installed on the ceiling?	Ceiling
Instance on 1st Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Theater Lighting System	Inspected

Building Condition Assessment Survey 2023 - 2024

stion	Response
UDITORIUM	
Theater Lighting System	
Dimming System	
Instance on 1st Floor	Inspected
Condition	4 - Between Fair and Poor
Deficiency	DIMMING RACK/LIGHT CONSOLE NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Theater Lighting	
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	28
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
AFETERIA	Inspected
Instance on Basement - East	Inspected
Instance on Basement - West	Inspected
Lighting	Inspected
Instance on Basement - West	Inspected
Instance on Basement - West	
	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement - West	Inspected
Instance on Basement - East	Inspected
Pendant Mounted	Does not Exist
Instance on Basement - West	Does not Exist
Instance on Basement - East	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Instance on Basement - West	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Basement - East	Does not Exist
Recessed Mounted	Does not Exist
Instance on Basement - West	Does not Exist
Instance on Basement - East	Does not Exist
Lighting Fixture - HID	
Instance on Basement - West	Does not Exist
	2000 1100 211100

Building Condition Assessment Survey 2023 - 2024

icai inspection	V-
stion	Response
AFETERIA	
Lighting	
Lighting Fixture - Incandescent	
Instance on Basement - West	Does not Exist
Instance on Basement - East	Does not Exist
Lighting Fixture - LED	
Instance on Basement - West	Does not Exist
Instance on Basement - East	Does not Exist
Local Sound System	Inspected
Instance on Basement - West	•
Installation Year	Inspected 2023
Source of Installation	Custodial Staff
Condition	1 - Good
Deficiency	No deficiencies recorded
Instance on Basement - East	Inspected
Installation Year	2023
Source of Installation	Custodial Staff
Condition	1 - Good
Deficiency	No deficiencies recorded
Projection System	Does not Exist
Instance on Basement - West	Does not Exist
Instance on Basement - East	Does not Exist
Theater Lighting System	Does not Exist
Instance on Basement - West	Does not Exist
Instance on Basement - East	Does not Exist
LASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected
Lighting	Inspected
Does a Chandelier exist?	No
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Surface Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
	Does not Exist Does not Exist

Building Condition Assessment Survey 2023 - 2024

ileai ilispection		QTO
estion	Response	
COMPUTER LAB		
Instance on Room 410	Inspected	
Power Panel	No	
Lighting	Inspected	
Instance on Room 410	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 410	Inspected	
Pendant Mounted	Inspected	
Instance on Room 410	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Does not Exist	
Instance on Room 410	Does not Exist	
Recessed Mounted		
	Does not Exist Does not Exist	
Instance on Room 410	Does not Exist	
Lighting Fixture - HID		
Instance on Room 410	Does not Exist	
Lighting Fixture - Incandescent		
Instance on Room 410	Does not Exist	
Lighting Fixture - LED		
Instance on Room 410	Does not Exist	
Raceway With Receptacles	Inspected	
Instance on Room 410	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
SYMNASIUM	Inspected	
Instance on 2nd Floor	Inspected	
Instance on 4th Floor	Inspected	
Lighting	Inspected	
Instance on 4th Floor	Inspected	
Instance on 2nd Floor	Inspected	
Lighting Fixture - Fluorescent	порессе	
Instance on 4th Floor	Does not Exist	
Instance on 2nd Floor	Inspected	
Pendant Mounted	Does not Exist	
Instance on 2nd Floor	Does not Exist	
Surface Mounted	Inspected	
Instance on 2nd Floor	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not Exist	
Instance on 2nd Floor	Does not Exist	
Lighting Fixture - HID		
Instance on 4th Floor	Does not Exist	
Instance on 2nd Floor	Does not Exist	
Lighting Fixture - Incandescent		
Instance on 4th Floor	Does not Exist	
Instance on 2nd Floor	Does not Exist	
	=	

Building Condition Assessment Survey 2023 - 2024

rical hispection	· ·
estion	Response
SYMNASIUM	
Lighting	
Lighting Fixture - LED	
Instance on 4th Floor	Inspected
Instance on 2nd Floor	Inspected
Pendant Mounted	Does not Exist
Instance on 4th Floor	Does not Exist
Instance on 2nd Floor	Does not Exist
Surface Mounted	Inspected
Instance on 4th Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on 2nd Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Recessed Mounted	Does not Exist
Instance on 4th Floor	Does not Exist
Instance on 2nd Floor	Does not Exist
Local Sound System	Inspected
Instance on 4th Floor	Inspected
Installation Year	2023
Source of Installation	Custodial Staff
Condition	1 - Good
Deficiency	No deficiencies recorded
Instance on 2nd Floor	Inspected
Installation Year	2023
Source of Installation	Custodial Staff
Condition	1 - Good
Deficiency	No deficiencies recorded
Projection System	Does not Exist
Instance on 4th Floor	Does not Exist
Instance on 2nd Floor	Does not Exist
Scoreboard	Does not Exist
Instance on 4th Floor	Does not Exist
Instance on 2nd Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Theater Lighting System	Does not Exist
Instance on 4th Floor	Does not Exist
Instance on 2nd Floor	Does not Exist
ITCHEN	Inspected
Instance on Basement	Inspected
Instance on Basement	Inspected

Building Condition Assessment Survey 2023 - 2024

ileai ilispection	\ \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\
estion	Response
KITCHEN	
Lighting	Inspected
Instance on Basement	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement	Inspected
Pendant Mounted	Inspected
Instance on Basement	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Instance on Basement	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Instance on Basement	Does not Exist
Lighting Fixture - HID	
Instance on Basement	Does not Exist
Lighting Fixture - Incandescent	
Instance on Basement	Does not Exist
Lighting Fixture - LED	
Instance on Basement	Does not Exist
IBRARY	Inspected
Instance on Room 213	Inspected
Lighting	Inspected
Instance on Room 213	Inspected
	nispected
Lighting Fixture - Fluorescent Instance on Room 213	Towns at al
	Inspected
Pendant Mounted	Does not Exist
Instance on Room 213	Does not Exist
Surface Mounted	Does not Exist
Instance on Room 213	Does not Exist
Recessed Mounted	Inspected
Instance on Room 213	Inspected
Condition	2 - Between Good and Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Lighting Fixture - HID	
Instance on Room 213	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 213	Does not Exist
Lighting Fixture - LED	
Instance on Room 213	Does not Exist

Building Condition Assessment Survey 2023 - 2024

icai inspection	
stion	Response
IBRARY	Inspected
Raceway With Receptacles	Does not Exist
Instance on Room 213	Does not Exist
Projection System	Does not Exist
Instance on Room 213	Does not Exist
OCKER ROOM	Inspected
Instance on 2nd Floor	Inspected
Alternative use	No
Instance on 4th Floor - Boys	Inspected
Alternative use	No
Instance on 4th Floor - Girls	Inspected
Alternative use	Yes
Lighting	Inspected
Instance on 4th Floor - Girls	Inspected
Instance on 4th Floor - Boys	Inspected
Instance on 2nd Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 4th Floor - Girls	Inspected
Instance on 4th Floor - Boys	Inspected
Instance on 2nd Floor	Inspected
Pendant Mounted	Does not Exist
Instance on 4th Floor - Girls	Does not Exist
Instance on 4th Floor - Boys	Does not Exist
Instance on 2nd Floor	Does not Exist
Surface Mounted	Does not Exist
Instance on 4th Floor - Girls	Does not Exist
Instance on 4th Floor - Boys	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on 2nd Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Instance on 4th Floor - Girls	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on 4th Floor - Boys	Does not Exist
Instance on 2nd Floor	Does not Exist
Lighting Fixture - HID	
Instance on 4th Floor - Girls	Does not Exist
Instance on 4th Floor - Boys	Does not Exist
Instance on 2nd Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 4th Floor - Girls	Does not Exist
Instance on 4th Floor - Boys	Does not Exist
Instance on 2nd Floor	Does not Exist

Building Condition Assessment Survey 2023 - 2024

curear mispection		Q450
Question	Response	
LOCKER ROOM	Inspected	
Lighting		
Lighting Fixture - LED		
Instance on 4th Floor - Boys	Does not Exist	
Instance on 2nd Floor	Does not Exist	
MULTIPURPOSE ROOM	Does not Exist	
SCIENCE DEMO ROOM	Inspected	
Instance on Room 312	Inspected	
Power Panel Alternative use	Yes No	
Instance on Rooms 301, 307, 309, 313, 314	Inspected	
Power Panel	No	
Alternative use	No	
Lighting	Inspected	
Instance on Rooms 301, 307, 309, 313, 314	Inspected	
Instance on Room 312	Inspected	
Lighting Fixture - Fluorescent		
Instance on Rooms 301, 307, 309, 313, 314	Inspected	
Instance on Room 312	Inspected	
Pendant Mounted	Inspected	
Instance on Rooms 301, 307, 309, 313, 314	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on Room 312	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Does not Exist	
Instance on Rooms 301, 307, 309, 313, 314	Does not Exist	
Instance on Room 312	Does not Exist	
Recessed Mounted	Does not Exist	
Instance on Rooms 301, 307, 309, 313, 314	Does not Exist	
Instance on Room 312	Does not Exist	
Lighting Fixture - HID		
Instance on Rooms 301, 307, 309, 313, 314	Does not Exist	
Instance on Room 312	Does not Exist	
Lighting Fixture - Incandescent		
Instance on Rooms 301, 307, 309, 313, 314	Does not Exist	
Instance on Room 312	Does not Exist	
	DOGS HOT LAIST	
Lighting Fixture - LED Instance on Rooms 301, 307, 309, 313, 314	Does not Exist	
Instance on Room 312	Does not Exist	
Emergency Gas Shut-Off Valve	Inspected	
Instance on Rooms 301, 307, 309, 313, 314	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Instance on Room 312	Inspected	
Condition Deficiency	3 - Fair No deficiencies recorded	
Emergency Shut-Off Power Instance on Pooms 301, 307, 309, 313, 314	Inspected	
Instance on Rooms 301, 307, 309, 313, 314	Inspected	

Building Condition Assessment Survey 2023 - 2024

irical inspection		QTO
nestion	Response	
SCIENCE DEMO ROOM	Inspected	
Emergency Shut-Off Power		
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Instance on Room 312	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Power Supply	Inspected	
Instance on Rooms 301, 307, 309, 313, 314	Inspected	
Instance on Room 312	Inspected	
Instructor Unit		
Instance on Rooms 301, 307, 309, 313, 314	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Instance on Room 312	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Meter Demonstration Unit		
Instance on Rooms 301, 307, 309, 313, 314	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Instance on Room 312	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Projection System	Does not Exist	
Instance on Rooms 301, 307, 309, 313, 314	Does not Exist	
Instance on Room 312	Does not Exist	
CIENCE LAB	Inspected	
Instance on Rooms 302, 308	Inspected	
Power Panel	Yes	
Alternative use	No	
Lighting	Inspected	
Instance on Rooms 302, 308	Inspected	
Lighting Fixture - Fluorescent		
Instance on Rooms 302, 308	Inspected	
Pendant Mounted	Inspected	
Instance on Rooms 302, 308	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Does not Exist	
Instance on Rooms 302, 308	Does not Exist	
Recessed Mounted	Does not Exist	
Instance on Rooms 302, 308	Does not Exist	
Lighting Fixture - HID		
Instance on Rooms 302, 308	Does not Exist	
	DOG HOLLAISE	
Lighting Fixture - Incandescent	Door wat Emire	
Instance on Rooms 302, 308	Does not Exist	
Lighting Fixture - LED		
Instance on Rooms 302, 308	Does not Exist	
Emergency Gas Shut-Off Valve	Inspected	

Building Condition Assessment Survey 2023 - 2024

ilear hispection		QTO
estion	Response	
CIENCE LAB		
Emergency Gas Shut-Off Valve	Inspected	
Instance on Rooms 302, 308	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Emergency Shut-Off Power	Inspected	
Instance on Rooms 302, 308	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Power Supply	Inspected	
Instance on Rooms 302, 308	Inspected	
Instructor Unit		
Instance on Rooms 302, 308	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Meter Demonstration Unit		
Instance on Rooms 302, 308	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Student Unit	110 001010100 10001000	
Instance on Rooms 302, 308	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Projection System	Does not Exist	
Instance on Rooms 302, 308	Does not Exist	
CIENCE PREP ROOM		
Instance on Room 304	Inspected	
Power Panel	Inspected No	
Alternative use	No	
Instance on Room 310	Under Construction	
Lighting	Inspected	
Instance on Room 304	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 304	Inspected	
Pendant Mounted	Inspected	
Instance on Room 304	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Does not Exist	-
Instance on Room 304	Does not Exist	
Recessed Mounted	Does not Exist	
Instance on Room 304	Does not Exist	
	DOGS HOL EAIST	
Lighting Fixture - HID	D (F.')	
Instance on Room 304	Does not Exist	
Lighting Fixture - Incandescent		
Instance on Room 304	Does not Exist	
Lighting Fixture - LED		
Instance on Room 304	Does not Exist	
Emergency Gas Shut-Off Valve	Inspected	
Instance on Room 304	Inspected	

Building Condition Assessment Survey 2023 - 2024

Question	Response
SCIENCE PREP ROOM	
Emergency Gas Shut-Off Valve	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	Inspected
Instance on Room 304	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Power Supply	Inspected
Instance on Room 304	Inspected
Instructor Unit	
Instance on Room 304	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
SWIMMING POOL	Does not Exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Replacement Quantity	136,000
Replacement Uom	S.F.
Condition	3 - Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not Exist
EMERGENCY GENERATOR SET	Does not Exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected

Building Condition Assessment Survey 2023 - 2024

nestion	Response
EMERGENCY LIGHT/EXIT LIGHT PANEL	
Condition	3 - Fair
Deficiency	PANEL BOARD COVER IS MISSING
Deficiency Location/Instance	Electrical Room SB8
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Non Battery Pack	Does not Exist
EXIT/EMERGENCY LIGHT	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
FIRE ALARM SYSTEM	Inspected
Replacement Quantity	136,000
Replacement Uom	S.F.
Bell/Horn	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Strobe	Does not Exist
Manual Pull Station	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Does not Exist
Duct Smoke Detector	Does not Exist
Area Smoke Detector	Does not Exist
CO Detector	Does not Exist
Heat Detector	Does not Exist
Elevator Recall	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Magnetic Door Holder/Contactor	Does not Exist
Fused Cutout Panel	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Does not Exist

Building Condition Assessment Survey 2023 - 2024

FIRE ALARM SYSTEM Inspected Main Panel Does not Exist Bell At Panel Does not Exist Fire Alarm Control Panel (Electronic) Does not Exist Fire Alarm Control Panel (Standard) Inspected Instance Condition 3 - Fair Instance Condition 3 - Fair Instance Quantity 1 Instance Quantity Uom EACH Instance Manufacturer Edwards Equipment Fire Alarm Installation Year 1954 Source of Installation Documented Deficiency No deficiencies recorded Sub-Panel Inspected Condition 1 - Good Deficiency No deficiencies recorded Fire Alarm Control Panel (Electronic) Inspected Instance Sub-Basement - Room SB1 Instance Condition 2 - Between Good and Fair Instance Condition 2 - Between Good and Fair Instance Condition EACH Instance Condition EACH Instance Condition EXT Equip
Bell At Panel Does not Exist Fire Alarm Control Panel (Electronic) Does not Exist Fire Alarm Control Panel (Standard) Inspected Instance Sub-Basement - Room SB1 Instance Condition 3 - Fair Instance Quantity 1 Instance Quantity Uom EACH Instance Manufacturer Edwards Equipment Fire Alarm Installation Year 1954 Source of Installation Documented Deficiency No deficiencies recorded Sub-Panel Inspected Bell At Panel Inspected Condition 1 - Good Deficiency No deficiencies recorded Fire Alarm Control Panel (Electronic) Inspected Instance Sub-Basement - Room SB1 Instance Condition 2 - Between Good and Fair Instance Quantity Uom EACH Instance Wanufacturer Edwards Equipment Fire Alarm Control Panel Equipment Fire Alarm Control Panel Equipment Fire Alarm Control Panel <
Fire Alarm Control Panel (Blandard) Inspected Instance Sub-Basement - Room SB1 Instance Condition 3 - Fair Instance Quantity 1 Instance Quantity Uom EACH Instance Manufacturer Edwards Equipment Fire Alarm Installation Year 1954 Source of Installation Documented Deficiency No deficiencies recorded Sub-Panel Inspected Condition 1 - Good Deficiency No deficiencies recorded Fire Alarm Control Panel (Electronic) Inspected Instance Oundition 2 - Between Good and Fair Instance Condition 2 - Between Good and Fair Instance Quantity Uom EACH Instance Quantity Uom EACH Instance Manufacturer Edwards Equipment Fire Alarm Control Panel Model EST 3 Installation Year 2023 Installation Year 2023 Installation Year 2023 Source of Installation
Instance
Instance Condition 3 - Fair Instance Quantity 1 Instance Quantity 1 Instance Quantity Win EACH Instance Manufacturer Edwards Equipment Fire Alarm Installation Year 1954 Source of Installation Documented Deficiency No deficiencies recorded Sub-Panel Inspected Bell At Panel Inspected Condition 1 - Good Deficiency No deficiencies recorded Fire Alarm Control Panel (Electronic) Inspected Inspected Instance Sub-Basement - Room SB1 Instance Condition 2 - Between Good and Fair Instance Quantity 1 Instance Quantity 1 Instance Quantity Equipment Edwards Equipment Edwards Equipment Fire Alarm Control Panel Est's 3 Instance Manufacturer Edwards Source of Installation Custodial Staff Deficiency PANEL DEFECTIVE Deficiency PANEL DEFECTIVE Deficiency Quantity 1 Quantity Und EACH Potential Action REPAIR Urgency of Action REPAIR
Instance Condition 3 - Fair Instance Quantity Uom EACH Instance Quantity Uom EACH Instance Manufacturer Edwards Equipment Fire Alarm Installation Year 1954 Source of Installation Documented Deficiency No deficiencies recorded Sub-Panel Inspected Bell At Panel Inspected Condition 1 - Good Deficiency No deficiencies recorded Fire Alarm Control Panel (Electronic) Inspected Inspected Instance Sub-Basement - Room SB1 Instance Quantity Uom EACH Instance Quantity I Instance Quantity I Instance Quantity Uom EACH Instance Good EST 3 Instance Model EST 3 Installation Year 2023 Source of Installation Custodial Staff Deficiency PANEL DEFECTIVE Deficiency PANEL DEFECTIVE Deficiency PRIORITY 5
Instance Quantity Uom EACH Instance Quantity Uom EACH Instance Manufacturer Edwards Equipment Fire Alarm Installation Year 1954 Source of Installation Decliciency No deficiencies recorded Sub-Panel Inspected Bell At Panel Inspected Condition 1-Good Deficiency No deficiencies recorded Fire Alarm Control Panel (Electronic) Inspected Inspected Fire Alarm Control Panel (Electronic) Inspected Instance Sub-Basement - Room SB1 Instance Condition 2-Between Good and Fair Instance Quantity Instance Quantity Instance Quantity EACH Instance Quantity EACH Instance Quantity Om EACH Instance Manufacturer Edwards Equipment Fire Alarm Control Panel Model EST 3 Source of Installation Custodial Staff Deficiency PANEL DEFECTIVE Deficiency Quantity Instance Quantity Installation Custodial Staff Potential Action REPAIR Urgency of Action PRIORITY 5
Instance Quantity Uom Edwards Equipment Fire Alarm Installation Year 1954 Source of Installation Deficiency No deficiencies recorded Sub-Panel Inspected Bell At Panel Inspected Condition 1 - Good Deficiency No deficiencies recorded Fire Alarm Control Panel (Electronic) Inspected Inspected Inspected Fire Alarm Control Panel (Electronic) Inspected Instance Quantity Instance Quantity Instance Quantity Uom EACH Instance Model EST 3 Source of Installation Custodial Staff Deficiency PANEL DEFECTIVE Deficiency PANEL DEFECTIVE Deficiency PANEL DEFECTIVE Deficiency PRIORITY 5
Instance Manufacturer
Equipment Fire Alarm Installation Year 1954 Source of Installation Documented Deficiency No deficiencies recorded Sub-Panel Inspected Bell At Panel Inspected Condition 1- Good Deficiency No deficiencies recorded Fire Alarm Control Panel (Electronic) Inspected Instance Sub-Basement - Room SB1 Instance Condition 2- Between Good and Fair Instance Quantity Instance Quantity Uom EACH Instance Manufacturer Edwards Equipment Fire Alarm Control Panel Model EST 3 Installation Year 2023 Source of Installation Custodial Staff Deficiency PANEL DEFECTIVE Deficiency Quantity In EACH Quantity Uom EACH Potential Action REPAIR Potential Action REPAIR
Installation Year 1954 Source of Installation Documented Deficiency No deficiencies recorded Sub-Panel Inspected Inspected Condition 1 - Good Deficiency No deficiencies recorded Price Alarm Control Panel (Electronic) Inspected Instance Instance Instance Condition 2 - Between Good and Fair Instance Quantity I Instance Quantity Uom EACH Instance Manufacturer Edwards Equipment Fire Alarm Control Panel Model EST 3 Installation Year 2023 Source of Installation Custodial Staff Deficiency PANEL DEFECTIVE Deficiency Quantity 1 Quantity Uom EACH Deficiency PANEL DEFECTIVE Deficiency PANEL DEFECTIVE Deficiency PANEL DEFECTIVE Potential Action REPAIR Potential Action REPAIR Urgency of Action PRIORITY 5
Source of Installation Documented Deficiency No deficiencies recorded Sub-Panel Inspected Bell At Panel Inspected Condition 1 - Good Deficiency No deficiencies recorded Fire Alarm Control Panel (Electronic) Inspected Instance Sub-Basement - Room SB1 Instance Condition 2 - Between Good and Fair Instance Quantity 1 Instance Quantity Uom EACH Instance Manufacturer Edwards Equipment Fire Alarm Control Panel Model EST 3 Installation Year 2023 Source of Installation Custodial Staff Deficiency PANEL DEFECTIVE Deficiency Quantity I Quantity Uom EACH Potential Action REPAIR Urgency of Action PRIORITY 5
Deficiency Sub-Panel Inspected Inspected Deficiency No deficiencies recorded Condition 1 - Good Deficiency No deficiencies recorded Fire Alarm Control Panel (Electronic) Instance Instance Condition 2 - Between Good and Fair Instance Quantity 1 Instance Quantity Uom EACH Instance Anunfacturer Edwards Equipment Fire Alarm Control Panel Extra Sub-Basement - Room SB1 Instance Quantity Uom EACH Instance Quantity Uom EACH Instance Anunfacturer Edwards Equipment Fire Alarm Control Panel EST 3 Installation Year 2023 Source of Installation Custodial Staff Deficiency PANEL DEFECTIVE Deficiency Quantity I Quantity Uom EACH Potential Action REPAIR Urgency of Action
Sub-Panel Inspected Bell At Panel Inspected Condition 1 - Good Deficiency No deficiencies recorded Fire Alarm Control Panel (Electronic) Inspected Instance Sub-Basement - Room SB1 Instance Condition 2 - Between Good and Fair Instance Quantity 1 Instance Quantity Uom EACH Instance Manufacturer Edwards Equipment Fire Alarm Control Panel Model EST 3 Installation Year 2023 Source of Installation Custodial Staff Deficiency PANEL DEFECTIVE Deficiency Quantity 1 Quantity Uom EACH Potential Action REPAIR Urgency of Action PRIORITY 5
Bell At Panel Condition Deficiency No deficiencies recorded Fire Alarm Control Panel (Electronic) Inspected Instance Sub-Basement - Room SB1 Instance Quantity Instance Quantity Instance Quantity Instance Quantity Instance Quantity Equipment Equipment Model EST 3 Installation Year Source of Installation Deficiency Deficiency Quantity I Custodial Staff Deficiency Quantity I Quantity Uom EACH EACH EACH EACH EST 3 Installation Custodial Staff Deficiency PANEL DEFECTIVE Deficiency Quantity I Quantity Uom EACH Potential Action REPAIR Urgency of Action
Condition 1 - Good Deficiency No deficiencies recorded Fire Alarm Control Panel (Electronic) Inspected Instance Sub-Basement - Room SB1 Instance Condition 2 - Between Good and Fair Instance Quantity Instance Quantity Uom EACH Instance Manufacturer Edwards Equipment Fire Alarm Control Panel Model EST 3 Installation Year 2023 Source of Installation Custodial Staff Deficiency PANEL DEFECTIVE Deficiency Quantity Instance Quantity Uom EACH Potential Action REPAIR Urgency of Action PRIORITY 5
Deficiency Fire Alarm Control Panel (Electronic) Instance Instance Condition Instance Quantity Instance Quantity Uom EACH Instance Manufacturer Equipment Model EST 3 Installation Year Source of Installation Deficiency Deficiency Deficiency Deficiency Quantity Uom EACH EACH EACH EACH EST 3 Installation Custodial Staff Deficiency Deficiency Deficiency Deficiency Deficiency Deficiency Quantity Deficiency
Fire Alarm Control Panel (Electronic) Instance Instance Condition 2 - Between Good and Fair Instance Quantity Instance Quantity Uom EACH Instance Manufacturer Edwards Equipment Model EST 3 Installation Year Source of Installation Deficiency Deficiency Quantity Quantity Uom EACH EACH EACH EACH EACH EACH EACH EST 3 Custodial Staff Deficiency PANEL DEFECTIVE Deficiency Quantity 1 Quantity Uom EACH EACH Potential Action REPAIR Urgency of Action
Instance Condition 2 - Between Good and Fair Instance Quantity 1 Instance Quantity Uom EACH Instance Manufacturer Edwards Equipment Fire Alarm Control Panel Model EST 3 Installation Year 2023 Source of Installation Custodial Staff Deficiency PANEL DEFECTIVE Deficiency Quantity 1 Quantity Uom EACH Potential Action REPAIR Urgency of Action PRIORITY 5
Instance Condition 2 - Between Good and Fair Instance Quantity Instance Quantity Uom EACH Instance Manufacturer Edwards Equipment Model EST 3 Installation Year 2023 Source of Installation Custodial Staff Deficiency PANEL DEFECTIVE Deficiency Quantity Quantity Uom EACH Potential Action Urgency of Action PRIORITY 5
Instance Quantity Uom EACH Instance Manufacturer Edwards Equipment Fire Alarm Control Panel Model EST 3 Installation Year 2023 Source of Installation Custodial Staff Deficiency PANEL DEFECTIVE Deficiency Quantity Uom EACH Potential Action REPAIR Urgency of Action PRIORITY 5
Instance Quantity Uom Instance Manufacturer Edwards Equipment Fire Alarm Control Panel Model EST 3 Installation Year 2023 Source of Installation Custodial Staff Deficiency PANEL DEFECTIVE Deficiency Quantity Quantity Uom EACH Potential Action REPAIR Urgency of Action Edwards Edwards Edwards Edwards Edwards Edwards Edwards Edwards Each EST 3 10 2023 2023 EACH PANEL DEFECTIVE PANEL DEFECTIVE PRIORITY 5
Instance Manufacturer Equipment Fire Alarm Control Panel Model EST 3 Installation Year 2023 Source of Installation Custodial Staff Deficiency PANEL DEFECTIVE Deficiency Quantity I Quantity Uom EACH Potential Action REPAIR Urgency of Action PRIORITY 5
Equipment Fire Alarm Control Panel Model EST 3 Installation Year 2023 Source of Installation Custodial Staff Deficiency PANEL DEFECTIVE Deficiency Quantity 1 Quantity Uom EACH Potential Action REPAIR Urgency of Action PRIORITY 5
Model EST 3 Installation Year 2023 Source of Installation Custodial Staff Deficiency PANEL DEFECTIVE Deficiency Quantity 1 Quantity Uom EACH Potential Action REPAIR Urgency of Action PRIORITY 5
Installation Year 2023 Source of Installation Custodial Staff Deficiency PANEL DEFECTIVE Deficiency Quantity 1 Quantity Uom EACH Potential Action REPAIR Urgency of Action PRIORITY 5
Source of Installation Custodial Staff Deficiency PANEL DEFECTIVE Deficiency Quantity 1 Quantity Uom EACH Potential Action REPAIR Urgency of Action PRIORITY 5
Deficiency Deficiency Quantity 1 Quantity Uom EACH Potential Action REPAIR Urgency of Action PANEL DEFECTIVE 1 REPAIR PRIORITY 5
Deficiency Quantity 1 Quantity Uom EACH Potential Action REPAIR Urgency of Action PRIORITY 5
Quantity UomEACHPotential ActionREPAIRUrgency of ActionPRIORITY 5
Potential Action REPAIR Urgency of Action PRIORITY 5
Urgency of Action PRIORITY 5
Purpose of Action
Deficiency Photo 1 No photo recorded
Violations No violations recorded.
Fire Alarm Control Panel (Standard) Inspected
Instance Sub-Basement - Room SB1
Instance Condition 3 - Fair
Instance Quantity 1
Instance Quantity Uom EACH
Instance Manufacturer Edwards
Equipment Fire Alarm
Installation Year 1954
Source of Installation Documented
Deficiency No deficiencies recorded
Instance Sub-Basement - Room SB1
Instance Condition 4 - Between Fair and Poor
Instance Quantity 1

Building Condition Assessment Survey 2023 - 2024

nestion	Response
FIRE ALARM SYSTEM	
Sub-Panel	
Fire Alarm Control Panel (Standard)	F.L.CV
Instance Quantity Uom	EACH
Instance Manufacturer	Edwards
Equipment	Sprinkler Alarm
Installation Year	1954
Source of Installation	Documented
Deficiency	PANEL DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Remote Annunciator	Inspected
Display Monitor	Does not Exist
Panel	Does not Exist
Printer	Does not Exist
Punch Register	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Tamper Flow Switch/Chain	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
NTERCOM SYSTEM	Inspected
Elevator	Inspected
Condition	3 - Fair
Deficiency	NOT CONNECTED TO REMOTE MONITORING STATION
Deficiency Location/Instance	Elevator - Device ID: 4P114
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL CONNECTION
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Holding Area	Does not Exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded

Building Condition Assessment Survey 2023 - 2024

nestion	Response
LAN	Inspected
Main Equipment Rack (MDF)	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not Exist
MOTOR CONTROLLER	Inspected
Motor Control Center	Inspected
Instance	Basement - Room 013
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Westinghouse
Equipment	N/A
Capacity/Size Quantity	100
Capacity/Size UOM	Amps
Capacity/Size2 Quantity	2
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Inspector Estimate
Installation Year	1956
Source of Installation	Documented
Deficiency	No deficiencies recorded
Motor Starter/Contactor	Inspected
Condition	3 - Fair
Deficiency	MOTOR STARTER PUSH BUTTON NOT OPERATIONAL
Deficiency Location/Instance	Boiler Room - Mechanical Room (Lunch Room Blower)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Variable Frequency Drive	Does not Exist
ANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Inspected
Condition	3 - Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
	EACH
Quantity Uom Potential Action	REPLACE-UPGRADE
	PRIORITY 1
Urgency of Action	I KIUKII I I
Urgency of Action	LEVEL 2
Purpose of Action	LEVEL 2
	LEVEL 2 No photo recorded No violations recorded.

Building Condition Assessment Survey 2023 - 2024

stion	Response
ANEL BOARD	
Fused Toggle Switch Type	
Condition	3 - Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Auditorium (Backstage Cage), Cafeteria - West
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Molded Case Circuit Breaker Type	Inspected
Condition	3 - Fair
Deficiency	PANEL BOARD COVER IS MISSING
Deficiency Location/Instance	Sub-Basement Fan Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL BOARD COVER IS MISSING
Deficiency Location/Instance	Gymnasium - 2nd Floor, Room 013, Basement Corridor by Room 01 1st Floor Corridor by Room 118, 3rd Floor Corridor by Room 319, 4 Floor Corridor by Room 412
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL BOARD DOOR LOCK IS MISSING
Deficiency Location/Instance	1st Floor Corridor by Room 108, 3rd Floor Corridor by Room 310, 4 Floor Corridor by Room 406
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	NO SPARE
Deficiency Location/Instance	Elevator Machine Room, Fan Room - Stair F, kitchen
Deficiency Quantity	3
Quantity Uom	EACH
	REPLACE PANEL BOARD
Potential Action	

Building Condition Assessment Survey 2023 - 2024

Question	Response
PANEL BOARD	
Molded Case Circuit Breaker Type	
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL BOARD DOOR LOCK IS MISSING
Deficiency Location/Instance	Boiler Room, Sub-Basement Fan Room
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	NO SPARE
Deficiency Location/Instance	Electrical Room SB8
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL NEW PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Auditorium (Backstage Cage), Boiler Room, Sub-Basement Fan Room, Gymnasium - 2nd Floor, Rooms (013, 413), Basement Corridor by Rooms (001, 013), 1st Floor Corridor by Rooms (106, 108, 118), 2nd Floor Corridor by Rooms (206, 210, 219), 3rd Floor Corridor by Rooms (304, 310, 319), 4th Floor Corridor by Rooms (406, 412)
Deficiency Quantity	23
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
PUBLIC ADDRESS SYSTEM	Inspected
Replacement Quantity	136,000
Replacement Uom	S.F.
Instance	Room 113A
Instance Condition	1 - Good
Instance Quantity	1
Instance Quantity Uom	EACH
Model	N/A
Installation Year	2023
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded
SECURITY	Inspected
IPDVS/CCTV System	Does not Exist
Intrusion Alarm System	Inspected
and usion marin system	шърсеси

Building Condition Assessment Survey 2023 - 2024

estion	Response	
SECURITY		
Intrusion Alarm System		
Replacement Quantity	136,000	
Replacement Uom	S.F.	
Central Control Panel	Inspected	
Instance	Room 113A	
Instance Condition	2 - Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Model	N/A	
Installation Year	2013	
Source of Installation	Inspector Estimate	
Deficiency	No deficiencies recorded	
Infrared Sensor	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Panic Switch	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Remote Annunciator	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Siren/Strobe	Inspected	
Condition	3 - Fair	
Deficiency V. I. C	No deficiencies recorded	
Lighting - Security	Inspected	
Replacement Uom Condition	EACH	
	3 - Fair	
Deficiency	TIME CLOCK NOT OPERATIONAL	
Deficiency Location/Instance	Electrical Room SB8	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 2	
Purpose of Action	LEVEL 3	
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
ERVICE SWITCH	Inspected	
Instance	Electrical Room SB8	
Instance Condition	3 - Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Instance Manufacturer	Siemens	
Equipment	Service Disconnect	
Capacity/Size Quantity	1,600	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	2002	
Source of Installation	Documented	

Building Condition Assessment Survey 2023 - 2024

Question	in pectron	Response
SERVICI	E SWITCH	-
	Deficiency	No deficiencies recorded
	Instance	Electrical Room SB9
	Instance Condition	3 - Fair
	Instance Quantity	1
	Instance Quantity Uom	EACH
	Instance Manufacturer	Westinghouse
	Equipment	N/A
	Capacity/Size Quantity	1,600
	Capacity/Size UOM	Amps
	Source of Capacity/Size	Inspector Estimate
	Installation Year	1954
	Source of Installation	Documented
	Deficiency	No deficiencies recorded
	Instance	Electrical Room SB9
	Instance Condition	3 - Fair
	Instance Quantity	1
	Instance Quantity Uom	EACH
	Instance Manufacturer	Westinghouse
	Equipment	N/A
	Capacity/Size Quantity	1,600
	Capacity/Size UOM	Amps
	Source of Capacity/Size	Inspector Estimate
	Installation Year	1954
	Source of Installation	Documented
	Deficiency	No deficiencies recorded
	Instance	Electrical Room SB9
	Instance Condition	3 - Fair
	Instance Quantity	1
	Instance Quantity Uom	EACH
	Instance Manufacturer	Westinghouse
	Equipment	Safety Switch
	Capacity/Size Quantity	400
	Capacity/Size UOM	Amps
	Source of Capacity/Size	Nameplate
	Installation Year	1954
	Source of Installation	Documented
	Deficiency	No deficiencies recorded
	Instance	Electrical Room SB9
	Instance Condition	3 - Fair
	Instance Quantity	1
	Instance Quantity Uom	EACH
	Instance Manufacturer	Westinghouse
	Equipment	Safety Switch
	Capacity/Size Quantity	400
	Capacity/Size UOM	Amps
	Source of Capacity/Size	Nameplate
	Installation Year	1954
	Source of Installation	Documented

Building Condition Assessment Survey 2023 - 2024

Electrical Inspection		Q450
Question	Response	

uestion	Response	
SERVICE SWITCH	Inspected	
Deficiency	No deficiencies recorded	
SWITCHBOARD	Inspected	
Number of Spares	1	
Fused Disconnect Switch Type	Inspected	
Instance	Electrical Room SB8	
Instance Condition	3 - Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Instance Manufacturer	Siemens	
Equipment	Switchboard MDB Section A, B	
Capacity/Size Quantity	1,600	
Capacity/Size UOM	Amps Total	
Capacity/Size2 Quantity	2	
Capacity/Size2 UOM	Section(S)	
Source of Capacity/Size	Nameplate	
Installation Year	2002	
Source of Installation	Documented	
Deficiency	No deficiencies recorded	
Fused Knife Switch Type	Does not Exist	
Molded Case Circuit Breaker Type	Inspected	
Instance	Electrical Room SB8	
Instance Condition	3 - Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Instance Manufacturer	Westinghouse	
Equipment	Service A	
Capacity/Size Quantity	1,600	
Capacity/Size UOM	Amps Total	
Capacity/Size2 Quantity	1	
Capacity/Size2 UOM	Section(S)	
Source of Capacity/Size	Nameplate	
Installation Year	1954	
Source of Installation	Documented	
Deficiency	No deficiencies recorded	
Instance	Electrical Room SB8	
Instance Condition	3 - Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Instance Manufacturer	Westinghouse	
Equipment	Service B	
Capacity/Size Quantity	1,600	
Capacity/Size UOM	Amps Total	
Capacity/Size2 Quantity	1	
Capacity/Size2 Quantity Capacity/Size2 UOM	Section(S)	
Source of Capacity/Size Installation Year	Nameplate 1954	
Source of Installation	Documented No. deficiencies recorded.	
Deficiency	No deficiencies recorded	

Building Condition Assessment Survey 2023 - 2024

uestion	Response
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
TRANSFORMER	Does not Exist