

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Architectural Inspection

Q452

Asset: LONG ISLAND CITY HS (NEW) - Q, 14-30 BROADWAY, New York, 11101

Inspection Id	Inspection Type	Time In	Last Edited
SA : Q452	Architectural - Senior	2024-05-07 7:57 AM	2024-06-17 10:13 AM
AA : Q452	Architectural - Associate	2024-05-07 8:24 AM	2024-06-03 8:14 AM

Asset Data

Question	Answer
Was the building fully accessible for inspection	No
Inspection Access Comment	Dunnage (Scaffolding, Netting), 2nd Floor Gymnasium (Testing), Playground (Scaffolding), Fences (Scaffolding), 2nd and 4th Floor Girls Shower Room (No key), Security Lights (Scaffolding)
Building Square Footage	380,000
Comments on the Area (for Athletic Field, Playing Surfaces, Leased Spaces)	None
Comments on the Stories (Floors) plus Basements	6+B+PH
Comments on the Number of Classrooms	108
Comments on the Year Built	1995
Student Population	1,981
Staff Population	278
Weather	Fair
Principal(s) Information	
Principal Name	Vivian Selenikas
Organization	Long Island City High School - Queens
Did you meet with this Principal?	No
Did this Principal provide feedback?	Yes
Summary of Principal's Feedback	Assistant Principal Jason Mudd commented on behalf of the Principal as follows: The elevators break down frequently.
Principal Name	Corey Prober
Organization	Coop Tech - Queens
Did you meet with this Principal?	No
Did this Principal provide feedback?	No
Principal Name	Jonathan Longshein
Organization	P993Q - District 75 - Queens
Did you meet with this Principal?	No
Did this Principal provide feedback?	Yes
Summary of Principal's Feedback	Assistant Principal Gina Raffi-Naporno spoke on behalf of the Principal and had no comments regarding the physical condition of the building at this time.
Principal Name	Jodi Kaltner
Organization	L.Y.F.E. Center - Queens
Did you meet with this Principal?	No
Did this Principal provide feedback?	No
Custodian	Ernesto Diaz
Fireman	Edward Jones

Facade Photo



Broadway - Southwest view

Main Entrance Photo



Facade A - Broadway

Roof Photo



Roof 1 - Northeast view



NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Architectural Inspection

Q452

Have any Systems/Major Building Components been upgraded?	Yes
	Systems: Coping, Exterior Walls, Exterior Soffits, Parapets, Roof Hatches/ Smoke Hatches, Leaders/Gutters/Downspouts/Scuppers, Roof Barriers, Roof Fences, Roofing, Roof Drains, Window Lintels
	Year: Under Construction
	Systems: Stairs/Ramps - limited (Main Entrance) repairs
	Year: 2018
	Systems: Parapet - repairs
	Year: 2008
Have there been any Building Additions?	No
Tandem Schools?	No
Leased Space?	No

Priority Condition

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	PhotoImage
No	Potential Falling Debris	Loose ceiling tile is a potential falling debris hazard.	INTERIOR KITCHEN Ceiling	Room Entrance From the Cafeteria	Edward Jones	Fireman	
No	Tripping Hazard	Seats Metal Base is a tripping hazard condition	Locker Room 2nd Floor -Girls	Near Locker 70	Edward Jones	Fireman	

Structural Engineer Required

Structural Condition Type	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	PhotoImage
No condition recorded						

Programmatic Accessibility

Programmatic Accessibility Status Question	Response
Is the primary or secondary entrance on an accessible route?	Yes
Is the building a multi-story building?	Yes
Are all floors of the building accessible through compliant means?	Yes
Accessible classrooms exists on each floor?	Yes
Boys and Girls or Unisex accessible toilets exist on at least every other floor?	Yes
If the following spaces exist, are they ALL accessible? Art Room, Auditorium, Cafeteria, Computer, Gymnasiums, Library, Multipurpose Room, Science Labs	Yes

Physical Breakdown Structure	Exists	Required	Complies	Deficiency	Assistive Fire Listening Alarm System	Fire Strobe
------------------------------	--------	----------	----------	------------	---------------------------------------	-------------

PROGRAMMATIC ACCESSIBILITY

Exterior Routes						
Exterior Entrances & Exits					Yes	
Exterior H/C Lifts			No	No		
Exterior Ramps and Railings			Yes		Yes	
Interior Routes						


NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Architectural Inspection

Q452

Physical Breakdown Structure	Exists	Required	Complies	Deficiency	Assistive Listening System	Fire Alarm Strobe
Interior Routes						
Corridor and Lobby H/C Lifts	No	No				
Interior Corridor Doors and Hardware	Yes		Yes			
Interior Corridors and Lobbies			Yes			
Interior Elevators	Yes		Yes			
Interior Lobby Doors and Hardware			Yes			
Interior Ramps	Yes		Yes			
Rooms & Spaces						
Art Rooms	Rooms 613, 617, 618	Yes	Yes			
Auditorium	1st Floor	Yes	Yes		FM System	Yes
Cafeteria	6th Floor	Yes	Yes		FM System	Yes
Classrooms	1st-6th Floor	Yes	Yes			
Computer Rooms	Rooms 201, 382, 384, 430, 494, 525, 594	Yes	Yes			
Gymnasium	2nd Floor, 4th Floor	Yes	Yes		FM System	Yes
Library	Room 446	Yes	Yes			
Main Office	Room 101 (Coop Tech), Room 121 (Long Island City High School), Room 160 (L.Y.F.E. Center), Room 462 (P993Q - District 75)	Yes	Yes			
Multi-purpose Room		No				
Nurse's Room	Rooms 546, 463	Yes	Yes			
Pool	1st Floor	Yes	Yes			
Science Lab	Rooms 608, 668, 680	Yes	Yes			
Toilet Rooms (Boys)	1st-6th Floor	Yes	Yes			
Toilet Rooms (Girls)	1st-6th Floor	Yes	Yes			
Toilet Rooms (Staff)	1st-6th Floor	Yes	Yes			

Building Template



**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q452

Inspection

Question	Response
----------	----------

Architectural

EXTERIOR

Inspected

AREAWAY

Inspected

Instance on AW1

Inspected

Instance Condition

3 - Fair

Instance Quantity

1


Instance Quantity Uom

EACH

Deficiency

AREAWAY WALLS: CRACKS AND SPALLING

Roof Plan reference



Deficiency Quantity

30

Quantity Uom

S.F.

Potential Action

REPAIR

Urgency of Action

PRIORITY 3

Purpose of Action

LEVEL 2

Deficiency Photo1



Facade E - AW1

Violations

No violations recorded.

AWNINGS AND CANOPIES

Does not Exist

CHIMNEY

Inspected

Material Type(s)

Metal


Condition

3 - Fair

Deficiency

METAL: DENTS, MAJOR RUSTING

Roof Plan reference



**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q452

Question	Response
----------	----------

EXTERIOR

CHIMNEY

Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 2
Deficiency Photo1	



Roof 1 - Chimney 1

Violations No violations recorded.

COPING Under Construction

CORNICE Does not Exist


DOORS Inspected

DOORS AND FRAMES Inspected

Condition 5 - Poor

Deficiency METAL: DETERIORATED DOOR AND FRAME - MINOR DETERIORATION

Roof Plan reference





Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.

Deficiency METAL: DETERIORATED DOOR AND FRAME - MAJOR DETERIORATION

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q452

Question	Response
EXTERIOR	
DOORS	
DOORS AND FRAMES	
Roof Plan reference	
Deficiency Quantity	10
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Facade A No violations recorded.
DOOR HARDWARE	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
LINTELS	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
TRANSOM/SIDE LIGHT	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
EXTERIOR WALLS	Inspected
Material Type(s)	Masonry
Replacement Quantity	115,000
Replacement Uom	S.F.
Instance on All Facades	Under Construction
Instance Quantity	115,000
Instance Quantity Uom	S.F.
EXTERIOR SOFFITS	Under Construction
LOADING DOCK	Inspected
Condition	5 - Poor
Deficiency	BAD BUMPERS

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q452


Question

Response

EXTERIOR

LOADING DOCK

Roof Plan reference



Deficiency Quantity
Quantity Uom
Potential Action
Urgency of Action
Purpose of Action
Deficiency Photo1

4
EACH
REPLACE
PRIORITY 4
LEVEL 2



Facade F


No violations recorded.

Violations

Deficiency

DETERIORATED CONCRETE PLATFORM WITH CRACKED, SPALLED CONCRETE OR EXPOSED REINFORCING

Roof Plan reference




Deficiency Quantity
Quantity Uom
Potential Action
Urgency of Action
Purpose of Action

10
S.F.
REPAIR
PRIORITY 3
LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q452

Question	Response
EXTERIOR	
LOADING DOCK	
Deficiency Photo1	
Violations	Facade F No violations recorded.
LOUVER	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
PARAPETS	Inspected
Material Type(s)	Masonry
Replacement Quantity	12,000
Replacement Uom	C.F.
Instance on All Facades	Under Construction
Instance Quantity	12,000
Instance Quantity Uom	C.F.
PLAZA DECK	Does not Exist
ROOF	Inspected
Roofing	Inspected
Replacement Quantity	62,000
Replacement Uom	S.F.
ROOF HATCH/SMOKE HATCH	Under Construction
LEADERS, GUTTERS, DOWNSPOUTS, SCUPPERS	Under Construction
ROOF BARRIER/FENCE	Under Construction
ROOF CAGE	Does not Exist
ROOFING	Inspected
Instance on Modified Bitumen: All Roofs	Under Construction
Instance Quantity	62,000
Instance Quantity Uom	S.F.
ROOFING DRAINS	Under Construction
Specialties	Inspected
BULKHEAD/PENTHOUSE	Inspected
Condition	3 - Fair
Deficiency	BULKHEAD/PENTHOUSE WALLS/EXTERIOR: EFFLORESCENCE

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q452

Question	Response
----------	----------


EXTERIOR

ROOF

Specialties

BULKHEAD/PENTHOUSE

Roof Plan reference



Deficiency Quantity
Quantity Uom
Potential Action
Urgency of Action
Purpose of Action
Deficiency Photo
Violations

30
S.F.
MAINTENANCE
PRIORITY 1
LEVEL 1
No photo recorded
No violations recorded.

CUPOLA/ SPIRES/ TOWERS

Does not Exist

DORMER

Does not Exist

DUNNAGE STEEL

Inaccessible

SKYLIGHT/ROOF VENT

Does not Exist

ROOF/GRAVITY TANK

Does not Exist

STAIRS/RAMPS: EXTERIOR

Inspected

BUILDING CHEEK/FLANK WALLS

Inspected


Condition

2 - Between Good and Fair

Deficiency

CAST IN PLACE CONCRETE: CRACKS/SPALLING - MINOR

Roof Plan reference



Deficiency Quantity
Quantity Uom
Potential Action
Urgency of Action
Purpose of Action

10
S.F.
REPAIR
PRIORITY 3
LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q452

Question	Response
----------	----------

EXTERIOR

STAIRS/RAMPS: EXTERIOR

BUILDING CHEEK/FLANK WALLS

Deficiency Photo1



Facade F

No violations recorded.

Violations

RAILINGS

Inspected


Condition

3 - Fair

Deficiency

DAMAGED

Roof Plan reference



Deficiency Quantity

10

Quantity Uom

L.F.

Potential Action

REPLACE

Urgency of Action

PRIORITY 4

Purpose of Action

LEVEL 2

Deficiency Photo1



Facade F

No violations recorded.

Violations

STAIRS/RAMPS

Inspected

Condition

3 - Fair

Deficiency

CONCRETE: CRACKS/SPALLING - MINOR

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q452

Question


Response

EXTERIOR

STAIRS/RAMPS: EXTERIOR


STAIRS/RAMPS

Roof Plan reference



Deficiency Quantity
Quantity Uom
Potential Action
Urgency of Action
Purpose of Action
Deficiency Photo1

30
S.F.
REPAIR
PRIORITY 3
LEVEL 2



Facade F


No violations recorded.

Violations

Violations

Deficiency
Roof Plan reference

CONCRETE: CRACKS/SPALLING - MAJOR




Deficiency Quantity
Quantity Uom
Potential Action
Urgency of Action
Purpose of Action

10
S.F.
REPLACE
PRIORITY 4
LEVEL 2

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Architectural Inspection

Q452

Question	Response
EXTERIOR	
STAIRS/RAMPS: EXTERIOR	
STAIRS/RAMPS	
Deficiency Photo1	
Violations	Facade F No violations recorded.
WINDOWS	Inspected
Replacement Quantity	15,500
Replacement Uom	S.F.
EXTERIOR GUARDS	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
LINTELS	Under Construction
WINDOWS	Inspected
Material Type(s)	Aluminum
Instance on Aluminum - Double Hung: All Facades	Inspected
Instance Condition	3 - Fair
Instance Quantity	15,000
Instance Quantity Uom	S.F.
Are these windows insulated	No
Installation Year	1995
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded
Instance on Aluminum - Other: Facades E, F	Inspected
Instance Condition	3 - Fair
Instance Quantity	500
Instance Quantity Uom	S.F.
Are these windows insulated	No
Installation Year	1995
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded
INTERIOR	Inspected
POOLS	Inspected
Instance on 1st Floor	Inspected
CEILING	
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	ACOUSTIC TILE: MISSING/WATER DAMAGED/BROKEN TILES
Deficiency Location/Instance	1st Floor
Deficiency Quantity	10
Quantity Uom	S.F.

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q452

Question	Response
----------	----------

INTERIOR

POOLS

CEILING

Potential Action	REPLACE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 2
Deficiency Photo1	



1st Floor

Violations	No violations recorded.
------------	-------------------------

DECK/FLOOR

Instance on 1st Floor	Inspected
Condition	4 - Between Fair and Poor

Deficiency	CONCRETE: CRACKS/SPALLING
Deficiency Location/Instance	1st Floor
Deficiency Quantity	30
Quantity Uom	S.F.
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	



1st Floor



Violations	No violations recorded.
------------	-------------------------

Deficiency	CERAMIC TILES: BROKEN/MISSING/WORN TILES
Deficiency Location/Instance	1st Floor
Deficiency Quantity	100
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q452

Question	Response
INTERIOR	
POOLS	
DECK/FLOOR	
Deficiency Photo1	
Violations	1st Floor No violations recorded.
DIVING BOARD/PLATFORM	
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
POOL LINING	
Instance on 1st Floor	Inspected
Condition	4 - Between Fair and Poor
Deficiency	TILE: BROKEN/MISSING/WORN TILES
Deficiency Location/Instance	1st Floor
Deficiency Quantity	100
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	1st Floor No violations recorded.
POOL STRUCTURE	
Instance on 1st Floor	Inspected
Condition	4 - Between Fair and Poor
Deficiency	FOUNDATION WALLS: WATER INFILTRATION
Deficiency Location/Instance	Basement - Pool Mechanical Equipment Room
Deficiency Quantity	100
Quantity Uom	S.F.
Potential Action	INSTALL WATERPROOFING
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 5

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection



Q452

Question	Response
INTERIOR	
POOLS	
POOL STRUCTURE	
Deficiency Photo1	
Violations	Basement - Pool Mechanical Equipment Room No violations recorded.
SEATING	
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
WALLS	
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	CERAMIC TILES: DETERIORATED GROUTING
Deficiency Location/Instance	1st Floor
Deficiency Quantity	30
Quantity Uom	S.F.
Potential Action	REGROUT
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	1st Floor No violations recorded.
STRUCTURAL	
COLUMNS/BEAMS/BEARING WALLS	
Condition	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
FLOOR STRUCTURE	
Condition	Inspected
Condition	5 - Poor
Deficiency	CONCRETE SLAB ON GRADE: THRU CRACKS
Deficiency Location/Instance	Basement - Corridor
Deficiency Quantity	50
Quantity Uom	S.F.
Potential Action	REPAIR

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q452

Question	Response
INTERIOR	
STRUCTURAL	
FLOOR STRUCTURE	
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 5
Deficiency Photo1	
	Basement - Corridor
Violations	No violations recorded.
Deficiency	CONCRETE SLAB ON GRADE: WATER INFILTRATION IN NON-INSTRUCTIONAL SPACE
Deficiency Location/Instance	Basement - near Freight Elevator and Staircase C, Fire Pump Room, Acid Tank Area, Pool Mechanical Equipment Room, Shop, Water Meter Room, Electrical Panel Room
Deficiency Quantity	700
Quantity Uom	S.F.
Potential Action	INSTALL WATERPROOFING
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 5
Deficiency Photo1	
	Basement - near Freight Elevator and Staircase C
Violations	35467696Y
FOUNDATION WALLS	
	Inspected
Material Type(s)	Concrete
Condition	4 - Between Fair and Poor
Deficiency	CONCRETE: WATER INFILTRATION IN ELECTRICAL PANEL ROOM
Deficiency Location/Instance	Basement - Electrical Panel Room
Deficiency Quantity	100
Quantity Uom	S.F.
Potential Action	INSTALL WATERPROOFING
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection


Q452

Question	Response
INTERIOR	
STRUCTURAL	
FOUNDATION WALLS	
Deficiency Photo1	
Violations	Basement - Corridor No violations recorded.
Deficiency	CONCRETE: WATER INFILTRATION IN NON- INSTRUCTIONAL SPACE
Deficiency Location/Instance	Basement - Oil Tank Room, Shop
Deficiency Quantity	200
Quantity Uom	S.F.
Potential Action	INSTALL WATERPROOFING
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 5
Deficiency Photo1	
Violations	Basement - Oil Tank Room No violations recorded.
ROOF STRUCTURE	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
VAULTS-BUNKERS	Does not Exist
AUDITORIUM	Inspected
Instance on 1st Floor (605 Seats)	Inspected
Ceiling	
Instance on 1st Floor (605 Seats)	Inspected
Condition	3 - Fair
Deficiency	GYPSUM BOARD: DAMAGED/DETERIORATED
Deficiency Location/Instance	Near Entrance, Center, projection Room, Balcony
Deficiency Quantity	160
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q452

Question	Response
INTERIOR	
AUDITORIUM	
Ceiling	
Deficiency Photo1	
Violations	Near center No violations recorded.
Door(s)	
Instance on 1st Floor (605 Seats)	Inspected
Condition	5 - Poor
Deficiency	METAL: DETERIORATED DOOR
Deficiency Location/Instance	Main Entrance
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Main Entrance No violations recorded.
Deficiency	METAL: DETERIORATED DOOR AND FRAME
Deficiency Location/Instance	Stage Lateral Entrance
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q452

Question	Response
INTERIOR	
AUDITORIUM	
Door(s)	
Deficiency Photo1	
Violations	Stage Lateral Entrance No violations recorded.
Fixed H/C Lift	
Instance on 1st Floor (605 Seats)	Does not Exist
Fixed Seating	
Instance on 1st Floor (605 Seats)	Inspected
Condition	5 - Poor
Deficiency	DAMAGED/BROKEN/INOPERABLE
Deficiency Location/Instance	Seats C/25, D/14, O/6, X/3, 4, and others
Deficiency Quantity	90
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Seat X/3 No violations recorded.
Floor Finish	
Instance on 1st Floor (605 Seats)	Inspected
Condition	2 - Between Good and Fair
Deficiency	RUBBER NOSING: DETERIORATED
Deficiency Location/Instance	Balcony Steps
Deficiency Quantity	20
Quantity Uom	L.F.
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q452

Question

Response

INTERIOR

AUDITORIUM

Floor Finish

Deficiency Photo1



Balcony Steps

Violations

No violations recorded.

Deficiency

VINYL TILES: BROKEN/DETERIORATED/MISSING TILES

Deficiency Location/Instance

Lateral Entrance

Deficiency Quantity

10

Quantity Uom

S.F.

Potential Action

REPLACE


Urgency of Action

PRIORITY 3

Purpose of Action

LEVEL 2

Deficiency Photo1



Lateral Entrance

Violations

No violations recorded.

Deficiency

CONCRETE: CRACKS

Deficiency Location/Instance

Near (Stage)Lateral Right Side

Deficiency Quantity

40

Quantity Uom

S.F.

Potential Action

REPLACE


Urgency of Action

PRIORITY 3

Purpose of Action

LEVEL 2

Deficiency Photo1



Near Lateral Right Side


Violations

No violations recorded.

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q452

Question	Response
INTERIOR	
AUDITORIUM	
Sliding-folding Partition	
Instance on 1st Floor (605 Seats)	Does not Exist
Stage	
Instance on 1st Floor (605 Seats)	Inspected
Stage	Inspected
Instance on 1st Floor (605 Seats)	Inspected
Condition	3 - Fair
Deficiency	DAMAGED STEPS
Deficiency Location/Instance	Right Side
Deficiency Quantity	20
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Right Side
Violations	No violations recorded.
Deficiency	DAMAGED FLOOR
Deficiency Location/Instance	Near Room 163G, Audience
Deficiency Quantity	100
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Near Room 163G
Violations	No violations recorded.
Stage Curtain Rigging	Inspected
Instance on 1st Floor (605 Seats)	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Stage Curtains	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q452

Question	Response
----------	----------


INTERIOR

AUDITORIUM

Stage

Stage Curtains

Instance on 1st Floor (605 Seats)	Inspected
Condition	4 - Between Fair and Poor
Deficiency	WORN/DETERIORATED
Deficiency Location/Instance	Lateral Right and Left Side
Deficiency Quantity	400
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	




Lateral Left Side

Violations No violations recorded.

Walls

Instance on 1st Floor (605 Seats)	Inspected
Condition	2 - Between Good and Fair
Deficiency	GLAZED BLOCK: CRACKS/SPALLING
Deficiency Location/Instance	Near Seats DD/32, L/28
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	



Near Seat L/28

Violations No violations recorded.

Window Curtains/Shades/Blinds

Instance on 1st Floor (605 Seats)	Does not Exist
-----------------------------------	----------------

CAFETERIA

Instance on 6th Floor	Inspected
-----------------------	-----------

Ceiling

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Architectural Inspection

Q452

Question	Response
INTERIOR	
CAFETERIA	
Ceiling	
Instance on 6th Floor	Inspected
Condition	3 - Fair
Deficiency	ACOUSTIC TILES: DAMAGED/MISSING
Deficiency Location/Instance	Near center
Deficiency Quantity	20
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Near center No violations recorded.
Deficiency	GYPSUM BOARD: DAMAGED/DETERIORATED
Deficiency Location/Instance	Near Center, Windows, Serving Areas, Exit
Deficiency Quantity	250
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Near Windows No violations recorded.
Door(s)	
Instance on 6th Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Fixed Equipment	
Instance on 6th Floor	Does not Exist
Floor Finish	
Instance on 6th Floor	Inspected
Condition	2 - Between Good and Fair

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q452


Question	Response
----------	----------

INTERIOR

CAFETERIA

Floor Finish

Deficiency	VINYL TILES: BROKEN/DETERIORATED/MISSING TILES
Deficiency Location/Instance	Near Windows, Serving Area
Deficiency Quantity	120
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	




Near Windows

Violations No violations recorded.

Sliding-folding Partition

Instance on 6th Floor	Inspected
Condition	3 - Fair

Deficiency	MOVABLE PANELS: DAMAGED
Deficiency Location/Instance	Near center, Windows
Deficiency Quantity	80
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	



Near center

Violations No violations recorded.

Stage

Instance on 6th Floor	Does not Exist
-----------------------	----------------



Walls

Instance on 6th Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	GYPSON BOARD: DETERIORATED
Deficiency Location/Instance	Near Serving Area
Deficiency Quantity	20

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q452

Question	Response
INTERIOR	
CAFETERIA	
Walls	
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Near Serving Area
Violations	No violations recorded.
Deficiency	GLAZED BLOCK: CRACKS/SPALLING
Deficiency Location/Instance	Near Windows
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Near Windows
Violations	No violations recorded.
Window Curtains/Shades/Blinds	
Instance on 6th Floor	Does not Exist
CLASSROOMS/CORRIDORS/ADMIN SPACES	
Ceiling	Inspected
Condition	2 - Between Good and Fair
Deficiency	METAL PAN: DAMAGED/MISSING
Deficiency Location/Instance	Room 648
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q452

Question	Response
INTERIOR	
CLASSROOMS/CORRIDORS/ADMIN SPACES	
Ceiling	
Deficiency Photo1 Violations	 Room 648 No violations recorded.
Deficiency Deficiency Location/Instance Deficiency Quantity Quantity Uom Potential Action Urgency of Action Purpose of Action Deficiency Photo1 Violations	TECTUM: DAMAGED/MISSING Corridor near Rooms 183, 192, 617, 663, 684, and others 150 S.F. REPLACE PRIORITY 3 LEVEL 2  Corridor near Room 684 No violations recorded.
Deficiency Deficiency Location/Instance Deficiency Quantity Quantity Uom Potential Action Urgency of Action Purpose of Action Deficiency Photo1 Violations	GYPSUM BOARD: DAMAGED/DETERIORATED Main Entrance Lobby Area, Corridor near Rooms 144, 149, 680 60 S.F. REPLACE PRIORITY 3 LEVEL 2  Main Entrance Lobby Area No violations recorded.

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q452

Question	Response
INTERIOR	
CLASSROOMS/CORRIDORS/ADMIN SPACES	
Ceiling	
Deficiency	ACOUSTIC TILES: DAMAGED/MISSING
Deficiency Location/Instance	Rooms 189, 562, 617, 668, Main Entrance Lobby Area, and others
Deficiency Quantity	1,500
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Room 617 No violations recorded.
Door(s)	Inspected
Condition	5 - Poor
Deficiency	METAL: DETERIORATED DOOR
Deficiency Location/Instance	Rooms 225, 345, Corridor near Room 122M
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Corridor near Room 122M No violations recorded.
Deficiency	WOOD: DETERIORATED DOOR
Deficiency Location/Instance	Rooms 189, 506, 543, 319A, Main Entrance Vestibule, and others
Deficiency Quantity	30
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q452

Question	Response
----------	----------

INTERIOR

CLASSROOMS/CORRIDORS/ADMIN SPACES

Door(s)

Deficiency Photo1



Room 189

No violations recorded.

Violations

Floor Finish

Inspected

Condition

2 - Between Good and Fair

Deficiency

VINYL TILES: BROKEN/DETERIORATED/MISSING TILES

Deficiency Location/Instance

Rooms 127, 274A, Corridor near Room 120B

Deficiency Quantity

150

Quantity Uom

S.F.

Potential Action

REPLACE


Urgency of Action

PRIORITY 3

Purpose of Action

LEVEL 2

Deficiency Photo1



Room 274A

No violations recorded.

Violations

Deficiency

WOOD: DAMAGED/DETERIORATED

Deficiency Location/Instance

Room 294

Deficiency Quantity

50

Quantity Uom

S.F.

Potential Action

REPLACE


Urgency of Action

PRIORITY 3

Purpose of Action

LEVEL 2



Deficiency Photo1



**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q452

Question	Response
INTERIOR	
CLASSROOMS/CORRIDORS/ADMIN SPACES	
Floor Finish	
Violations	Room 294 No violations recorded.
Deficiency	VINYL TILES: TRIPPING HAZARD - ELECTRICAL OUTLET
Deficiency Location/Instance	Rooms 313, 380
Deficiency Quantity	100
Quantity Uom	S.F.
Potential Action	REMOVE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	
Violations	Room 313 No violations recorded.
Deficiency	EPOXY FLOORING: CRACKS/SPALLING
Deficiency Location/Instance	Rooms 602, 662, 684, 668, 674, and others
Deficiency Quantity	600
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Room 668 No violations recorded.
Deficiency	VINYL TILES: DETERIORATED SUBSTRATE
Deficiency Location/Instance	Corridor near Room 480
Deficiency Quantity	50
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q452

Question	Response
----------	----------

INTERIOR

CLASSROOMS/CORRIDORS/ADMIN SPACES

Floor Finish

Deficiency Photo1



Corridor near Room 480

Violations

No violations recorded.

Walls

Inspected

Condition

2 - Between Good and Fair

Deficiency

MASONRY: CRACKS/SPALLING

Deficiency Location/Instance

Room 189

Deficiency Quantity

10

Quantity Uom

S.F.

Potential Action

REPLACE

Urgency of Action

PRIORITY 3

Purpose of Action

LEVEL 2

Deficiency Photo1



Room 189

Violations

No violations recorded.

Deficiency

GLAZED BLOCK: CRACKS/SPALLING

Deficiency Location/Instance

Corridor near Rooms 101, 125, 199G, 365W, 382, and others

Deficiency Quantity

40

Quantity Uom

S.F.

Potential Action

REPLACE

Urgency of Action

PRIORITY 3

Purpose of Action

LEVEL 2



Deficiency Photo1



NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Architectural Inspection



Q452

Question	Response
INTERIOR	
CLASSROOMS/CORRIDORS/ADMIN SPACES	
Walls	
Violations	Corridor near Room 382 No violations recorded.
Deficiency	GYP SUM BOARD: DETERIORATED
Deficiency Location/Instance	Corridor near Rooms 220, 274, 349, 369, 674, and others
Deficiency Quantity	200
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Corridor near Room 674 No violations recorded.
Specialties	Inspected
Classroom Locker(s)	Inspected
Condition	2 - Between Good and Fair
Deficiency	DAMAGED UNITS
Deficiency Location/Instance	Locker 6-130, 346
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Locker 6- 346 No violations recorded.
Fixed Seating	Does not Exist
GYMNASIUM	
Instance on 2nd Floor	Inspected
Instance on 4th Floor	Inaccessible
Ceiling	

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Architectural Inspection

Q452

Question	Response
INTERIOR	
GYMNASIUM	
Ceiling	
Instance on 2nd Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	TECTUM: DAMAGED/MISSING
Deficiency Location/Instance	Near Entrance
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Near Entrance No violations recorded.
Deficiency	ACOUSTIC TILES: DAMAGED/MISSING
Deficiency Location/Instance	Room 286 Gymnasium Office, Near Entrance
Deficiency Quantity	40
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Room 286 Gymnasium Office No violations recorded.
Door(s)	
Instance on 2nd Floor	Inspected
Condition	5 - Poor
Deficiency	WOOD: DETERIORATED DOOR
Deficiency Location/Instance	Room 286 Gymnasium - Office outside Gymnasium, Room 284 - Office outside Gymnasium
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Architectural Inspection

Q452

Question	Response
INTERIOR	
GYMNASIUM	
Door(s)	
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Room 286 Gymnasium Office
Violations	No violations recorded.
Deficiency	METAL: DETERIORATED DOOR
Deficiency Location/Instance	Storage Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Storage Room
Violations	No violations recorded.
Fixed Equipment	
Instance on 2nd Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Floor Finish	
Instance on 2nd Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	VINYL TILES: BROKEN/DETERIORATED/MISSING TILES
Deficiency Location/Instance	Entrance Storage Room
Deficiency Quantity	20
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q452

Question	Response
----------	----------

INTERIOR

GYMNASIUM

Floor Finish

Deficiency Photo1



Entrance Storage Room

No violations recorded.

Violations

Seating

Instance on 2nd Floor

Inspected

Condition

5 - Poor

Deficiency

DAMAGED BLEACHERS

Deficiency Location/Instance

Near Windows

Deficiency Quantity

720

Quantity Uom

S.F.

Potential Action

REPLACE

Urgency of Action

PRIORITY 3

Purpose of Action

LEVEL 2

Deficiency Photo1

No photo recorded

Violations

No violations recorded.

Sliding-folding Partition

Instance on 2nd Floor

Does not Exist

Stage

Instance on 2nd Floor

Does not Exist

Walls

Instance on 2nd Floor

Inspected

Condition

2 - Between Good and Fair

Deficiency

GLAZED BLOCK: CRACKS/SPALLING

Deficiency Location/Instance

Near Windows

Deficiency Quantity

10

Quantity Uom

S.F.

Potential Action

REPLACE

Urgency of Action

PRIORITY 3

Purpose of Action

LEVEL 2

Deficiency Photo1



Near Windows

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection



Q452

Question	Response
INTERIOR	
GYMNASIUM	Inspected
Walls	
Violations	No violations recorded.
Window Curtains/Shades/Blinds	
Instance on 2nd Floor	Does not Exist
INTERIOR DOOR HARDWARE	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
INTERIOR GUARDS	Inspected
Condition	2 - Between Good and Fair
Deficiency	DETERIORATED/TORN-OUT/MISSING
Deficiency Location/Instance	Team 2nd Floor Boys - Locker Room
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Team 2nd Floor Boys - Locker Room No violations recorded.
KITCHEN	Inspected
Instance on Sixth Floor	Inspected
Ceiling	
Instance on Sixth Floor	Inspected
Condition	5 - Poor
Deficiency	METAL PAN: DAMAGED/MISSING
Deficiency Location/Instance	Entrance room From Cafeteria Left Serving Area
Deficiency Quantity	20
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection


Q452

Question	Response
INTERIOR	
KITCHEN	
Ceiling	
Violations	Entrance room From Cafeteria Left Serving Area No violations recorded.
Deficiency	ACOUSTIC TILES: DAMAGED/MISSING
Deficiency Location/Instance	Rooms 647J, 647N, 647Q
Deficiency Quantity	120
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Room 647N No violations recorded.
Deficiency	METAL PAN: DAMAGED/MISSING
Deficiency Location/Instance	Serving Area Right and Left Side
Deficiency Quantity	30
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Serving Area Right Side No violations recorded.
Door(s)	
Instance on Sixth Floor	Inspected
Condition	3 - Fair
Deficiency	METAL: DETERIORATED DOOR
Deficiency Location/Instance	Front Serving Area
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q452

Question	Response
INTERIOR	
KITCHEN	
Door(s)	
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Front Serving Area
Violations	No violations recorded.

Floor Finish	
Instance on Sixth Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	QUARRY TILE: BROKEN/MISSING TILES
Deficiency Location/Instance	Sink Room, Near Oven Area, Walking Fridge
Deficiency Quantity	20
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Sink Room
Violations	No violations recorded.

Walls	
Instance on Sixth Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	MASONRY: CRACKS/SPALLING
Deficiency Location/Instance	Room 647N
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q452

Question	Response
INTERIOR	
KITCHEN	
Walls	
Deficiency Photo1	
	Room 647N
Violations	No violations recorded.
Deficiency	CERAMIC TILE: BROKEN/ MISSING
Deficiency Location/Instance	Corridor near Room 647N, Serving Areas
Deficiency Quantity	30
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Corridor near Room 647N
Violations	No violations recorded.
LIBRARY	Inspected
Instance on Room 446	Inspected
Built-in Furnishing	
Instance on Room 446	Does not Exist
Ceiling	
Instance on Room 446	Inspected
Condition	3 - Fair
Deficiency	GYPSUM BOARD: DAMAGED/DETERIORATED
Deficiency Location/Instance	Near Room 446C
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q452

Question	Response
INTERIOR	
LIBRARY	

Ceiling

Deficiency Photo1



Near Room 446C

Violations

No violations recorded.

Deficiency	ACOUSTIC TILES: DAMAGED/MISSING
Deficiency Location/Instance	Rooms 446C, 446E, Near Entrance, Room 446D
Deficiency Quantity	60
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	



Room 446C

Violations

No violations recorded.



Door(s)

Instance on Room 446	Inspected
Condition	5 - Poor
Deficiency	WOOD: DETERIORATED DOOR
Deficiency Location/Instance	Entrances, Room 446E
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection


Q452

Question	Response
INTERIOR	
LIBRARY	
Door(s)	
Deficiency Photo1	
Violations	Entrance No violations recorded.
Floor Finish	
Instance on Room 446	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Walls	
Instance on Room 446	Inspected
Condition	2 - Between Good and Fair
Deficiency	GYPSON BOARD: DETERIORATED
Deficiency Location/Instance	Near Windows
Deficiency Quantity	20
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Near Windows No violations recorded.
LOCKER ROOM	
Instance on 1st Floor - Boys (70 Lockers)	Inspected
Alternative use	No
Instance on 1st Floor - Girls (70 Lockers)	Inspected
Alternative use	No
Instance on 2nd Floor - Boys (746 Lockers)	Inspected
Alternative use	No
Instance on 2nd Floor - Girls (776 Lockers)	Inspected
Alternative use	No
Instance on 2nd Floor - Visitors (76 Lockers - 500 SF)	Inspected
Alternative use	No

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q452

Question	Response
INTERIOR	
LOCKER ROOM	
Instance on 4th Floor - Boys (957 Lockers)	Inspected
Alternative use	Yes
Instance on 4th Floor - Girls (658 Lockers)	Inspected
Alternative use	Yes
Ceiling	
Instance on 2nd Floor - Boys (746 Lockers)	Does not Exist
Instance on 2nd Floor - Girls (776 Lockers)	Does not Exist
Instance on 2nd Floor - Visitors (76 Lockers - 500 SF)	Does not Exist
Instance on 4th Floor - Girls (658 Lockers)	Does not Exist
Instance on 4th Floor - Boys (957 Lockers)	Does not Exist
Instance on 1st Floor - Boys (70 Lockers)	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on 1st Floor - Girls (70 Lockers)	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Door(s)	
Instance on 4th Floor - Girls (658 Lockers)	Inspected
Condition	3 - Fair
Deficiency	WOOD: DETERIORATED DOOR
Deficiency Location/Instance	Entrance
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Entrance
Violations	No violations recorded.
Instance on 4th Floor - Boys (957 Lockers)	Inspected
Condition	3 - Fair
Deficiency	WOOD: DETERIORATED DOOR
Deficiency Location/Instance	Entrance
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q452

Question	Response
INTERIOR	
LOCKER ROOM	
Door(s)	
Deficiency Photo1	
Violations	Entrance No violations recorded.
Instance on 2nd Floor - Girls (776 Lockers)	Inspected
Condition	3 - Fair
Deficiency	WOOD: DETERIORATED DOOR
Deficiency Location/Instance	Entrance
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Entrance No violations recorded.
Instance on 2nd Floor - Boys (746 Lockers)	Inspected
Condition	3 - Fair
Deficiency	WOOD: DETERIORATED DOOR
Deficiency Location/Instance	Entrance
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q452

Question	Response
----------	----------

INTERIOR

LOCKER ROOM

Door(s)

Deficiency Photo1




Entrance

Violations

No violations recorded.

Floor Finish

Instance on 1st Floor - Boys (70 Lockers)	Inspected
Condition	2 - Between Good and Fair
Deficiency	CERAMIC TILE: BROKEN/MISSING TILES
Deficiency Location/Instance	Near locker 132
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	



Near locker 132

Violations

No violations recorded.

Instance on 1st Floor - Girls (70 Lockers)	Inspected
Condition	2 - Between Good and Fair
Deficiency	CERAMIC TILE: BROKEN/MISSING TILES
Deficiency Location/Instance	Near Locker 046
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection



Q452

Question	Response
INTERIOR	
LOCKER ROOM	
Floor Finish	
Deficiency Photo1	
	Near Locker 046
Violations	No violations recorded.
Instance on 2nd Floor - Boys (746 Lockers)	Inspected
Condition	2 - Between Good and Fair
Deficiency	CERAMIC TILE: BROKEN/MISSING TILES
Deficiency Location/Instance	Near Shower Room, Lockers 80, 315, 508, 704,
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Near Locker 315
Violations	No violations recorded.
Instance on 2nd Floor - Girls (776 Lockers)	Inspected
Condition	2 - Between Good and Fair
Deficiency	CERAMIC TILE: BROKEN/MISSING TILES
Deficiency Location/Instance	Near Locker 405, team Lockers
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q452

Question	Response
INTERIOR	
LOCKER ROOM	
Floor Finish	
Deficiency Photo1	
Violations	Near Locker 405 No violations recorded.
Instance on 4th Floor - Boys (957 Lockers)	Inspected
Condition	2 - Between Good and Fair
Deficiency	CERAMIC TILE: BROKEN/MISSING TILES
Deficiency Location/Instance	Near Lockers 154, 304, 322, 886
Deficiency Quantity	20
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Near Locker 322 No violations recorded.
Instance on 4th Floor - Girls (658 Lockers)	Inspected
Condition	2 - Between Good and Fair
Deficiency	CERAMIC TILE: BROKEN/MISSING TILES
Deficiency Location/Instance	Near Lockers 34, 324, 704, 720, 879, and others
Deficiency Quantity	20
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q452

Question	Response
----------	----------

INTERIOR

LOCKER ROOM

Floor Finish

Deficiency Photo1




Near Locker 34

Violations

No violations recorded.

Locker Room Lockers

Instance on 2nd Floor - Visitors (76 Lockers - 500 SF)	Inspected
Condition	2 - Between Good and Fair
Deficiency	DAMAGED UNITS
Deficiency Location/Instance	Lockers 77, 89, 90, 103, 104
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	



Lockers 89, 90

Violations

No violations recorded.

Instance on 4th Floor - Girls (658 Lockers)	Inspected
Condition	2 - Between Good and Fair
Deficiency	DAMAGED UNITS
Deficiency Location/Instance	Lockers 704, 705
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q452

Question	Response
----------	----------

INTERIOR

LOCKER ROOM

Locker Room Lockers

Deficiency Photo1



Locker 704

Violations

No violations recorded.

Instance on 4th Floor - Boys (957 Lockers)

Inspected

Condition

2 - Between Good and Fair

Deficiency

DAMAGED UNITS

Deficiency Location/Instance

Lockers 2, 3, 141, 668, 792

Deficiency Quantity

5

Quantity Uom

EACH

Potential Action

REPLACE

Urgency of Action

PRIORITY 3

Purpose of Action

LEVEL 2

Deficiency Photo1



Locker 141

Violations

No violations recorded.

Instance on 2nd Floor - Girls (776 Lockers)

Inspected

Condition

2 - Between Good and Fair

Deficiency

DAMAGED UNITS

Deficiency Location/Instance

Lockers 529, 771, 772

Deficiency Quantity

3

Quantity Uom

EACH

Potential Action

REPLACE

Urgency of Action

PRIORITY 3



Purpose of Action

LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q452

Question	Response
INTERIOR	
LOCKER ROOM	
Locker Room Lockers	
Deficiency Photo1	
	Locker 519
Violations	No violations recorded.
Instance on 2nd Floor - Boys (746 Lockers)	Inspected
Condition	2 - Between Good and Fair
Deficiency	DAMAGED UNITS
Deficiency Location/Instance	Lockers 420, 478, 705, 734
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Locker 705
Violations	No violations recorded.
Instance on 1st Floor - Girls (70 Lockers)	Inspected
Condition	5 - Poor
Deficiency	DAMAGED UNITS
Deficiency Location/Instance	Lockers 042, 055, 061, 067, 069, and others
Deficiency Quantity	15
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q452

Question	Response
----------	----------

INTERIOR

LOCKER ROOM

Locker Room Lockers

Deficiency Photo1



Locker 067

Violations

No violations recorded.

Instance on 1st Floor - Boys (70 Lockers)

Inspected

Condition

5 - Poor

Deficiency

DAMAGED UNITS

Deficiency Location/Instance

Lockers 071, 079, 121, 123, 124, and others

Deficiency Quantity

10

Quantity Uom

EACH

Potential Action

REPLACE


Urgency of Action

PRIORITY 3

Purpose of Action

LEVEL 2

Deficiency Photo1



Locker 071

Violations

No violations recorded.

Walls

Instance on 1st Floor - Boys (70 Lockers)

Inspected

Condition

2 - Between Good and Fair

Deficiency

CERAMIC TILE: BROKEN/ MISSING

Deficiency Location/Instance

Near Shower Rooms, Exit

Deficiency Quantity

20

Quantity Uom

S.F.

Potential Action

REPLACE

Urgency of Action

PRIORITY 3



Purpose of Action

LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q452

Question	Response
INTERIOR	
LOCKER ROOM	
Walls	
Deficiency Photo1	
	Near Shower Room
Violations	No violations recorded.
Instance on 1st Floor - Girls (70 Lockers)	Inspected
Condition	2 - Between Good and Fair
Deficiency	CERAMIC TILE: BROKEN/ MISSING
Deficiency Location/Instance	Near Entrance, Shower Room
Deficiency Quantity	20
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Near Entrance
Violations	No violations recorded.
Instance on 2nd Floor - Visitors (76 Lockers - 500 SF)	Inspected
Condition	2 - Between Good and Fair
Deficiency	CERAMIC TILE: BROKEN/ MISSING
Deficiency Location/Instance	Near Entrance
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q452

Question	Response
----------	----------

INTERIOR

LOCKER ROOM

Walls

Deficiency Photo1



Near Entrance

Violations

No violations recorded.

Instance on 2nd Floor - Boys (746 Lockers)

Inspected

Condition

2 - Between Good and Fair

Deficiency

CERAMIC TILE: BROKEN/ MISSING

Deficiency Location/Instance

Near Entrances, Locker 114, Inside Team Locker Room

Deficiency Quantity

10

Quantity Uom

S.F.

Potential Action

REPLACE


Urgency of Action

PRIORITY 3

Purpose of Action

LEVEL 2

Deficiency Photo1



Near Entrance

Violations

No violations recorded.

Instance on 2nd Floor - Girls (776 Lockers)

Inspected

Condition

2 - Between Good and Fair

Deficiency

CERAMIC TILE: BROKEN/ MISSING

Deficiency Location/Instance

Near Toilet Room

Deficiency Quantity

10

Quantity Uom

S.F.

Potential Action

REPLACE

Urgency of Action

PRIORITY 3

Purpose of Action

LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection



Q452

Question	Response
INTERIOR	
LOCKER ROOM	
Walls	
Deficiency Photo1	
Violations	Near Toilet Room No violations recorded.
Instance on 4th Floor - Boys (957 Lockers)	Inspected
Condition	3 - Fair
Deficiency	CERAMIC TILE: BROKEN/ MISSING
Deficiency Location/Instance	Near Entrance, Lockers 254, 304, 414, 674, and others
Deficiency Quantity	100
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Near Lockers254 No violations recorded.
MULTI-PURPOSE ROOM	Does not Exist
SCIENCE DEMO ROOM	Inspected
Instance on Room 675	Inspected
Alternative use	No
Fixed Equipment	
Instance on Room 675	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
SCIENCE LAB	Inspected
Instance on Rooms 608, 668, 680	Inspected
Alternative use	No
Fixed Equipment	
Instance on Rooms 608, 668, 680	Inspected
Condition	4 - Between Fair and Poor
Deficiency	CABINETS: MISSING/DAMAGED
Deficiency Location/Instance	Rooms 608, 668, 680

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q452

Question	Response
INTERIOR	
SCIENCE LAB	
Fixed Equipment	
Deficiency Quantity	20
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Room 684
Violations	No violations recorded.
SCIENCE PREP ROOM	
	Inspected
Instance on Room 674	Inspected
Alternative use	No
Instance on Room 602	Inspected
Alternative use	No
Fixed Equipment	
Instance on Room 674	Inspected
Condition	3 - Fair
Deficiency	CABINETS: MISSING/DAMAGED
Deficiency Location/Instance	Room 674
Deficiency Quantity	10
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Room 674
Violations	No violations recorded.
SHOWER ROOM	
	Inspected
Instance on 1st Floor - Boys	Inspected
Alternative use	No
Instance on 1st Floor - Girls	Inspected
Alternative use	No

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q452

Question	Response
INTERIOR	
SHOWER ROOM	
Instance on 2nd Floor - Boys	Inspected
Alternative use	No
Instance on 2nd Floor - Girls	Inaccessible
Instance on 2nd Floor - Visitors	Inspected
Alternative use	No
Instance on 4th Floor - Boys	Inspected
Alternative use	Yes
Instance on 4th Floor - Girls	Inaccessible
Ceiling	
Instance on 4th Floor - Boys	Inspected
Condition	3 - Fair
Deficiency	GYPSON BOARD: DAMAGED/DETERIORATED
Deficiency Location/Instance	Near Entrance
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Near Entrance No violations recorded.
Door(s)	
Instance on 1st Floor - Boys	Does not Exist
Instance on 1st Floor - Girls	Does not Exist
Instance on 2nd Floor - Boys	Does not Exist
Instance on 2nd Floor - Visitors	Does not Exist
Instance on 4th Floor - Boys	Does not Exist
Floor Finish	
Instance on 2nd Floor - Boys	Inspected
Condition	3 - Fair
Deficiency	CERAMIC TILE: BROKEN/MISSING TILES
Deficiency Location/Instance	Near Entrance
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q452

Question	Response
----------	----------

INTERIOR

SHOWER ROOM

Floor Finish

Deficiency Photo1




Near Entrance

Violations

No violations recorded.

Walls

Instance on 2nd Floor - Boys	Inspected
Condition	2 - Between Good and Fair
Deficiency	CERAMIC TILE: BROKEN/ MISSING
Deficiency Location/Instance	Inside Multiple Shower Room
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	



Inside Multiple Shower Room

Violations

No violations recorded.

STAIRS/RAMPS: INTERIOR

Do Letter Stair Signs Exist?	Inspected
	Yes

Ceiling

Condition	Inspected
	2 - Between Good and Fair
Deficiency	TECTUM: DAMAGED/MISSING
Deficiency Location/Instance	Stair F/1
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q452

Question	Response
----------	----------

INTERIOR

STAIRS/RAMPS: INTERIOR

Ceiling

Deficiency Photo1



Stair F/1

Violations

No violations recorded.

Deficiency

GYPSUM BOARD: DAMAGED/DETERIORATED

Deficiency Location/Instance

Stairs A/6, C/1, 4, E/4, D/6, and others

Deficiency Quantity

200

Quantity Uom

S.F.

Potential Action

REPLACE

Urgency of Action

PRIORITY 3

Purpose of Action

LEVEL 2

Deficiency Photo1



Stair A/6

Violations

No violations recorded.

Door(s)

Inspected

Condition

5 - Poor

Deficiency

METAL: DETERIORATED DOOR

Deficiency Location/Instance

Stairs C/2, E/2, 4, 5, F/2, and others

Deficiency Quantity

10

Quantity Uom

EACH

Potential Action

MAINTENANCE

Urgency of Action

PRIORITY 3

Purpose of Action

LEVEL 2



Deficiency Photo1



**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q452

Question	Response
INTERIOR	
STAIRS/RAMPS: INTERIOR	
Door(s)	Inspected
	Stair E/2
Violations	No violations recorded.
Partition	Inspected
Condition	2 - Between Good and Fair
Deficiency	GLASS PANEL: DAMAGED/DETERIORATED
Deficiency Location/Instance	Main Entrance Stair
Deficiency Quantity	30
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Main Entrance Stair
Violations	No violations recorded.
Railings	Inspected
Condition	5 - Poor
Deficiency	METAL: MISSING
Deficiency Location/Instance	Stairs E/1, 4, 6
Deficiency Quantity	50
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	
	Stair E/1
Violations	No violations recorded.
Stairs and Landings	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Walls	Inspected
Condition	2 - Between Good and Fair

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Architectural Inspection



Q452

Question	Response
INTERIOR	
STAIRS/RAMPS: INTERIOR	
Walls	
Deficiency	GLAZED BLOCK: CRACKS/SPALLING
Deficiency Location/Instance	Stairs A/1, B/5, E/1
Deficiency Quantity	20
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Stair A/1
Violations	No violations recorded.
Deficiency	GYPSON BOARD: DETERIORATED
Deficiency Location/Instance	Stairs E/5, F/1
Deficiency Quantity	20
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Stair E/5
Violations	No violations recorded.
TOILET ROOMS - STAFF	Inspected
Ceiling	Inspected
Condition	3 - Fair
Deficiency	GYPSON BOARD: DAMAGED/DETERIORATED
Deficiency Location/Instance	Rooms 143, 677M
Deficiency Quantity	40
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection



Q452

Question	Response
INTERIOR	
TOILET ROOMS - STAFF	
Ceiling	
Deficiency Photo1	
Violations	Room 677M No violations recorded.
Door(s)	Inspected
Condition	5 - Poor
Deficiency	WOOD: DAMAGED LOUVER
Deficiency Location/Instance	Room 277G
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Room 277G No violations recorded.
Deficiency	WOOD: DETERIORATED DOOR
Deficiency Location/Instance	Rooms 122W, 277B, 546B (Kitchen), 546G (Kitchen), Room 286B Gymnasium Office
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q452

Question	Response
INTERIOR	
TOILET ROOMS - STAFF	
Door(s)	Inspected
Deficiency Photo1	
	Room 277B
Violations	No violations recorded.
Floor Finish	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Stalls	Inspected
Condition	4 - Between Fair and Poor
Deficiency	RUST - MAJOR
Deficiency Location/Instance	Room 143
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Room 143
Violations	No violations recorded.
Walls	Inspected
Condition	2 - Between Good and Fair
Deficiency	GLAZED BLOCK: CRACKS/SPALLING
Deficiency Location/Instance	1st Floor Men
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q452

Question	Response
INTERIOR	
TOILET ROOMS - STAFF	
Walls	
Deficiency Photo1	
	1st Floor Men
Violations	No violations recorded.
Deficiency	CERAMIC TILE: BROKEN/ MISSING
Deficiency Location/Instance	Room 647P (kitchen)
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Room 647P (kitchen)
Violations	No violations recorded.
TOILET ROOMS - STUDENTS	
	Inspected
Ceiling	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Door(s)	Inspected
Condition	5 - Poor
Deficiency	WOOD: DAMAGED LOUVER
Deficiency Location/Instance	Room 641G
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q452

Question	Response
INTERIOR	
TOILET ROOMS - STUDENTS	
Door(s)	
Deficiency Photo1	
Violations	Room 641G No violations recorded.
Deficiency	WOOD: DETERIORATED DOOR
Deficiency Location/Instance	Rooms 477B, 477G, 577B, 577G, 641B, and others
Deficiency Quantity	7
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Room 641B No violations recorded.
Floor Finish	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Stalls	Inspected
Condition	5 - Poor
Deficiency	RUST - MAJOR
Deficiency Location/Instance	Rooms 377B, 377G, 477B, 641B, 641G
Deficiency Quantity	17
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q452

Question	Response
INTERIOR	
TOILET ROOMS - STUDENTS	
Stalls	
Deficiency Photo1	
Violations	Room 641B No violations recorded.
Walls	
Condition	Inspected 2 - Between Good and Fair
Deficiency	CERAMIC TILE: BROKEN/ MISSING
Deficiency Location/Instance	2nd Floor Boys - Locker Room, Pool Girls Locker Room
Deficiency Quantity	20
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	2nd Floor Boys - Locker Room No violations recorded.
LIFE SAFETY	
Inspected	
F.D. HOLDING AREA	
Does not Exist	
STEEL STAIRS	
Does not Exist	
SITE	
Inspected	
CONTAINERIZATION	
Inspected	
Condition	5 - Poor
Deficiency	CONCRETE PAD DAMAGED
Deficiency Location/Instance	Containerization Area
Deficiency Quantity	200
Quantity Uom	S.F.
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q452

Question	Response
SITE	
CONTAINERIZATION	
Deficiency Photo1	
Violations	Containerization Area No violations recorded.
Deficiency	FENCING MISSING
Deficiency Location/Instance	Containerization Area
Deficiency Quantity	600
Quantity Uom	S.F.
Potential Action	INSTALL NEW
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	CONTAINER DAMAGED
Deficiency Location/Instance	Containerization Area
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Containerization Area No violations recorded.
Drainage System for Asphalt	Does not Exist
Drainage System for Concrete	Inspected
Catch Basins/Manhole - Surrounded by concrete	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Culverts - Concrete Covering	Does not Exist
Drainage System for Soil	Does not Exist
DRINKING FOUNTAINS	Does not Exist
FENCES	Inaccessible

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection



Q452

Question	Response
SITE	
IRRIGATION SYSTEM	Does not Exist
PAVING	Inspected
Student Non-Use	Inspected
Gravel Exists?	No
Asphalt	Does not Exist
Concrete	Inspected
Condition	3 - Fair
Deficiency	DAMAGED/DETERIORATED/MISSING SECTIONS
Deficiency Location/Instance	Containerization Area
Deficiency Quantity	300
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Containerization Area No violations recorded.
Pavers	Does not Exist
Student Use	Does not Exist
Site Sidewalks & Walkways	Inspected
Asphalt	Does not Exist
Concrete	Inspected
Condition	3 - Fair
Deficiency	DAMAGED/DETERIORATED/MISSING SECTIONS
Deficiency Location/Instance	Main Entrance, Near Athletic Field Exit
Deficiency Quantity	100
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection



Q452

Question	Response
SITE	
PAVING	
Site Sidewalks & Walkways	Inspected
Concrete	Inspected
Violations	No violations recorded.
Pavers	Does not Exist
DOT Sidewalk	Inspected
Asphalt	Does not Exist
Concrete	Inspected
Condition	3 - Fair
Deficiency	HEAVING
Deficiency Location/Instance	Broadway avenue
Deficiency Quantity	50
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	
Violations	Broadway Avenue No violations recorded.
Deficiency	DAMAGED/DETERIORATED/MISSING SECTIONS
Deficiency Location/Instance	Broadway Avenue, 33rd Ave
Deficiency Quantity	250
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Broadway Avenue No violations recorded.
Deficiency	DAMAGED CURBS
Deficiency Location/Instance	Broadway Avenue
Deficiency Quantity	50

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection





Q452

Question	Response
SITE	
PAVING	
DOT Sidewalk	Inspected
Concrete	
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Broadway Avenue No violations recorded.
Pavers	Does not Exist
PLAYGROUNDS	Inspected
Instance on East Side of the building	Inaccessible
PLAYING SURFACE	Does not Exist
RETAINING WALLS	Inspected
Are there any Retaining Walls 6' OR higher facing public street/sidewalk?	No
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
SEATING	Does not Exist
SITE WALLS (NOT RETAINING WALLS)	Inspected
Condition	3 - Fair
Deficiency	STONE: CRACKS/SPALLING - MAJOR
Deficiency Location/Instance	Containerization Area
Deficiency Quantity	40
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Containerization Area No violations recorded.
Deficiency	BRICK: CRACKS/SPALLING - MAJOR

**NYC Department of Education
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q452

Question	Response
SITE	
SITE WALLS (NOT RETAINING WALLS)	
Deficiency Location/Instance	Containerization Area
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Containerization Area No violations recorded.
STAIRS/RAMPS: EXTERIOR	
	Does not Exist
ARTWORK	
Instance	Inspected
Instance Photo	Interior - Drinking Fountains - 11746
	
	Drinking Fountains
Instance ID	11746
Artwork exist at stated location?	Yes
Instance	Interior and Exterior - Lobby - 10644
Instance Photo	
	Lobby
Instance ID	10644
Artwork exist at stated location?	Yes
Instance	Interior - Lobby - 21370
Instance Photo	
	Lobby

NYC Department of Education
Building Condition Assessment Survey 2023 - 2024

Architectural Inspection

Q452

Question	Response
ARTWORK	
Instance ID	21370
Artwork exist at stated location?	Yes