

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q452

**Asset:** LONG ISLAND CITY HS (NEW) - Q, 14-30 BROADWAY, New York, 11101

Inspection Id	Inspection Type	Time In	Last Edited
EE : Q452	Electrical	2024-05-07 8:17 AM	2024-05-29 12:41 PM

Asset Data

Question	Answer
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration in Electrical Room?	Yes
Have any Systems/Major Building Components been upgraded?	Yes
	Systems: Lightning Protection
	Years: Under Construction
	Systems: Motor Controller (Variable Frequency Drive), Swimming Pool (Retrofitted LED Lighting)
	Years: 2023
	Systems: Gymnasium (Retrofitted LED Lighting)
	Years: 2022
	Systems: LED Lighting (Culinary Arts - Room 642), Most Emergency Lighting (Battery Pack), IPDVS/CCTV System
	Years: 2020
	Systems: Fire Alarm System - Except (Sub-Panels), Motor Controller (Partial Motor Starter/Contactor)
	Years: 2018
	Systems: Auditorium (Local Sound system)
	Years: 2017
	Systems: Intrusion Alarm System (Remote Annunciator)
	Years: 2013
	Systems: Fire Alarm System (Sprinkler Flow/Air Pressure Switch, Tamper Flow Switch/Chain)
	Years: 1995, 2018
	Systems: Transformer
	Years: 1995, 2016
	Systems: Molded Case Circuit Breaker Type Panel Board
	Years: 1995, 1998, 2016
	Systems: All Other Electrical Systems and Components
	Years: 1995

**DEDICATED INTERCOMS IN FIRE RESCUE AREAS**

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	Yes
Are dedicated intercoms available in all of these spaces for use during a fire?	Yes
Are all dedicated intercoms operational?	Yes

Priority Condition

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
Yes	Water Penetration in Electrical Room	N/A	Electrical Equipment	Electrical Switchgear Room B56	Ernesto Diaz	Custodian	Sent to DSF	

Inspection

Question	Response
<b>Electrical</b>	
<b>AUDITORIUM</b>	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q452

Question	Response
<b>AUDITORIUM</b>	
Instance on 1st Floor	Inspected
<b>House Lighting</b>	Inspected
Does a Chandelier exist?	No
Instance on 1st Floor	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 1st Floor	Inspected
<b>Pendant Mounted</b>	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Surface Mounted</b>	Inspected
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	20
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Recessed Mounted</b>	Inspected
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	69
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Lighting Fixture - HID</b>	
Instance on 1st Floor	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 1st Floor	Inspected
<b>Pendant Mounted</b>	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Surface Mounted</b>	Inspected
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Inspected
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - LED</b>	
Instance on 1st Floor	Does not Exist
<b>Local Sound System</b>	Inspected
Instance on 1st Floor	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q452

Question	Response
<b>AUDITORIUM</b>	
<b>Local Sound System</b>	Inspected
Installation Year	2017
Source of Installation	Custodial Staff
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Projection System</b>	Inspected
Is the projector on a cart or installed on the ceiling?	Ceiling
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Theater Lighting System</b>	Inspected
Instance on 1st Floor	Inspected
<b>Dimming System</b>	
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	DIMMING RACK/LIGHT CONSOLE BEYOND USEFUL LIFE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Theater Lighting</b>	
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	172
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>CAFETERIA</b>	
Instance on 6th Floor	Inspected
<b>Lighting</b>	Inspected
Instance on 6th Floor	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 6th Floor	Inspected
<b>Pendant Mounted</b>	
Instance on 6th Floor	Does not Exist
<b>Surface Mounted</b>	
Instance on 6th Floor	Does not Exist
<b>Recessed Mounted</b>	
Instance on 6th Floor	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q452

Question	Response
<b>CAFETERIA</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Recessed Mounted</b>	
Deficiency Quantity	240
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	22
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Lighting Fixture - HID</b>	
Instance on 6th Floor	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 6th Floor	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on 6th Floor	Does not Exist
<b>Local Sound System</b>	
Instance on 6th Floor	Inspected
Installation Year	1995
Source of Installation	Documented
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Projection System</b>	
Instance on 6th Floor	Does not Exist
<b>Theater Lighting System</b>	
Instance on 6th Floor	Does not Exist
<b>CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE</b>	
<b>Lighting</b>	Inspected
Does a Chandelier exist?	No
<b>Lighting Fixture - Fluorescent</b>	
<b>Pendant Mounted</b>	
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	19
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q452

Question	Response
<b>CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Pendant Mounted</b>	
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	492
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Surface Mounted</b>	
Condition	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	57
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Recessed Mounted</b>	
Condition	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	2,072
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	27
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Lighting Fixture - HID</b>	
Condition	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q452

Question	Response
<b>CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE</b>	
<b>Lighting</b>	
<b>Lighting Fixture - HID</b>	
<b>Pendant Mounted</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Recessed Mounted</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - Incandescent</b>	Does not Exist
<b>Lighting Fixture - LED</b>	Inspected
<b>Pendant Mounted</b>	Does not Exist
<b>Surface Mounted</b>	Does not Exist
<b>Recessed Mounted</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>COMPUTER LAB</b>	
	Inspected
Instance on Rooms 201, 494	Inspected
Power Panel	Yes
Instance on Rooms 382, 384, 430, 525, 594	Inspected
Power Panel	Yes
<b>Lighting</b>	Inspected
Instance on Rooms 382, 384, 430, 525, 594	Inspected
Instance on Rooms 201, 494	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Rooms 382, 384, 430, 525, 594	Inspected
Instance on Rooms 201, 494	Inspected
<b>Pendant Mounted</b>	Inspected
Instance on Rooms 382, 384, 430, 525, 594	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	120
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Rooms 201, 494	Does not Exist
<b>Surface Mounted</b>	Does not Exist
Instance on Rooms 382, 384, 430, 525, 594	Does not Exist
Instance on Rooms 201, 494	Does not Exist
<b>Recessed Mounted</b>	Does not Exist
Instance on Rooms 382, 384, 430, 525, 594	Does not Exist
Instance on Rooms 201, 494	Inspected
Condition	3 - Fair

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q452

Question	Response
<b>COMPUTER LAB</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Recessed Mounted</b>	
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	58
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Lighting Fixture - HID</b>	
Instance on Rooms 382, 384, 430, 525, 594	Does not Exist
Instance on Rooms 201, 494	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Rooms 382, 384, 430, 525, 594	Does not Exist
Instance on Rooms 201, 494	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Rooms 382, 384, 430, 525, 594	Does not Exist
Instance on Rooms 201, 494	Does not Exist
<b>Raceway With Receptacles</b>	
Instance on Rooms 382, 384, 430, 525, 594	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 201, 494	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>GYMNASIUM</b>	
Instance on 2nd Floor	Inspected
Instance on 4th Floor	Inaccessible
<b>Lighting</b>	
Instance on 2nd Floor	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 2nd Floor	Inspected
<b>Pendant Mounted</b>	
Instance on 2nd Floor	Does not Exist
<b>Surface Mounted</b>	
Instance on 2nd Floor	Does not Exist
<b>Recessed Mounted</b>	
Instance on 2nd Floor	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	8
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q452

Question	Response
<b>GYMNASIUM</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Recessed Mounted</b>	Inspected
Violations	No violations recorded.
<b>Lighting Fixture - HID</b>	
Instance on 2nd Floor	Inspected
<b>Pendant Mounted</b>	Inspected
Instance on 2nd Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Does not Exist
Instance on 2nd Floor	Does not Exist
<b>Recessed Mounted</b>	Does not Exist
Instance on 2nd Floor	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 2nd Floor	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on 2nd Floor	Inspected
<b>Pendant Mounted</b>	Does not Exist
Instance on 2nd Floor	Does not Exist
<b>Surface Mounted</b>	Does not Exist
Instance on 2nd Floor	Does not Exist
<b>Recessed Mounted</b>	Inspected
Instance on 2nd Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Local Sound System</b>	
Instance on 2nd Floor	Inspected
Installation Year	1995
Source of Installation	Documented
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Projection System</b>	
Instance on 2nd Floor	Does not Exist
<b>Scoreboard</b>	
Instance on 2nd Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Theater Lighting System</b>	
Instance on 2nd Floor	Does not Exist
<b>KITCHEN</b>	
Instance on 6th Floor	Inspected
<b>Lighting</b>	
Instance on 6th Floor	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 6th Floor	Inspected
<b>Pendant Mounted</b>	Does not Exist
Instance on 6th Floor	Does not Exist



**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q452

Question	Response
<b>KITCHEN</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Surface Mounted</b>	Does not Exist
Instance on 6th Floor	Does not Exist
<b>Recessed Mounted</b>	Inspected
Instance on 6th Floor	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	7
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	53
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Lighting Fixture - HID</b>	
Instance on 6th Floor	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 6th Floor	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on 6th Floor	Does not Exist
<b>LIBRARY</b>	
Instance on Room 446	Inspected
<b>Lighting</b>	
Instance on Room 446	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 446	Inspected
<b>Pendant Mounted</b>	Does not Exist
Instance on Room 446	Does not Exist
<b>Surface Mounted</b>	Does not Exist
Instance on Room 446	Does not Exist
<b>Recessed Mounted</b>	Inspected
Instance on Room 446	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	15
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q452

Question	Response
<b>LIBRARY</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Recessed Mounted</b>	
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	85
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Lighting Fixture - HID</b>	
Instance on Room 446	Inspected
<b>Pendant Mounted</b>	Does not Exist
Instance on Room 446	Does not Exist
<b>Surface Mounted</b>	Does not Exist
Instance on Room 446	Does not Exist
<b>Recessed Mounted</b>	Inspected
Instance on Room 446	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 446	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on Room 446	Does not Exist
<b>Raceway With Receptacles</b>	Inspected
Instance on Room 446	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Projection System</b>	Does not Exist
Instance on Room 446	Does not Exist
<b>LOCKER ROOM</b>	Inspected
Instance on 1st Floor - Boys, 1st Floor - Girls	Inspected
Alternative use	No
Instance on 2nd Floor - Boys, 2nd Floor - Girls	Inspected
Alternative use	No
Instance on 2nd Floor - Visitors	Inspected
Alternative use	No
Instance on 4th Floor - Girls, 4th Floor - Boys	Inspected
Alternative use	Yes
<b>Lighting</b>	Inspected
Instance on 4th Floor - Girls, 4th Floor - Boys	Inspected
Instance on 2nd Floor - Visitors	Inspected
Instance on 2nd Floor - Boys, 2nd Floor - Girls	Inspected
Instance on 1st Floor - Boys, 1st Floor - Girls	Inspected
<b>Lighting Fixture - Fluorescent</b>	

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q452

Question	Response
<b>LOCKER ROOM</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
Instance on 4th Floor - Girls, 4th Floor - Boys	Inspected
Instance on 2nd Floor - Visitors	Inspected
Instance on 2nd Floor - Boys, 2nd Floor - Girls	Inspected
Instance on 1st Floor - Boys, 1st Floor - Girls	Inspected
<b>Pendant Mounted</b>	Inspected
Instance on 4th Floor - Girls, 4th Floor - Boys	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	64
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on 2nd Floor - Visitors	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on 2nd Floor - Boys, 2nd Floor - Girls	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	64
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on 1st Floor - Boys, 1st Floor - Girls	Does not Exist
<b>Surface Mounted</b>	Does not Exist
Instance on 4th Floor - Girls, 4th Floor - Boys	Does not Exist
Instance on 2nd Floor - Visitors	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q452

Question	Response
<b>LOCKER ROOM</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Surface Mounted</b>	
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on 2nd Floor - Boys, 2nd Floor - Girls	Does not Exist
Instance on 1st Floor - Boys, 1st Floor - Girls	Does not Exist
<b>Recessed Mounted</b>	
Instance on 4th Floor - Girls, 4th Floor - Boys	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	16
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on 2nd Floor - Visitors	Does not Exist
Instance on 2nd Floor - Boys, 2nd Floor - Girls	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	16
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on 1st Floor - Boys, 1st Floor - Girls	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	26
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Lighting Fixture - HID</b>	
Instance on 4th Floor - Girls, 4th Floor - Boys	Does not Exist
Instance on 2nd Floor - Visitors	Does not Exist
Instance on 2nd Floor - Boys, 2nd Floor - Girls	Does not Exist
Instance on 1st Floor - Boys, 1st Floor - Girls	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on 4th Floor - Girls, 4th Floor - Boys	Inspected
Instance on 2nd Floor - Visitors	Does not Exist

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q452

Question	Response
<b>LOCKER ROOM</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Incandescent</b>	
Instance on 2nd Floor - Boys, 2nd Floor - Girls	Inspected
Instance on 1st Floor - Boys, 1st Floor - Girls	Inspected
<b>Pendant Mounted</b>	Does not Exist
Instance on 4th Floor - Girls, 4th Floor - Boys	Does not Exist
Instance on 2nd Floor - Boys, 2nd Floor - Girls	Does not Exist
Instance on 1st Floor - Boys, 1st Floor - Girls	Does not Exist
<b>Surface Mounted</b>	Inspected
Instance on 4th Floor - Girls, 4th Floor - Boys	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on 2nd Floor - Boys, 2nd Floor - Girls	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on 1st Floor - Boys, 1st Floor - Girls	Does not Exist
<b>Recessed Mounted</b>	Does not Exist
Instance on 4th Floor - Girls, 4th Floor - Boys	Does not Exist
Instance on 2nd Floor - Boys, 2nd Floor - Girls	Does not Exist
Instance on 1st Floor - Boys, 1st Floor - Girls	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - LED</b>	
Instance on 4th Floor - Girls, 4th Floor - Boys	Does not Exist
Instance on 2nd Floor - Visitors	Does not Exist
Instance on 2nd Floor - Boys, 2nd Floor - Girls	Does not Exist
Instance on 1st Floor - Boys, 1st Floor - Girls	Does not Exist
<b>MULTIPURPOSE ROOM</b>	Does not Exist
<b>SCIENCE DEMO ROOM</b>	Inspected
Instance on Room 603	Inspected
Power Panel	No
Alternative use	No
Instance on Rooms 661, 662, 663, 682, 684	Inspected
Power Panel	No
Alternative use	No
Instance on Rooms 673, 675	Inspected
Power Panel	No
Alternative use	No
<b>Lighting</b>	Inspected
Instance on Rooms 673, 675	Inspected
Instance on Rooms 661, 662, 663, 682, 684	Inspected
Instance on Room 603	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Rooms 673, 675	Inspected
Instance on Rooms 661, 662, 663, 682, 684	Inspected
Instance on Room 603	Inspected
<b>Pendant Mounted</b>	Does not Exist
Instance on Rooms 673, 675	Does not Exist

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q452

Question	Response
<b>SCIENCE DEMO ROOM</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Pendant Mounted</b>	Does not Exist
Instance on Rooms 661, 662, 663, 682, 684	Does not Exist
Instance on Room 603	Does not Exist
<b>Surface Mounted</b>	Does not Exist
Instance on Rooms 673, 675	Does not Exist
Instance on Rooms 661, 662, 663, 682, 684	Does not Exist
Instance on Room 603	Does not Exist
<b>Recessed Mounted</b>	Inspected
Instance on Rooms 673, 675	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	30
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Rooms 661, 662, 663, 682, 684	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	60
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room 603	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	20
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Lighting Fixture - HID</b>	
Instance on Rooms 673, 675	Does not Exist
Instance on Rooms 661, 662, 663, 682, 684	Does not Exist
Instance on Room 603	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Rooms 673, 675	Inspected
Instance on Rooms 661, 662, 663, 682, 684	Inspected
Instance on Room 603	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q452

Question	Response
<b>SCIENCE DEMO ROOM</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Incandescent</b>	
<b>Pendant Mounted</b>	Does not Exist
Instance on Rooms 673, 675	Does not Exist
Instance on Rooms 661, 662, 663, 682, 684	Does not Exist
Instance on Room 603	Does not Exist
<b>Surface Mounted</b>	Does not Exist
Instance on Rooms 673, 675	Does not Exist
Instance on Rooms 661, 662, 663, 682, 684	Does not Exist
Instance on Room 603	Does not Exist
<b>Recessed Mounted</b>	Inspected
Instance on Rooms 673, 675	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 661, 662, 663, 682, 684	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 603	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - LED</b>	
Instance on Rooms 673, 675	Does not Exist
Instance on Rooms 661, 662, 663, 682, 684	Does not Exist
Instance on Room 603	Does not Exist
<b>Emergency Gas Shut-Off Valve</b>	Inspected
Instance on Rooms 673, 675	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 661, 662, 663, 682, 684	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 603	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Emergency Shut-Off Power</b>	Does not Exist
Instance on Rooms 673, 675	Does not Exist
Instance on Rooms 661, 662, 663, 682, 684	Does not Exist
Instance on Room 603	Does not Exist
<b>Power Supply</b>	Inspected
Instance on Rooms 673, 675	Inspected
Instance on Rooms 661, 662, 663, 682, 684	Inspected
Instance on Room 603	Inspected
<b>Instructor Unit</b>	
Instance on Rooms 673, 675	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 661, 662, 663, 682, 684	Inspected
Condition	3 - Fair

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q452

Question	Response
<b>SCIENCE DEMO ROOM</b>	
<b>Power Supply</b>	
<b>Instructor Unit</b>	
Deficiency	No deficiencies recorded
Instance on Room 603	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Meter Demonstration Unit</b>	
Instance on Rooms 673, 675	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 661, 662, 663, 682, 684	Does not Exist
Instance on Room 603	Does not Exist
<b>Projection System</b>	
	Does not Exist
Instance on Rooms 673, 675	Does not Exist
Instance on Rooms 661, 662, 663, 682, 684	Does not Exist
Instance on Room 603	Does not Exist
<b>SCIENCE LAB</b>	Inspected
Instance on Room 608	Inspected
Power Panel Alternative use	Yes No
Instance on Room 668	Inspected
Power Panel Alternative use	Yes No
Instance on Room 680	Inspected
Power Panel Alternative use	Yes No
<b>Lighting</b>	Inspected
Instance on Room 680	Inspected
Instance on Room 668	Inspected
Instance on Room 608	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 680	Inspected
Instance on Room 668	Inspected
Instance on Room 608	Inspected
<b>Pendant Mounted</b>	
	Does not Exist
Instance on Room 680	Does not Exist
Instance on Room 668	Does not Exist
Instance on Room 608	Does not Exist
<b>Surface Mounted</b>	
	Does not Exist
Instance on Room 680	Does not Exist
Instance on Room 668	Does not Exist
Instance on Room 608	Does not Exist
<b>Recessed Mounted</b>	
	Inspected
Instance on Room 680	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	15
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE



**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q452

Question	Response
<b>SCIENCE LAB</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Recessed Mounted</b>	
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room 668	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	16
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance on Room 608	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	18
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Lighting Fixture - HID</b>	
Instance on Room 680	Does not Exist
Instance on Room 668	Does not Exist
Instance on Room 608	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 680	Inspected
Instance on Room 668	Inspected
Instance on Room 608	Inspected
<b>Pendant Mounted</b>	
Instance on Room 680	Does not Exist
Instance on Room 668	Does not Exist
Instance on Room 608	Does not Exist
<b>Surface Mounted</b>	
Instance on Room 680	Does not Exist
Instance on Room 668	Does not Exist
Instance on Room 608	Does not Exist
<b>Recessed Mounted</b>	
Instance on Room 680	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q452

Question	Response
<b>SCIENCE LAB</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Incandescent</b>	
<b>Recessed Mounted</b>	
Instance on Room 668	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 608	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - LED</b>	
Instance on Room 680	Does not Exist
Instance on Room 668	Does not Exist
Instance on Room 608	Does not Exist
<b>Emergency Gas Shut-Off Valve</b>	
Instance on Room 680	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 668	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 608	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Emergency Shut-Off Power</b>	
Instance on Room 680	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 668	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 608	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Power Supply</b>	
Instance on Room 680	Inspected
Instance on Room 668	Inspected
Instance on Room 608	Inspected
<b>Instructor Unit</b>	
Instance on Room 680	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 668	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 608	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Meter Demonstration Unit</b>	
Instance on Room 680	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q452

Question	Response
<b>SCIENCE LAB</b>	
<b>Power Supply</b>	
<b>Meter Demonstration Unit</b>	
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 668	Does not Exist
Instance on Room 608	Does not Exist
<b>Student Unit</b>	
Instance on Room 680	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 668	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 608	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Projection System</b>	Does not Exist
Instance on Room 680	Does not Exist
Instance on Room 668	Does not Exist
Instance on Room 608	Does not Exist
<b>SCIENCE PREP ROOM</b>	
Instance on Room 602	Inspected
Power Panel Alternative use	No No
Instance on Room 674	Inspected
Power Panel Alternative use	No No
<b>Lighting</b>	Inspected
Instance on Room 674	Inspected
Instance on Room 602	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on Room 674	Inspected
Instance on Room 602	Inspected
<b>Pendant Mounted</b>	Does not Exist
Instance on Room 674	Does not Exist
Instance on Room 602	Does not Exist
<b>Surface Mounted</b>	Does not Exist
Instance on Room 674	Does not Exist
Instance on Room 602	Does not Exist
<b>Recessed Mounted</b>	Inspected
Instance on Room 674	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	19
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q452

Question	Response
<b>SCIENCE PREP ROOM</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	
<b>Recessed Mounted</b>	
Violations	No violations recorded.
Instance on Room 602	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	18
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Lighting Fixture - HID</b>	
Instance on Room 674	Does not Exist
Instance on Room 602	Does not Exist
<b>Lighting Fixture - Incandescent</b>	
Instance on Room 674	Inspected
Instance on Room 602	Does not Exist
<b>Pendant Mounted</b>	
Instance on Room 674	Does not Exist
<b>Surface Mounted</b>	
Instance on Room 674	Does not Exist
<b>Recessed Mounted</b>	
Instance on Room 674	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Lighting Fixture - LED</b>	
Instance on Room 674	Does not Exist
Instance on Room 602	Does not Exist
<b>Emergency Gas Shut-Off Valve</b>	
Instance on Room 674	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 602	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Emergency Shut-Off Power</b>	
Instance on Room 674	Does not Exist
Instance on Room 602	Does not Exist

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q452

Question	Response
<b>SCIENCE PREP ROOM</b>	
<b>Power Supply</b>	Inspected
Instance on Room 674	Inspected
Instance on Room 602	Inspected
<b>Instructor Unit</b>	
Instance on Room 674	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 602	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>SWIMMING POOL</b>	Inspected
Instance on 1st Floor	Inspected
<b>Lighting</b>	Inspected
Instance on 1st Floor	Inspected
<b>Lighting Fixture - Fluorescent</b>	
Instance on 1st Floor	Inspected
<b>Pendant Mounted</b>	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Surface Mounted</b>	Inspected
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	11
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Recessed Mounted</b>	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Lighting Fixture - HID</b>	
Instance on 1st Floor	Inspected
<b>Pendant Mounted</b>	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Surface Mounted</b>	Inspected
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Recessed Mounted</b>	Does not Exist
Instance on 1st Floor	Does not Exist

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q452

Question	Response
<b>SWIMMING POOL</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Incandescent</b>	
Instance on 1st Floor	Does not Exist
<b>Lighting Fixture - LED</b>	
Instance on 1st Floor	Inspected
<b>Pendant Mounted</b>	Inspected
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Surface Mounted</b>	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Recessed Mounted</b>	Does not Exist
Instance on 1st Floor	Does not Exist
<b>Local Sound System</b>	Inspected
Instance on 1st Floor	Inspected
Installation Year	1995
Source of Installation	Documented
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Scoreboard</b>	Inspected
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>TOILET ROOM - STAFF</b>	Inspected
<b>Lighting</b>	Inspected
<b>Lighting Fixture - Fluorescent</b>	Inspected
<b>Pendant Mounted</b>	Does not Exist
<b>Surface Mounted</b>	Does not Exist
<b>Recessed Mounted</b>	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	45
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Lighting Fixture - HID</b>	Does not Exist
<b>Lighting Fixture - Incandescent</b>	Inspected
<b>Pendant Mounted</b>	Does not Exist
<b>Surface Mounted</b>	Does not Exist
<b>Recessed Mounted</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Lighting Fixture - LED</b>	Does not Exist
<b>TOILET ROOM - STUDENT</b>	Inspected
<b>Lighting</b>	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q452

Question	Response
<b>TOILET ROOM - STUDENT</b>	
<b>Lighting</b>	
<b>Lighting Fixture - Fluorescent</b>	Inspected
<b>Pendant Mounted</b>	Does not Exist
<b>Surface Mounted</b>	Does not Exist
<b>Recessed Mounted</b>	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	169
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>Lighting Fixture - HID</b>	Does not Exist
<b>Lighting Fixture - Incandescent</b>	Does not Exist
<b>Lighting Fixture - LED</b>	Does not Exist
<b>AUXILIARY SIGNAL/BELL SYSTEM</b>	Inspected
Replacement Quantity	380,000
Replacement Uom	S.F.
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>EMERGENCY DC STANDBY BATTERY POWER</b>	Does not Exist
<b>EMERGENCY GENERATOR SET</b>	Inspected
<b>Automatic Transfer Switch (ATS)</b>	Inspected
Instance	Electrical Switchgear Room B56
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	ASCO
Equipment	ATS #3 (FIRE ALARM SYSTEM AUTOMATIC TRANSFER SWITCH)
Capacity/Size Quantity	70
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1995
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Fire Pump Room B44A (Inside Water Meter Room B44)
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Firetrol
Equipment	ATS # 4
Capacity/Size Quantity	60
Capacity/Size UOM	HP
Source of Capacity/Size	Nameplate
Installation Year	1995

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q452

Question	Response
<b>EMERGENCY GENERATOR SET</b>	
<b>Automatic Transfer Switch (ATS)</b>	
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Penthouse - Generator Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	ASCO
Equipment	ATS #1
Capacity/Size Quantity	1,000
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1995
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Penthouse - Generator Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	ASCO
Equipment	ATS # 2
Capacity/Size Quantity	400
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1995
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>Battery Charger</b>	Inspected
Instance	Penthouse - Generator Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Charles Industries
Equipment	Battery Charger
Capacity/Size Quantity	10
Capacity/Size UOM	AmpsDC
Capacity/Size2 Quantity	24
Capacity/Size2 UOM	VDC
Source of Capacity/Size	Nameplate
Installation Year	1995
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>Emergency Distribution Board</b>	Inspected
Number of Spares	0
<b>Fused Disconnect Switch Type</b>	Inspected
Instance	Penthouse - Generator Room
Instance Condition	3 - Fair
Instance Quantity	1



**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q452

Question	Response
<b>EMERGENCY GENERATOR SET</b>	
<b>Emergency Distribution Board</b>	
<b>Fused Disconnect Switch Type</b>	
Instance Quantity Uom	EACH
Instance Manufacturer	General Electric
Equipment	DP-GEN
Capacity/Size Quantity	1,600
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	1
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Nameplate
Installation Year	1995
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>Molded Case Circuit Breaker Type</b>	Does not Exist
<b>Diesel</b>	Inspected
Instance	Penthouse - Generator Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Caterpillar
Equipment	Emergency Generator
Capacity/Size Quantity	1,000
Capacity/Size UOM	KVA
Capacity/Size2 Quantity	800
Capacity/Size2 UOM	KW
Capacity/Size3Quantity	1,202
Capacity/Size3 UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1995
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>Natural Gas</b>	Does not Exist
<b>EMERGENCY LIGHT/EXIT LIGHT PANEL</b>	Does not Exist
<b>EMERGENCY LIGHTING</b>	Inspected
<b>Battery Pack</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Non Battery Pack</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>EXIT LIGHT</b>	Inspected
<b>Battery Pack</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Non Battery Pack</b>	Inspected
Condition	3 - Fair
Deficiency	FIXTURE LAMP NOT OPERATIONAL

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q452

Question	Response
<b>EXIT LIGHT</b>	
<b>Non Battery Pack</b>	
Deficiency Location/Instance	Penthouse, 2nd Floor - Gymnasium, 2nd Floor - Locker Room (Boys, Girls)
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 4
Deficiency Photo1	No photo recorded
Violations	35663197H
<b>EXIT/EMERGENCY LIGHT</b>	Does not Exist
<b>FIRE ALARM SYSTEM</b>	Inspected
Replacement Quantity	380,000
Replacement Uom	S.F.
<b>Bell/Horn</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Strobe</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Manual Pull Station</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Fan Shutdown Control</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Duct Smoke Detector</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Area Smoke Detector</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>CO Detector</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Heat Detector</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Elevator Recall</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Magnetic Door Holder/Contactor</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Fused Cutout Panel</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Fire Alarm Digital Communicator</b>	Does not Exist
<b>Main Panel</b>	Inspected
<b>Bell At Panel</b>	Does not Exist

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q452

Question	Response
<b>FIRE ALARM SYSTEM</b>	
<b>Main Panel</b>	
<b>Fire Alarm Control Panel (Electronic)</b>	Inspected
Instance	Main Entrance Lobby
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Edwards System Technology
Equipment	Fire Alarm Command Center
Model	EST 3
Installation Year	2018
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded
<b>Fire Alarm Control Panel (Standard)</b>	Does not Exist
<b>Sub-Panel</b>	
<b>Bell At Panel</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Fire Alarm Control Panel (Electronic)</b>	Inspected
Instance	Auditorium Stage - Room 163H (Inside Room 163G)
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Notifier
Equipment	Deluge System Control Panel
Model	RP - 1001
Installation Year	1995
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Custodian's Office
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Altronix
Equipment	Door Holder Control Panel
Model	N/A
Installation Year	1995
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>Fire Alarm Control Panel (Standard)</b>	Does not Exist
<b>Remote Annunciator</b>	
<b>Display Monitor</b>	Does not Exist
<b>Panel</b>	
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Printer</b>	
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Punch Register</b>	Does not Exist

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q452

Question	Response
<b>FIRE ALARM SYSTEM</b>	
<b>Sprinkler Flow/Air Pressure Switch</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Tamper Flow Switch/Chain</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>GROUNDING SYSTEM</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>INTERCOM SYSTEM</b>	Inspected
<b>Elevator</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Holding Area</b>	Does not Exist
<b>LAN</b>	Inspected
<b>Local Distribution Frame (I/LDF)</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Main Equipment Rack (MDF)</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>LIGHTNING PROTECTION</b>	Under Construction
<b>MOTOR CONTROLLER</b>	Inspected
<b>Motor Control Center</b>	Inspected
Instance	Penthouse
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Cutler Hammer
Equipment	MCC-EP
Capacity/Size Quantity	1,200
Capacity/Size UOM	Amps
Capacity/Size2 Quantity	14
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Nameplate
Installation Year	1995
Source of Installation	Documented
Deficiency	MCC PUSH BUTTON NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Instance	Penthouse
Instance Condition	3 - Fair
Instance Quantity	1

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q452

Question	Response
<b>MOTOR CONTROLLER</b>	
<b>Motor Control Center</b>	
Instance Quantity Uom	EACH
Instance Manufacturer	Cutler Hammer
Equipment	MCC-PA
Capacity/Size Quantity	1,200
Capacity/Size UOM	Amps
Capacity/Size2 Quantity	11
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Nameplate
Installation Year	1995
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Penthouse
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Cutler Hammer
Equipment	MCC-PB
Capacity/Size Quantity	1,200
Capacity/Size UOM	Amps
Capacity/Size2 Quantity	11
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Nameplate
Installation Year	1995
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>Motor Starter/Contactor</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Variable Frequency Drive</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>PANEL BOARD</b>	Inspected
<b>Fused Disconnect Switch Type</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Fused Knife Switch Type</b>	Does not Exist
<b>Fused Toggle Switch Type</b>	Does not Exist
<b>Molded Case Circuit Breaker Type</b>	Inspected
Condition	3 - Fair
Deficiency	NO SPARE
Deficiency Location/Instance	Kitchen
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL NEW PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q452

Question	Response
<b>PANEL BOARD</b>	
<b>Molded Case Circuit Breaker Type</b>	
Violations	No violations recorded.
Deficiency	PANEL BOARD COVER IS MISSING
Deficiency Location/Instance	Rooms 181, 562
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL BOARD COVER IS MISSING
Deficiency Location/Instance	Electrical Closet Rooms (266, 293)
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>PUBLIC ADDRESS SYSTEM</b>	Inspected
Replacement Quantity	380,000
Replacement Uom	S.F.
Instance	Room 110B (Inside Assistant Principal's Office - Room 110)
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Dukane 250
Installation Year	1995
Source of Installation	Documented
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Classrooms and Corridors
Deficiency Quantity	45
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	MASTER CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Room 110B (Inside Assistant Principal's Office - Room 110)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q452

Question	Response
<b>SECURITY</b>	Inspected
<b>IPDVS/CCTV System</b>	Inspected
Replacement Quantity	380,000
Replacement Uom	S.F.
Installation Year	2020
Source of Installation	Custodial Staff
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Intrusion Alarm System</b>	Inspected
Replacement Quantity	380,000
Replacement Uom	S.F.
<b>Central Control Panel</b>	Inspected
Instance	Custodian's Office
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista-50P
Installation Year	1995
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>Infrared Sensor</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Panic Switch</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Remote Annunciator</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Siren/Strobe</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Lighting - Security</b>	Inaccessible
<b>SERVICE SWITCH</b>	Inspected
Instance	Electrical Switchgear Room B56
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Gallagher
Equipment	Main Switch
Capacity/Size Quantity	4,000
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1995
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Switchgear Room B56
Instance Condition	3 - Fair
Instance Quantity	1

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q452

Question	Response
<b>SERVICE SWITCH</b>	
Instance Quantity Uom	EACH
Instance Manufacturer	Gallagher
Equipment	2000A Bus Duct
Capacity/Size Quantity	2,000
Capacity/Size UOM	Amps
Source of Capacity/Size	Fuse Size
Installation Year	1995
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Switchgear Room B56
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Gallagher
Equipment	Fire Pump
Capacity/Size Quantity	1,200
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1995
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Switchgear Room B56
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Gallagher
Equipment	MCC-PA
Capacity/Size Quantity	800
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1995
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Switchgear Room B56
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Gallagher
Equipment	Spare
Capacity/Size Quantity	800
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1995
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Switchgear Room B56
Instance Condition	3 - Fair
Instance Quantity	1



**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q452

Question	Response
<b>SERVICE SWITCH</b>	
Instance Quantity Uom	EACH
Instance Manufacturer	Gallagher
Equipment	Refrigeration Machine R1
Capacity/Size Quantity	800
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1995
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>SWITCHBOARD</b>	
	Inspected
Number of Spares	2
<b>Fused Disconnect Switch Type</b>	
	Inspected
Instance	Electrical Switchgear Room B56
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Gallagher Switchboard Co.
Equipment	N/A
Capacity/Size Quantity	4,000
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	3
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Nameplate
Installation Year	1995
Source of Installation	Documented
Deficiency	No deficiencies recorded
<b>Fused Knife Switch Type</b>	
	Does not Exist
<b>Molded Case Circuit Breaker Type</b>	
	Does not Exist
<b>TELEPHONE SYSTEM</b>	
	Inspected
<b>PBX/Intercom</b>	
	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>Standard</b>	
	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>TRANSFORMER</b>	
	Inspected
Instance	Auditorium Stage - Dimming System Room 163F
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Liebert
Equipment	N/A
Capacity/Size Quantity	75
Capacity/Size UOM	KVA
Source of Capacity/Size	Nameplate
Installation Year	1995
Source of Installation	Documented
Deficiency	No deficiencies recorded

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q452

Question	Response
<b>TRANSFORMER</b>	
Instance	Electrical Switchgear Room B56
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Magnetek
Equipment	Fire Alarm System Transformer
Capacity/Size Quantity	45
Capacity/Size UOM	KVA
Source of Capacity/Size	Nameplate
Installation Year	1995
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Switchgear Room B56
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Magnetek
Equipment	500KVA X FORMER TO AUDITORIUM
Capacity/Size Quantity	500
Capacity/Size UOM	KVA
Source of Capacity/Size	Nameplate
Installation Year	1995
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Switchgear Room B56, Penthouse - Next to Elevator Machine Room
Instance Condition	3 - Fair
Instance Quantity	2
Instance Quantity Uom	EACH
Instance Manufacturer	Magnetek
Equipment	N/A
Capacity/Size Quantity	75
Capacity/Size UOM	KVA
Source of Capacity/Size	Nameplate
Installation Year	1995
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Penthouse - Next to Generator Room
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Rex Power Magnetics
Equipment	N/A
Capacity/Size Quantity	75
Capacity/Size UOM	KVA
Source of Capacity/Size	Nameplate
Installation Year	2016
Source of Installation	Inspector Estimate

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q452

Question	Response
<b>TRANSFORMER</b>	
Deficiency	No deficiencies recorded
Instance	Penthouse - Next to Generator Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Magnetek
Equipment	N/A
Capacity/Size Quantity	45
Capacity/Size UOM	KVA
Source of Capacity/Size	Nameplate
Installation Year	1995
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Room 281
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Olsun Electric
Equipment	N/A
Capacity/Size Quantity	45
Capacity/Size UOM	KVA
Source of Capacity/Size	Nameplate
Installation Year	1995
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Room 581
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Magnetek
Equipment	N/A
Capacity/Size Quantity	30
Capacity/Size UOM	KVA
Source of Capacity/Size	Nameplate
Installation Year	1995
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Rooms 181, 281, 481, 681
Instance Condition	3 - Fair
Instance Quantity	4
Instance Quantity Uom	EACH
Instance Manufacturer	Magnetek
Equipment	N/A
Capacity/Size Quantity	225
Capacity/Size UOM	KVA
Source of Capacity/Size	Nameplate
Installation Year	1995
Source of Installation	Documented

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Electrical Inspection

Q452

Question	Response
<b>TRANSFORMER</b>	
Deficiency	No deficiencies recorded
Instance	Rooms 381, 581
Instance Condition	3 - Fair
Instance Quantity	2
Instance Quantity Uom	EACH
Instance Manufacturer	Magnetek
Equipment	N/A
Capacity/Size Quantity	300
Capacity/Size UOM	KVA
Source of Capacity/Size	Nameplate
Installation Year	1995
Source of Installation	Documented
Deficiency	No deficiencies recorded