## **Building Condition Assessment Survey 2023 - 2024**

Inspection Id	1356 Inspection Type	e				Time In	Last Edited
EE : Q454	Electrical					2023-11-01 12:53 PM	2023-11-07 11:46 AM
Asset Data							
Question					Answer		
Type of Service					Below Gro	ound	
Does Interactive V	Whiteboard (IWB)	) Exist?			Yes		
Water Penetration	in Electrical Roo	om?			No		
Have any Systems	Major Building	Components	been upgraded?		Yes		
					Systems:	Interior Fluorescent Lighting, A System, Partial Emergency Ligh Exit Lights (Battery Pack), Mos Fire Alarm System (Main Panel Detector, Remote Annunciator). Telephone System, Lightning P System, IPDVS/CCTV System, Alarm System	ating (Battery Pack), Most t Exit/Emergency Light, , Manual Pull Station, CO Grounding System, LAN rotection, Public Address
					Years:	2017	
					Systems:	Fire Alarm System	
					Years:	2010	
					Systems:	Students Toilet Rooms (Surface	Fluorescent Lighting)
					Years:	2000, 2017	
					Systems:	Most Molded Case Circuit Brea	ker Type Panel Board
					Years:	2000, 2016	
					Systems:	Gymnasium (Fluorescent Lighti	ng, HID Lighting)
					Years:	2000	
					Systems:	Security Lights	
					Years:	1995	
DEDICATED IN	TERCOMS IN I	FIRE RESC	UE AREAS				
Question  Are there any Life	e Rescue Assistat	oce Areas Fir	re Rescue Areas		Response No		
and/or Holding R			Te Research Freus,				
Priority Condition							
Priority Priority Condition Exist Cat Last Year?	•	ondition escription	Component Affected	Location Description	Person(s) Notified	Person(s) Title Status	PhotoImage
	d						
No condition recorded							
					Respons	se	
Inspection					Respons	se	
Inspection  Question					Respons  Does no		
Inspection Question Electrical					<u> </u>	t Exist	
Inspection Question Electrical AUDITORIUM	ORRIDOR/AD	MINISTRA'	FIVE SPACE		Does no	t Exist t Exist	
Inspection  Question  Electrical  AUDITORIUM  CAFETERIA  CLASSROOM/C	ORRIDOR/AD!	MINISTRA'	TIVE SPACE		Does no Does no Inspecte	t Exist t Exist d	
Inspection  Question  Electrical  AUDITORIUM  CAFETERIA  CLASSROOM/C  Lighting	CORRIDOR/AD! Chandelier exist?		TIVE SPACE		Does no	t Exist t Exist d	
Inspection Question Electrical AUDITORIUM CAFETERIA CLASSROOM/C Lighting Does a	Chandelier exist?	?	ΓIVE SPACE		Does no Does no Inspecte Inspecte No	t Exist t Exist d	
Inspection  Question  Electrical  AUDITORIUM  CAFETERIA  CLASSROOM/C  Lighting  Does a  Lighting Fixt	Chandelier exist?	?	TIVE SPACE		Does no Does no Inspecte No Inspecte	t Exist t Exist d d	
Inspection Question Electrical AUDITORIUM CAFETERIA CLASSROOM/C Lighting Does a	Chandelier exist? ture - Fluorescen Iounted	?	FIVE SPACE		Does no Does no Inspecte Inspecte No Inspecte Inspecte	t Exist t Exist d d	
Inspection  Question  Electrical  AUDITORIUM  CAFETERIA  CLASSROOM/C  Lighting  Does a  Lighting Fixt  Pendant M	Chandelier exist? ture - Fluorescen Iounted n	?	TIVE SPACE		Does no Does no Inspecte Inspecte No Inspecte 2 - Betw	t Exist t Exist d d d	
Inspection  Question  Electrical  AUDITORIUM  CAFETERIA  CLASSROOM/C  Lighting  Does a  Lighting Fixt  Pendant M  Condition	Chandelier exist? ture - Fluorescen founted n	?	TIVE SPACE		Does no Does no Inspecte Inspecte No Inspecte 2 - Betw	t Exist t Exist d d d d een Good and Fair iencies recorded	
Inspection  Question  Electrical  AUDITORIUM  CAFETERIA  CLASSROOM/C  Lighting  Does a  Lighting Fixt  Pendant M  Condition  Deficie	Chandelier exist? ture - Fluorescen Iounted n incy ounted	?	TIVE SPACE		Does no Does no Inspecte Inspecte No Inspecte 2 - Betw No defic Inspecte	t Exist t Exist d d d d een Good and Fair iencies recorded	
Inspection  Question  Electrical  AUDITORIUM  CAFETERIA  CLASSROOM/C  Lighting  Does a  Lighting Fixt  Pendant M  Condition  Deficie  Surface Mo	Chandelier exist? ture - Fluorescen Iounted n ency ounted n	?	TIVE SPACE		Does no Does no Inspecte Inspecte No Inspecte 2 - Betw No defic Inspecte 2 - Betw	t Exist t Exist d d d d deen Good and Fair	

## **Building Condition Assessment Survey 2023 - 2024**

uestion	Response	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE		
Lighting		
Lighting Fixture - HID	Does not Exist	
Lighting Fixture - Incandescent	Does not Exist	
Lighting Fixture - LED	Does not Exist	
COMPUTER LAB	Does not Exist	
GYMNASIUM	Inspected	
Instance on Basement	Inspected	
Lighting	Inspected	
Instance on Basement	Inspected	
Lighting Fixture - Fluorescent	•	
Instance on Basement	Inspected	
Pendant Mounted	Does not Exist	
Instance on Basement	Does not Exist	
Surface Mounted	Inspected	
Instance on Basement	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not Exist	
Instance on Basement	Does not Exist	
Lighting Fixture - HID		
Instance on Basement	Inspected	
Pendant Mounted	Inspected	
Instance on Basement	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Does not Exist	
Instance on Basement	Does not Exist	
Recessed Mounted	Does not Exist	
Instance on Basement	Does not Exist	
Lighting Fixture - Incandescent		
Instance on Basement	Inspected	
Pendant Mounted	Inspected	-
Instance on Basement	Inspected	
Condition	3 - Fair	
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE	
Deficiency Quantity	3	
Quantity Uom	EACH	
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
Surface Mounted	Does not Exist	
Instance on Basement	Does not Exist	
Recessed Mounted	Does not Exist	
Instance on Basement	Does not Exist	
Lighting Fixture - LED		

# **Building Condition Assessment Survey 2023 - 2024**

estion	Response
YMNASIUM	
Local Sound System	Does not Exist
Instance on Basement	Does not Exist
Projection System	Does not Exist
Instance on Basement	Does not Exist
Scoreboard	Inspected
Instance on Basement	Inspected
Condition	5 - Poor
Deficiency	NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Theater Lighting System	Inspected
Instance on Basement	Inspected
Dimming System	
Instance on Basement	Does not Exist
Theater Lighting	
Instance on Basement	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	18
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
ITCHEN	Inspected
Instance on 1st Floor	Inspected
Lighting	Inspected
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Surface Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not Exist

# **Building Condition Assessment Survey 2023 - 2024**

Question	Response
KITCHEN	Inspected
Lighting	
Lighting Fixture - LED	
Instance on 1st Floor	Does not Exist
LIBRARY	Does not Exist
LOCKER ROOM	Does not Exist
MULTIPURPOSE ROOM	Does not Exist
SCIENCE DEMO ROOM	Does not Exist
SCIENCE LAB	Does not Exist
SCIENCE PREP ROOM	Does not Exist
SWIMMING POOL	Does not Exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Replacement Quantity	14,500
Replacement Uom	S.F.
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not Exist
EMERGENCY GENERATOR SET	Does not Exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not Exist
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	2 - Between Good and Fair
Deficiency	BATTERY NOT OPERATIONAL
Deficiency Location/Instance	3rd Floor - Staircase B, 1st Floor Corridor by Rooms (105, 108), Basement
Deficiency Quantity	5

# **Building Condition Assessment Survey 2023 - 2024**

fieur inspection	
estion	Response
EMERGENCY LIGHTING	
Battery Pack	
Quantity Uom	EACH
Potential Action	REPLACE BATTERY
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Non Battery Pack	Does not Exist
EXIT LIGHT	Inspected
Battery Pack Condition	Inspected  2 - Between Good and Fair
Deficiency	BATTERY NOT OPERATIONAL
Deficiency Location/Instance	1st Floor Corridor by Rooms (105, 108), Gymnasium
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE BATTERY
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 4
Deficiency Photo1	No photo recorded
Violations	35643550L
Non Battery Pack	Does not Exist
EXIT/EMERGENCY LIGHT	Inspected
Condition	2 - Between Good and Fair
Deficiency	BATTERY NOT OPERATIONAL
Deficiency Location/Instance	1st Floor Corridor by Exit 2, Gymnasium
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE BATTERY
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 4
Deficiency Photo1	No photo recorded
Violations	35671986K
FIRE ALARM SYSTEM	Inspected
Replacement Quantity	14,500
Replacement Uom	S.F.
Bell/Horn	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Manual Pull Station	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Deficiency	
Duct Smoke Detector	Inspected
Fan Shutdown Control  Condition  Deficiency	Inspected  2 - Between Good and Fair  No deficiencies recorded

# **Building Condition Assessment Survey 2023 - 2024**

Response  Inspected No deficiencies recorded Inspected Property of the second of the s
No deficiencies recorded  nspected 2 - Between Good and Fair No deficiencies recorded nspected 2 - Between Good and Fair No deficiencies recorded nspected 2 - Between Good and Fair No deficiencies recorded nspected 2 - Between Good and Fair No deficiencies recorded
No deficiencies recorded  nspected 2 - Between Good and Fair No deficiencies recorded nspected 2 - Between Good and Fair No deficiencies recorded nspected 2 - Between Good and Fair No deficiencies recorded nspected 2 - Between Good and Fair No deficiencies recorded
nspected 2 - Between Good and Fair No deficiencies recorded nspected 2 - Between Good and Fair No deficiencies recorded nspected 2 - Between Good and Fair No deficiencies recorded nspected 2 - Between Good and Fair No deficiencies recorded
2 - Between Good and Fair No deficiencies recorded nspected 2 - Between Good and Fair No deficiencies recorded nspected 2 - Between Good and Fair No deficiencies recorded nspected 2 - Between Good and Fair No deficiencies recorded
No deficiencies recorded nspected 2 - Between Good and Fair No deficiencies recorded nspected 2 - Between Good and Fair No deficiencies recorded
nspected 2 - Between Good and Fair No deficiencies recorded nspected 2 - Between Good and Fair No deficiencies recorded
2 - Between Good and Fair No deficiencies recorded nspected 2 - Between Good and Fair No deficiencies recorded
No deficiencies recorded  nspected  - Between Good and Fair  No deficiencies recorded
nspected 2 - Between Good and Fair No deficiencies recorded
2 - Between Good and Fair No deficiencies recorded
No deficiencies recorded
Does not Exist
JOES HOT EXIST
Does not Exist
nspected
2 - Between Good and Fair
No deficiencies recorded
inspected
Boiler Room B10
2 - Between Good and Fair
EACH
Ademco
Central Office Communicator
2010
nspector Estimate
No deficiencies recorded
nspected
nspected
2 - Between Good and Fair
No deficiencies recorded
nspected
Main Entrance Lobby
2 - Between Good and Fair
EACH
Gamewell
Fire Alarm Control Panel
33 Series
2017
Documented
No deficiencies recorded
Does not Exist
Does not Exist
nspected
Does not Exist
nspected 2 - Between Good and Fair
2 - Between Good and Fair No deficiencies recorded

# **Building Condition Assessment Survey 2023 - 2024**

uestion	Response
FIRE ALARM SYSTEM	кезриве
Remote Annunciator	Inspected
Printer	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Punch Register	Does not Exist
Sprinkler Flow/Air Pressure Switch	Does not Exist
Tamper Flow Switch/Chain	Does not Exist
GROUNDING SYSTEM	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Does not Exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Does not Exist
Main Equipment Rack (MDF)	Inspected
Condition Deficiency	2 - Between Good and Fair  No deficiencies recorded
LIGHTNING PROTECTION	
Condition	Inspected  2 - Between Good and Fair
Deficiency	No deficiencies recorded
MOTOR CONTROLLER	Inspected
Motor Control Center	Does not Exist
Motor Starter/Contactor	
Condition	Inspected 3 - Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Does not Exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Does not Exist
Fused Knife Switch Type	Does not Exist
Fused Toggle Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Inspected
Condition	2 - Between Good and Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room B10, 2nd Floor Corridor by Room 202, 3rd Floor Corridor by Room 302
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
PUBLIC ADDRESS SYSTEM	Inspected
Replacement Quantity	14,500
Replacement Uom	S.F.
Instance	Telecom Room 203
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH

## **Building Condition Assessment Survey 2023 - 2024**

estion	Response
UBLIC ADDRESS SYSTEM	Inspected
Model	N/A
Installation Year	2017
Source of Installation	Documented
Deficiency	No deficiencies recorded
ECURITY	Inspected
IPDVS/CCTV System	Inspected
Replacement Quantity	14,500
Replacement Uom	S.F.
Installation Year	2017
Source of Installation	Documented
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Intrusion Alarm System	Inspected
Replacement Quantity	14,500
Replacement Uom	S.F.
Central Control Panel	Inspected
Instance	Custodian's Office
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista-128BPT
Installation Year	2017
Source of Installation	Documented  No deficiencies recorded
Deficiency Infrared Sensor	Inspected
Condition	2 - Between Good and Fair
Deficiency	SENSOR NOT OPERATIONAL
Deficiency Location/Instance	Basement
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
- <del></del>	
Panic Switch	Inspected
Condition	2 - Between Good and Fair
Deficiency Remote Annunciator	No deficiencies recorded
	Inspected 2 - Between Good and Fair
Condition	2 - Between Good and Fair  No deficiencies recorded
Deficiency Siren/Strobe	
Condition	Inspected  2 - Between Good and Fair
Deficiency	2 - Between Good and Fair  No deficiencies recorded
Lighting - Security	
Replacement Uom	Inspected EACH
Condition	3 - Fair
Condition	5 - Fair

# **Building Condition Assessment Survey 2023 - 2024**

nestion	Response
SERVICE SWITCH	Inspected
Instance	Electrical Room (Inside Boiler Room B10)
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Metropolitan
Equipment	Service Switch
Capacity/Size Quantity	400
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1962
Source of Installation	Documented
Deficiency	No deficiencies recorded
SWITCHBOARD	Inspected
Number of Spares	1
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room (Inside Boiler Room B10)
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Siemens
Equipment	MDP
Capacity/Size Quantity	400
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	1
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Service Switch Size
Installation Year	2017
Source of Installation	Documented
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Does not Exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
TRANSFORMER	Does not Exist