Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

Inspection I	d Inspection	Туре				Time In		Last Edited
EE : Q4	61 Electrical					2023-11-	-16 12:06 PM	2023-12-04 11:17 AM
Asset Data								
Question					Answer			
Type of Servi	ice				Below Grou	und		
Does Interact	ive Whiteboard (I	IWB) Exist?			Yes			
Water Penetra	ation in Electrical	Room?			No			
Have any Sys	Have any Systems/Major Building Components been upgraded?				Yes			
					Systems:	All Electrical Sy	stems and Comp	ponents
					Years:	2022		
	D INTERCOMS	S IN FIRE RESC	CUE AREAS					
Question	y Life Rescue Ass	sistance Areas Fi	re Rescue Areas		Response No			
and/or Holdi	ng Rooms in you		ie Reseue Areas,		110			
Priority Condit	ion							
Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
No	Water Leaks onto Electrical Equipment	Roof Leak	Lighting Fixture	Kitchen, Room 103B	Robert Albino	Cleaner	Sent to DSF	
Inspection								
Question					Respons	e		
Electrical								
AUDITORI	UM				Does not	Exist		
CAFETERIA				Does not	Exist			
CLASSROO	M/CORRIDOR	ADMINISTRA	TIVE SPACE		Inspected	1		
Lighting					Inspected	l		
Do	oes a Chandelier e	exist?			No			
Lighting	g Fixture - Fluore	escent			Does not	Exist		
Lighting	Fixture - HID				Does not	Exist		
Lighting	Fixture - Incano	descent			Does not	Exist		
Lighting	Fixture - LED			Inspected				
	nt Mounted				Inspected			
	dition				1 - Good			
	eficiency					encies recorded		
	e Mounted				Inspected	1		
Cone	dition				1 - Good			
De	eficiency				No defici	encies recorded		
Recess	sed Mounted				Inspected	l		
Cone	dition				1 - Good			
De	eficiency				No defici	encies recorded		
COMPUTE	R LAB				Does not	Exist		
GYMNASIU	M				Does not	Exist		
KITCHEN					Inspected	1		
Ins	stance on 1st Floo	or			Inspected	1		
Lighting					Inspected	1		
Ins	stance on 1st Floo	r			Inspected	1		
	Fixture - Fluore	scont						

Lighting Fixture - Fluorescent

Building Condition Assessment Survey 2023 - 2024

uestion	Response	
KITCHEN		
Lighting		
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Does not Exist	
Lighting Fixture - HID		
Instance on 1st Floor	Does not Exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not Exist	
Lighting Fixture - LED		
Instance on 1st Floor	Inspected	
Pendant Mounted	Does not Exist	
Instance on 1st Floor	Does not Exist	
Surface Mounted	Does not Exist	
Instance on 1st Floor	Does not Exist	
Recessed Mounted	Inspected	
Instance on 1st Floor	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
LIBRARY	Does not Exist	
LOCKER ROOM	Does not Exist	
MULTIPURPOSE ROOM	Does not Exist	
SCIENCE DEMO ROOM	Does not Exist	
SCIENCE LAB	Does not Exist	
SCIENCE PREP ROOM	Does not Exist	
SWIMMING POOL	Does not Exist	
TOILET ROOM - STAFF	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Does not Exist	
Lighting Fixture - HID	Does not Exist	
Lighting Fixture - Incandescent	Does not Exist	
Lighting Fixture - LED	Inspected	
Pendant Mounted	Does not Exist	
Surface Mounted	Does not Exist	
Recessed Mounted	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
TOILET ROOM - STUDENT	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Does not Exist	
Lighting Fixture - HID	Does not Exist	
Lighting Fixture - Incandescent	Does not Exist	
Lighting Fixture - LED	Inspected	
Pendant Mounted	Does not Exist	
Surface Mounted	Does not Exist	
Recessed Mounted Condition	Inspected	
Deficiency	1 - Good No deficiencies recorded	
AUXILIARY SIGNAL/BELL SYSTEM	no deficiencies recorded	

Building Condition Assessment Survey 2023 - 2024

uestion	Response	
AUXILIARY SIGNAL/BELL SYSTEM		
Replacement Quantity	12,000	
Replacement Uom	S.F.	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
EMERGENCY DC STANDBY BATTERY POWER	Does not Exist	
EMERGENCY GENERATOR SET	Does not Exist	
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not Exist	
EMERGENCY LIGHTING	Inspected	
Battery Pack	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Non Battery Pack	Does not Exist	
EXIT LIGHT	Inspected	
Battery Pack	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Non Battery Pack	Does not Exist	
EXIT/EMERGENCY LIGHT	Does not Exist	
FIRE ALARM SYSTEM	Inspected	
Replacement Quantity	12,000	
Replacement Uom	S.F.	
Bell/Horn	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Strobe	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Manual Pull Station	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Fan Shutdown Control	Does not Exist	
Duct Smoke Detector	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Area Smoke Detector	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
CO Detector	Does not Exist	
Heat Detector	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Elevator Recall	Does not Exist	
Magnetic Door Holder/Contactor	Does not Exist	
Fused Cutout Panel	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Fire Alarm Digital Communicator	Does not Exist	

Building Condition Assessment Survey 2023 - 2024

uestion	Response	
FIRE ALARM SYSTEM		
Main Panel		
Bell At Panel	Does not Exist	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Main Entrance Lobby	
Instance Condition	1 - Good	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Instance Quality com	Mircom	
Equipment	Fire Alarm Control Panel	
Model	FleX-Net	
Installation Year	2022	
Source of Installation	Documented	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Standard)	Does not Exist	
Sub-Panel	Does not Exist	
Remote Annunciator	Inspected	
Display Monitor	Does not Exist	
Panel	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Printer	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Punch Register	Does not Exist	
Sprinkler Flow/Air Pressure Switch	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Tamper Flow Switch/Chain	Inspected	
Condition	1 - Good	
Deficiency CROUNDING SWETEN	No deficiencies recorded	
GROUNDING SYSTEM Condition	Inspected 1 - Good	
Deficiency	No deficiencies recorded	
INTERCOM SYSTEM	Does not Exist	
LAN		
	Inspected	
Local Distribution Frame (I/LDF)	Inspected	
Condition	1 - Good No deficiencies recorded	
Deficiency Main Equipment Rack (MDF)		
Condition	Inspected 1 - Good	
Deficiency	No deficiencies recorded	
LIGHTNING PROTECTION	Does not Exist	
MOTOR CONTROLLER	Inspected	
Motor Control Center	Does not Exist	
Motor Starter/Contactor	Inspected	
Condition	1 - Good	
Deficiency Variable Frequency Drive	No deficiencies recorded Does not Exist	

(P)

Building Condition Assessment Survey 2023 - 2024

uestion	Response	
PANEL BOARD	Inspected	
Fused Disconnect Switch Type	Does not Exist	
Fused Knife Switch Type	Does not Exist	
Fused Toggle Switch Type	Does not Exist	
Molded Case Circuit Breaker Type	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
PUBLIC ADDRESS SYSTEM	Inspected	
Replacement Quantity	12,000	
Replacement Uom	S.F.	
Instance	Telecommunication Room 114	
Instance Condition	1 - Good	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Model	Bogen Multicom - 2000	
Installation Year	2022	
Source of Installation	Documented	
Deficiency	No deficiencies recorded	
SECURITY	Inspected	
IPDVS/CCTV System	Inspected	
Replacement Quantity	12,000	
Replacement Uom	S.F.	
Installation Year	2022	
Source of Installation	Documented	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Intrusion Alarm System	Inspected	
Replacement Quantity	12,000	
Replacement Uom	S.F.	
Central Control Panel	Inspected	
Instance	Room 111	
Instance Condition	1 - Good	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Model	Vista-128BPT	
Installation Year	2022	
Source of Installation	Documented	
Deficiency	No deficiencies recorded	
Infrared Sensor	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Panic Switch	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Remote Annunciator	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Siren/Strobe	Inspected	

Building Condition Assessment Survey 2023 - 2024

Response	
Inspected	
No deficiencies recorded	
Inspected	
EACH	
1 - Good	
No deficiencies recorded	
Inspected	
Electrical Room 101	
1 - Good	
1	
EACH	
Delta Metal Product	
Main Disconnect Switch	
1,200	
Amps	
Nameplate	
2022	
Documented	
No deficiencies recorded	
Inspected	
2	
Inspected	
Electrical Room 101	
1 - Good	
1	
EACH	
Delta Metal Product	
MDB	
1,200	
Amps Total	
2	
Section(S)	
Nameplate	
2022	
Documented	
No deficiencies recorded	
Does not Exist	
Does not Exist	
Inspected	
-	
1 - Good	
No deficiencies recorded	
Inspected	
1 - Good	
No deficiencies recorded	
	Inspected No deficiencies recorded Inspected EACH 1 - Good No deficiencies recorded Inspected Electrical Room 101 1 - Good Amps Nameplate 2022 Documented No deficiencies recorded Inspected 2 Inspected 2 Inspected 2 Inspected 2 Inspected 1 - Good 1 - Good 1 - Good 1 - Good 2 - Section(S) Nameplate 2022 Documented No deficiencies recorded Does not Exist Does not Exist Does not Exist Does not Ex

(P)