Building Condition Assessment Survey 2023 - 2024

lectrical Inspe	ection							Q48
Asset:	3K CENTE York, 11428		MAICA AVEN	UE - QUEEN	IS, 207-01 JAM	AICA AVENUE	, New	
Inspection I	d Inspection	Туре				Time In		Last Edited
EE : Q48	83 Electrical					2024-05	-17 11:34 AM	2024-05-23 2:02 PI
sset Data								
Question					Answer			
Type of Service	ce				Below Gro	und		
Does Interacti	ve Whiteboard (I	(WB) Exist?			Yes			
Water Penetra	tion in Electrical	Room?			No			
Have any Syst	tems/Major Build	ling Components	been upgraded?		Yes			
					Systems:	Intrusion Alarm	System	
					Years:	2022		
					Systems:	All Other Electri	cal Systems and	Components
					Years:	2020		
	DINTERCOMS	IN FIRE RESC	UE AREAS		D			
Question Are there any	Life Rescue Ass	sistance Areas, Fir	re Rescue Areas		Yes			
	ng Rooms in you		te Reseuc Areas,		103			
Are dedicated during a fi		vailable in all of th	nese spaces for use		Yes			
Are all	dedicated interc	oms operational?			Yes			
riority Conditi	on							
Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
No	Water Leaks onto Electrical Equipment	N/A	Lighting Fixture	Room 205	Kevin Seneriz	Fireman	Sent to DSF	
spection								
Question					Respons	e		
Electrical								
AUDITORIU	J M				Does not	Exist		
CAFETERIA	<u> </u>				Does not	Exist		
		/ADMINISTRA	TIVE SPACE		Inspected			
Lighting	, 0 0 11112 0 14		11,2511102		Inspected			
	es a Chandelier e	exist?			No	1		
	Fixture - Fluore				Does not	Eviet		
		scent						
	Fixture - HID	•			Does not			
	Fixture - Incano	descent			Does not			
Lighting	Fixture - LED				Inspected	1		
Pendant Mounted			Inspected					
Cond	lition				1 - Good			
	ficiency					encies recorded		
	e Mounted				Inspected			
Cond					1 - Good			
-	ficiency					iencies recorded		
	ed Mounted				Inspected			
Cond	lition				1 - Good			
	ficiency					iencies recorded		
COMPUTER LAB				Does not Exist				

Does not Exist

GYMNASIUM

Building Condition Assessment Survey 2023 - 2024

Electrical Inspection		Q483
Question	Response	

Question	Response
KITCHEN	Inspected
Instance on 1st Floor	Inspected
Lighting	Inspected
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor	Inspected
Pendant Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Surface Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Recessed Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
LIBRARY	Does not Exist
LOCKER ROOM	Does not Exist
MULTIPURPOSE ROOM	Inspected
Instance on 1st Floor, 2nd Floor	Inspected
Lighting	Inspected
Instance on 1st Floor, 2nd Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor, 2nd Floor	Does not Exist
Lighting Fixture - HID	
Instance on 1st Floor, 2nd Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor, 2nd Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor, 2nd Floor	Inspected
Pendant Mounted	Does not Exist
Instance on 1st Floor, 2nd Floor	Does not Exist
Surface Mounted	Does not Exist
Instance on 1st Floor, 2nd Floor	Does not Exist
Recessed Mounted	Inspected
Instance on 1st Floor, 2nd Floor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Local Sound System	Does not Exist
Instance on 1st Floor, 2nd Floor	Does not Exist
Projection System	Does not Exist
Instance on 1st Floor, 2nd Floor	Does not Exist
Theater Lighting System	Does not Exist
Instance on 1st Floor, 2nd Floor	Does not Exist
SCIENCE DEMO ROOM	Does not Exist
(P)	Page 2 of 7 Print Date: 6/25/2024

Building Condition Assessment Survey 2023 - 2024

ectrical Inspection		Q483
Question	Response	
SCIENCE LAB	Does not Exist	
SCIENCE PREP ROOM	Does not Exist	
SWIMMING POOL	Does not Exist	
TOILET ROOM - STAFF	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Does not Exist	
Lighting Fixture - HID	Does not Exist	
Lighting Fixture - Incandescent	Does not Exist	
Lighting Fixture - LED	Inspected	
Pendant Mounted	Does not Exist	
Surface Mounted	Does not Exist	
Recessed Mounted		
Condition	Inspected 1 - Good	
Deficiency	No deficiencies recorded	
TOILET ROOM - STUDENT	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Does not Exist	
	Does not Exist	
Lighting Fixture - HID		
Lighting Fixture - Incandescent	Does not Exist	
Lighting Fixture - LED	Inspected	
Pendant Mounted	Does not Exist	
Surface Mounted	Does not Exist	
Recessed Mounted	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
AUXILIARY SIGNAL/BELL SYSTEM Perlacement Overtity	Inspected 20,000	
Replacement Quantity		
Replacement Uom	S.F.	
Condition	1 - Good No deficiencies recorded	
Deficiency EMERGENCY DC STANDBY BATTERY POWER	Does not Exist	
EMERGENCY GENERATOR SET	Does not Exist	
EMERGENCY LIGHT/EXIT LIGHT PANEL		
	Does not Exist	
EMERGENCY LIGHTING	Inspected	
Battery Pack	Inspected	
Condition Deficiency	1 - Good No deficiencies recorded	
Non Battery Pack	Does not Exist	
EXIT LIGHT		
	Inspected	
Battery Pack	Inspected	
Condition Deficiency	1 - Good No deficiencies recorded	
Non Battery Pack	Does not Exist	
EXIT/EMERGENCY LIGHT	Does not Exist	
FIRE ALARM SYSTEM Replacement Quantity	Inspected 20,000	
	20,000 S.F.	
Replacement Uom		
Bell/Horn	Inspected	

Building Condition Assessment Survey 2023 - 2024

estion (NOTE AN ADM GNOCKEN)	Response	
IRE ALARM SYSTEM		
Bell/Horn	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Strobe	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Manual Pull Station	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Fan Shutdown Control	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Duct Smoke Detector	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Area Smoke Detector	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
CO Detector	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Heat Detector	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Elevator Recall	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Magnetic Door Holder/Contactor	Does not Exist	
Fused Cutout Panel	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Fire Alarm Digital Communicator	Does not Exist	
Main Panel	Inspected	
Bell At Panel	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Main Entrance Lobby	
Instance Condition	1 - Good	
-		
Instance Quantity	1 EACH	
Instance Quantity Uom	EACH	
Instance Manufacturer	Edwards	
Equipment	Fire Alarm Control Panel	
Model	EST	
Installation Year	2020	
Source of Installation	Documented	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Standard)	Does not Exist	

Building Condition Assessment Survey 2023 - 2024

Question	Response
FIRE ALARM SYSTEM	
Remote Annunciator	Inspected
Display Monitor	Does not Exist
Panel	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Printer	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Punch Register	Does not Exist
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Tamper Flow Switch/Chain	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Inspected
Elevator	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Holding Area	Does not Exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Does not Exist
Main Equipment Rack (MDF)	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
MOTOR CONTROLLER	Inspected
Motor Control Center	Does not Exist
Motor Starter/Contactor	Does not Exist
Variable Frequency Drive	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Does not Exist
Fused Knife Switch Type	Does not Exist
Fused Toggle Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
PUBLIC ADDRESS SYSTEM	Inspected
Replacement Quantity	20,000
Replacement Uom	S.F.
	Telecom Room 210
Instance	rejecom Room 210

Building Condition Assessment Survey 2023 - 2024

		Response	
PUBLIC	ADDRESS SYSTEM		
	Instance Condition	1 - Good	
	Instance Quantity	1	
	Instance Quantity Uom	EACH	
	Model	Bogen Multicom - 2000	
	Installation Year	2020	
	Source of Installation	Documented	
	Deficiency	No deficiencies recorded	
SECURI	ГҮ	Inspected	
IPDVS.	CCTV System	Inspected	
Repla	cement Quantity	20,000	
Repla	cement Uom	S.F.	
	Installation Year	2020	
	Source of Installation	Documented	
Cond	ition	1 - Good	
	Deficiency	No deficiencies recorded	
Intrusi	on Alarm System	Inspected	
Repla	cement Quantity	20,000	
Repla	cement Uom	S.F.	
Cent	ral Control Panel	Inspected	
	Instance	Custodian's Office	
	Instance Condition	1 - Good	
	Instance Quantity	1	
	Instance Quantity Uom	EACH	
	Model	Vista-128BPT	
	Installation Year	2022	
	Source of Installation	Custodial Staff	
	Deficiency	No deficiencies recorded	
Infra	red Sensor	Inspected	
	ndition	1 - Good	
	Deficiency	No deficiencies recorded	
Panio	Switch	Inspected	
	ndition	1 - Good	
	Deficiency	No deficiencies recorded	
Remo	ote Annunciator	Inspected	
Con	ndition	1 - Good	
	Deficiency	No deficiencies recorded	
Siren	/Strobe	Inspected	
Cor	ndition	1 - Good	
	Deficiency	No deficiencies recorded	
Lightin	g - Security	Inspected	
Repla	cement Uom	EACH	
Cond	ition	1 - Good	
	Deficiency	No deficiencies recorded	
SERVIC	E SWITCH	Inspected	
	Instance	Electrical Room 104	
	Instance Condition	1 - Good	
	Instance Quantity	1	

Building Condition Assessment Survey 2023 - 2024

Question	Response
SERVICE SWITCH	
Instance Manufacturer	Apelio
Equipment	N/A
Capacity/Size Quantity	1,600
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2020
Source of Installation	Documented
Deficiency	No deficiencies recorded
SWITCHBOARD	Inspected
Number of Spares	2
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room 104
Instance Condition	1 - Good
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Apelio
Equipment	MAIN DISTRIBUTION SWITCHBOARD "MDSB"
Capacity/Size Quantity	1,600
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	1
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Nameplate
Installation Year	2020
Source of Installation	Documented
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Does not Exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
TRANSFORMER	Does not Exist