Building Condition Assessment Survey 2023 - 2024

Inspection I	HILLCRE d Inspection	Type				Time In		Last Edited
		туре						
EE : Q5 Asset Data	05 Electrical					2024-03-	-14 8:45 AM	2024-05-30 11:43 AN
Question					Answer			
Type of Servi	ce				Below Gro	und		
* *	ive Whiteboard	(IWR) Friet?			Yes	und		
	ation in Electrica				Yes			
		lding Components	been upgraded?		Yes			
					Systems:	Gymnasium A/E	(LED Lighting Room 458, Boil	rd, LED Lighting), y), LED Lighting (1st er Room), Fire Alarm (Contactor)
					Years:	2024		
					Systems:	Partial I/LDF), C	Computer Lab - s), Science Lab	System, LAN (MDF, Room 466/468 (Raceway - Room 356 (Emergency
					Years:	2022		
					Systems:	Fire Alarm Syste	em, Auditorium	(Local Sound System)
					Years:	2018		
					Systems:	Mounted, Science Lighting, Intrusi- Infrared Sensor, (Variable Freque	te Lab - Rooms on Alarm Syste Remote Annun ency Drive), Mo	Except (Library - Recessed 301, 385, 485), LED m (Central Control Panel, ciator), Motor Controller ost Exit Lights (Battery ergency Lighting (Non
					Years:	2015		
					Systems:	Emergency Gene Switch)	erator Set (Parti	al Automatic Transfer
					Years:	2013		
					Systems:	Gymnasiums (Lo Lighting System	•	tem), Auditorium (Theater
					Years:	2010		
					Systems:	Most Security L	ghts	
					Years:	2009, 2022		
					Systems:	Library (Recesse	d Fluorescent I	Lighting)
					Years:	2009		
					Systems:	Fluorescent Ligh 485)	ting (Science L	ab - Rooms 301, 385,
					Years:	2007		
					Systems:		System, Emerge	ncy Light/Exit Light Pane
					Years:	1996		
					Systems:			aker Type Panel Board
					Years:	1990, 2007, 2010	0, 2015, 2019, 2	2022
	DINTERCOM	S IN FIRE RESC	UE AREAS		D			
	Life Rescue As	ssistance Areas, Fi	re Rescue Areas,		No No			
Priority Condit								
Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
No	Water Penetration in Electrical Roor	N/A n	Electrical Equipment	Electrical Room B26	William Hirt	Fireman	Sent to DSF	

Building Condition Assessment Survey 2023 - 2024

ection		
uestion	Response	
lectrical	· ·	
AUDITORIUM	Inspected	
Instance on Basement	Inspected	
House Lighting	Inspected	
Does a Chandelier exist?	No	
Instance on Basement	Inspected	
Lighting Fixture - Fluorescent		
Instance on Basement	Inspected	
Pendant Mounted	Does not Exist	
Instance on Basement	Does not Exist	
Surface Mounted	Inspected	
Instance on Basement	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not Exist	
Instance on Basement	Does not Exist	
Lighting Fixture - HID	Does Not Exist	
Instance on Basement	Does not Exist	
	DOGS HOT EAST	
Lighting Fixture - Incandescent Instance on Basement	Does not Exist	
	Does not exist	
Lighting Fixture - LED	T 1	
Instance on Basement	Inspected	
Pendant Mounted	Does not Exist	
Instance on Basement	Does not Exist	
Surface Mounted	Does not Exist	
Instance on Basement	Does not Exist	
Recessed Mounted	Inspected	
Instance on Basement	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Local Sound System	Inspected	
Instance on Basement	Inspected	
Installation Year	2018	
Source of Installation	Custodial Staff	
Condition	3 - Fair	
Deficiency	SYSTEM DEFECTIVE	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPAIR SYSTEM	
Urgency of Action	PRIORITY 2	
Purpose of Action	LEVEL 2	
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
Projection System	Inspected	
Is the projector on a cart or installed on the ceiling?	Ceiling	
Instance on Basement	Inspected	
Condition	3 - Fair	

Building Condition Assessment Survey 2023 - 2024

Electrical Inspection Q505

Question	Response
AUDITORIUM	
Theater Lighting System	Inspected
Instance on Basement	Inspected
Dimming System	
Instance on Basement	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Theater Lighting	
Instance on Basement	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
CAFETERIA	Inspected
Instance on 3rd Floor - Students, 4th Floor - Students	Inspected
Instance on 4th Floor - Staff	Inspected
Lighting	Inspected
Instance on 4th Floor - Staff	Inspected
Instance on 3rd Floor - Students, 4th Floor - Students	Inspected
Lighting Fixture - Fluorescent	
Instance on 4th Floor - Staff	Inspected
Instance on 3rd Floor - Students, 4th Floor - Students	Inspected
Pendant Mounted	Does not Exist
Instance on 4th Floor - Staff	Does not Exist
Instance on 3rd Floor - Students, 4th Floor - Students	Does not Exist
Surface Mounted Instance on 4th Floor - Staff	Does not Exist Does not Exist
Instance on 3rd Floor - Students, 4th Floor - Students	Does not Exist
Recessed Mounted	Inspected
Instance on 4th Floor - Staff	Inspected
Condition	2 - Between Good and Fair No deficiencies recorded
Deficiency Instance on 3rd Floor - Students, 4th Floor - Students	
Condition	Inspected 2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	110 deficiencies recorded
Instance on 4th Floor - Staff	Does not Exist
Instance on 3rd Floor - Students, 4th Floor - Students	Does not Exist
	Does not Exist
Lighting Fixture - Incandescent Instance on 4th Floor - Staff	Does not Exist
Instance on 3rd Floor - Students, 4th Floor - Students	
	Does not Exist
Lighting Fixture - LED	D P
Instance on 4th Floor - Staff	Does not Exist
Instance on 3rd Floor - Students, 4th Floor - Students	Does not Exist
Local Sound System	Does not Exist
Instance on 4th Floor - Staff	Does not Exist
Instance on 3rd Floor - Students, 4th Floor - Students	Inspected
Installation Year	1996
Source of Installation	Inspector Estimate
Condition	5 - Poor
Deficiency	AMPLIFIER NOT OPERATIONAL
(D) Page 2 of 26	Drint Data: 6/25/2024

Print Date: 6/25/2024

Building Condition Assessment Survey 2023 - 2024

Question	Response
CAFETERIA	
Local Sound System	
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE SYSTEM
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Projection System	Does not Exist
Instance on 4th Floor - Staff	Does not Exist
Instance on 3rd Floor - Students, 4th Floor - Students	Does not Exist
Theater Lighting System	Does not Exist
Instance on 4th Floor - Staff	Does not Exist
Instance on 3rd Floor - Students, 4th Floor - Students	Does not Exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected
Lighting	Inspected
Does a Chandelier exist?	No
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Inspected
Pendant Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
COMPUTER LAB	Inspected
Instance on Room 256/258	Inspected
Power Panel	No
Instance on Room 466/468	Inspected
Power Panel	Yes
Instance on Rooms 244, 246, 280B	Inspected
Power Panel	Yes
Lighting	Inspected
Instance on Rooms 244, 246, 280B	Inspected

Building Condition Assessment Survey 2023 - 2024

uestion	Response
COMPUTER LAB	
Lighting	
Instance on Room 466/468	Inspected
Instance on Room 256/258	Inspected
Lighting Fixture - Fluorescent	
Instance on Rooms 244, 246, 280B	Inspected
Instance on Room 466/468	Inspected
Instance on Room 256/258	Inspected
Pendant Mounted	Inspected
Instance on Rooms 244, 246, 280B	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 466/468	Does not Exist
Instance on Room 256/258	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Instance on Rooms 244, 246, 280B	Does not Exist
Instance on Room 466/468	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 256/258	Does not Exist
Recessed Mounted	Does not Exist
Instance on Rooms 244, 246, 280B	Does not Exist
Instance on Room 466/468	Does not Exist
Instance on Room 256/258	Does not Exist
Lighting Fixture - HID	
Instance on Rooms 244, 246, 280B	Does not Exist
Instance on Room 466/468	Does not Exist
Instance on Room 256/258	Does not Exist
	DOES HOL EXIST
Lighting Fixture - Incandescent Instance on Rooms 244, 246, 280B	Does not Exist
Instance on Room 466/468	Does not Exist
Instance on Room 256/258	Does not Exist
Lighting Fixture - LED	
Instance on Rooms 244, 246, 280B	Does not Exist
Instance on Room 466/468	Does not Exist
Instance on Room 256/258	Does not Exist
Raceway With Receptacles	Inspected
Instance on Rooms 244, 246, 280B	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 466/468	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Instance on Room 256/258	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
GYMNASIUM	Inspected
(D)	Page 5 of 26

Building Condition Assessment Survey 2023 - 2024

estion	Response	
YMNASIUM		
Instance on 1st Floor - Gymnasium A/B	Inspected	
Instance on 1st Floor - Gymnasium C/D/E/F	Inspected	
Lighting	Inspected	
Instance on 1st Floor - Gymnasium C/D/E/F	Inspected	
Instance on 1st Floor - Gymnasium A/B	Inspected	
Lighting Fixture - Fluorescent		
Instance on 1st Floor - Gymnasium C/D/E/F	Inspected	
Instance on 1st Floor - Gymnasium A/B	Inspected	
Pendant Mounted	Does not Exist	
Instance on 1st Floor - Gymnasium C/D/E/F	Does not Exist	
Instance on 1st Floor - Gymnasium A/B	Does not Exist	
Surface Mounted	Inspected	
Instance on 1st Floor - Gymnasium C/D/E/F	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on 1st Floor - Gymnasium A/B	Does not Exist	
Recessed Mounted	Does not Exist	
Instance on 1st Floor - Gymnasium C/D/E/F	Does not Exist	
Instance on 1st Floor - Gymnasium A/B	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on 1st Floor - Gymnasium C/D/E/F	Does not Exist	
Instance on 1st Floor - Gymnasium A/B	Does not Exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor - Gymnasium C/D/E/F	Does not Exist	
Instance on 1st Floor - Gymnasium A/B	Does not Exist	
Lighting Fixture - LED		
Instance on 1st Floor - Gymnasium C/D/E/F	Inspected	
Instance on 1st Floor - Gymnasium A/B	Inspected	
Pendant Mounted	Does not Exist	
Instance on 1st Floor - Gymnasium C/D/E/F	Does not Exist	
Instance on 1st Floor - Gymnasium A/B	Does not Exist	
Surface Mounted	Does not Exist	
Instance on 1st Floor - Gymnasium C/D/E/F	Does not Exist	
Instance on 1st Floor - Gymnasium A/B	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Recessed Mounted	Inspected	
Instance on 1st Floor - Gymnasium C/D/E/F	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Instance on 1st Floor - Gymnasium A/B	Does not Exist	
Local Sound System	Inspected	
Instance on 1st Floor - Gymnasium C/D/E/F	Inspected	
Installation Year	2010	
Source of Installation	Custodial Staff	
Condition	4 - Between Fair and Poor	

Building Condition Assessment Survey 2023 - 2024

Electrical Inspection Q505

Question	Response		
GYMNASIUM			
Local Sound System			
Deficiency	AMPLIFIER NOT OPERATIONAL		
Deficiency Quantity	1		
Quantity Uom	EACH		
Potential Action	REPAIR		
Urgency of Action	PRIORITY 2		
Purpose of Action	LEVEL 2		
Deficiency Photo1	No photo recorded		
Violations	No violations recorded.		
Instance on 1st Floor - Gymnasium A/B	Inspected		
Installation Year	2010		
Source of Installation	Custodial Staff		
Condition	3 - Fair		
Deficiency	No deficiencies recorded		
Projection System	Does not Exist		
Instance on 1st Floor - Gymnasium C/D/E/F	Does not Exist		
Instance on 1st Floor - Gymnasium A/B	Does not Exist		
Scoreboard	Inspected		
Instance on 1st Floor - Gymnasium C/D/E/F	Inspected		
Condition	1 - Good		
Deficiency	No deficiencies recorded		
Instance on 1st Floor - Gymnasium A/B	Inspected		
Condition	3 - Fair		
Deficiency	No deficiencies recorded		
Theater Lighting System	Does not Exist		
Instance on 1st Floor - Gymnasium C/D/E/F	Does not Exist		
Instance on 1st Floor - Gymnasium A/B	Does not Exist		
KITCHEN	Inspected		
Instance on 3rd Floor, 4th Floor	Inspected		
Lighting	Inspected		
Instance on 3rd Floor, 4th Floor	Inspected		
Lighting Fixture - Fluorescent	-		
Instance on 3rd Floor, 4th Floor	Inspected		
Pendant Mounted	Does not Exist		
Instance on 3rd Floor, 4th Floor	Does not Exist		
Surface Mounted	Does not Exist		
Instance on 3rd Floor, 4th Floor	Does not Exist		
Recessed Mounted	Inspected		
Instance on 3rd Floor, 4th Floor	Inspected		
Condition	2 - Between Good and Fair		
Deficiency	No deficiencies recorded		
Lighting Fixture - HID			
Instance on 3rd Floor, 4th Floor	Does not Exist		
Lighting Fixture - Incandescent			
Instance on 3rd Floor, 4th Floor	Does not Exist		
Lighting Fixture - LED			
Instance on 3rd Floor, 4th Floor	Does not Exist		
LIBRARY	Inspected		

Print Date: 6/25/2024

Building Condition Assessment Survey 2023 - 2024

rical hispection		QSO
estion	Response	
JBRARY		
Instance on Room 230	Inspected	
Lighting	Inspected	
Instance on Room 230	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 230	Inspected	
Pendant Mounted	Does not Exist	
Instance on Room 230	Does not Exist	
Surface Mounted	Inspected	
Instance on Room 230	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Inspected	
Instance on Room 230	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on Room 230	Does not Exist	
Lighting Fixture - Incandescent		
Instance on Room 230	Does not Exist	
Lighting Fixture - LED		
Instance on Room 230	Does not Exist	
Raceway With Receptacles	Inspected	
Instance on Room 230	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Projection System	Does not Exist	
Instance on Room 230	Does not Exist	
OCKER ROOM	Inspected	
Instance on 1st Floor - Girls	Inspected	
Alternative use	Yes	
Instance on 1st Floor - Visitors	Inspected	
Alternative use	Yes	
Instance on 2nd Floor - Boys	Inspected	
Alternative use	Yes	
Lighting	Inspected	
Instance on 2nd Floor - Boys	Inspected	
Instance on 1st Floor - Visitors	Inspected	
Instance on 1st Floor - Girls	Inspected	
Lighting Fixture - Fluorescent	торести	
Instance on 2nd Floor - Boys	Inspected	
Instance on 1st Floor - Visitors	Inspected	
Instance on 1st Floor - Girls	Inspected	
Pendant Mounted	Does not Exist	
Instance on 2nd Floor - Boys	Does not Exist	
Instance on 1st Floor - Visitors	Does not Exist	
Instance on 1st Floor - Girls	Does not Exist	
Surface Mounted	Inspected	
Instance on 2nd Floor - Boys	Inspected	

Building Condition Assessment Survey 2023 - 2024

estion	Response	
OCKER ROOM		
Lighting		
Lighting Fixture - Fluorescent		
Surface Mounted		
Condition	2 - Between Good and Fair	
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE	
Deficiency Quantity	2	
Quantity Uom	EACH	
Potential Action	REPLACE BALLAST	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
Instance on 1st Floor - Visitors	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on 1st Floor - Girls	Does not Exist	
Recessed Mounted	Does not Exist	
Instance on 2nd Floor - Boys	Does not Exist	
Instance on 1st Floor - Visitors	Does not Exist	
Instance on 1st Floor - Girls	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on 2nd Floor - Boys	Does not Exist	
Instance on 1st Floor - Visitors	Does not Exist	
Instance on 1st Floor - Girls	Does not Exist	
Lighting Fixture - Incandescent		
Instance on 2nd Floor - Boys	Does not Exist	
Instance on 1st Floor - Visitors	Does not Exist	
Instance on 1st Floor - Girls	Does not Exist	
Lighting Fixture - LED	DOGS HOT EAST	
Instance on 2nd Floor - Boys	Does not Exist	
Instance on 1st Floor - Visitors	Does not Exist	
Instance on 1st Floor - Visitors	Does not Exist	
JLTIPURPOSE ROOM	Does not Exist Does not Exist	
IENCE DEMO ROOM	Inspected	
Instance on Rooms 307, 367, 407, 467, 471, 473 Power Panel	Inspected	
Alternative use	No No	
Instance on Rooms 371, 373	Inspected	
Power Panel	No	
Alternative use	No	
Instance on Rooms 389, 489	Inspected	
Power Panel Alternative use	No No	
Lighting	Inspected	
Instance on Rooms 389, 489	Inspected	
-	-	
Instance on Rooms 371, 373	Inspected	
Instance on Rooms 307, 367, 407, 467, 471, 473	Inspected Print Date:	

Building Condition Assessment Survey 2023 - 2024

ENCE DEMO ROOM		
ghting		
Lighting Fixture - Fluorescent		
Instance on Rooms 389, 489	Inspected	
Instance on Rooms 371, 373	Inspected	
Instance on Rooms 307, 367, 407, 467, 471, 473	Inspected	
Pendant Mounted	Does not Exist	
Instance on Rooms 389, 489	Does not Exist	
Instance on Rooms 371, 373	Does not Exist	
Instance on Rooms 307, 367, 407, 467, 471, 473	Does not Exist	
Surface Mounted	Does not Exist	
Instance on Rooms 389, 489	Does not Exist	
Instance on Rooms 371, 373	Does not Exist	
Instance on Rooms 307, 367, 407, 467, 471, 473	Inspected	
Condition	2 - Between Good and Fair	_
Deficiency	No deficiencies recorded	
Recessed Mounted	Inspected	
Instance on Rooms 389, 489	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on Rooms 371, 373	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on Rooms 307, 367, 407, 467, 471, 473	Does not Exist	
Lighting Fixture - HID		
Instance on Rooms 389, 489	Does not Exist	
Instance on Rooms 371, 373	Does not Exist	
Instance on Rooms 307, 367, 407, 467, 471, 473	Does not Exist	
Lighting Fixture - Incandescent		
Instance on Rooms 389, 489	Inspected	
Instance on Rooms 371, 373	Does not Exist	
Instance on Rooms 307, 367, 407, 467, 471, 473	Does not Exist	
Pendant Mounted	Does not Exist	_
Instance on Rooms 389, 489	Does not Exist	
Surface Mounted	Does not Exist	_
Instance on Rooms 389, 489	Does not Exist	
Recessed Mounted	Inspected	_
Instance on Rooms 389, 489	Inspected	_
Condition	3 - Fair	
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE	_
Deficiency Quantity	4	
Quantity Uom	EACH	
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
Lighting Fixture - LED		

Building Condition Assessment Survey 2023 - 2024

estion	Response	
CIENCE DEMO ROOM		
Lighting	Inspected	
Lighting Fixture - LED		
Instance on Rooms 371, 373	Does not Exist	
Instance on Rooms 307, 367, 407, 467, 471, 473	Does not Exist	
Emergency Gas Shut-Off Valve	Does not Exist	
Instance on Rooms 389, 489	Does not Exist	
Instance on Rooms 371, 373	Does not Exist	
Instance on Rooms 307, 367, 407, 467, 471, 473	Does not Exist	
Emergency Shut-Off Power	Does not Exist	
Instance on Rooms 389, 489	Does not Exist	
Instance on Rooms 371, 373	Does not Exist	
Instance on Rooms 307, 367, 407, 467, 471, 473	Does not Exist	
Power Supply	Inspected	
Instance on Rooms 389, 489	Inspected	
Instance on Rooms 371, 373	Inspected	
Instance on Rooms 307, 367, 407, 467, 471, 473	Inspected	
Instructor Unit	Inspected	
Instance on Rooms 389, 489	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Instance on Rooms 371, 373	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Instance on Rooms 307, 367, 407, 467, 471, 473	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Meter Demonstration Unit		
Instance on Rooms 389, 489	Does not Exist	
Instance on Rooms 371, 373	Does not Exist	
Instance on Rooms 307, 367, 407, 467, 471, 473	Does not Exist	
Projection System	Does not Exist	
Instance on Rooms 389, 489	Does not Exist	
Instance on Rooms 371, 373	Does not Exist	
Instance on Rooms 307, 367, 407, 467, 471, 473	Does not Exist	
CIENCE LAB	Inspected	
Instance on Room 356	Inspected	
Power Panel	Yes	
Alternative use	No	
Instance on Room 401	Inspected	
Power Panel Alternative use	Yes No	
Instance on Rooms 301, 385	Inspected	
Power Panel Alternative use	Yes No	
Instance on Room 485	Inspected	
Power Panel	Yes	
Alternative use	No	
Lighting	Inspected	
Instance on Room 485	Inspected	

Building Condition Assessment Survey 2023 - 2024

stion	Response
CIENCE LAB	
Lighting	
Instance on Rooms 301, 385	Inspected
Instance on Room 401	Inspected
Instance on Room 356	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 485	Inspected
Instance on Rooms 301, 385	Inspected
Instance on Room 401	Inspected
Instance on Room 356	Inspected
Pendant Mounted	Does not Exist
Instance on Room 485	Does not Exist
Instance on Rooms 301, 385	Does not Exist
Instance on Room 401	Does not Exist
Instance on Room 356	Does not Exist
Surface Mounted	Does not Exist
Instance on Room 485	Does not Exist Does not Exist
	Does not Exist
Instance on Rooms 301, 385	
Instance on Room 401	Does not Exist
Instance on Room 356	Inspected
Condition	2 - Between Good and Fair
Deficiency Recessed Mounted	No deficiencies recorded
Instance on Room 485	Inspected
Condition	Inspected 3 - Fair
Deficiency	No deficiencies recorded
Instance on Rooms 301, 385	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 401	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 356	Does not Exist
Lighting Fixture - HID	
Instance on Room 485	Does not Exist
Instance on Rooms 301, 385	Does not Exist
Instance on Room 401	Does not Exist
Instance on Room 356	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 485	Does not Exist
Instance on Rooms 301, 385	Does not Exist
Instance on Room 401	Inspected
Instance on Room 356	Does not Exist
Pendant Mounted	Does not Exist
Instance on Room 401	Does not Exist
Surface Mounted	Does not Exist
Instance on Room 401	Does not Exist
Recessed Mounted	Inspected

Building Condition Assessment Survey 2023 - 2024

stion	Response	
CIENCE LAB		
Lighting		
Lighting Fixture - Incandescent		
Recessed Mounted		
Instance on Room 401	Inspected	
Condition	3 - Fair	
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE	
Deficiency Quantity	2	
Quantity Uom	EACH	
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
Lighting Fixture - LED		
Instance on Room 485	Does not Exist	
Instance on Rooms 301, 385	Does not Exist	
Instance on Room 401	Does not Exist	
Instance on Room 356	Does not Exist	
Emergency Gas Shut-Off Valve	Inspected	
Instance on Room 485	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Instance on Rooms 301, 385	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Instance on Room 401	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Instance on Room 356	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Emergency Shut-Off Power	Inspected	
Instance on Room 485	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Instance on Rooms 301, 385	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Instance on Room 401	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Instance on Room 356	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Power Supply	Inspected	
Instance on Room 485	Inspected	
Instance on Room 403	Inspected	
Instance on Rooms 301, 363		
HISTAIRCE OII KOOHI 401	Inspected	

Building Condition Assessment Survey 2023 - 2024

icai inspection		V
stion	Response	
CIENCE LAB		
Power Supply		
Instructor Unit		
Instance on Room 485	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Instance on Rooms 301, 385	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Instance on Room 401	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Meter Demonstration Unit		
Instance on Room 485	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Instance on Rooms 301, 385	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Instance on Room 401	Does not Exist	
Student Unit		
Instance on Room 485	Does not Exist	
Instance on Rooms 301, 385	Does not Exist	
· · · · · · · · · · · · · · · · · · ·		
Instance on Room 401	Does not Exist	
Projection System	Does not Exist	
Instance on Room 485	Does not Exist	
Instance on Rooms 301, 385	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Instance on Room 401	Does not Exist	
Instance on Room 356	Does not Exist	
CIENCE PREP ROOM	Inspected	
Instance on Room 303/305	Inspected	
Power Panel	No	
Alternative use	No	
Instance on Room 303B/305B	Inspected	
Power Panel	No	
Alternative use	No	
Instance on Room 405	Inspected	
Power Panel Alternative use	No No	
Instance on Room 405A Power Panel	Inspected No	
Alternative use	No No	
Instance on Room 405B	Inspected	
Power Panel	No	
Alternative use	No	
Lighting	Inspected	
Instance on Room 405B	Inspected	
	Ţ.	
Instance on Room 405A	Inspected	

Building Condition Assessment Survey 2023 - 2024

stion		Response	
CIENCE PREP ROOM			
Lighting			
Instance on Room 303B/305B		Inspected	
Instance on Room 303/305		Inspected	
Lighting Fixture - Fluorescent			
Instance on Room 405B		Inspected	
Instance on Room 405A		Inspected	
Instance on Room 405		Inspected	
Instance on Room 303B/305B		Inspected	
Instance on Room 303/305		Inspected	
Pendant Mounted		Does not Exist	
Instance on Room 405B		Does not Exist	
Instance on Room 405A		Does not Exist	
Instance on Room 405		Does not Exist	
Instance on Room 303B/305B			
		Does not Exist	
Instance on Room 303/305		Does not Exist	
Surface Mounted		Inspected	
Instance on Room 405B		Inspected 2 - Between Good and Fair	
Condition			
Deficiency Instance on Room 405A		No deficiencies recorded Does not Exist	
Instance on Room 405		Does not Exist	
Instance on Room 303B/305B		Does not Exist	
Instance on Room 303/305		Inspected	
Condition		2 - Between Good and Fair	
Deficiency		No deficiencies recorded	
Recessed Mounted Instance on Room 405B		Does not Exist	
		Does not Exist	
Instance on Room 405A		Inspected	
Condition		2 - Between Good and Fair	
Deficiency Instance on Room 405		No deficiencies recorded	
Condition		Inspected 2 - Between Good and Fair	
Deficiency		No deficiencies recorded	
Instance on Room 303B/305B		Inspected	
Condition		2 - Between Good and Fair	
Deficiency		No deficiencies recorded	
Instance on Room 303/305		Inspected	
Condition		2 - Between Good and Fair	
Deficiency		No deficiencies recorded	
Lighting Fixture - HID			
Instance on Room 405B		Does not Exist	
Instance on Room 405A		Does not Exist	
Instance on Room 405		Does not Exist	
Instance on Room 303B/305B		Does not Exist	
Instance on Room 303/305		Does not Exist	
Lighting Fixture - Incandescent		2-	
Instance on Room 405B		Does not Exist	
Instance on Room 405A		Does not Exist	
P)	Page 15 of 26	Does not Laist	Print Date: 6/25/2024

Building Condition Assessment Survey 2023 - 2024

•	
stion	Response
CIENCE PREP ROOM	
Lighting	
Lighting Fixture - Incandescent	
Instance on Room 405	Inspected
Instance on Room 303B/305B	Does not Exist
Instance on Room 303/305	Does not Exist
Pendant Mounted	Does not Exist
Instance on Room 405	Does not Exist
Surface Mounted	Does not Exist
Instance on Room 405	Does not Exist
Recessed Mounted	Inspected
Instance on Room 405	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Lighting Fixture - LED	
Instance on Room 405B	Does not Exist
Instance on Room 405A	Does not Exist
Instance on Room 405	Does not Exist
Instance on Room 303B/305B	Does not Exist
Instance on Room 303/305	Does not Exist
Emergency Gas Shut-Off Valve	Does not Exist
Instance on Room 405B	Does not Exist
Instance on Room 405A	Does not Exist
Instance on Room 405	Does not Exist
Instance on Room 303B/305B	Does not Exist
Instance on Room 303/305	Does not Exist
Emergency Shut-Off Power	Does not Exist
Instance on Room 405B	Does not Exist
Instance on Room 405A	Does not Exist
Instance on Room 405	Does not Exist
Instance on Room 303B/305B	Does not Exist Does not Exist
Instance on Room 303/305	
	Does not Exist
Power Supply	Does not Exist
Instance on Room 405B	Does not Exist
Instance on Room 405A	Does not Exist
Instance on Room 405	Inspected
Instance on Room 303B/305B	Inspected
Instance on Room 303/305	Inspected
Instructor Unit	
Instance on Room 405	Inspected
Condition	3 - Fair

Building Condition Assessment Survey 2023 - 2024

Question	Response
SCIENCE PREP ROOM	
Power Supply	
Instructor Unit	
Deficiency	No deficiencies recorded
Instance on Room 303B/305B	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on Room 303/305	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
SWIMMING POOL	Does not Exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Replacement Quantity	419,000
Replacement Uom	S.F.
Condition	3 - Fair
Deficiency	INDICATOR PANEL NOT OPERATIONAL
Deficiency Location/Instance	Custodian's Office
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE PANEL
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
EMERGENCY DC STANDBY BATTERY POWER	Does not Exist
EMERGENCY GENERATOR SET	Inspected
EMERGENCI GENERATUR SEI	тореска

Building Condition Assessment Survey 2023 - 2024

-	11		
estion		Response	
EMERGENCY G	ENERATOR SET		
Automatic Tran	sfer Switch (ATS)	Inspected	
Instance		Electrical Closet - Dist 2 (Inside Boiler Room)	
Instance	Condition	2 - Between Good and Fair	
Instance	Quantity	1	
Instance	Quantity Uom	EACH	
Instance	Manufacturer	ASCO	
Equipme	nt	Fire Alarm ATS	
Capacity	/Size Quantity	30	
Capacity	/Size UOM	Amps	
Source of	f Capacity/Size	Nameplate	
Installati	on Year	2013	
Source of	f Installation	Custodial Staff	
Deficien	cy	No deficiencies recorded	
Instance		Electrical Closet - Dist 2 (Inside Boiler Room)	
Instance	Condition	3 - Fair	
Instance	Quantity	1	
Instance	Quantity Uom	EACH	
Instance	Manufacturer	ASCO	
Equipme	nt	Trans. SW.	
Capacity	/Size Quantity	100	
Capacity	/Size UOM	Amps	
	f Capacity/Size	Nameplate	
Installati		1971	
Source of	f Installation	Documented	
Deficien	су	PILOT LIGHT NOT OPERATIONAL	
Deficie	ncy Quantity	2	
Quanti	y Uom	EACH	
Potenti	al Action	MAINTENANCE	
Urgeno	y of Action	PRIORITY 5	
Purpos	e of Action	LEVEL 2	
Deficie	ncy Photo1	No photo recorded	
Violati	ons	No violations recorded.	
Battery Charge		Inspected	
Instance		Boiler Room	
Instance	Condition	3 - Fair	
Instance	Quantity	1	
Instance	Quantity Uom	EACH	
Instance	Manufacturer	Cummins Onan	
Equipme	nt	Battery Charger	
Capacity	/Size Quantity	10	
Capacity	/Size UOM	AmpsDC	
	/Size2 Quantity	12	
	/Size2 UOM	VDC	
	f Capacity/Size	Nameplate	
Installati		1971	
	f Installation	Documented	
Deficien		No deficiencies recorded	
Emergency Dist		Inspected	

Building Condition Assessment Survey 2023 - 2024

_		
nestion	Response	
EMERGENCY GENERATOR SET		
Emergency Distribution Board		
Number of Spares	0	
Fused Disconnect Switch Type	Does not Exist	
Molded Case Circuit Breaker Type	Inspected	
Instance	Electrical Closet - Dist 2 (Inside Boiler Room)	
Instance Condition	3 - Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Instance Manufacturer	Lexington Standard Co.	
Equipment	EMDP	
Capacity/Size Quantity	150	
Capacity/Size UOM	Amps Total	
Capacity/Size2 Quantity	1	
Capacity/Size2 UOM	Section(S)	
Source of Capacity/Size	Nameplate	
Installation Year	1971	
Source of Installation	Documented	
Deficiency	No deficiencies recorded	
Diesel	Does not Exist	
Natural Gas	Inspected	
Instance	Boiler Room	
Instance Condition	3 - Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Instance Manufacturer	Cummins Onan	
Equipment	Emergency Generator	
Capacity/Size Quantity	38	
Capacity/Size UOM	KVA	
Capacity/Size2 Quantity	30	
Capacity/Size2 UOM	KW	
Capacity/Size3Quantity	104	
Capacity/Size3 UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	1971	
Source of Installation	Documented	
Deficiency	No deficiencies recorded	
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
EMERGENCY LIGHTING	Inspected	
Battery Pack	Inspected	
Condition	3 - Fair	
Deficiency	BATTERY NOT OPERATIONAL	
Deficiency Location/Instance	Auditorium - Balcony	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE BATTERY	
Urgency of Action	PRIORITY 5	

Building Condition Assessment Survey 2023 - 2024

nestion	Response
EMERGENCY LIGHTING	
Battery Pack	Inspected
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Non Battery Pack	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Does not Exist
EXIT/EMERGENCY LIGHT	Does not Exist
FIRE ALARM SYSTEM	Inspected
Replacement Quantity	419,000
Replacement Uom	S.F.
Bell/Horn	
Condition	Inspected 2 - Between Good and Fair
	No deficiencies recorded
Deficiency Strobe	
Condition	Inspected 2 - Between Good and Fair
Deficiency	No deficiencies recorded
Manual Pull Station	
Condition	Inspected 2 - Between Good and Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Duct Smoke Detector	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Area Smoke Detector	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
CO Detector	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Heat Detector	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Elevator Recall	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Magnetic Door Holder/Contactor	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Fused Cutout Panel	Inspected
Condition	2 - Between Good and Fair

Building Condition Assessment Survey 2023 - 2024

urear mspection		QSO
uestion	Response	
FIRE ALARM SYSTEM		
Fire Alarm Digital Communicator	Does not Exist	
Main Panel	Inspected	
Bell At Panel	Does not Exist	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Main Entrance Lobby	
Instance Condition	2 - Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Instance Manufacturer	Edwards System Technology Fire Alarm Control Panel	
Equipment		
Model	EST	
Installation Year	2018	
Source of Installation	Custodial Staff	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Standard)	Does not Exist	
Sub-Panel	Does not Exist	
Remote Annunciator	Inspected	
Display Monitor	Does not Exist	
Panel	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Printer	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Punch Register	Does not Exist	
Sprinkler Flow/Air Pressure Switch	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Tamper Flow Switch/Chain	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
GROUNDING SYSTEM	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
NTERCOM SYSTEM	Inspected	
Elevator	-	
Condition	Inspected	
· · · · · · · · · · · · · · · · · · ·	3 - Fair	
Deficiency	No deficiencies recorded	
Holding Area	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
LAN	Inspected	
Local Distribution Frame (I/LDF)	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Main Equipment Rack (MDF)	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
LIGHTNING PROTECTION	Does not Exist	

Building Condition Assessment Survey 2023 - 2024

Question	Response
LIGHTNING PROTECTION	Does not Exist
MOTOR CONTROLLER	Inspected
Motor Control Center	Does not Exist
Motor Starter/Contactor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	3 - Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Mechanical Rooms (403, 451), Electrical Closets (Inside Boiler Room 178), Boiler Room
Deficiency Quantity	9
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Fused Knife Switch Type	Does not Exist
Fused Toggle Switch Type	Inspected
Condition	3 - Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room B26
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Molded Case Circuit Breaker Type	Inspected
Condition	3 - Fair
Deficiency	PANEL BOARD COVER IS MISSING
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL BOARD DOOR LOCK IS MISSING
Deficiency Location/Instance	4th Floor Kitchen, Electrical Room B26
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	MAINTENANCE Print Potes (4)5/2024

Building Condition Assessment Survey 2023 - 2024

Question	Response
PANEL BOARD	
Molded Case Circuit Breaker Type	
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	NO SPARE
Deficiency Location/Instance	Corridors by Rooms (458, 430, 230, 120, B14, B6), Kitchens, Gymnasium C/D/E/F, Mechanical Room 451
Deficiency Quantity	11
Quantity Uom	EACH
Potential Action	REPLACE PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Corridors by Rooms (484, 480, 444, 410, 402, 384, 380, 360, 344, 33 310, 302, 288, 260, 244, 212, 172, 158, 150, 144, 120, 104, B24), Rooms (466/468, 401, 368, 364, 356, 352, 340, 280B, 246, 244), Kitchens, Gymnasium A/B, Mechanical Room 403, Boiler Room, Electrical Room B26, Electrical Closet 178
Deficiency Quantity	46
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
PUBLIC ADDRESS SYSTEM	Inspected
Replacement Quantity	419,000
Replacement Uom	S.F.
Instance	Room 144
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Rauland Telecenter System 21
Installation Year	1996
Source of Installation	Inspector Estimate
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Classrooms and Corridors
Deficiency Quantity	27
Quantity Uom	EACH
Potential Action	REPLACE
	PRIORITY 3
Urgency of Action	
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
SECURITY	Inspected
IPDVS/CCTV System	Inspected

Building Condition Assessment Survey 2023 - 2024

19,000 .F. 022 Custodial Staff - Good To deficiencies recorded Inspected 19,000 .F. Inspected Coom 122 - Between Good and Fair EACH Vista-128BPT 015 Custodial Staff
Custodial Staff - Good To deficiencies recorded Inspected 19,000 I.F. Inspected Toom 122 - Between Good and Fair EACH Vista-128BPT 0015
Custodial Staff - Good To deficiencies recorded Inspected 19,000 I.F. Inspected Toom 122 - Between Good and Fair EACH Vista-128BPT 0015
Oustodial Staff - Good No deficiencies recorded Inspected I19,000 I.F. Inspected Room 122 - Between Good and Fair EACH Vista-128BPT O15
Custodial Staff - Good To deficiencies recorded Inspected 19,000 I.F. Inspected Coom 122 - Between Good and Fair CACH Vista-128BPT 015
- Good To deficiencies recorded Inspected I19,000 I.F. Inspected It coom 122 I coom 122 I coom Good and Fair I cach
Jo deficiencies recorded Inspected I19,000 I.F. Inspected I20
nspected 19,000 .F. nspected 200m 122 - Between Good and Fair EACH Vista-128BPT 015
19,000 .F. Inspected Coom 122 - Between Good and Fair EACH Vista-128BPT 015
.F. nspected 200m 122 - Between Good and Fair EACH Vista-128BPT 015
nspected 200m 122 - Between Good and Fair EACH Vista-128BPT
- Between Good and Fair EACH Vista-128BPT
- Between Good and Fair EACH Vista-128BPT
EACH Vista-128BPT 015
CACH Vista-128BPT 015
Vista-128BPT 015
Vista-128BPT 015
015
ustodiai Staii
To deficiencies recorded
nspected
- Between Good and Fair
No deficiencies recorded
nspected
- Fair
To deficiencies recorded
nspected
- Between Good and Fair
To deficiencies recorded
nspected
- Fair
IREN/STROBE NOT ACTIVE
Exterior Wall - by Main Entrance
•
ACH
MAINTENANCE
RIORITY 4
EVEL 3
No photo recorded
To violations recorded.
nspected
ACH
- Fair
JGHTING FIXTURE BEYOND USEFUL LIFE
oading Dock, Canopy - facing Parsons Boulevard
, ACH
REPLACE-UPGRADE
PRIORITY 1
EVEL 3
- Honsell Constitution of the Constitution of

Building Condition Assessment Survey 2023 - 2024

Question	Response	
SECURITY		
Lighting - Security		
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
Deficiency	LIGHTING FIXTURE NOT OPERATIONAL	
Deficiency Location/Instance	On Poles facing (Highland Avenue, 86th Avenue)	
Deficiency Quantity	16	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 3	
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE	
Deficiency Location/Instance	Exterior Walls - facing (86th Avenue, Athletic Field)	
Deficiency Quantity	4	
Quantity Uom	EACH	
Potential Action	REPLACE BALLAST	
Urgency of Action	PRIORITY 2	
Purpose of Action	LEVEL 3	
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
Deficiency	LIGHTING FIXTURE PHOTOCELL NOT OPERATIONAL	
Deficiency Location/Instance	Roof - facing Parsons Boulevard	
Deficiency Quantity	3	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 2	
Purpose of Action	LEVEL 3	
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
SERVICE SWITCH	Inspected	
Instance	Electrical Room B26	
Instance Condition	1 - Good	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Instance Manufacturer	All City Switchboard	
Equipment	Main Switch Keyinterlocked	
Capacity/Size Quantity	4,000	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	2022	
Source of Installation	Custodial Staff	
Deficiency	No deficiencies recorded	
SWITCHBOARD	Inspected	
Number of Spares	0	
Fused Disconnect Switch Type	Inspected	
Instance	Electrical Room B26	
Instance Condition	3 - Fair	

Building Condition Assessment Survey 2023 - 2024

Response
1
EACH
All City Switchboard
N/A
4,000
Amps Total
10
Section(S)
Service Switch Size
1971
Documented
No deficiencies recorded
Does not Exist
Does not Exist
Inspected
Inspected
3 - Fair
No deficiencies recorded
Inspected
3 - Fair
No deficiencies recorded
Inspected
Electrical Room B26
2 - Between Good and Fair
1
EACH
Hammond Power Solutions
N/A
330
KVA
Nameplate
2015
Custodial Staff
No deficiencies recorded