NYC Department of Education

Building Condition Assessment Survey 2023 - 2024

Mechanical Inspection		Q72'
Asset: P.S. 106 TRANSPORTABLE - Q, 180 BEACH 35 S	STREET, New York, 11691	
Inspection Id Inspection Type	Time In Las	st Edited
ME: Q727 Mechanical	2024-04-09 9:52 AM 202	24-04-23 5:20 PM
Asset Data		
Question	Answer	
Are there fuel tanks?	No	
Total # of water main service entries to the asset	0	
MERs/Fan Rooms Locations	None	
Are there any spaces with Missing or Defective CO Detectors?	No	
Are there any Emergency Stop Switches with Missing Hammers? Are there any Painted/Obstructed Sprinkler Heads?	No No	
Have any Systems/Major Building Components been upgraded?	No	
Priority Condition	110	
·	D () D ()Tril G()	. •
Priority Priority Condition Component Location Condition Exist Category Description Affected Description Last Year?	Person(s) Person(s) Title Status Photon Notified	toImage
No condition recorded		
Inspection		
Question	Response	
Mechanical		
AIR CONDITIONING	Inspected	
Packaged Terminal A/C	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Refrigerant Leak Detection System	Does not Exist	
DOMESTIC WATER SYSTEM	Inspected	
Domestic Hot Water System	Inspected	
Electric Domestic Water Heater	Inspected	
Condition	5 - Poor	
Deficiency	DEFECTIVE/DETERIORATED	
Deficiency Location/Instance	Toilet Room inside Room T-1	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
Domestic Water Distribution Piping	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
DRAIN/WASTE/VENT AND STORM SYSTEM	Inspected	
Sewage/Waste/Vent Piping	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	SEWAGE/WASTE PIPING: DEFECTIVE/LEAKS	<u> </u>
Deficiency Location/Instance	Play Ground/in front of the TCUs	
Deficiency Quantity	10	
Quantity Uom	L.F.	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	

NYC Department of Education

Building Condition Assessment Survey 2023 - 2024

Mechanical Inspection Q727 Question Response DRAIN/WASTE/VENT AND STORM SYSTEM Sewage/Waste/Vent Piping Purpose of Action LEVEL 2 Deficiency Photo1 No photo recorded Violations No violations recorded. Sewage Ejector Pump Does not Exist **FIXTURES** Inspected Staff And Other Inspected **Janitor Sink** Does not Exist Lavatory/Sink Inspected Condition 3 - Fair Deficiency No deficiencies recorded **Toilet** Inspected Condition 3 - Fair Deficiency No deficiencies recorded Urinal Does not Exist Student Inspected **Drinking Fountain** Does not Exist Lavatory/Sink Inspected Condition 3 - Fair Deficiency No deficiencies recorded Sink And Fountain Combo Unit Does not Exist **Toilet** Inspected Condition 3 - Fair Deficiency No deficiencies recorded Urinal Does not Exist HEATING Does not Exist **Enclosed IDF Room** Does not Exist VENTILATION Inspected Is the building mechanically ventilated? Yes **Exhaust Fan** Inspected 1-25 Approximate Total # of Fans Condition 3 - Fair No deficiencies recorded Deficiency **Metal Ductwork** Inspected Are there any uninsulated ductwork by design in Mechanical Rooms? No Are there chain operated dampers? Condition 2 - Between Good and Fair Deficiency No deficiencies recorded