

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q732

**Asset:** ALTERNATIVE HS SUPERINTENDENT-Q, 90-27 SUTPHIN BLVD, New York, 11435

Inspection Id	Inspection Type	Time In	Last Edited
SA : Q732	Architectural - Senior	2024-01-12 7:34 AM	2024-01-24 8:42 AM
AA : Q732	Architectural - Associate	2024-01-12 8:31 AM	2024-01-24 5:42 PM

**Asset Data**

Question	Answer
Was the building fully accessible for inspection	No
Inspection Access Comment	Areaways (no access ladder)
Building Square Footage	33,000
Comments on the Area (for Athletic Field, Playing Surfaces, Leased Spaces)	110,000 S.F. Total Building (33,000 S.F. Leased)
Comments on the Stories (Floors) plus Basements	5+B
Comments on the Number of Classrooms	0
Comments on the Year Built	1931
Student Population	0
Staff Population	75
Weather	Fair
Principal(s) Information	
Principal Name	Judy Aquayo-Nunez (Building Manager)
Organization	Department of Education Administration and Support Facility (District 28) - Queens
Did you meet with this Principal?	Yes
Did this Principal provide feedback?	Yes
Summary of Principal's Feedback	The Building Manager's comment is as follows: The ceiling A/C ductwork condensate leaks in the offices.
Custodian	Vincent Stanzione
Fireman	Sam Wizansky (Handyman)
Facade Photo	



Sutphin Boulevard - North view

**NYC Department of Education  
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q732

Main Entrance Photo



Facade A - Sutphin Boulevard

Roof Photo

Nil

Have any Systems/Major Building Components been upgraded?

Yes

Systems: Exterior Door (roll up) - repairs

Year: 2023

Systems: Louvers - repairs

Year: 2021

Systems: Windows - replacement

Year: 2001

Have there been any Building Additions?

No

Tandem Schools?

No

Leased Space?

Yes

Year Leased

2002

Inspection

Full Inspection

**Priority Condition**

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	PhotoImage
-------------------------------------	-------------------	-----------------------	--------------------	----------------------	--------------------	-----------------	------------

No condition recorded

**Structural Engineer Required**

Structural Condition Type	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	PhotoImage
---------------------------	-----------------------	--------------------	----------------------	--------------------	-----------------	------------

No condition recorded

**Programmatic Accessibility**

Programmatic Accessibility Status Question	Response
Is the primary or secondary entrance on an accessible route?	Yes
Is the building a multi-story building?	Yes
Are all floors of the building accessible through compliant means?	Yes
Accessible classrooms exists on each floor?	Yes
Boys and Girls or Unisex accessible toilets exist on at least every other floor?	Yes
If the following spaces exist, are they ALL accessible? Art Room, Auditorium, Cafeteria, Computer, Gymnasiums, Library, Multipurpose Room, Science Labs	Yes

Physical Breakdown Structure	Exists	Required	Complies	Deficiency	Assistive Fire Listening Alarm System	Fire Alarm Strobe
------------------------------	--------	----------	----------	------------	---------------------------------------	-------------------

**PROGRAMMATIC ACCESSIBILITY**

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q732


Physical Breakdown Structure	Exists	Required	Complies	Deficiency	Assistive Listening System	Fire Alarm Strobe
<b>Exterior Routes</b>						
Exterior Entrances & Exits			Yes			
Exterior H/C Lifts	No	No				
Exterior Ramps and Railings	No	No				
<b>Interior Routes</b>						
Corridor and Lobby H/C Lifts	No	No				
Interior Corridor Doors and Hardware	Yes		Yes			
Interior Corridors and Lobbies			Yes			
Interior Elevators	Yes		Yes			
Interior Lobby Doors and Hardware			Yes			
Interior Ramps	No					
<b>Rooms &amp; Spaces</b>						
Art Rooms	No					
Auditorium	No					
Cafeteria	No					
Classrooms	No					
Computer Rooms	No					
Gymnasium	No					
Library	No					
Main Office	No					
Multi-purpose Room	No					
Nurse's Room	No					
Pool	No					
Science Lab	No					
Toilet Rooms (Boys)	No					
Toilet Rooms (Girls)	No					
Toilet Rooms (Staff)	1st, 2nd Floor	Yes		Yes		

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q732

Building Template



Inspection

Question	Response
<b>Architectural</b>	
<b>EXTERIOR</b>	Inspected
<b>AREAWAY</b>	Inspected
Instance on AW1, AW2	Inaccessible
Instance Quantity	2
Instance Quantity Uom	EACH
<b>AWNINGS AND CANOPIES</b>	Does not Exist
<b>CHIMNEY</b>	Inspected
Material Type(s)	Metal
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>COPING</b>	Not Required
<b>CORNICE</b>	Does not Exist
<b>DOORS</b>	Inspected
<b>DOORS AND FRAMES</b>	Inspected
Condition	3 - Fair
Deficiency	METAL: DETERIORATED DOOR AND FRAME - MINOR DETERIORATION
Roof Plan reference	
Deficiency Quantity	1
Quantity Uom	EACH

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q732

Question	Response
----------	----------

**EXTERIOR**

**DOORS**

**DOORS AND FRAMES**

Potential Action  
 Urgency of Action  
 Purpose of Action  
 Deficiency Photo1

MAINTENANCE  
 PRIORITY 3  
 LEVEL 2



Facade A

Violations

No violations recorded.

**DOOR HARDWARE**

Inspected

Condition

3 - Fair

Deficiency

No deficiencies recorded

**LINTELS**

Inspected

Condition

2 - Between Good and Fair

Deficiency

No deficiencies recorded

**TRANSOM/SIDE LIGHT**

Does not Exist

**EXTERIOR WALLS**

Inspected

Material Type(s)

Concrete, Masonry

Replacement Quantity

20,000

Replacement Uom

S.F.

Instance on All Facades

Inspected

Instance Condition

3 - Fair

Instance Quantity

20,000


Instance Quantity Uom

S.F.

Deficiency

STUCCO CEMENT SURFACE: CRACKS, SPALLING

Roof Plan reference



**NYC Department of Education  
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q732


**Question**

**Response**

**EXTERIOR**

**EXTERIOR WALLS**

Elevation



Deficiency Quantity

30

Quantity Uom

S.F.

Potential Action

REPLACE

Urgency of Action

PRIORITY 4

Purpose of Action

LEVEL 2

Deficiency Photo1



Facade B


No violations recorded.

Violations

Deficiency

BRICK: DETERIORATED JOINTS

Roof Plan reference



Elevation



Deficiency Quantity

300

Quantity Uom

S.F.

Potential Action

REPOINT

**NYC Department of Education  
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q732

**Question**

**Response**

**EXTERIOR**

**EXTERIOR WALLS**

Urgency of Action  
Purpose of Action  
Deficiency Photo1

PRIORITY 3  
LEVEL 2



Facade B


Violations

No violations recorded.


Deficiency

**BRICK: CRACKS/DISPLACED/SPALLED BRICK AT BUILDING CORNERS**

Roof Plan reference




Elevation



Deficiency Quantity  
Quantity Uom  
Potential Action  
Urgency of Action  
Purpose of Action  
Deficiency Photo1

10  
S.F.  
REMOVE AND REBUILD  
PRIORITY 4  
LEVEL 2



**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q732

**Question**

**Response**

**EXTERIOR**

**EXTERIOR WALLS**

Violations


Facade A

No violations recorded.


Deficiency

CERAMIC TILE: CHIPPED, SPALLED, BROKEN PIECES

Roof Plan reference



Elevation



Deficiency Quantity  
 Quantity Uom  
 Potential Action  
 Urgency of Action  
 Purpose of Action  
 Deficiency Photo1

10  
 S.F.  
 REPLACE  
 PRIORITY 3  
 LEVEL 2



Violations

Facade A

No violations recorded.

Deficiency

BRICK: MINOR CRACKS AND SPALLING



**NYC Department of Education  
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q732


**Question**

**Response**


**EXTERIOR**

**EXTERIOR WALLS**

Roof Plan reference



Elevation



Deficiency Quantity  
Quantity Uom  
Potential Action  
Urgency of Action  
Purpose of Action  
Deficiency Photo1

30  
S.F.  
RESTITCH  
PRIORITY 3  
LEVEL 2



Facade A


No violations recorded.

Violations

Deficiency

BRICK: DETERIORATED JOINTS

Roof Plan reference



**NYC Department of Education  
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q732

**Question**

**Response**

**EXTERIOR**

**EXTERIOR WALLS**

Elevation



Deficiency Quantity

10

Quantity Uom

S.F.

Potential Action

REPOINT

Urgency of Action

PRIORITY 4

Purpose of Action

LEVEL 2

Deficiency Photo1



Facade A

Violations

No violations recorded.

**EXTERIOR SOFFITS**

Inspected

Condition

2 - Between Good and Fair

Deficiency

No deficiencies recorded

**LOADING DOCK**

Does not Exist

**LOUVER**

Inspected

Condition


3 - Fair

Deficiency

BROKEN/ DENTED BLADES

Roof Plan reference


Q732



**NYC Department of Education  
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q732

Question	Response
<b>EXTERIOR</b>	
<b>LOUVER</b>	
Elevation	
Deficiency Quantity	30
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Facade A No violations recorded.
<b>PARAPETS</b>	Not Required
<b>PLAZA DECK</b>	Does not Exist
<b>ROOF</b>	Inspected
<b>Roofing</b>	Not Required
<b>Specialties</b>	Inspected
<b>BULKHEAD/PENTHOUSE</b>	Not Required
<b>CUPOLA/ SPIRES/ TOWERS</b>	Does not Exist
<b>DORMER</b>	Does not Exist
<b>DUNNAGE STEEL</b>	Not Required
<b>SKYLIGHT/ROOF VENT</b>	Does not Exist
<b>ROOF/GRAVITY TANK</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>STAIRS/RAMPS: EXTERIOR</b>	Not Required
<b>WINDOWS</b>	Inspected
Replacement Quantity	3,000
Replacement Uom	S.F.
<b>EXTERIOR GUARDS</b>	Does not Exist
<b>LINTELS</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded

**NYC Department of Education  
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q732


Question	Response
----------	----------

**EXTERIOR**

**WINDOWS**


**WINDOWS**

Material Type(s)	Inspected Aluminum
Instance on Aluminum - Double Hung: Facade C	Inspected
Instance Condition	3 - Fair
Instance Quantity	400
Instance Quantity Uom	S.F.
Are these windows insulated	No
Installation Year	2001
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded
Instance on Aluminum - Other: Facade A	Inspected
Instance Condition	3 - Fair
Instance Quantity	2,600
Instance Quantity Uom	S.F.
Are these windows insulated	Yes
Installation Year	2001
Source of Installation	Custodial Staff
Deficiency	ALUMINUM - OTHER: BROKEN PANE
Roof Plan reference	Q732



Sutphin Boulevard

Elevation





Deficiency Quantity	30
Quantity Uom	S.F.
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education  
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection



Q732

Question	Response
<b>EXTERIOR</b>	
<b>WINDOWS</b>	
<b>WINDOWS</b>	
Deficiency Photo1	
Violations	Facade A No violations recorded.
<b>INTERIOR</b>	Inspected
<b>POOLS</b>	Does not Exist
<b>STRUCTURAL</b>	Inspected
<b>COLUMNS/BEAMS/BEARING WALLS</b>	Inspected
Condition	3 - Fair
Deficiency	STEEL COLUMNS/BEAMS: DETERIORATED MASONRY FIREPROOFING
Deficiency Location/Instance	Basement - Garage
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 5
Deficiency Photo1	
Violations	Basement - Garage No violations recorded.
Deficiency	STEEL COLUMNS/BEAMS: DETERIORATED CONCRETE FIREPROOFING
Deficiency Location/Instance	2nd Floor - Mechanical Room, 1st Floor - Mechanical Room
Deficiency Quantity	30
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 5

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q732

Question	Response
<b>INTERIOR</b>	
<b>STRUCTURAL</b>	
<b>COLUMNS/BEAMS/BEARING WALLS</b>	
Deficiency Photo1	
Violations	2nd Floor - Mechanical Room No violations recorded.
<b>FLOOR STRUCTURE</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>FOUNDATION WALLS</b>	Inspected
Material Type(s)	Concrete
Condition	3 - Fair
Deficiency	CONCRETE: CRACKED/SPALLED/REINFORCEMENT EXPOSED
Deficiency Location/Instance	Basement - Electrical Panel Room
Deficiency Quantity	30
Quantity Uom	S.F.
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 5
Deficiency Photo1	
Violations	Basement - Electrical Panel Room No violations recorded.
<b>ROOF STRUCTURE</b>	Not Required
<b>VAULTS-BUNKERS</b>	Does not Exist
<b>AUDITORIUM</b>	Does not Exist
<b>CAFETERIA</b>	Does not Exist
<b>CLASSROOMS/CORRIDORS/ADMIN SPACES</b>	Inspected
<b>Ceiling</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	ACOUSTIC TILES: DAMAGED/MISSING
Deficiency Location/Instance	Corridor near Stair B/2, Rooms 139, 214, Corridor near 1st Floor Toilets, Near Room 243, and others
Deficiency Quantity	100

**NYC Department of Education  
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q732

Question	Response
<b>INTERIOR</b>	
<b>CLASSROOMS/CORRIDORS/ADMIN SPACES</b>	
<b>Ceiling</b>	
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Room 214
Violations	No violations recorded.
<b>Door(s)</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Floor Finish</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	VINYL TILES: DETERIORATED SUBSTRATE
Deficiency Location/Instance	Corridor near Rooms 145, 147, Main Entrance Lobby
Deficiency Quantity	30
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Corridor near Stair B/2
Violations	No violations recorded.
Deficiency	VINYL TILES: BROKEN/DETERIORATED/MISSING TILES
Deficiency Location/Instance	Near 2nd Floor Toilet Rooms, Near 1st Floor Toilet Rooms
Deficiency Quantity	20
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education  
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q732

Question	Response
<b>INTERIOR</b>	
<b>CLASSROOMS/CORRIDORS/ADMIN SPACES</b>	
<b>Floor Finish</b>	
Deficiency Photo1	
Violations	Near 2nd Floor Toilet Rooms No violations recorded.
Deficiency	CARPET: WORN/DETERIORATED
Deficiency Location/Instance	Rooms 127, 151, 213, Near Room 219
Deficiency Quantity	40
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Room 151 No violations recorded.
<b>Walls</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	GYPSON BOARD: DETERIORATED
Deficiency Location/Instance	Near 2nd Floor Toilet Rooms, Near Rooms 110, 221, Rooms 214, 243, and others
Deficiency Quantity	120
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2



**NYC Department of Education  
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q732

Question	Response
<b>INTERIOR</b>	
<b>CLASSROOMS/CORRIDORS/ADMIN SPACES</b>	
<b>Walls</b>	Inspected
Deficiency Photo1	
Violations	Near 2nd Floor Toilet Rooms No violations recorded.
<b>Specialties</b>	Does not Exist
<b>GYMNASIUM</b>	Does not Exist
<b>INTERIOR DOOR HARDWARE</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>INTERIOR GUARDS</b>	Does not Exist
<b>KITCHEN</b>	Does not Exist
<b>LIBRARY</b>	Does not Exist
<b>LOCKER ROOM</b>	Does not Exist
<b>MULTI-PURPOSE ROOM</b>	Does not Exist
<b>SCIENCE DEMO ROOM</b>	Does not Exist
<b>SCIENCE LAB</b>	Does not Exist
<b>SCIENCE PREP ROOM</b>	Does not Exist
<b>SHOWER ROOM</b>	Does not Exist
<b>STAIRS/RAMPS: INTERIOR</b>	Inspected
Do Letter Stair Signs Exist?	Yes
<b>Ceiling</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Door(s)</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Partition</b>	Does not Exist
<b>Railings</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Stairs and Landings</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Walls</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>TOILET ROOMS - STAFF</b>	Inspected
<b>Ceiling</b>	Inspected
Condition	5 - Poor

**NYC Department of Education  
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q732

Question	Response
<b>INTERIOR</b>	
<b>TOILET ROOMS - STAFF</b>	
<b>Ceiling</b>	
Deficiency	GYP SUM BOARD: DAMAGED/DETERIORATED
Deficiency Location/Instance	In Room 243
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	In Room 243 No violations recorded.
Deficiency	ACOUSTIC TILES: DAMAGED/MISSING
Deficiency Location/Instance	1st Floor Men, 1st Floor Women
Deficiency Quantity	20
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	1st Floor Men No violations recorded.
<b>Door(s)</b>	Inspected
Condition	5 - Poor
Deficiency	METAL: DETERIORATED DOOR AND FRAME
Deficiency Location/Instance	2nd Floor Men
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education  
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q732

Question	Response
<b>INTERIOR</b>	
<b>TOILET ROOMS - STAFF</b>	
<b>Door(s)</b>	
Deficiency Photo1	
Violations	2nd Floor Men No violations recorded.
<b>Floor Finish</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Stalls</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Walls</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	GYPSUM BOARD: DETERIORATED
Deficiency Location/Instance	1st Floor Men
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	1st Floor Men No violations recorded.
Deficiency	CERAMIC TILE: BROKEN/ MISSING
Deficiency Location/Instance	2nd Floor Men
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education  
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection


Q732

Question	Response
<b>INTERIOR</b>	
<b>TOILET ROOMS - STAFF</b>	
Walls	
Deficiency Photo1	
Violations	2nd Floor Men No violations recorded.
<b>TOILET ROOMS - STUDENTS</b>	Does not Exist
<b>LIFE SAFETY</b>	Inspected
<b>F.D. HOLDING AREA</b>	Does not Exist
<b>STEEL STAIRS</b>	Does not Exist
<b>SITE</b>	Inspected
<b>CONTAINERIZATION</b>	Does not Exist
<b>Drainage System for Asphalt</b>	Does not Exist
<b>Drainage System for Concrete</b>	Inspected
<b>Catch Basins/Manhole - Surrounded by concrete</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Culverts - Concrete Covering</b>	Does not Exist
<b>Drainage System for Soil</b>	Does not Exist
<b>DRINKING FOUNTAINS</b>	Does not Exist
<b>FENCES</b>	Inspected
Condition	3 - Fair
Deficiency	CHAIN LINK: DAMAGED/DETERIORATED
Deficiency Location/Instance	Sutphin Boulevard
Deficiency Quantity	50
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Sutphin Boulevard No violations recorded.
<b>IRRIGATION SYSTEM</b>	Does not Exist

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection



Q732

Question	Response
<b>SITE</b>	
<b>PAVING</b>	Inspected
<b>Student Non-Use</b>	Inspected
Gravel Exists?	No
<b>Asphalt</b>	Does not Exist
<b>Concrete</b>	Inspected
Condition	3 - Fair
Deficiency	DAMAGED/DETERIORATED/MISSING SECTIONS
Deficiency Location/Instance	Driveway
Deficiency Quantity	50
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Driveway No violations recorded.
<b>Pavers</b>	Does not Exist
<b>Student Use</b>	Does not Exist
<b>Site Sidewalks &amp; Walkways</b>	Inspected
<b>Asphalt</b>	Does not Exist
<b>Concrete</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	DAMAGED/DETERIORATED/MISSING SECTIONS
Deficiency Location/Instance	Sutphin Boulevard
Deficiency Quantity	25
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Sutphin Boulevard No violations recorded.

**NYC Department of Education  
Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q732

Question	Response
<b>SITE</b>	
<b>PAVING</b>	
<b>Site Sidewalks &amp; Walkways</b>	Inspected
<b>Pavers</b>	Does not Exist
<b>DOT Sidewalk</b>	Inspected
<b>Asphalt</b>	Does not Exist
<b>Concrete</b>	Inspected
Condition	3 - Fair
Deficiency	DAMAGED CURBS
Deficiency Location/Instance	Sutphin Boulevard
Deficiency Quantity	10
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Sutphin Boulevard
Violations	No violations recorded.
Deficiency	DAMAGED/DETERIORATED/MISSING SECTIONS
Deficiency Location/Instance	Sutphin Boulevard
Deficiency Quantity	150
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Sutphin Boulevard
Violations	No violations recorded.
<b>Pavers</b>	Does not Exist
<b>PLAYGROUNDS</b>	Does not Exist
<b>PLAYING SURFACE</b>	Does not Exist
<b>RETAINING WALLS</b>	Does not Exist
<b>SEATING</b>	Does not Exist

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

Q732

<b>Question</b>	<b>Response</b>
<b>SITE</b>	Inspected
<b>SITE WALLS (NOT RETAINING WALLS)</b>	Does not Exist
<b>STAIRS/RAMPS: EXTERIOR</b>	Does not Exist
<b>ARTWORK</b>	Does not Exist