Building Condition Assessment Survey 2023 - 2024

Inspection Id Inspection Type		Time In	Last Edited
EE: Q781 Electrical		2024-01-30 7:47 AM	2024-02-12 12:35 PN
Asset Data			
Question	Answer		
Type of Service	Below Gro	und	
Does Interactive Whiteboard (IWB) Exist?	Yes		
Water Penetration in Electrical Room?	No		
Have any Systems/Major Building Components been upgraded?	Yes		
	Systems:	IPDVS/CCTV System	
	Years:	Under Construction	
	Systems:	Retrofitted LED Lighting (Multi Classrooms), LAN, Retrofitted S	
	Years:	2023	· · · · · · · · · · · · · · · · · · ·
	Systems:	Intrusion Alarm System (Panic S 2022	Switch)
	Years:	Grounding System	
	Systems: Years:	2021	
	Systems:	LED Lighting (Corridors)	
	Years:	2018	
	Systems:	Security Lights (Exterior Wall), Lighting, Exit/Emergency Light	
	Years:	2016	
	Systems:	Intrusion Alarm System	
	Years:	2012	
	Systems:	Molded Case Circuit Breaker Ty	pe Panel Board
	Years:	2005, 2018, 2023	
	Systems:	All Other Electrical Systems and	l Components
	Years:	2005	
DEDICATED INTERCOMS IN FIRE RESCUE AREAS			
Question Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	Response No		
Priority Condition			
Priority Priority Condition Component Location Condition Exist Category Description Affected Description Last Year?	Person(s) on Notified	Person(s) Title Status	PhotoImage
No condition recorded			
nspection			
Question	Respons	se	
Electrical			
AUDITORIUM	Does not	Exist	
CAFETERIA	Does not	Exist	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected	d	
Lighting	Inspected	d	
Does a Chandelier exist?	No		
Lighting Fixture - Fluorescent	Inspected	d	
<u> </u>	Inspected		
Pendant Mounted	- F	een Good and Fair	
Pendant Mounted Condition	2 - Betwe		
Condition		iencies recorded	
		iencies recorded	

Building Condition Assessment Survey 2023 - 2024

Question	Response
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Inspected
Pendant Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
COMPUTER LAB	Does not Exist
GYMNASIUM	Does not Exist
KITCHEN	Inspected
Instance on Basement	Inspected
Lighting	Inspected
Instance on Basement	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement	Inspected
Pendant Mounted	Does not Exist
Instance on Basement	Does not Exist
Surface Mounted	Does not Exist
Instance on Basement	Does not Exist
Recessed Mounted	Inspected
Instance on Basement	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Basement	Does not Exist
Lighting Fixture - Incandescent	
Instance on Basement	Does not Exist
Lighting Fixture - LED	
Instance on Basement	Does not Exist
LIBRARY	Does not Exist
LOCKER ROOM	Does not Exist
MULTIPURPOSE ROOM	Inspected
Instance on Basement - North, Basement - South	Inspected
Lighting	Inspected
Instance on Basement - North, Basement - South	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement - North, Basement - South	Inspected
Pendant Mounted	Does not Exist
	2000 not 2 not

Building Condition Assessment Survey 2023 - 2024

Question	Response
MULTIPURPOSE ROOM	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	Does not Exist
Instance on Basement - North, Basement - South	Does not Exist
Surface Mounted	Does not Exist
Instance on Basement - North, Basement - South	Does not Exist
Recessed Mounted	Inspected
Instance on Basement - North, Basement - South	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Basement - North, Basement - South	Does not Exist
Lighting Fixture - Incandescent	
Instance on Basement - North, Basement - South	Does not Exist
Lighting Fixture - LED	
Instance on Basement - North, Basement - South	Inspected
Pendant Mounted	Inspected
Instance on Basement - North, Basement - South	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Instance on Basement - North, Basement - South	Does not Exist
Recessed Mounted	Does not Exist
Instance on Basement - North, Basement - South	Does not Exist
Local Sound System	Inspected
Instance on Basement - North, Basement - South	Inspected
Installation Year	2005
Source of Installation	Documented
Condition	3 - Fair
Deficiency	No deficiencies recorded
Projection System	Does not Exist
Instance on Basement - North, Basement - South	Does not Exist
Theater Lighting System	Does not Exist
Instance on Basement - North, Basement - South	Does not Exist
SCIENCE DEMO ROOM	Does not Exist
SCIENCE LAB	Does not Exist
SCIENCE PREP ROOM	Does not Exist
SWIMMING POOL	Does not Exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Inspected 2. Part of the LET.
Condition	2 - Between Good and Fair
Deficiency Recessed Mounted	No deficiencies recorded
	Does not Exist
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist

Building Condition Assessment Survey 2023 - 2024

Question	Response
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - LED	Does not Exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Recessed Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Replacement Quantity	24,000
Replacement Uom	S.F.
Condition	3 - Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not Exist
EMERGENCY GENERATOR SET	Does not Exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not Exist
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Does not Exist
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Does not Exist
EXIT/EMERGENCY LIGHT	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
FIRE ALARM SYSTEM	Inspected
Replacement Quantity	24,000
Replacement Uom	S.F.
Bell/Horn	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Manual Pull Station	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded

Building Condition Assessment Survey 2023 - 2024

icai inspection		Q'
estion	Response	
IRE ALARM SYSTEM		
Fan Shutdown Control	Does not Exist	
Duct Smoke Detector	Does not Exist	
Area Smoke Detector	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
CO Detector	Does not Exist	
Heat Detector	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Elevator Recall	Does not Exist	
Magnetic Door Holder/Contactor	Does not Exist	
Fused Cutout Panel	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Digital Communicator	Does not Exist	
Main Panel	Inspected	
Bell At Panel	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Electrical Room	
Instance Condition	3 - Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Instance Manufacturer	Edwards System Technology	
Equipment	Fire Alarm Control Panel	
Model	EST 2	
Installation Year	2005	
Source of Installation	Documented	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Standard)	Does not Exist	
Sub-Panel	Does not Exist	
Remote Annunciator	Inspected	
Display Monitor	Does not Exist	
Panel	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Printer	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Punch Register	Does not Exist	
Sprinkler Flow/Air Pressure Switch	Does not Exist	
Tamper Flow Switch/Chain	Does not Exist	
ROUNDING SYSTEM	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
NTERCOM SYSTEM	Does not Exist	
AN	Inspected	

Building Condition Assessment Survey 2023 - 2024

Question	Response
LAN	
Local Distribution Frame (I/LDF)	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not Exist
MOTOR CONTROLLER	Does not Exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Does not Exist
Fused Knife Switch Type	Does not Exist
Fused Toggle Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
PUBLIC ADDRESS SYSTEM	Inspected
Replacement Quantity	24,000
Replacement Uom	S.F.
Instance	MDF Room 18.4
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Dukane 60
Installation Year	2005
Source of Installation	Documented
Deficiency	No deficiencies recorded
SECURITY	Inspected
IPDVS/CCTV System	Under Construction
Intrusion Alarm System	Inspected
Replacement Quantity	24,000
Replacement Uom	S.F.
Central Control Panel	Inspected
Instance	MDF Room 18.4
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	N/A
Installation Year	2012
Source of Installation	Inspector Estimate
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	2 - Between Good and Fair

Building Condition Assessment Survey 2023 - 2024

Question	Response
SECURITY	
Intrusion Alarm System	Inspected
Remote Annunciator	Inspected
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting - Security	Inspected
Replacement Uom	EACH
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
SERVICE SWITCH	Inspected
Instance	Electrical Room
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Delta Metal Product
Equipment	Main Service Disconnect
Capacity/Size Quantity	400
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2005
Source of Installation	Documented
Deficiency	No deficiencies recorded
SWITCHBOARD	Inspected
Number of Spares	1
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	General Electric
Equipment	N/A
Capacity/Size Quantity	400
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	1
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Nameplate
Installation Year	2005
Source of Installation	Documented
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Does not Exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	3 - Fair
Condition	J 1 WII

Building Condition Assessment Survey 2023 - 2024

Question	Response
TELEPHONE SYSTEM	Inspected
Standard	
Deficiency	No deficiencies recorded
TRANSFORMER	Does not Exist