Building Condition Assessment Survey 2023 - 2024

Asset:	PS 150 AN	NEX - QUEEN	IS, 41-12 44TH	STREET, New	York, 11104			
Inspection Io	d Inspection	п Туре				Time In		Last Edited
EE : Q79	97 Electrical					2023-11-	14 12:49 PM	2023-12-01 5:29 PM
sset Data								
Question					Answer			
Type of Service	ce				Below Gro	und		
Does Interacti	ve Whiteboard	(IWB) Exist?			Yes			
	tion in Electric				Yes			
Have any Syst	tems/Major Bu	llding Components	been upgraded?		Yes			
					Systems:	LAN		
					Years:	2021		
					Systems:	System	gency Light, Sec	curity Lights, Telephone
					Years:	2018		5 1) T
					Systems:	System (Central		ery Pack), Intrusion Alarn
					Years:	2017	D 11' A 11	0 4 1 10 1
					Systems:	System	m, Public Addr	ess System, Local Sound
					Years:	2014	(T 1 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	MILIC C
					Systems:	Breaker Type Pa		ost Molded Case Circuit sion Alarm System
					Years:	2007		
	DINTERCOM	IS IN FIRE RESC	CUE AREAS		D			
	Life Rescue A	ssistance Areas, Four building?	ire Rescue Areas,		Response No			
Priority Conditi								
Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
	Water Penetration in Electrical Roo	N/A m	Electrical Equipment	Boiler Room	Danilo Cosico	Cleaner	Sent to DSF	
nspection								
Question					Respons	se		
Electrical								
AUDITORIU	J M				Does not	Exist		
CAFETERIA					Does not			
		R/ADMINISTRA	TIME CDACE		Inspected			
	WI/CORKIDO	KADWIINISTKA	TIVE SPACE					
Lighting	es a Chandelier	awist?			Inspected No	1		
	Fixture - Fluo	rescent			Inspected			
	nt Mounted				Inspected	i		
Cond					3 - Fair			
	ficiency					iencies recorded		
	e Mounted				Inspected	i		
Cond					3 - Fair			
	ficiency					iencies recorded		
	ed Mounted				Does not			
	Fixture - HID				Does not	Exist		
Lighting	Fixture - Inca	ndescent			Does not	Exist		
WSP (P)				Dogo	1 of 8			Print Date: 6/25/2024

Building Condition Assessment Survey 2023 - 2024

Question	Response	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE		
Lighting		
Lighting Fixture - LED	Does not Exist	
COMPUTER LAB	Does not Exist	
GYMNASIUM	Does not Exist	
KITCHEN	Does not Exist	
LIBRARY	Inspected	
Instance on Room 001	Inspected	
Lighting	Inspected	
Instance on Room 001	Inspected	
Lighting Fixture - Fluorescent	mspecce	
Instance on Room 001	Inspected	
Pendant Mounted		
Instance on Room 001	Does not Exist Does not Exist	
Surface Mounted	Inspected	
Instance on Room 001 Condition	Inspected 3 - Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not Exist	
Instance on Room 001	Does not Exist	
Lighting Fixture - HID	2003 100 2.1100	
Instance on Room 001	Does not Exist	
Lighting Fixture - Incandescent	Does not Exist	
Instance on Room 001	Does not Exist	
Lighting Fixture - LED	DOGS HOT EASST	
Instance on Room 001	Does not Exist	
Raceway With Receptacles	Does not Exist	
Instance on Room 001	Does not Exist	
Projection System	Does not Exist	
Instance on Room 001	Does not Exist Does not Exist	
LOCKER ROOM	Does not Exist	
MULTIPURPOSE ROOM		
Instance on Basement - Room 002, Basement - Room 004	Inspected Inspected	
Lighting	Inspected	
Instance on Basement - Room 002, Basement - Room 004	Inspected	
Lighting Fixture - Fluorescent		
Instance on Basement - Room 002, Basement - Room 004	Inspected	
Pendant Mounted Lectures on Resement - Resem 002 - Resement - Resem 004	Does not Exist	
Instance on Basement - Room 002, Basement - Room 004	Does not Exist	
Surface Mounted Instance on Pagement - Pagem 002 - Pagement - Pagem 004	Inspected	
Instance on Basement - Room 002, Basement - Room 004	Inspected	
Condition	3 - Fair No deficiencies recorded	
Deficiency Recessed Mounted	Does not Exist	
Instance on Basement - Room 002, Basement - Room 004	Does not Exist Does not Exist	
	Does not Exist	
Lighting Fixture - HID Instance on Basement - Room 002, Basement - Room 004	Does not Exist	
	DUCS HOLEAIST	
Lighting Fixture - Incandescent Justines on Resement Ream 002 Resement Ream 004	Doos not Evist	
Instance on Basement - Room 002, Basement - Room 004	Does not Exist	10.5 10.00 1

Building Condition Assessment Survey 2023 - 2024

Question	Response
MULTIPURPOSE ROOM	
Lighting	Inspected
Lighting Fixture - LED	
Instance on Basement - Room 002, Basement - Room 004	Does not Exist
Local Sound System	Inspected
Instance on Basement - Room 002, Basement - Room 004	Inspected
Installation Year	2014
Source of Installation	Documented
Condition	3 - Fair
Deficiency	No deficiencies recorded
Projection System	Does not Exist
Instance on Basement - Room 002, Basement - Room 004	Does not Exist
Theater Lighting System	Does not Exist
Instance on Basement - Room 002, Basement - Room 004	Does not Exist
SCIENCE DEMO ROOM	Does not Exist
SCIENCE LAB	Does not Exist
SCIENCE PREP ROOM	Does not Exist
SWIMMING POOL	Does not Exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Replacement Quantity	22,000
Replacement Uom	S.F.
Condition	3 - Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not Exist
EMERGENCY GENERATOR SET	Does not Exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not Exist

Building Condition Assessment Survey 2023 - 2024

Inspected	
Inspected	
Does not Exist	
Inspected	
Inspected	
3 - Fair	
No deficiencies recorded	
Does not Exist	
Inspected	
1 - Good	
No deficiencies recorded	
Inspected	
22,000	
S.F.	
Inspected	
2 - Between Good and Fair	
No deficiencies recorded	
Inspected	
2 - Between Good and Fair	
No deficiencies recorded	
Inspected	
2 - Between Good and Fair	
No deficiencies recorded	
Does not Exist	
Does not Exist	
Inspected	
2 - Between Good and Fair	
No deficiencies recorded	
Inspected	
2 - Between Good and Fair	
No deficiencies recorded	
Inspected	
2 - Between Good and Fair	
No deficiencies recorded	
Does not Exist	
Does not Exist	
Inspected	
2 - Between Good and Fair	
No deficiencies recorded	
-	
Does not Exist	
Does not Exist Inspected	
Inspected	
Inspected Does not Exist	
Inspected Does not Exist Inspected	
Inspected Does not Exist Inspected Main Entrance Lobby	
	Inspected 1 - Good No deficiencies recorded Does not Exist Inspected Inspected 3 - Fair No deficiencies recorded Does not Exist Inspected 1 - Good No deficiencies recorded Inspected 2 - Good Inspected 2 - Between Good and Fair No deficiencies recorded Inspected 2 - Between Good and Fair No deficiencies recorded Inspected 2 - Between Good and Fair No deficiencies recorded Inspected 2 - Between Good and Fair No deficiencies recorded Inspected 2 - Between Good and Fair No deficiencies recorded Inspected 2 - Between Good and Fair No deficiencies recorded Does not Exist Does not Exist Inspected 2 - Between Good and Fair No deficiencies recorded Inspected 2 - Between Good and Fair No deficiencies recorded Inspected 2 - Between Good and Fair No deficiencies recorded Inspected 2 - Between Good and Fair No deficiencies recorded Inspected 2 - Between Good and Fair No deficiencies recorded Inspected 2 - Between Good and Fair No deficiencies recorded Inspected 2 - Between Good and Fair No deficiencies recorded Does not Exist Inspected 2 - Between Good and Fair No deficiencies recorded Does not Exist Inspected 2 - Between Good and Fair

Building Condition Assessment Survey 2023 - 2024

Question	Response
FIRE ALARM SYSTEM	
Main Panel	
Fire Alarm Control Panel (Electronic)	
Instance Manufacturer	Mircom
Equipment	Fire Alarm Control
Model	FX - 2000
Installation Year	2014
Source of Installation	Documented
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Does not Exist
Sub-Panel	Does not Exist
Remote Annunciator	Inspected
Display Monitor	Does not Exist
Panel	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Printer	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Punch Register	Does not Exist
Sprinkler Flow/Air Pressure Switch	Does not Exist
Tamper Flow Switch/Chain	Does not Exist
GROUNDING SYSTEM	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Does not Exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not Exist
MOTOR CONTROLLER	Inspected
Motor Control Center	Does not Exist
Motor Starter/Contactor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Does not Exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Does not Exist
Fused Knife Switch Type	Does not Exist
Fused Toggle Switch Type	Inspected
Condition	3 - Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH
Control of the contro	

Building Condition Assessment Survey 2023 - 2024

urear inspection		Qisi
uestion	Response	
PANEL BOARD		
Fused Toggle Switch Type		
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
Molded Case Circuit Breaker Type	Inspected	
Condition Condition	2 - Between Good and Fair	
Deficiency	NO SPARE	
Deficiency Location/Instance	Room 107	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	INSTALL NEW PANEL BOARD	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
Deficiency	PANEL BOARD BEYOND USEFUL LIFE	
Deficiency Location/Instance	Room A2	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
PUBLIC ADDRESS SYSTEM	Inspected	
Replacement Quantity	22,000	
Replacement Uom	S.F.	
Instance	Assistant Principal's Office	
Instance Condition	2 - Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Model	Bogen Multicom - 2000	
Installation Year	2014	
Source of Installation	Documented	
Deficiency	No deficiencies recorded	
SECURITY	Inspected	
IPDVS/CCTV System	Inspected	
Replacement Quantity	22,000	
Replacement Uom	S.F.	
Installation Year	1995	
Source of Installation	Inspector Estimate	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Intrusion Alarm System	Inspected	
Replacement Quantity	22,000	
Replacement Uom	S.F.	

Building Condition Assessment Survey 2023 - 2024

icai inspection		Q,		
estion	Response			
ECURITY				
Intrusion Alarm System				
Central Control Panel	Inspected			
Instance	Assistant Principal's Office			
Instance Condition	2 - Between Good and Fair			
Instance Quantity	1			
Instance Quantity Uom	EACH			
Model	Vista-128BPT			
Installation Year	2017			
Source of Installation	Custodial Staff			
Deficiency	No deficiencies recorded			
Infrared Sensor	Inspected			
Condition	3 - Fair			
Deficiency	No deficiencies recorded			
Panic Switch	Inspected			
Condition	3 - Fair			
Deficiency	No deficiencies recorded			
Remote Annunciator	Inspected			
Condition	3 - Fair			
Deficiency	No deficiencies recorded			
Siren/Strobe	Inspected			
Condition	3 - Fair			
Deficiency	No deficiencies recorded			
Lighting - Security	Inspected			
Replacement Uom	EACH			
Condition	2 - Between Good and Fair			
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE			
Deficiency Location/Instance	Exterior Wall by Exit 2			
Deficiency Quantity	1			
Quantity Uom	EACH			
Potential Action	REPLACE BALLAST			
Urgency of Action	PRIORITY 2			
Purpose of Action	LEVEL 3			
Deficiency Photo1	No photo recorded			
Violations	No violations recorded.			
ERVICE SWITCH	Inspected			
Instance	Boiler Room	-		
Instance Condition	3 - Fair			
Instance Quantity	1			
Instance Quantity Uom	ЕАСН			
Instance Manufacturer	Bulldog Electric Product Co.			
Equipment	N/A			
Capacity/Size Quantity	1,000			
Capacity/Size UOM	Amps			
	Nameplate			
Source of Capacity/Size Installation Year	1956			
Source of Installation	Documented No. definition in a mondad			
Deficiency WITCHING A RD	No deficiencies recorded			
WITCHBOARD	Inspected			
Number of Spares	2 Print Date	6/25/20		

Building Condition Assessment Survey 2023 - 2024

nestion	Response		
SWITCHBOARD			
Fused Disconnect Switch Type	Inspected		
Instance	Boiler Room		
Instance Condition	3 - Fair		
Instance Quantity	1		
Instance Quantity Uom	EACH		
Instance Manufacturer	Bulldog Electric Product Co.		
Equipment	N/A		
Capacity/Size Quantity	800		
Capacity/Size UOM	Amps Total		
Capacity/Size2 Quantity	1		
Capacity/Size2 UOM	Section(S)		
Source of Capacity/Size	Nameplate		
Installation Year	1956		
Source of Installation	Documented		
Deficiency	No deficiencies recorded		
Fused Knife Switch Type	Does not Exist		
Molded Case Circuit Breaker Type	Does not Exist		
ELEPHONE SYSTEM	Inspected		
PBX/Intercom	Inspected		
Condition	1 - Good		
Deficiency	No deficiencies recorded		
Standard	Inspected		
Condition	1 - Good		
Deficiency	No deficiencies recorded		
TRANSFORMER	Does not Exist		