Building Condition Assessment Survey 2023 - 2024

Asset:	TEL GIOITE		DENT - QUEE	110,02 01 110		VD, New York, 11		
Inspection Id	Inspection 7	Гуре				Time In		Last Edited
EE: Q823	Electrical					2024-02-2	0 12:43 PM	2024-06-21 12:07 PI
Asset Data								
Question					Answer			
Type of Service					Below Gro	und		
Does Interactive Whiteboard (IWB) Exist?				Yes				
Water Penetratio	on in Electrical	Room?			No			
Have any Syster	ms/Major Build	ing Components	been upgraded?		Yes			
					Systems:	Retrofitted LED S	urface Lightin	g (Room 101)
					Years:	2023		
					Systems:	Emergency Lighti	ng (Battery Pa	ck)
					Years:	2021		
					Systems:	Retrofitted Interio Mounted), LED L Telephone System	ighting (Excep	Lighting (Except Surface of Toilet Room),
					Years:	2018		
					Systems:	Toilet Room (LEI	D Lighting), Se	ecurity Lights
					Years:	2015		
					Systems:	Intrusion Alarm S	ystem, IPDVS	/CCTV System
					Years:	2005		
					Systems:	Fire Alarm System	n	
					Years:	1995		
					Systems:	Molded Case Circ	uit Breaker Ty	pe Panel Board
					Years:	1986, 2009		
					Systems:	Switchboard		
					Years:	1986		
DEDICATED I	INTERCOMS	IN FIRE RESC	UE AREAS					
Question					Response			
Are there any L and/or Holding	Life Rescue Ass Rooms in your	istance Areas, Fir building?	re Rescue Areas,		No			
riority Condition	n							
Priority Priority Condition Exist C Last Year?	riority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
	Vater Leaks nto Electrical	N/A	Lighting Fixture	4th Floor Corridor near	Donna Perez	Handyperson	Sent to DSF	
	Equipment			Elevator				
E				Elevator				
E				Elevator	Respons	se		
nspection				Elevator	Respons	se e		
nspection Question	quipment			Elevator	Respons Does not			
nspection Question Electrical AUDITORIUM	quipment			Elevator	Does not	Exist		
nspection Question Electrical AUDITORIUM CAFETERIA	quipment			Elevator	Does not	Exist Exist		
nspection Question Electrical AUDITORIUM CAFETERIA CLASSROOM	quipment	ADMINISTRAT	TIVE SPACE	Elevator	Does not Does not Inspected	Exist Exist		
nspection Question Electrical AUDITORIUM CAFETERIA CLASSROOM Lighting	A/CORRIDOR/		TIVE SPACE	Elevator	Does not Does not Inspected Inspected	Exist Exist		
nspection Question Electrical AUDITORIUM CAFETERIA CLASSROOM Lighting	quipment		TIVE SPACE	Elevator	Does not Does not Inspected	Exist Exist		
nspection Question Electrical AUDITORIUM CAFETERIA CLASSROOM Lighting Does	A/CORRIDOR/	xist?	TIVE SPACE	Elevator	Does not Does not Inspected Inspected	Exist Exist		
nspection Question Electrical AUDITORIUM CAFETERIA CLASSROOM Lighting Does Lighting Fi	A CORRIDOR a Chandelier ex	xist?	TIVE SPACE	Elevator	Does not Does not Inspected Inspected No	Exist Exist 1 1		
nspection Question Electrical AUDITORIUM CAFETERIA CLASSROOM Lighting Does Lighting Fi	//CORRIDOR/ a Chandelier exixture - Fluore Mounted	xist?	TIVE SPACE	Elevator	Does not Does not Inspected Inspected No Inspected	Exist Exist 1 1		
Section Question Electrical AUDITORIUM CAFETERIA CLASSROOM Lighting Does Lighting Fi Pendant Condition	(CORRIDOR/ a Chandelier exixture - Fluore Mounted ion	xist?	TIVE SPACE	Elevator	Does not Does not Inspected Inspected No Inspected Inspected Inspected Inspected Inspected Inspected	Exist Exist 1 1		
AUDITORIUM CAFETERIA CLASSROOM Lighting Does Lighting Fi Pendant Conditi	A //CORRIDOR/ a Chandelier exixture - Fluore Mounted ion ciency	xist?	TIVE SPACE	Elevator	Does not Does not Inspected Inspected No Inspected Inspected Inspected Inspected Inspected Inspected Inspected Inspected	Exist Exist d d d in initial		
nspection Question Electrical AUDITORIUM CAFETERIA CLASSROOM Lighting Does Lighting Fi Pendant Conditi	A CORRIDOR a Chandelier exixture - Fluore Mounted ion ciency Mounted	xist?	TIVE SPACE	Elevator	Does not Does not Inspected Inspected No Inspected Inspected Inspected Inspected Inspected Inspected	Exist Exist d d d in initial		

Building Condition Assessment Survey 2023 - 2024

Question	Domana
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Response
Lighting Lighting Fixture - Fluorescent	
Surface Mounted	
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	8
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Recessed Mounted	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Inspected
Pendant Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
COMPUTER LAB	Does not Exist
GYMNASIUM	Does not Exist
KITCHEN	Does not Exist
LIBRARY	Does not Exist
LOCKER ROOM	Does not Exist
MULTIPURPOSE ROOM	Does not Exist
SCIENCE DEMO ROOM	Does not Exist
SCIENCE LAB	Does not Exist
SCIENCE PREP ROOM	Does not Exist
SWIMMING POOL	Does not Exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	•
	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Does not Exist
Recessed Mounted	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Inspected

Building Condition Assessment Survey 2023 - 2024

Question	Response
TOILET ROOM - STAFF	
Lighting	
Lighting Fixture - LED	
Pendant Mounted	Does not Exist
Surface Mounted	Does not Exist
Recessed Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
TOILET ROOM - STUDENT	Does not Exist
AUXILIARY SIGNAL/BELL SYSTEM	Does not Exist
EMERGENCY DC STANDBY BATTERY POWER	Does not Exist
EMERGENCY GENERATOR SET	Does not Exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not Exist
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Non Battery Pack	Does not Exist
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Does not Exist
EXIT/EMERGENCY LIGHT	Does not Exist
FIRE ALARM SYSTEM	Inspected
Replacement Quantity	42,500
Replacement Uom	S.F.
Bell/Horn	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Strobe	Does not Exist
Manual Pull Station	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Does not Exist
Duct Smoke Detector	Does not Exist
Area Smoke Detector	Does not Exist
CO Detector	Does not Exist
Heat Detector	Does not Exist
Elevator Recall	Does not Exist
Magnetic Door Holder/Contactor	Does not Exist
Fused Cutout Panel	Inaccessible
Fire Alarm Digital Communicator	Inaccessible
Main Panel	Inspected
Bell At Panel	Does not Exist
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Main Entrance Lobby
Instance Condition	3 - Fair

Building Condition Assessment Survey 2023 - 2024

Question	Response
FIRE ALARM SYSTEM	
Main Panel	
Fire Alarm Control Panel (Electronic)	
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Edwards
Equipment	Fire Alarm / Communicator Control
Model	5800
Installation Year	1999
Source of Installation	Documented
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Does not Exist
Sub-Panel	Does not Exist
Remote Annunciator	Does not Exist
Sprinkler Flow/Air Pressure Switch	Inaccessible
Tamper Flow Switch/Chain	Inaccessible
GROUNDING SYSTEM	Inaccessible
INTERCOM SYSTEM	Inspected
Elevator	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Holding Area	Does not Exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not Exist
MOTOR CONTROLLER	Does not Exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Does not Exist
Fused Knife Switch Type	Does not Exist
Fused Toggle Switch Type	Does not Exist
Molded Case Circuit Breaker Type Condition	Inspected 3 - Fair
Deficiency	No deficiencies recorded
PUBLIC ADDRESS SYSTEM	Does not Exist
SECURITY	Inspected
Popleoment Questity	Inspected
Replacement Users	42,500
Replacement Uom	S.F.
Installation Year	2005
Source of Installation	Custodial Staff
Condition	4 - Between Fair and Poor
Deficiency	SYSTEM DEFECTIVE
Deficiency Location/Instance	Room 208A
Deficiency Quantity Description (D) Description (D)	1 Print Data (/05/0024

Building Condition Assessment Survey 2023 - 2024

trical hispection		Q02
uestion	Response	
SECURITY		
IPDVS/CCTV System		
Quantity Uom	EACH	
Potential Action	REPAIR SYSTEM	
Urgency of Action	PRIORITY 4	
Purpose of Action	LEVEL 3	
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
Intrusion Alarm System	Inspected	
Replacement Quantity	42,500	
Replacement Uom	S.F.	
Central Control Panel	Inspected	
Instance	Room 208A	
Instance Condition	4 - Between Fair and Poor	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Model	N/A	
Installation Year	2005	
Source of Installation	Custodial Staff	
	SYSTEM DEFECTIVE	
Deficiency Overtity	1	
Deficiency Quantity	EACH	
Quantity Uom		
Potential Action	REPAIR SYSTEM	
Urgency of Action	PRIORITY 4	
Purpose of Action	LEVEL 3	
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
Infrared Sensor	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Panic Switch	Does not Exist	
Remote Annunciator	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Siren/Strobe	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Lighting - Security	Inspected	
Replacement Uom	EACH	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
SERVICE SWITCH	Inaccessible	
SWITCHBOARD	Inaccessible	
TELEPHONE SYSTEM	Inspected	
PBX/Intercom	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Standard	Inspected	
Condition	1 - Good	

Building Condition Assessment Survey 2023 - 2024

Question	Response
TELEPHONE SYSTEM	Inspected
Standard	
Deficiency	No deficiencies recorded
TRANSFORMER	Does not Exist