Building Condition Assessment Survey 2023 - 2024

Inspection I	d Inspection	Гуре		·		Time In		Last Edited
EE : Q8		J.F.					16 8:45 AM	2024-01-26 2:07 PN
Asset Data								
Question					Answer			
Type of Servi	ice				Below Gro	und		
	ive Whiteboard (I'	WB) Exist?			Yes			
	ation in Electrical				No			
Have any Sys	tems/Major Build	ing Components	been upgraded?		Yes			
					Systems:	LAN		
					Years:	2022		
					Systems:	Fire Alarm Syste	em, Kitchen (Lig	ghting)
					Years:	2016		
					Systems:	Recessed Fluores Toilet Rooms (L		Except (General Office) Security Lights
					Years:	2015		
					Systems:	Telephone Syste	m	
					Years:	2014		
					Systems:	All Other Electri	cal Systems and	l Components
					Years:	1992		
DEDICATE	D INTERCOMS	IN FIRE RESC	CUE AREAS					
Question	Tic D	·	D 1		Response			
	y Life Rescue Assi ng Rooms in your		re Rescue Areas,		No			
Priority Conditi	ion							
Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
Yes	Emergency DC Standby Battery Power - Battery Bank Not Operational	N/A	EMERGENCY DC STANDBY BATTERY POWER	Electrical Room (Inside Kitchen)	Robert Cetina	Custodian	Sent to DSF	
nspection								
Question					Respons	e		
Electrical								
AUDITORIU	U M				Does not	Exist		
CAFETERIA				Inspected	1			
Ins	stance on 1st Floor	- Staff			Inspected			
Instance on 1st Floor - Students				Inspected				
Lighting					Inspected			
	stance on 1st Floor	Students		Inspected				
Instance on 1st Floor - Students Instance on 1st Floor - Staff								
					Inspected	1		
	Fixture - Fluores							
	stance on 1st Floor				Does not			
Instance on 1st Floor - Staff			Inspected					
Pendant Mounted				Does not				
Instance on 1st Floor - Staff			Does not Exist					
Surfac	ce Mounted			Does not Exist				
Instance on 1st Floor - Staff			Does not Exist					
Ins	stance on 1st Floor	- Stall				2.1150		

Building Condition Assessment Survey 2023 - 2024

tion	Response
FETERIA	
ighting	
Lighting Fixture - Fluorescent	
Recessed Mounted	
Instance on 1st Floor - Staff	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor - Students	Inspected
Instance on 1st Floor - Staff	Does not Exist
Pendant Mounted	Inspected
Instance on 1st Floor - Students	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	12
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Surface Mounted	Does not Exist
Instance on 1st Floor - Students	Does not Exist
Recessed Mounted	Does not Exist
Instance on 1st Floor - Students	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor - Students	Does not Exist
Instance on 1st Floor - Staff	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor - Students	Does not Exist
Instance on 1st Floor - Staff	Does not Exist
ocal Sound System	Inspected
Instance on 1st Floor - Students	Inspected
Installation Year	1992
Source of Installation	Documented
Condition	3 - Fair
Deficiency	No deficiencies recorded
Instance on 1st Floor - Staff	Does not Exist
Projection System	Does not Exist
Instance on 1st Floor - Students	Does not Exist
Instance on 1st Floor - Staff	Does not Exist
Cheater Lighting System	Does not Exist
Instance on 1st Floor - Students	Does not Exist Does not Exist
Instance on 1st Floor - Staff	Does not Exist
ASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected
Lighting	Inspected
Does a Chandelier exist?	No
Lighting Fixture - Fluorescent	Inspected

Building Condition Assessment Survey 2023 - 2024

estion	Response
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	3 - Fair
Condition	
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	8 EAGH
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1 LEVEL 2
Purpose of Action	
Deficiency Photo1 Violations	No photo recorded No violations recorded.
Surface Mounted	Inspected
Condition	3 - Fair
Deficiency Overtity	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	58
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Recessed Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
COMPUTER LAB	Does not Exist
YMNASIUM	Does not Exist
ITCHEN	Inspected
Instance on 1st Floor	Inspected
Lighting	Inspected
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Surface Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Recessed Mounted	Inspected

Building Condition Assessment Survey 2023 - 2024

Question	Response
KITCHEN	
Lighting	
Lighting Fixture - Fluorescent	
Recessed Mounted	
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not Exist
LIBRARY	Does not Exist
LOCKER ROOM	Does not Exist
MULTIPURPOSE ROOM	Does not Exist
SCIENCE DEMO ROOM	Does not Exist
SCIENCE LAB	Does not Exist
SCIENCE PREP ROOM	Does not Exist
SWIMMING POOL	Does not Exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Replacement Quantity	17,000
Replacement Uom	S.F.
Condition	3 - Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Inspected
·	

Building Condition Assessment Survey 2023 - 2024

Question	Response		
EMERGENCY DC STANDBY BATTERY POWER			
Condition	5 - Poor		
Deficiency	BATTERY BANK NOT OPERATIONAL		
Deficiency Location/Instance	Electrical Room (Inside Kitchen)		
Deficiency Quantity	1		
Quantity Uom	EACH		
Potential Action	REPLACE		
Urgency of Action	PRIORITY 5		
Purpose of Action	LEVEL 6		
Deficiency Photo1	No photo recorded		
Violations	No violations recorded.		
EMERGENCY GENERATOR SET	Does not Exist		
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not Exist		
EMERGENCY LIGHTING	Inspected		
Battery Pack	Inspected		
Condition	3 - Fair		
Deficiency	No deficiencies recorded		
Non Battery Pack	Inspected		
Condition	3 - Fair		
Deficiency	No deficiencies recorded		
EXIT LIGHT	Inspected		
Battery Pack	Inspected		
Condition	3 - Fair		
Deficiency	FIXTURE LAMP NOT OPERATIONAL		
Deficiency Location/Instance	Corridor by Room 125, Kitchen		
Deficiency Quantity	2		
Quantity Uom	EACH		
Potential Action	MAINTENANCE		
Urgency of Action	PRIORITY 5		
Purpose of Action	LEVEL 2		
Deficiency Photo1	No photo recorded		
Violations	No violations recorded.		
Non Battery Pack	Does not Exist		
EXIT/EMERGENCY LIGHT	Does not Exist		
FIRE ALARM SYSTEM	Inspected		
Replacement Quantity	17,000		
Replacement Uom	S.F.		
Bell/Horn	Inspected		
Condition	2 - Between Good and Fair		
Deficiency	No deficiencies recorded		
Strobe	Inspected		
Condition	2 - Between Good and Fair		
Deficiency	No deficiencies recorded		
Manual Pull Station	Inspected		
Condition	2 - Between Good and Fair		
Deficiency	No deficiencies recorded		
Fan Shutdown Control	Inspected		
Condition	2 - Between Good and Fair		
Deficiency	No deficiencies recorded		

Building Condition Assessment Survey 2023 - 2024

icai inspection		Qu
estion	Response	
IRE ALARM SYSTEM		
Duct Smoke Detector	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Area Smoke Detector	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
CO Detector	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Heat Detector	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Elevator Recall	Does not Exist	
Magnetic Door Holder/Contactor	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Fused Cutout Panel	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Digital Communicator	Does not Exist	
Main Panel	Inspected	
Bell At Panel	Does not Exist	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Main Entrance Lobby	
Instance Condition	2 - Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	ЕАСН	
Instance Manufacturer	Siemens	
Equipment	Fire Alarm Control Panel	
Model	FireFinder-XLS	
Installation Year	2016	
Source of Installation	Custodial Staff	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Standard)	Does not Exist	
Sub-Panel	Does not Exist	
Remote Annunciator	Inspected	
Display Monitor	Does not Exist	
Panel	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Printer	Does not Exist	
Punch Register	Does not Exist	
Sprinkler Flow/Air Pressure Switch	Does not Exist	
Tamper Flow Switch/Chain	Does not Exist	
ROUNDING SYSTEM	Inaccessible	
NTERCOM SYSTEM	Inaccessible Does not Exist	

Building Condition Assessment Survey 2023 - 2024

Question	Response
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Does not Exist
LIGHTNING PROTECTION	Does not Exist
MOTOR CONTROLLER	Inspected
Motor Control Center	Does not Exist
Motor Starter/Contactor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Does not Exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not Exist
Fused Toggle Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
PUBLIC ADDRESS SYSTEM	Inspected
Replacement Quantity	17,000
Replacement Uom	S.F.
Instance	General Office
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	N/A
Installation Year	1992
Source of Installation	Documented
Deficiency	No deficiencies recorded
SECURITY	Inspected
IPDVS/CCTV System	Does not Exist
Intrusion Alarm System	Inspected
Replacement Quantity	17,000
Replacement Uom	S.F.
Central Control Panel	Inspected
Instance	General Office
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	N/A
Installation Year	1996
Source of Installation	Inspector Estimate
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<u> </u>	

Building Condition Assessment Survey 2023 - 2024

urear inspection	· ·
uestion	Response
SECURITY	
Intrusion Alarm System	
Panic Switch	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Lighting - Security	Inspected
Replacement Uom	EACH
Condition	2 - Between Good and Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Location/Instance	Building Perimeter, Pole
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 3
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
SERVICE SWITCH	Does not Exist
SWITCHBOARD	Inspected
Number of Spares	1
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room (Inside Kitchen)
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	ЕАСН
Instance Quantity Con	Siemens
Equipment	N/A
Capacity/Size Quantity	800
Capacity/Size UOM	Amps Total
	•
Capacity/Size2 Quantity	1
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Nameplate
Installation Year	1992
Source of Installation	Documented
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Does not Exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Standard	Inspected

Building Condition Assessment Survey 2023 - 2024

Question	Response		
TELEPHONE SYSTEM	Inspected		
Standard			
Deficiency	No deficiencies recorded		
TRANSFORMER	Does not Exist		