# **Building Condition Assessment Survey 2023 - 2024**

Inspection Id Inspection Type		Time In	Last Edited
EE: Q885 Electrical		2024-04-18 8:29 AM	2024-04-25 9:12 AN
sset Data			
Question	Answer		
Type of Service	Below Gro	und	
Does Interactive Whiteboard (IWB) Exist?	Yes		
Water Penetration in Electrical Room?	No		
Have any Systems/Major Building Components been upgraded?	Yes		
	Systems:	Intrusion Alarm System	
	Years:	2023	
	Systems:	Intercom System (Elevator), IPD	OVS/CCTV System
	Years:	2021	
	Systems:	All Other Electrical Systems and	Components
	Years:	1994	
DEDICATED INTERCOMS IN FIRE RESCUE AREAS	Dama		
Question  Are there any Life Rescue Assistance Areas, Fire Rescue Areas,	Response Yes		
and/or Holding Rooms in your building?	103		
Are dedicated intercoms available in all of these spaces for use during a fire?	No		
Which spaces do not have dedicated intercoms?	Multipurpo	ose Room, Room 302	
riority Condition			
Last Year? No condition recorded			
No condition recorded aspection			
No condition recorded aspection Question	Respons	se	
No condition recorded  spection  Question  Electrical	<u> </u>		
No condition recorded  Ispection  Question  Electrical  AUDITORIUM	Does not	Exist	
No condition recorded  Ispection  Question  Electrical  AUDITORIUM  CAFETERIA	Does not Inspected	Exist	
No condition recorded  Ispection  Question  Electrical  AUDITORIUM	Does not	Exist	
No condition recorded  Ispection  Question  Electrical  AUDITORIUM  CAFETERIA	Does not Inspected Inspected Inspected	Exist d d	
No condition recorded  Ispection  Question  Electrical  AUDITORIUM  CAFETERIA  Instance on Basement	Does not Inspected Inspected	Exist d d	
No condition recorded  Ispection  Question  Electrical  AUDITORIUM  CAFETERIA  Instance on Basement  Lighting	Does not Inspected Inspected Inspected	Exist d d	
No condition recorded  Ispection  Question  Electrical  AUDITORIUM  CAFETERIA  Instance on Basement  Lighting  Instance on Basement	Does not Inspected Inspected Inspected	Exist d d d	
No condition recorded  Ispection  Question  Electrical  AUDITORIUM  CAFETERIA  Instance on Basement  Lighting  Instance on Basement  Lighting Fixture - Fluorescent	Does not Inspected Inspected Inspected Inspected Inspected	Exist d d d d	
No condition recorded  Ispection  Question  Electrical  AUDITORIUM  CAFETERIA  Instance on Basement  Lighting  Instance on Basement  Lighting Fixture - Fluorescent  Instance on Basement	Does not Inspected Inspected Inspected Inspected Inspected Inspected	Exist  d d d d t Exist	
No condition recorded  Ispection  Question  Electrical  AUDITORIUM  CAFETERIA  Instance on Basement  Lighting  Instance on Basement  Lighting Fixture - Fluorescent  Instance on Basement  Pendant Mounted	Does not Inspected Inspect	Exist  d  d  d  d  d  Exist  Exist	
No condition recorded  Ispection  Question  Electrical  AUDITORIUM  CAFETERIA  Instance on Basement  Lighting  Instance on Basement  Lighting Fixture - Fluorescent  Instance on Basement  Pendant Mounted  Instance on Basement	Does not Inspected Inspected Inspected Inspected Inspected Inspected Inspected Does not Does not	Exist  d  d  d  d  d  f  Exist  Exist  Exist	
No condition recorded  Spection  Question  Electrical  AUDITORIUM  CAFETERIA  Instance on Basement  Lighting  Instance on Basement  Lighting Fixture - Fluorescent  Instance on Basement  Pendant Mounted  Instance on Basement  Surface Mounted	Does not Inspected Inspected Inspected Inspected Inspected Inspected Does not Does not Does not	Exist  d d d d t Exist Exist Exist Exist Exist	
No condition recorded  Spection  Question  Electrical  AUDITORIUM  CAFETERIA  Instance on Basement  Lighting  Instance on Basement  Lighting Fixture - Fluorescent  Instance on Basement  Pendant Mounted  Instance on Basement  Surface Mounted  Instance on Basement	Does not Inspected Inspected Inspected Inspected Inspected Inspected Does not Does not Does not Does not Does not	Exist  d  d  d  d  d  Exist  Exist  Exist  Exist  Exist	
No condition recorded  Spection  Question  Electrical  AUDITORIUM  CAFETERIA  Instance on Basement  Lighting  Instance on Basement  Lighting Fixture - Fluorescent  Instance on Basement  Pendant Mounted  Instance on Basement  Surface Mounted  Instance on Basement  Recessed Mounted	Does not Inspected Inspected Inspected Inspected Inspected Inspected Inspected Does not Does not Does not Inspected Inspected	Exist  d  d  d  d  d  Exist  Exist  Exist  Exist  Exist	
No condition recorded  spection  Question  Electrical  AUDITORIUM  CAFETERIA  Instance on Basement  Lighting  Instance on Basement  Lighting Fixture - Fluorescent  Instance on Basement  Pendant Mounted  Instance on Basement  Surface Mounted  Instance on Basement  Recessed Mounted  Instance on Basement  Recessed Mounted  Instance on Basement	Does not Inspected Inspected Inspected Inspected Inspected Inspected Inspected Does not Does not Does not Inspected	Exist  d  d  d  d  d  Exist  Exist  Exist  Exist  Exist	ΓΙVE
No condition recorded  spection  Question  Electrical  AUDITORIUM  CAFETERIA  Instance on Basement  Lighting  Instance on Basement  Lighting Fixture - Fluorescent  Instance on Basement  Pendant Mounted  Instance on Basement  Surface Mounted  Instance on Basement  Recessed Mounted  Instance on Basement  Condition	Does not Inspected Inspected Inspected Inspected Inspected Inspected Does not Does not Does not Inspected	Exist  d d d d t Exist Exist Exist Exist d d d d d d d d d d d d d d d d d d d	TIVE
No condition recorded  spection  Question  Electrical  AUDITORIUM  CAFETERIA  Instance on Basement  Lighting  Instance on Basement  Lighting Fixture - Fluorescent  Instance on Basement  Pendant Mounted  Instance on Basement  Surface Mounted  Instance on Basement  Recessed Mounted  Instance on Basement  Condition  Deficiency	Does not Inspected Inspected Inspected Inspected Inspected Inspected Does not Does not Does not Inspected	Exist  d d d d t Exist Exist Exist Exist d d d d d d d d d d d d d d d d d d d	TIVE
No condition recorded  Spection  Question  Electrical  AUDITORIUM  CAFETERIA  Instance on Basement  Lighting  Instance on Basement  Lighting Fixture - Fluorescent  Instance on Basement  Pendant Mounted  Instance on Basement  Surface Mounted  Instance on Basement  Recessed Mounted  Instance on Basement  Condition  Deficiency  Deficiency Quantity	Does not Inspected Inspected Inspected Inspected Inspected Inspected Does not Does not Does not Inspected	Exist  d d d d t Exist Exist Exist Exist d d d d d d d d d d d d d d d d d d d	TIVE
No condition recorded  Ispection  Question  Electrical  AUDITORIUM  CAFETERIA  Instance on Basement  Lighting  Instance on Basement  Lighting Fixture - Fluorescent  Instance on Basement  Pendant Mounted  Instance on Basement  Surface Mounted  Instance on Basement  Recessed Mounted  Instance on Basement  Condition  Deficiency  Deficiency Quantity  Quantity Uom	Does not Inspected Inspected Inspected Inspected Inspected Inspected Does not Does not Does not Inspected	Exist  d  d  d  d  Exist Exist Exist Exist  Exist Cxist Cxis	TIVE
No condition recorded  Spection  Question  Electrical  AUDITORIUM  CAFETERIA  Instance on Basement  Lighting  Instance on Basement  Lighting Fixture - Fluorescent  Instance on Basement  Pendant Mounted  Instance on Basement  Surface Mounted  Instance on Basement  Recessed Mounted  Instance on Basement  Condition  Deficiency  Deficiency Quantity  Quantity Uom  Potential Action	Does not Inspected Inspected Inspected Inspected Inspected Inspected Does not Does not Does not Inspected	Exist  d d d d d d Exist Exist Exist Exist D Exist Exist C Exist D Exist	ΓΙVE

# **Building Condition Assessment Survey 2023 - 2024**

stion	Response
AFETERIA	
Lighting	
Lighting Fixture - Fluorescent	
Recessed Mounted	
Violations	No violations recorded.
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	25
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
	140 violations recorded.
Lighting Fixture - HID	
Instance on Basement	Does not Exist
Lighting Fixture - Incandescent	
Instance on Basement	Does not Exist
Lighting Fixture - LED	
Instance on Basement	Does not Exist
Local Sound System	Inspected
Instance on Basement	Inspected
Installation Year	1994
Source of Installation	Documented
Condition	3 - Fair
Deficiency	No deficiencies recorded
Projection System	Does not Exist
Instance on Basement	Does not Exist
Theater Lighting System	Does not Exist
Instance on Basement	Does not Exist
LASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected
Lighting	Inspected
Does a Chandelier exist?	No
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	21
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1

# **Building Condition Assessment Survey 2023 - 2024**

stion	Response
LASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	Inspected
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Surface Mounted	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	12
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	497
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Recessed Mounted	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	18
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	567
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Lighting Fixture - HID Lighting Fixture - Incandescent	Does not Exist  Does not Exist
Lighting Fixture - LED	Does not Exist  Does not Exist
OMPUTER LAB	Does not Exist  Does not Exist
YMNASIUM	Inspected
Instance on 2nd Floor	Inspected
mistance on 2nd rioor	торски

# **Building Condition Assessment Survey 2023 - 2024**

icai inspection	Y
stion	Response
YMNASIUM	
Lighting	Inspected
Instance on 2nd Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 2nd Floor	Inspected
Pendant Mounted	Does not Exist
Instance on 2nd Floor	Does not Exist
Surface Mounted	Does not Exist
Instance on 2nd Floor	Does not Exist
Recessed Mounted	Inspected
Instance on 2nd Floor	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Lighting Fixture - HID	
Instance on 2nd Floor	Inspected
Pendant Mounted	Does not Exist
Instance on 2nd Floor	Does not Exist
Surface Mounted	Inspected
Instance on 2nd Floor	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Recessed Mounted	Does not Exist
Instance on 2nd Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 2nd Floor	Does not Exist
Lighting Fixture - LED	
Instance on 2nd Floor	Does not Exist
Local Sound System	Inspected
Instance on 2nd Floor	Inspected
Installation Year	1994
Source of Installation	Documented
Condition	3 - Fair
Deficiency	No deficiencies recorded
Projection System	Does not Exist
Instance on 2nd Floor	Does not Exist

### **Building Condition Assessment Survey 2023 - 2024**

**Electrical Inspection** Q885 Question Response GYMNASIUM Scoreboard Does not Exist Instance on 2nd Floor Does not Exist Theater Lighting System Does not Exist Instance on 2nd Floor Does not Exist KITCHEN Inspected

TCHEN	Inspected
Instance on Basement	Inspected
Lighting	Inspected
Instance on Basement	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement	Inspected
Pendant Mounted	Does not Exist
Instance on Basement	Does not Exist
Surface Mounted	Inspected
Instance on Basement	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Recessed Mounted	Inspected
Instance on Basement	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	23
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Lighting Fixture - HID  Instance on Basement	Does not Exist
	DOES HOLEXIST
Instance on Basement	Does not Exist
	DOES HOLEXIST
Instance on Basement	Does not Exist
instance on dascincill	DOGS HOLEXIST

# **Building Condition Assessment Survey 2023 - 2024**

Response  Does not Exist
Does not Exist
Does not Exist
Inspected
Inspected
Inspected
Inspected
Inspected
Does not Exist
Inspected
Inspected
3 - Fair
LIGHTING FIXTURE BALLAST DEFECTIVE
6
EACH
REPLACE BALLAST
PRIORITY 3
LEVEL 2
No photo recorded
No violations recorded.
LIGHTING FIXTURE BEYOND USEFUL LIFE
34
EACH
REPLACE-UPGRADE
PRIORITY 1
LEVEL 2
No photo recorded
No violations recorded.
Does not Exist
Does not exist
Does not Exist
DOES HOL EXIST
Does not Exist
Inspected
Inspected
1994
Documented
5 - Poor
AMPLIFIER NOT OPERATIONAL
AMPLIFIER NOT OPERATIONAL  1
I EACH
EACH REPLACE SYSTEM
PRIORITY 2
LEVEL 2

### **Building Condition Assessment Survey 2023 - 2024**

Response
Inspected
No violations recorded.
Does not Exist
Does not Exist
Inspected
Inspected
Inspected
5 - Poor
DIMMING RACK/LIGHT CONSOLE NOT OPERATIONAL
1
EACH
REPLACE
PRIORITY 3
LEVEL 2
No photo recorded
No violations recorded.
Inspected
3 - Fair
LIGHTING FIXTURE BEYOND USEFUL LIFE
86
EACH
REPLACE-UPGRADE
PRIORITY 1
LEVEL 2
No photo recorded
No violations recorded.
Does not Exist
Inspected
Inaccessible
Does not Exist
Does not Exist
Inspected
Inspected
Inspected
Does not Exist
Inspected
3 - Fair
LIGHTING FIXTURE BEYOND USEFUL LIFE
1
EACH
REPLACE-UPGRADE
PRIORITY 1
LEVEL 2
No photo recorded

### **Building Condition Assessment Survey 2023 - 2024**

on LET ROOM - STAFF	Response
ghting	
Lighting Fixture - Fluorescent	
Recessed Mounted	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
LET ROOM - STUDENT	Inspected
ghting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Does not Exist
Recessed Mounted	Inspected
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	24
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Violations  Lighting Fixture - HID	No violations recorded.  Does not Exist

# **Building Condition Assessment Survey 2023 - 2024**

ectrical inspection		Q005
Question	Response	
TOILET ROOM - STUDENT	Inspected	
Lighting		
Lighting Fixture - Incandescent	Does not Exist	
Lighting Fixture - LED	Does not Exist	
AUXILIARY SIGNAL/BELL SYSTEM	Inspected	
Replacement Quantity	65,000	
Replacement Uom	S.F.	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
EMERGENCY DC STANDBY BATTERY POWER	Does not Exist	
EMERGENCY GENERATOR SET	Inspected	
Automatic Transfer Switch (ATS)	Inspected	
Instance	Penthouse	
Instance Condition	3 - Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Instance Manufacturer	Cummins Onan	
Equipment	Elevator	
Capacity/Size Quantity	225	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	1994	
Source of Installation	Documented	
Deficiency	No deficiencies recorded	
Instance	Penthouse	
Instance Condition	3 - Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Instance Manufacturer	Cummins Onan	
Equipment	Fire Alarm Transfer	
Capacity/Size Quantity	40	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	1994	
Source of Installation	Documented	
Deficiency	No deficiencies recorded	
Instance	Penthouse	
Instance Condition	3 - Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Instance Manufacturer	Cummins Onan	
Equipment	Transfer Switch #1	
Capacity/Size Quantity	1,600	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	1994	
Source of Installation	Documented	
Deficiency	No deficiencies recorded	
Instance	Penthouse	

### **Building Condition Assessment Survey 2023 - 2024**

-	11		Qui
estion		Response	
MERGENCY GI	ENERATOR SET		
Automatic Tran	sfer Switch (ATS)		
Instance	Condition	3 - Fair	
Instance	Quantity	1	
Instance	Quantity Uom	EACH	
Instance	Manufacturer	Cummins Onan	
Equipme	nt	EDP	
Capacity	Size Quantity	225	
Capacity	/Size UOM	Amps	
Source o	f Capacity/Size	Nameplate	
Installati	on Year	1994	
Source o	f Installation	Documented	
Deficien	су	No deficiencies recorded	
Battery Charger		Inspected	
Instance		Penthouse	
Instance	Condition	3 - Fair	
Instance	Quantity	1	
Instance	Quantity Uom	EACH	
Instance	Manufacturer	Cummins Onan	
Equipme	nt	Battery Charger	
Capacity	Size Quantity	10	
Capacity	/Size UOM	AmpsDC	
Capacity	/Size2 Quantity	24	
Capacity	/Size2 UOM	VDC	
Source o	f Capacity/Size	Nameplate	
Installati	on Year	1994	
Source o	f Installation	Documented	
Deficien	су	No deficiencies recorded	
<b>Emergency Dist</b>	ribution Board	Inspected	
Number	of Spares	0	
Fused Disconn	ect Switch Type	Inspected	
Instance		Penthouse	
Instance	Condition	3 - Fair	
Instance	Quantity	1	
Instance	Quantity Uom	EACH	
Instance	Manufacturer	All City Switchboard	
Equipme	nt	N/A	
Capacity	Size Quantity	1,600	
Capacity	/Size UOM	Amps Total	
Capacity	/Size2 Quantity	3	
Capacity	/Size2 UOM	Section(S)	
Source o	f Capacity/Size	Emergency Distribution Board Mains Size	
Installati	on Year	1994	
Source o	fInstallation	Documented	
Deficien	ру	No deficiencies recorded	
Molded Case (	Circuit Breaker Type	Does not Exist	
Diesel		Inspected	
Instance		Penthouse	
Instance	Condition	3 - Fair	

### **Building Condition Assessment Survey 2023 - 2024**

Question	Response
EMERGENCY GENERATOR SET	
Diesel	
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Cummins Onan
Equipment	Emergency Generator
Capacity/Size Quantity	343
Capacity/Size UOM	KVA
Capacity/Size2 Quantity	275
Capacity/Size2 UOM	KW
Capacity/Size3Quantity	954
Capacity/Size3 UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1994
Source of Installation	Documented
Deficiency	No deficiencies recorded
Natural Gas	Does not Exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not Exist
EMERGENCY LIGHTING	Inspected
Battery Pack	
Condition	Inspected 3 - Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Does not Exist
EXIT LIGHT	
-	Inspected
Battery Pack	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Does not Exist
EXIT/EMERGENCY LIGHT	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
FIRE ALARM SYSTEM	Inspected
Replacement Quantity	65,000
Replacement Uom	S.F.
Bell/Horn	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Manual Pull Station	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Inspected
Condition	3 - Fair
Duct Smoke Detector	No deficiencies recorded
Condition	Inspected 3 - Fair
	No deficiencies recorded
Deficiency	no deficiencies recorded

# **Building Condition Assessment Survey 2023 - 2024**

	Qu
Response	
Inspected	
3 - Fair	
No deficiencies recorded	
Does not Exist	
Does not Exist	
Inspected	
3 - Fair	
No deficiencies recorded	
Does not Exist	
Inspected	
3 - Fair	
No deficiencies recorded	
Does not Exist	
Inspected	
Inspected	
3 - Fair	
No deficiencies recorded	
Inspected	
Main Entrance Lobby	
3 - Fair	
1	
EACH	
Notifier	
N/A	
System 5000	
1994	
Documented	
No deficiencies recorded	
Does not Exist	
Inspected	
Does not Exist	
Inspected	
Main Entrance Lobby	
3 - Fair	
1	
EACH	
Space Age Electronics	
N/A	
N/A	
1994	
Documented	
No deficiencies recorded	
Does not Exist	
Inspected	
Does not Exist	
Does not Exist  Inspected	
	Inspected  3 - Fair No deficiencies recorded Does not Exist Does not Exist Inspected 3 - Fair No deficiencies recorded Does not Exist Inspected 3 - Fair No deficiencies recorded Does not Exist Inspected 3 - Fair No deficiencies recorded Does not Exist Inspected Inspected Inspected Inspected Inspected Inspected Main Entrance Lobby 3 - Fair I EACH Notifier N/A System 5000 I994 Documented No deficiencies recorded Does not Exist Inspected Main Entrance Lobby 3 - Fair 1 EACH Notifier N/A System 5000 I994 Documented No deficiencies recorded Does not Exist Inspected Does not Exist Inspected Main Entrance Lobby 3 - Fair 1 EACH Space Age Electronics N/A N/A I994 Documented No deficiencies recorded Documented No deficiencies recorded

### **Building Condition Assessment Survey 2023 - 2024**

Question	Response
FIRE ALARM SYSTEM	
Remote Annunciator	
Printer	Inspected
Condition	5 - Poor
Deficiency	PRINTER NOT OPERATIONAL
Deficiency Location/Instance	Custodian's Office
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Punch Register	Does not Exist
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Tamper Flow Switch/Chain	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Inspected
Elevator	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Holding Area	Does not Exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not Exist
MOTOR CONTROLLER	Inspected
Motor Control Center	Does not Exist
Motor Starter/Contactor	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Does not Exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not Exist
Fused Toggle Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Inspected
	······································

# **Building Condition Assessment Survey 2023 - 2024**

Response
Inspected
3 - Fair
No deficiencies recorded
Inspected
65,000
S.F.
Room B6
3 - Fair
1
EACH
Rauland TC2100
1994
Documented
No deficiencies recorded
Inspected
Inspected
65,000
S.F.
2021
Custodial Staff
1 - Good
No deficiencies recorded
Inspected
65,000
S.F.
Inspected
Custodian's Office
1 - Good
1
EACH
Vista-128BPT
2023
Documented
No deficiencies recorded
Inspected
1 - Good
No deficiencies recorded
Inspected
1 - Good
No deficiencies recorded
Inspected
1 - Good
No deficiencies recorded
Inspected
nispected
1 - Good
1 - Good

# **Building Condition Assessment Survey 2023 - 2024**

Question	Response
SECURITY	
Lighting - Security	
Condition	3 - Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Location/Instance	Exterior Walls (Building Perimeter)
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 3
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
SERVICE SWITCH	Inspected
Instance	Electrical Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	All City Switchboard
Equipment	Main Switch Renaissance School
Capacity/Size Quantity	4,000
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1994
Source of Installation	Documented
Deficiency	No deficiencies recorded
SWITCHBOARD	Inspected
Number of Spares	0
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room
Instance Condition	3 - Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	All City Switchboard
Equipment	N/A
Capacity/Size Quantity	4,000
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	3
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Service Switch Size
Installation Year	1994
Source of Installation	Documented
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Does not Exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Standard	Inspected

### **Building Condition Assessment Survey 2023 - 2024**

Question	Response
TELEPHONE SYSTEM	Inspected
Standard	
Condition	3 - Fair
Deficiency	No deficiencies recorded
TRANSFORMER	Does not Exist