Building Condition Assessment Survey 2023 - 2024

Asset:	P.S. 892 - Q	UEENS, 199-1	0 112TH AVE	NUE, New Yor	·k, 11412			
Inspection Io	d Inspection	Туре				Time In		Last Edited
EE : Q89	92 Electrical					2024-01-	18 7:50 AM	2024-01-24 2:32 PN
Asset Data								
Question					Answer			
Type of Service	ce				Below Gro	ound		
	ve Whiteboard (I				Yes			
	tion in Electrical				No			
Have any Syst	tems/Major Build	ling Components	been upgraded?		Yes			
					Systems:	Gymnasium (LE	D Lighting)	
					Years: Systems:	2023 LAN		
					Years:	2022		
					Systems:		cal Sound Syste	m, Projection System)
					Years:	2018	cai Souliu Syste	iii, i rojection system)
					Systems:	Exit Lights (Batt	erv Pack)	
					Years:	2015, 2023	cry ruck)	
					Systems:	All Other Electri	cal Systems and	1 Components
					Years:	2015	5 , 5 com 5 and	- components
DEDICATEI	D INTERCOMS	IN FIRE RESC	CUE AREAS					
Question					Response			
Are there any	Life Rescue Ass	sistance Areas, Fi	re Rescue Areas,		No			
and/or Holdin	ng Rooms in you	building?						
riority Conditi	on							
Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
No	Intercom - Not Connected to Remote Monitoring Station	N/A	INTERCOM SYSTEM Elevator	Elevator - Device ID: 4P2953	Jonathan Villanueva	Fireman	Sent to DSF	
nspection								
Question					Respons	se		
Electrical								
AUDITORIU	J M				Does not	t Exist		
CAFETERIA	1				Inspecte	d		
Inst	tance on Baseme	nt			Inspecte	d		
Lighting					Inspecte	d		
Inst	tance on Baseme	nt			Inspecte	d		
Lighting	Fixture - Fluore	escent						
	tance on Baseme				Inspecte	d		
Pendar	nt Mounted				Does not	t Exist		
	tance on Baseme	nt			Does not			
Surface	e Mounted				Inspecte			
	tance on Baseme	nt			Inspected			
Cond						een Good and Fair		
-	ficiency					iencies recorded		
	ed Mounted							
	tance on Baseme	nt			Inspecte			
		III			Inspecte			
Cond						een Good and Fair		
	ficiency					iencies recorded		
WSP (P)				Page	1 of 12			Print Date: 6/25/202

Building Condition Assessment Survey 2023 - 2024

rical hispection		Qu.
estion	Response	
CAFETERIA		
Lighting		
Lighting Fixture - HID		
Instance on Basement	Does not Exist	
Lighting Fixture - Incandescent		
Instance on Basement	Does not Exist	
Lighting Fixture - LED		
Instance on Basement	Does not Exist	
Local Sound System	Inspected	
Instance on Basement	Inspected	
Installation Year	2015	
Source of Installation	Custodial Staff	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Projection System	Does not Exist	
Instance on Basement	Does not Exist	
Theater Lighting System	Does not Exist	
Instance on Basement	Does not Exist	
LASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected	
Lighting	Inspected	
Does a Chandelier exist?	No	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE	
Deficiency Quantity	4	
Quantity Uom	EACH	
Potential Action	REPLACE BALLAST	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
Recessed Mounted	Inspected	
Condition	2 - Between Good and Fair	
	LIGHTING FIXTURE BALLAST DEFECTIVE	
Deficiency Opentity		
Deficiency Quantity Quantity Uom	1 EACH	
Quantity Com Potential Action		
	REPLACE BALLAST	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
Lighting Fixture - HID	Does not Exist	
Lighting Fixture - Incandescent	Does not Exist	
Lighting Fixture - LED	Does not Exist	
COMPUTER LAB	Does not Exist	

Building Condition Assessment Survey 2023 - 2024

estion	Dagnanga
	Response
GYMNASIUM Instance on Percent	Inspected
Instance on Basement	Inspected
Lighting	Inspected
Instance on Basement	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement	Inspected
Pendant Mounted	Inspected
Instance on Basement	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Instance on Basement	Does not Exist
Recessed Mounted	Does not Exist
Instance on Basement	Does not Exist
Lighting Fixture - HID	
Instance on Basement	Does not Exist
Lighting Fixture - Incandescent	
Instance on Basement	Does not Exist
Lighting Fixture - LED	
Instance on Basement	Inspected
Pendant Mounted	Inspected
Instance on Basement	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Instance on Basement	Does not Exist
Recessed Mounted	Does not Exist
Instance on Basement	Does not Exist
Local Sound System	Inspected
Instance on Basement	Inspected
Installation Year	2018
Source of Installation	Custodial Staff
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Projection System	Inspected
Is the projector on a cart or installed on the ceiling?	Ceiling
Instance on Basement	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Scoreboard	Does not Exist
Instance on Basement	Does not Exist
Theater Lighting System	Inspected
Instance on Basement	Inspected
Dimming System	4 ******
Instance on Basement	Inspected
Condition	4 - Between Fair and Poor
Deficiency	DIMMING RACK/LIGHT CONSOLE NOT OPERATIONAL
Deficiency Quantity	DIMINING RACK/LIGHT CONSOLE NOT OPERATIONAL 1
	I EACH
Quantity Uom Potential Action	EACH REPAIR

Building Condition Assessment Survey 2023 - 2024

uestion	Response
GYMNASIUM	
Theater Lighting System	
Dimming System	
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Theater Lighting	
Instance on Basement	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
KITCHEN	Inspected
Instance on Basement	Inspected
Lighting	Inspected
Instance on Basement	Inspected
Lighting Fixture - Fluorescent	
Instance on Basement	Inspected
Pendant Mounted	Does not Exist
Instance on Basement	Does not Exist
Surface Mounted	Does not Exist
Instance on Basement	Does not Exist
Recessed Mounted	Inspected
Instance on Basement	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Basement	Does not Exist
Lighting Fixture - Incandescent	
Instance on Basement	Does not Exist
Lighting Fixture - LED	
Instance on Basement	Does not Exist
LIBRARY	
Instance on Room 203	Inspected Inspected
Lighting Instance on Room 203	Inspected
	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 203	Inspected
Pendant Mounted	Inspected
Instance on Room 203	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Instance on Room 203	Does not Exist
Recessed Mounted	Inspected
Instance on Room 203	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on Room 203	Does not Exist

Building Condition Assessment Survey 2023 - 2024

uestion	Response
LIBRARY	
Lighting	Inspected
Lighting Fixture - Incandescent	
Instance on Room 203	Does not Exist
Lighting Fixture - LED	
Instance on Room 203	Does not Exist
Raceway With Receptacles	Inspected
Instance on Room 203	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Projection System	Does not Exist
Instance on Room 203	Does not Exist
LOCKER ROOM	Does not Exist
MULTIPURPOSE ROOM	Does not Exist
SCIENCE DEMO ROOM	Does not Exist
SCIENCE LAB	Inspected
Instance on Room 210	Inspected
Power Panel	No
Alternative use	No
Lighting	Inspected
Instance on Room 210	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 210	Inspected
Pendant Mounted	Inspected
Instance on Room 210	Inspected
Condition	2 - Between Good and Fair
Deficiency Surface Mounted	No deficiencies recorded Does not Exist
Instance on Room 210	Does not Exist
Recessed Mounted	Does not Exist
Instance on Room 210	Does not Exist Does not Exist
Lighting Fixture - HID	DOGS HOL EARST
Instance on Room 210	Inspected
Pendant Mounted	Does not Exist
Instance on Room 210	Does not Exist
Surface Mounted	Inspected
Instance on Room 210	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Instance on Room 210	Does not Exist
Lighting Fixture - Incandescent	
Instance on Room 210	Does not Exist
Lighting Fixture - LED	
Instance on Room 210	Does not Exist
Emergency Gas Shut-Off Valve	Does not Exist
Instance on Room 210	Does not Exist
Emergency Shut-Off Power	Does not Exist
Instance on Room 210	Does not Exist

Building Condition Assessment Survey 2023 - 2024

estion	Response	
SCIENCE LAB	Inspected	
Power Supply	Does not Exist	
Instance on Room 210	Does not Exist	
Projection System	Does not Exist	
Instance on Room 210	Does not Exist Does not Exist	
SCIENCE PREP ROOM	Inspected	
Instance on Room 208	Inspected	
Power Panel	No	
Alternative use	No	
Lighting	Inspected	
Instance on Room 208	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 208	Inspected	
Pendant Mounted	Inspected	
Instance on Room 208	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Does not Exist	
Instance on Room 208	Does not Exist	
Recessed Mounted	Does not Exist	
Instance on Room 208	Does not Exist	
Lighting Fixture - HID		
Instance on Room 208	Does not Exist	
Lighting Fixture - Incandescent	2000 100 21100	
Instance on Room 208	Does not Exist	
Lighting Fixture - LED	DOGS HOT EXIST	
Instance on Room 208	Does not Exist	
Emergency Gas Shut-Off Valve	Does not Exist	
Instance on Room 208	Does not Exist	
Emergency Shut-Off Power	Does not Exist	
Instance on Room 208	Does not Exist	
Power Supply	Does not Exist	
Instance on Room 208	Does not Exist	
SWIMMING POOL	Does not Exist	
TOILET ROOM - STAFF	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Does not Exist	
Surface Mounted	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID	Does not Exist	
Lighting Fixture - Incandescent	Does not Exist	
Lighting Fixture - LED	Does not Exist	
FOILET ROOM - STUDENT		
TOTLET ROOM - STUDENT	Inspected	

Building Condition Assessment Survey 2023 - 2024

Question	Response
TOILET ROOM - STUDENT	
Lighting	
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Replacement Quantity	55,000
Replacement Uom	S.F.
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not Exist
EMERGENCY GENERATOR SET	Does not Exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not Exist
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	2 - Between Good and Fair
Deficiency	BATTERY NOT OPERATIONAL
Deficiency Location/Instance	Gymnasium
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE BATTERY
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 4
Deficiency Photo1	No photo recorded
Violations	35658000Z
Non Battery Pack	Does not Exist
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Does not Exist
EXIT/EMERGENCY LIGHT	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
FIRE ALARM SYSTEM	Inspected
Replacement Quantity	55,000
Replacement Uom	S.F.
Bell/Horn	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Strobe	Inspected

Building Condition Assessment Survey 2023 - 2024

ical hispection		Qu
estion	Response	
IRE ALARM SYSTEM		
Strobe	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Manual Pull Station	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Fan Shutdown Control	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Duct Smoke Detector	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Area Smoke Detector	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
CO Detector	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Heat Detector	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Elevator Recall	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Magnetic Door Holder/Contactor	Does not Exist	
Fused Cutout Panel	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Digital Communicator	Does not Exist	
Main Panel	Inspected	
Bell At Panel	Does not Exist	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Main Entrance Lobby	
Instance Condition	2 - Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Instance Manufacturer	Edwards System Technology	
Equipment	Fire Alarm Control Panel	
Model	EST 3	
Installation Year	2015	
Source of Installation	Documented	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Standard)	Does not Exist	
Sub-Panel	Does not Exist	
Remote Annunciator	Inspected	
Display Monitor	Does not Exist	
Panel	Inspected	
Condition	2 - Between Good and Fair	
* · · ·		

Building Condition Assessment Survey 2023 - 2024

Question	Response
FIRE ALARM SYSTEM	
Remote Annunciator	
Printer	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Punch Register	Does not Exist
Sprinkler Flow/Air Pressure Switch	Does not Exist
Tamper Flow Switch/Chain	Does not Exist
GROUNDING SYSTEM	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Inspected
Elevator	Inspected
Condition	2 - Between Good and Fair
Deficiency	NOT CONNECTED TO REMOTE MONITORING STATION
Deficiency Location/Instance	Elevator - Device ID: 4P2953
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL CONNECTION
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Holding Area	Does not Exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
MOTOR CONTROLLER	Inspected
Motor Control Center	Does not Exist
Motor Starter/Contactor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not Exist
Fused Toggle Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Inspected
monded Case Circuit Dicarci Type	nispected

Building Condition Assessment Survey 2023 - 2024

estion	Response	
ANEL BOARD	Inspected	
Molded Case Circuit Breaker Type		
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
UBLIC ADDRESS SYSTEM	Inspected	
Replacement Quantity	55,000	
Replacement Uom	S.F.	
Instance	MDF Room 410	
Instance Condition	2 - Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Model	Rauland Telecenter	
Installation Year	2015	
Source of Installation	Custodial Staff	
Deficiency	No deficiencies recorded	
ECURITY	Inspected	
IPDVS/CCTV System	Inspected	
Replacement Quantity	55,000	
Replacement Uom	S.F.	
Installation Year	2015	
Source of Installation	Custodial Staff	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Intrusion Alarm System	Inspected	
Replacement Quantity	55,000	
Replacement Uom	S.F.	
Central Control Panel	Inspected	
Instance	Custodian's Office	
Instance Condition	2 - Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Model	Vista-128BP	
Installation Year	2015	
Source of Installation	Custodial Staff	
Deficiency	No deficiencies recorded	
Infrared Sensor	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Panic Switch	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Remote Annunciator	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Siren/Strobe	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	SIREN/STROBE NOT ACTIVE	
Deficiency Location/Instance	Cafeteria	
Deficiency Quantity	1	

Building Condition Assessment Survey 2023 - 2024

Question	•	Response
SECUR	ITY	
Intrus	sion Alarm System	
Sire	en/Strobe	
	Potential Action	MAINTENANCE
	Urgency of Action	PRIORITY 4
	Purpose of Action	LEVEL 3
	Deficiency Photo1	No photo recorded
	Violations	No violations recorded.
Lighti	ing - Security	Inspected
Rep	lacement Uom	EACH
Con	dition	2 - Between Good and Fair
	Deficiency	No deficiencies recorded
SERVIC	CE SWITCH	Inspected
	Instance	Electrical Room C31 (Inside Receiving Room C17)
	Instance Condition	2 - Between Good and Fair
	Instance Quantity	1
	Instance Quantity Uom	EACH
	Instance Manufacturer	Electrotech
	Equipment	MRPP (1600 A4BQ)
	Capacity/Size Quantity	1,600
	Capacity/Size UOM	Amps
	Source of Capacity/Size	Nameplate
	Installation Year	2015
	Source of Installation	Documented
	Deficiency	No deficiencies recorded
	Instance	Electrical Room C31 (Inside Receiving Room C17)
	Instance Condition	2 - Between Good and Fair
	Instance Quantity	1
	Instance Quantity Uom	ЕАСН
	Instance Manufacturer	Electrotech
	Equipment	MDB (1200 A4BQ)
	Capacity/Size Quantity	1,200
	Capacity/Size UOM	Amps
	Source of Capacity/Size	Nameplate
	Installation Year	2015
	Source of Installation	Documented
	Deficiency	No deficiencies recorded
SWITC	HBOARD	Inspected
	Number of Spares	10
Fused	Disconnect Switch Type	Inspected
	Instance	Boiler Room 402
	Instance Condition	2 - Between Good and Fair
	Instance Quantity	1
	Instance Quantity Uom	EACH
	Instance Manufacturer	Electrotech
	Equipment	N/A
	Capacity/Size Quantity	1,600
	Capacity/Size UOM	Amps Total
	Capacity/Size2 Quantity	2

Building Condition Assessment Survey 2023 - 2024

estion	Response
SWITCHBOARD	
Fused Disconnect Switch Type	
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Service Switch Size
Installation Year	2015
Source of Installation	Documented
Deficiency	No deficiencies recorded
Instance	Electrical Room C31 (Inside Receiving Room C17)
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Electrotech
Equipment	Service Switchboard
Capacity/Size Quantity	1,200
Capacity/Size UOM	Amps Total
Capacity/Size2 Quantity	2
Capacity/Size2 UOM	Section(S)
Source of Capacity/Size	Nameplate
Installation Year	2015
Source of Installation	Documented
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not Exist
Molded Case Circuit Breaker Type	Does not Exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
TRANSFORMER	Does not Exist