Building Condition Assessment Survey 2023 - 2024

Inspection Id Inspection Type		Time In	Last Edited
EE: Q907 Electrical		2024-04-09 8:53 AM	2024-06-21 11:58 AM
Asset Data			
Question	Answer		
Type of Service	Below Gro	ound	
Does Interactive Whiteboard (IWB) Exist?	Yes		
Water Penetration in Electrical Room?	No		
Have any Systems/Major Building Components been upgraded?	Yes		
	Systems:	Retrofitted LED Lighting, Exit/Lights	Emergency Light, Security
	Years:	2023	
	Systems:	LAN	
	Years:	2022	
	Systems:	Auxiliary Signal/Bell System	
	Years:	2019	
	Systems:	Emergency Generator Set, Public Clocks), Telephone System	ic Address System (Excep
	Years:	2018	
	Systems:	Intrusion Alarm System (Panic S	Switch)
	Years:	2015	
	Systems:	Molded Case Circuit Breaker Ty	ype Panel Board
	Years:	2004, 2018	10
	Systems:	All Other Electrical Systems and	a Components
DEDUCATED INTERCOMONY FIRE DECOME A DEAG	Years:	2004	
DEDICATED INTERCOMS IN FIRE RESCUE AREAS Ouestion	Dognongo		
Are there any Life Rescue Assistance Areas, Fire Rescue Areas,	Response No		
and/or Holding Rooms in your building?			
Priority Condition			
Priority Priority Condition Component Condition Exist Category Description Affected Last Year?	Location Person(s) Description Notified	Person(s) Title Status	PhotoImage
No condition recorded			
nspection			
Question	Respon	se	
Electrical	*		
AUDITORIUM	Does no	ot Exist	
CAFETERIA	Does not Exist		
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspecte		
Lighting	Inspecte		
Does a Chandelier exist?	No	ou .	
		t Eviat	
Lighting Fixture - Fluorescent	Does not Exist		
Lighting Fixture - HID	Does not Exist		
Lighting Fixture - Incandescent	Does no	t Exist	
	Inspecte	ed	
Lighting Fixture - LED		t Exist	
Lighting Fixture - LED Pendant Mounted	Does no		
	Does no Inspecte	ed	
Pendant Mounted	Inspecte	een Good and Fair	
Pendant Mounted Surface Mounted	Inspecte 2 - Betw		
Pendant Mounted Surface Mounted Condition	Inspecte 2 - Betw	veen Good and Fair	
Pendant Mounted Surface Mounted Condition Deficiency	Inspecte 2 - Betw No defic Inspecte	veen Good and Fair	

Building Condition Assessment Survey 2023 - 2024

oction inspection	
Question	Response
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	
Lighting Fixture - LED	
Recessed Mounted	
Deficiency	No deficiencies recorded
COMPUTER LAB	Does not Exist
GYMNASIUM	Does not Exist
KITCHEN	Does not Exist
LIBRARY	Does not Exist
LOCKER ROOM	Does not Exist
MULTIPURPOSE ROOM	Inspected
Instance on 1st Floor	Inspected
Lighting	Inspected
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not Exist
Lighting Fixture - LED	
Instance on 1st Floor	Inspected
Pendant Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Surface Mounted	Does not Exist
Instance on 1st Floor	Does not Exist
Recessed Mounted	Inspected
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Local Sound System	Does not Exist
Instance on 1st Floor	Does not Exist
Projection System	Does not Exist
Instance on 1st Floor	Does not Exist
Theater Lighting System	Does not Exist
Instance on 1st Floor	Does not Exist
SCIENCE DEMO ROOM	Does not Exist
SCIENCE LAB	Does not Exist
SCIENCE PREP ROOM	Does not Exist
SWIMMING POOL	Does not Exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Does not Exist
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Inspected
Pendant Mounted	Does not Exist
Surface Mounted	Does not Exist Does not Exist
Sufface Mounted	DOGS HOL EXIST

Building Condition Assessment Survey 2023 - 2024

uestion	Response		
TOILET ROOM - STAFF	Inspected		
Lighting			
Lighting Fixture - LED	·		
Recessed Mounted	Inspected		
Condition Deficiency	2 - Between Good and Fair		
TOILET ROOM - STUDENT	No deficiencies recorded		
Lighting	Inspected		
<u> </u>	Inspected		
Lighting Fixture - Fluorescent	Does not Exist		
Lighting Fixture - HID	Does not Exist		
Lighting Fixture - Incandescent	Does not Exist		
Lighting Fixture - LED	Inspected		
Pendant Mounted	Does not Exist		
Surface Mounted	Does not Exist		
Recessed Mounted	Inspected		
Condition	2 - Between Good and Fair		
Deficiency	No deficiencies recorded		
AUXILIARY SIGNAL/BELL SYSTEM	Inspected		
Replacement Quantity	11,000		
Replacement Uom	S.F.		
Condition	1 - Good		
Deficiency	No deficiencies recorded		
EMERGENCY DC STANDBY BATTERY POWER	Does not Exist		
EMERGENCY GENERATOR SET	Inspected		
Automatic Transfer Switch (ATS)	Inspected		
Instance	Outdoor Electrical Enclosure - By Playground		
Instance Condition	2 - Between Good and Fair		
Instance Quantity	1		
Instance Quantity Uom	EACH		
Instance Manufacturer	Cummins Onan		
Equipment	ATS #1		
Capacity/Size Quantity	125		
Capacity/Size UOM	Amps		
Source of Capacity/Size	Nameplate		
Installation Year	2018		
Source of Installation	Custodial Staff		
Deficiency	No deficiencies recorded		
Instance	Outdoor Electrical Enclosure - By Playground		
Instance Condition	2 - Between Good and Fair		
Instance Quantity	1		
Instance Quantity Uom	EACH		
Instance Manufacturer	Cummins Onan		
Equipment	FA-ATS		
Capacity/Size Quantity	70		
Capacity/Size UOM	Amps		
Source of Capacity/Size	Nameplate		
Installation Year	2018		
Source of Installation	Custodial Staff		
Deficiency	No deficiencies recorded		

Building Condition Assessment Survey 2023 - 2024

Y	
Response	
Inspected	
Outdoor Electrical Enclosure - By Playground	
2 - Between Good and Fair	
1	
EACH	
SENS	
Battery Charger	
10	
AmpsDC	
24	
VDC	
Nameplate	
2018	
Custodial Staff	
No deficiencies recorded	
Does not Exist	
Does not Exist	
Inspected	
Outdoor Electrical Enclosure - By Playground	
2 - Between Good and Fair	
1	
EACH	
Cummins Onan	
Emergency Generator	
45	
KVA	
36	
KW	
125	
Amps	
Nameplate	
2018	
Custodial Staff	
No deficiencies recorded	
Does not Exist	
Does not Exist	
Does not Exist	
Inspected	
1 - Good	
No deficiencies recorded	
Inspected	
11,000	
S.F.	
Inspected	
3 - Fair	
2 1 411	
No deficiencies recorded	

Building Condition Assessment Survey 2023 - 2024

icai inspection		
estion	Response	
IRE ALARM SYSTEM		
Strobe	Inspected	
Deficiency	No deficiencies recorded	
Manual Pull Station	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Fan Shutdown Control	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Duct Smoke Detector	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Area Smoke Detector	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
CO Detector	Does not Exist	
Heat Detector	Does not Exist	
Elevator Recall	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Magnetic Door Holder/Contactor	Does not Exist	
Fused Cutout Panel	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Digital Communicator	Inspected	
Instance	Main Entrance Lobby	
Instance Condition	3 - Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Instance Manufacturer	Silent Knight	
Equipment	N/A	
Installation Year	2004	
Source of Installation	Documented	
Deficiency	No deficiencies recorded	
Main Panel	Inspected	
Bell At Panel	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Main Entrance Lobby	
Instance Condition	3 - Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Instance Manufacturer	Secutron	
Equipment	Fire Alarm Control Panel	
Model	MR-2900	
Installation Year	2004	
Source of Installation	Documented	
	No deficiencies recorded	

Building Condition Assessment Survey 2023 - 2024

Does not Exist	
Dogs not Exist	
Does not Exist	
Does not Exist	
Inspected	
3 - Fair	
No deficiencies recorded	
Inspected	
3 - Fair	
No deficiencies recorded	
Inspected	
3 - Fair	
No deficiencies recorded	
Inspected	
Inspected	
3 - Fair	
No deficiencies recorded	
Does not Exist	
Inspected	
Inspected	
1 - Good	
No deficiencies recorded	
Inspected	
1 - Good	
No deficiencies recorded	
Does not Exist	
Does not Exist	
Inspected	
Does not Exist	
Does not Exist	
Does not Exist	
Inspected	
3 - Fair	
No deficiencies recorded	
Inspected	
11,000	
S.F.	
General Office	
2 - Between Good and Fair	
1	
EACH	
Bogen-Power Vector WV150	
2018	
Custodial Staff	
CLOCK NOT OPERATIONAL	
Corridors by Rooms (102, 200), Multipurpose Room	
3	
EACH	
EACH	
EACH REPLACE	

Building Condition Assessment Survey 2023 - 2024

Electrical Inspection O907 Question Response PUBLIC ADDRESS SYSTEM Inspected Purpose of Action LEVEL 2 Deficiency Photo1 No photo recorded Violations No violations recorded. **SECURITY** Inspected IPDVS/CCTV System Does not Exist **Intrusion Alarm System** Inspected Replacement Quantity 11,000 S.F. Replacement Uom Central Control Panel Inspected Instance Electrical Closet (Inside Custodian's Office) Instance Condition 3 - Fair Instance Quantity 1 Instance Quantity Uom EACH Model Vista-128B 2004 Installation Year Source of Installation Documented Deficiency No deficiencies recorded **Infrared Sensor** Inspected Condition 3 - Fair No deficiencies recorded Deficiency Panic Switch Inspected Condition 2 - Between Good and Fair Deficiency No deficiencies recorded **Remote Annunciator** Inspected Condition 3 - Fair Deficiency No deficiencies recorded Siren/Strobe Inspected Condition 3 - Fair Deficiency No deficiencies recorded **Lighting - Security** Inspected Replacement Uom **EACH** Condition 1 - Good Deficiency No deficiencies recorded SERVICE SWITCH Does not Exist SWITCHBOARD Does not Exist TELEPHONE SYSTEM Inspected PBX/Intercom Inspected Condition 1 - Good Deficiency No deficiencies recorded Standard Inspected Condition 1 - Good No deficiencies recorded Deficiency

Does not Exist

TRANSFORMER