Building Condition Assessment Survey 2023-2024

Electrical Inspection R002

Asset:	I.S. 2 - STATEN ISLAND, 333 MIDLAND AVENUE, STATEN ISLAND, NY, 10306			
Inspection Id	ection Id Inspection Type Time In Last Edited			
4097	ELECTRICAL	2024-03-20 07:21AM	2024-04-09 09:22AM	

Asset Data Question

Have any Systems/Major Building Components been upgraded?	Systems:	Molded Case Circuit Breaker Panel Board
	Years:	2024, 2017, 2005

Systems: Interior Retrofitted LED Lighting, IPDVS / CCTV System, Exit Light, LAN

Years: 2021

Systems: Motor Starter Years: 2017, 2013

Systems: Emergency Generator Set, Service Switch,

Switchboard, Lightning Protection, Fused Disconnect Switch Type Panel Board, Variable Frequency Drive

Years: 2017

Answer

 $Systems: \quad Auditorium \ (LED \ Lighting), \ Gymnasium \ (Local \ Sound$

System) 2016

Years: 2016 Systems: Fire Alarm System, Grounding System

Years: 2015

Systems: Auditorium (Projection System, Local Sound System),

Gymnasium (Scoreboard), Intrusion Alarm System

(Infrared Sensor)

Years: 2014

Systems: Emergency Light/Exit Light Panel, Partial Emergency

Lighting (Battery Pack)

Years: 2013

Systems: Intrusion Alarm System

Years: 2003

Systems: Security Lighting

Years: 2001

Systems: Public Address System (Amplifier, Tuner)

Years: 1998 Below Ground Yes

Yes

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Does Interactive Whiteboard (IWB) Exist?

Water Penetration In Electrical Room?

DEDICATED INTERCOMS IN FIRE RESCUE AREAS	
Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in	No
your building?	

Priority Condition

Type of Service

Exist	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo
Last Year?	Category	Description	Affected	Description	Notified	Title	Image
Yes	Water Penetration in Electrical Room	Water penetrates into Electrical Room through Foundation Wall.	Electrical Equipment	Electrical Room B18	Nicholas Souto	Custodian	

Inspection

Question	Response	
Electrical		
ATHLETIC FIELD	Does not exist	
AUDITORIUM	Inspected	
Instance on 1st Floor	Inspected	

Building Condition Assessment Survey 2023-2024

Electrical Inspection	R002
Question	Dogwongo

Question	Response
AUDITORIUM	
House Lighting	
Instance on 1st Floor	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Surface Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Local Sound System	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Installation Year	2014
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Projection System	
Instance on 1st Floor	Inspected 2- Between Good and Fair
Instance Condition	
Is the projector on a cart or installed on the ceiling?	Ceiling No deficiencies recorded
Deficiency	No deficiencies recorded
Theater Lighting System Instance on 1st Floor	Inchested
Dimming System	Inspected
Instance on 1st Floor	Does not exist
	DOCS HOLCAIST
Theater Lighting Instance on 1st Floor	Inspected
Instance On 1st Floor Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE

Building Condition Assessment Survey 2023-2024

estion	Response	
AUDITORIUM		
Theater Lighting System		
Theater Lighting		
Deficiency Quantity	138	
Quantity Uom	EACH	
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
CAFETERIA	Inspected	
Instance on 1st Floor - Students	Inspected	
Instance on 1st Floor - Staff	Inspected	
Lighting	ı	
Instance on 1st Floor - Students	Inspected	
Instance on 1st Floor - Staff	Inspected	
Lighting Fixture - Fluorescent	1	
Instance on 1st Floor - Students	Does not exist	
Instance on 1st Floor - Staff	Does not exist	
Lighting Fixture - HID	2000 1000 011100	
Instance on 1st Floor - Students	Does not exist	
Instance on 1st Floor - Staff	Does not exist	
	Does not exist	
Lighting Fixture - Incandescent Instance on 1st Floor - Students	Does not exist	
Instance on 1st Floor - Staff	Does not exist	
	Does not exist	
Lighting Fixture - LED	Toron and a d	
Instance on 1st Floor - Students	Inspected	
Instance on 1st Floor - Staff	Inspected	
Pendant Mounted	D	
Instance on 1st Floor - Students	Does not exist	
Instance on 1st Floor - Staff	Does not exist	
Surface Mounted		
Instance on 1st Floor - Students	Does not exist	
Instance on 1st Floor - Staff	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 1st Floor - Students	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on 1st Floor - Staff	Does not exist	
Local Sound System		
Instance on 1st Floor - Students	Inspected	
Instance Condition	5- Poor	
Installation Year	1998	
Source of Installation Year	Documented	
Deficiency	AMPLIFIER NOT OPERATIONAL	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE SYSTEM	
Urgency of Action	PRIORITY 2	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Instance on 1st Floor - Staff	Does not exist	

Building Condition Assessment Survey 2023-2024

incui Inspection		1002
Question	Response	
CAFETERIA		
Projection System		
Instance on 1st Floor - Students	Does not exist	
Instance on 1st Floor - Staff	Does not exist	
Theater Lighting System		
Instance on 1st Floor - Students	Does not exist	
Instance on 1st Floor - Staff	Does not exist	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected	
Lighting	Inspected	
Does a Chandelier Exist?	No	
Lighting Fixture - Fluorescent	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Inspected	
Pendant Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
COMPUTER LAB	Inspected	
Instance on Room 221	Inspected	
Power Panel?	Yes	
Lighting		
Instance on Room 221	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 221	Does not exist	
Lighting Fixture - HID		
Instance on Room 221	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 221	Does not exist	
Lighting Fixture - LED		
Instance on Room 221	Inspected	
Pendant Mounted		
Instance on Room 221	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 221	Does not exist	
Recessed Mounted		
Instance on Room 221	Does not exist	
Raceway With Receptacles		
Instance on Room 221	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
GYMNASIUM	Inspected	
Instance on 1st Floor	Inspected	
Lighting		
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent	•	
Instance on 1st Floor	Does not exist	

Building Condition Assessment Survey 2023-2024

Electrical Inspection	R002
Question	Response

Question	Response
GYMNASIUM	
Lighting	
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Inspected
Pendant Mounted	•
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Does not exist
Local Sound System	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Installation Year	2016
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Projection System	
Instance on 1st Floor	Does not exist
Scoreboard	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Theater Lighting System	
Instance on 1st Floor	Does not exist
KITCHEN	Inspected
Instance on 1st Floor	Inspected
Lighting	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
LIBRARY	Inspected
Instance on Room 204	Inspected
mountee on Room 201	<u>-</u>

Building Condition Assessment Survey 2023-2024

Question	Response	
LIBRARY		
Lighting		
Instance on Room 204	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 204	Does not exist	
Lighting Fixture - HID		
Instance on Room 204	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 204	Does not exist	
Lighting Fixture - LED		
Instance on Room 204	Inspected	
Pendant Mounted		
Instance on Room 204	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 204	Does not exist	
Recessed Mounted		
Instance on Room 204	Does not exist	
Raceway With Receptacles		
Instance on Room 204	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Projection System		
Instance on Room 204	Does not exist	
LOCKER ROOM	Does not exist	
MULTIPURPOSE ROOM	Does not exist	
SCIENCE DEMO ROOM	Inspected	
Instance on Room 223	Inspected	
Power Panel?	No	
Alternative Use	Yes	
Lighting		
Instance on Room 223	Inspected	
Lighting Fixture - Fluorescent	•	
Instance on Room 223	Does not exist	
Lighting Fixture - HID		
Instance on Room 223	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 223	Does not exist	
Lighting Fixture - LED		
Instance on Room 223	Inspected	
Pendant Mounted		
Instance on Room 223	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 223	Does not exist	
Recessed Mounted		
Instance on Room 223	Does not exist	
Emergency Gas Shut-Off Valve		
Instance on Room 223	Does not exist	
Emergency Shut-Off Power		
Instance on Room 223	Does not exist	

Building Condition Assessment Survey 2023-2024

irea inspection		1002
Question	Response	
SCIENCE DEMO ROOM		
Power Supply		
Instance on Room 223	Does not exist	
Projection System		
Instance on Room 223	Does not exist	
SCIENCE LAB	Inspected	
Instance on Room 215	Inspected	
Power Panel?	Yes	
Alternative Use	No	
Lighting	110	
Instance on Room 215	Inspected	
Lighting Fixture - Fluorescent	- Improved	
Instance on Room 215	Does not exist	
Lighting Fixture - HID	Does not exist	
Instance on Room 215	Does not exist	
	Does not exist	
Lighting Fixture - Incandescent Instance on Room 215	Does not exist	
	Does not exist	
Lighting Fixture - LED	T 1	
Instance on Room 215	Inspected	
Pendant Mounted		
Instance on Room 215	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 215	Does not exist	
Recessed Mounted		
Instance on Room 215	Does not exist	
Emergency Gas Shut-Off Valve		
Instance on Room 215	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Emergency Shut-Off Power		
Instance on Room 215	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Power Supply		
Instance on Room 215	Does not exist	
Projection System		
Instance on Room 215	Does not exist	
SCIENCE PREP ROOM	Does not exist	
SWIMMING POOL	Does not exist	
TOILET ROOM - STAFF	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
Recessed Mounted	DOES HOLEXIST	

Building Condition Assessment Survey 2023-2024

T.
Response
Inspected
Does not exist
Does not exist
Does not exist
Inspected
Does not exist
Inspected
2- Between Good and Fair
No deficiencies recorded
Does not exist
Inspected
3- Fair
No deficiencies recorded
Does not exist
Inspected
Inspected
Room B20
2- Between Good and Fair
1
EACH
ASCO
ATS-1
400
Amps
Nameplate
2017
Documented
No deficiencies recorded
Room B20
2- Between Good and Fair
1
EACH
ASCO
ATS-2
30
Amps
Nameplate
2017
Documented
No deficiencies recorded
Inspected
Outside Generator Enclosure
2- Between Good and Fair
1
EACH
SENS
Battery Charger
10
AmpsDC
AmpsDC 26
VDC
VDC
Nemanlata
Nameplate 2017

Building Condition Assessment Survey 2023-2024

rical Inspection		KUU.
uestion	Response	
EMERGENCY GENERATOR SET		
Battery Charger		
Deficiency	No deficiencies recorded	
Emergency Distribution Board	Inspected	
Number of Spares	4	
Fused Disconnect Switch Type	Inspected	
Instance	Electrical Room B18	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Electrotech	
EquipmentId	EM Power Distribution Panel	
Capacity/Size Quantity	400	
Capacity/Size UOM	Amps Total	
Capacity/Size 2 Quantity	1	
Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Inspector Estimate 2017	
Installation Year Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Molded Case Circuit Breaker Type	Does not exist	
Diesel	Does not exist	
Natural Gas	Inspected	
Instance	Outside Generator Enclosure	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	MTU Onsite Energy Emergency Generator	
EquipmentId Capacity/Size Quantity	125	
Capacity/Size UOM	kVA	
Capacity/Size 2 Quantity	100	
Capacity/Size 2 UOM	kW	
Capacity/Size 3 Quantity	346	
Capacity/Size 3 UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	2017	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
EMERGENCY LIGHTING	Inspected	
Battery Pack	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	-
Non Battery Pack	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EXIT LIGHT	Inspected	
Battery Pack	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Non Battery Pack	Does not exist	
EXIT/EMERGENCY LIGHT	Does not exist	

Building Condition Assessment Survey 2023-2024

estion	Response	
IRE ALARM SYSTEM	Inspected	
Bell/Horn	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Strobe	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Manual Pull Station	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Fan Shutdown Control	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Duct Smoke Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Area Smoke Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
CO Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Heat Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Elevator Recall	Does not exist	
Magnetic Door Holder/Contactor	Does not exist	
Fused Cutout Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Digital Communicator	Does not exist	
Main Panel	Inspected	
Bell At Panel	Does not exist	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Main Entrance Lobby	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Gamewell	
Model	E3 Series	
EquipmentId	Fire Alarm Control Panel	
Installation Year	2015	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Standard)	Does not exist	
Sub-Panel	Does not exist	
Remote Annunciator	Inspected	
Display Monitor	Does not exist	
Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Printer	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	

Building Condition Assessment Survey 2023-2024

Question	Response	
FIRE ALARM SYSTEM		
Remote Annunciator		
Punch Register	Does not exist	
Sprinkler Flow/Air Pressure Switch	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Tamper Flow Switch/Chain	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
GROUNDING SYSTEM	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
INTERCOM SYSTEM	Does not exist	
LAN	Inspected	
Local Distribution Frame (I/LDF)	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Main Equipment Rack (MDF)	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
LIGHTNING PROTECTION	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
- · · · · · · · · · · · · · · · · · · ·		
MOTOR CONTROLLER	Inspected	
MOTOR CONTROL CENTER	Does not exist	
MOTOR STARTER/CONTACTOR Condition	Inspected 2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Variable Frequency Drive	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
<u> </u>		
PANEL BOARD	Inspected	
Fused Disconnect Switch Type	Inspected 2- Between Good and Fair	
Condition	No deficiencies recorded	
Deficiency		
Fused Knife Switch Type	Does not exist Does not exist	
Fused Toggle Switch Type Model Cose Cinneit Progles Type	Inspected	
Molded Case Circuit Breaker Type Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
PUBLIC ADDRESS SYSTEM	Inspected	
Instance	Main Office - Room 105 3- Fair	
Instance Condition	<u> </u>	
Instance Quantity	1 EACH	
Instance Quantity Uom		
Model	Rauland FAX 250	
Installation Year	1962	
Source of Installation Year	Documented CLOCK NOT OPERATIONAL	
Deficiency Location/Instance	CLOCK NOT OPERATIONAL Throughout the Puilding	
Deficiency Location/Instance Deficiency Quantity	Throughout the Building	
Quantity Uom	9 EACH	
Quantity Uom Potential Action	EACH REPLACE	
Urgency of Action	PRIORITY 3	
organicy or Action	1 MOM1 1 J	

Building Condition Assessment Survey 2023-2024

•		
Question	Response	
PUBLIC ADDRESS SYSTEM		
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Main Office - Room 105	
Deficiency Quantity	152,000	
Quantity Uom	S.F.	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
SECURITY	Inspected	
IPDVS/CCTV System	Inspected	
Condition	1- Good	
Installation Year	2021	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Intrusion Alarm System	Inspected	
Central Control Panel	Inspected	
Instance	Custodian's Office - Room 111	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Model	Vista - 128B	
Installation Year	2003	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Infrared Sensor	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Panic Switch	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Remote Annunciator	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Siren/Strobe	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting - Security	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
SERVICE SWITCH	Inspected	
	Electrical Room B18	
Instance Instance Condition	2- Between Good and Fair	
Instance Quantity	1 EACH	
Instance Quantity Uom	EACH	
Manufacturer	East Coast	
EquipmentId	Main. Switchboard	
Capacity/Size Quantity	3000	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Nameplate	
Installation Year	2017	
Source of Installation Year	Documented	

Building Condition Assessment Survey 2023-2024

uestion	Response	
SERVICE SWITCH		
Deficiency	No deficiencies recorded	
SWITCHBOARD	Inspected	-
Number of Spares	4	
Fused Disconnect Switch Type	Inspected	
Instance	Electrical Room B18	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	East Coast	
EquipmentId	N/A	
Capacity/Size Quantity	2000	
Capacity/Size UOM	Amps Total	
Capacity/Size 2 Quantity	3	
Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Nameplate	
Installation Year	2017	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fused Knife Switch Type	Does not exist	
Molded Case Circuit Breaker Type	Does not exist	
FELEPHONE SYSTEM	Inspected	
PBX/Intercom	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Standard	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
TRANSFORMER	Does not exist	